The right choice for the ultimate yield!

LS ELECTRIC strives to maximize your profits in gratitude for choosing us as your partner.

Programmable Logic Control

XGB Built-in Positioning

XGT Series

User Manual

XGB Modular Type XBC High-end/Standard Type XEC High-end/Standard Type





A Safety Instructions

- Read this manual carefully before installing, wiring, operating, servicing or inspecting this equipment.
- Keep this manual within easy reach for quick reference.



Before using the product ...

For your safety and effective operation, please read the safety instructions thoroughly before using the product.

- Safety Instructions should always be observed in order to prevent accident or risk with the safe and proper use the product.
- Instructions are divided into "Warning" and "Caution", and the meaning of the terms is as follows.

Warning This symbol indicates the possibility of serious injury or death if some applicable instruction is violated

⚠ Caution

This symbol indicates the possibility of severe or slight injury, and property damages if some applicable instruction is violated

Moreover, even classified events under its caution category may develop into serious accidents relying on situations. Therefore we strongly advise users to observe all precautions properly just like warnings.

► The marks displayed on the product and in the user's manual have the following meanings.

Be careful! Danger may be expected.

 $\underline{/4}$ Be careful! Electric shock may occur.

The user's manual even after read shall be kept available and accessible to any user of the product.

Safety Instructions for design process

- Please install a protection circuit on the exterior of PLC so that the whole system may operate safely regardless of failures from external power or PLC. Any abnormal output or operation from PLC may cause serious problems to safety in whole system.
 - Install protection units on the exterior of PLC like an interlock circuit that deals with opposite operations such as emergency stop, protection circuit, and forward/reverse rotation or install an interlock circuit that deals with high/low limit under its position controls.
 - If any system error (watch-dog timer error, module installation error, etc.) is detected during
 CPU operation in PLC, all output signals are designed to be turned off and stopped for safety.
 However, there are cases when output signals remain active due to device failures in Relay and
 TR which can't be detected. Thus, you are recommended to install an addition circuit to monitor
 the output status for those critical outputs which may cause significant problems.
- Never overload more than rated current of output module nor allow to have a short circuit.
 Over current for a long period time maycause a fire .
- Never let the external power of the output circuit to be on earlier than PLC power, which may cause accidents from abnormal output oroperation.
- Please install interlock circuits in the sequence program for safe operations in the system when exchange data with PLC or modify operation modes using a computer or other external equipments Read specific instructions thoroughly when conducting control operations with PLC.

Safety Instructions for design process

 I/O signal or communication line shall be wired at least 100mm away from a high-voltage cable or power line. Fail to follow this

Safety Instructions on installation process

- Use PLC only in the environment specified in PLC manual or general standard of data sheet. If not, electric shock, fire, abnormal operation of the product may be caused.
- Before install or remove the module, be sure PLC power is off. If not, electric shock or damage on the product may be caused.
- Be sure that every module is securely attached after adding a module or an extension connector. If the product is installed loosely or incorrectly, abnormal operation, error or dropping may be caused. In addition, contact failures under poor cable installation will be causing malfunctions as well.
- Be sure that screws get tighten securely under vibrating environments. Fail to do so will put the product under direct vibrations which will cause electric shock, fire and abnormal operation.
- Do not come in contact with conducting parts in each module, which may cause electric shock, malfunctions or abnormal operation.

3

Safety Instructions for wiring process

- Prior to wiring works, make sure that every power is turned off. If not, electric shock or damage on the product may be caused.
- After wiring process is done, make sure that terminal covers are installed properly before

its use. Fail to install the cover may cause electric shocks.

$\underline{\land}$ Caution

- Check rated voltages and terminal arrangements in each product prior to its wiring process. Applying incorrect voltages other than rated voltages and misarrangement among terminals may cause fire or malfunctions.
- Secure terminal screws tightly applying with specified torque. If the screws get loose, short circuit, fire or abnormal operation may be caused. Securing screws too tightly will cause damages to the module or malfunctions, short circuit, and dropping.
- Be sure to earth to the ground using Class 3 wires for FG terminals which is exclusively used for PLC. If the terminals not grounded correctly, abnormal operation or electric shock may be caused.
- Don't let any foreign materials such as wiring waste inside the module while wiring, which may cause fire, damage on the product or abnormal operation.
- Make sure that pressed terminals get tighten following the specified torque. External connector type shall be pressed or soldered using proper equipments.

Safety Instructions for test-operation and maintenance

- > Don't touch the terminal when powered. Electric shock or abnormal operation may occur.
- Prior to cleaning or tightening the terminal screws, let all the external power off including
 PLC power. If not, electric shock or abnormal operation may occur.
- Don't let the battery recharged, disassembled, heated, short or soldered. Heat, explosion or ignition may cause injuries or fire.
- Caution
 Do not make modifications or disassemble each module. Fire, electric shock or abnormal operation may occur.
 Prior to installing or disassembling the module, let all the external power off including PLC power. If not, electric shock or abnormal operation may occur.
 Keep any wireless equipment such as walkie-talkie or cell phones at least 30cm away from PLC. If not, abnormal operation may be caused.
 When making a modification on programs or using run to modify functions under PLC operations, read and comprehend all contents in the manual fully. Mismanagement will cause damages to products and accidents.
 Avoid any physical impact to the battery and prevent it from dropping as well. Damages to battery may cause leakage from its fluid. When battery was dropped or exposed under strong impact, never reuse the battery again. Moreover skilled workers are needed when exchanging

5

batteries.

Safety Instructions for waste disposal



• Product or battery waste shall be processed as industrial waste. The waste may discharge

toxic materials or explode itself.

Γ

Revision History

٦

Version	Date	Remark	Page
V 1.0	2008.1	1. Positioning first edition according to XGB user manual separation	
		2. Added contents	1-8
		(1) IO wiring method through smart link board	3-1
		(2) Positioning function list	3-26
		(3) How to check the positioning	6-1
		(4) Positioning monitoring package	8-1
		(5) Positioning trouble shooting method	01
		3. Modified contents	1-6
		(1) IO signal allocation	/ U
		(2) Positioning parameter setting method	+-1 5_1
		(3) Positioning instruction contents	5-1
		(4) Modifying safety precaution for safety	-
V1.1	2008.3	1. Added type and function according to developing XGB compact type basic unit (XBC-DxxxH)	-
V1.2	2009.8	1. Added type and function according to developing XGB compact type basic unit (XEC-DxxxH)	-
		(1) Description on positioning flag added	
		(2) Description on positioning instruction added	
		(3) Positioning program example added	
V1.4	2011.6	1. type and function according to developing XGB compact type	-
		basic unit (XBC-DxxxS(U)) added	
V1.5	2013.7	1. Motor Wiring Examples Added(XGT-Servo:XDL-S)	APP3-6, 7
		2. Modules(XB(E)C-DPxxSU) added	1-9,10
			2-2,3
V1.6	2013.12	1. PWM instruction added	5-47,95
		2. HOME, DOG Device Modified	3-2,3-3
		3. Domain Of Homepage Changed	Front/Back cover
V1.7	2015.07	1. Input/Output contact point list Added	Ch2, Ch8
		2. XEC Function block list Added	APP2
V1.8	2020.06	1. Changed company name to LS ELECTRIC	-
		2. Correction according to XGB Positioning K area	3-51, 3-52
		Flag for Positioning Instruction and Command	
V1.9	2022.09	1. Domain changed	-

 $\ensuremath{\mathbbmm}$ The number of User's manual is indicated right part of the back cover.

© LS ELECTRIC Co.,Ltd. 2010 All Rights Reserved.

About User's Manual

Thank you for purchasing PLC of LS ELECTRIC Co.,Ltd.

Before use, make sure to carefully read and understand the User's Manual about the functions, performances, installation and programming of the product you purchased in order for correct use and importantly, let the end user and maintenance administrator to be provided with the User's Manual.

The User's Manual describes the product. If necessary, you may refer to the following description and order accordingly. In addition, you may connect our website(<u>http://www.ls-electric.com/</u>) and download the information as a PDF file.

Title	Description	No. of User's
XG5000 user's manual (for XGK/XGB)	It describes how to use XG5000 software about online functions such as programming, printing, monitoring and debugging when using XGB series products.	10310000512
XG5000 user's manual (for XGI/XGR/XEC)	It describes how to use XG5000 software about online functions such as programming, printing, monitoring and debugging when using XGB (IEC language) series products	10310000834
XGK/XGKB Instructions & Programming	It is the user's manual for programming to explain how to use instructions that are used PLC system with XGB CPU.	10310000510
XGI/XGR/XEC Instructions & Programming	It is the user's manual for programming to explain how to use instructions that are used in XGB (IEC language) CPU	10310000833
XGB hardware	It describes power, IO, extension specification and system configuration, built-in high speed counter of XGB main unit.	10310000693
XGB hardware (IEC)	It describes power, IO, extension specification and system configuration, built-in high speed counter of XGB (IEC) main unit.	10310000983
XGB Analog user's manual	It describes how to use the analog input, analog output, temperature input module, system configuration and built-in PID control for XGB basic unit.	10310000920
XGB Cnet I/F	It is the user's manual about XGB Cnet I/F that describes built-in communication function and external Cnet I/F module of XGB basic unit	10310000816
XGB FEnet I/F	It describes how to use XGB FEnet I/F module.	10310000873

Relevant User's Manuals

\bigcirc Contents \bigcirc

٦

Chapter 1 General		1-1~1-12
-------------------	--	----------

1.1 General	1-1
1.1.1 Purpose of position function	1-1
1.1.2 Features	1-2
1.2 Performance specifications	1-3
1.2.1 Performance specifications of XGB built-in positioning	1-3
1.3 Operation Sequence of Positioning	1-4
1.3.1 Operation Sequence of Positioning	1-4
1.3.2 Flow of position signal	1-5
1.4 I/O Signal Allocation	1-6
1.4.1 Allocation of modular type input signal	1-6
1.4.2 Allocation of modular type output signal	1-7
1.4.3 Allocation of compact type (S/H type) input signal	1-8
1.4.4 Allocation of compact type (S/H type) output signal	1-10
1.5 I/O wiring by using Smart Link Board	1-11
1.5.1 Smart link board	1-11

Chapter 2 General Specification2-1~2-10

2.1 General Specification	2-1
2.2 Power Specification	2-2
2.2.1 Modular type(XBM-DN□□S) power specification	2-2
2.2.2 Compact standard type (XB(E)C-DR/DN/DP S(U)) power specification	2-2
2.2.3 Compact high-end type (XB(E)C-DR/DN/DP□□H) power specification	2-3
2.3 I/O specification	2-4
2.3.1 Input Specification	2-4
2.3.2 Output specification	2-7
2.3.3 Output pulse level	2-10

Chapter 3 Before Positioning3-1	~3-58
---------------------------------	-------

Г

3.1 Positioning Function	3-1
3.1.1 Positioning function list	3-1
3.1.2 Position control	
3.1.3 Speed control	3-5
3.1.4 Speed/position switching control	3-7
3.1.5 Position/speed switching control	
3.1.6 Linear interpolation control	3-9
3.1.7 Simultaneous start control	3-12
3.1.8 Sync control	3-13
3.1.9 Home return	3-14
3.1.10 Position and speed override	
3.1.11 Positioning stop signal	3-21
3.1.12 Manual operation	
3.1.13 Stroke Upper/Lower Limits	
3.1.14 Output of positioning completion signal	3-25
3.2 Positioning Parameter	
3.2.1 Positioning parameter setting sequence	3-26
3.2.2 Relationship between positioning parameter and dedicated K area	3-30
3.2.3 Setting basic positioning parameters	3-31
3.2.4 Origin/Manual Parameter Setting for Positioning	3-38
3.3 Positioning Operation Data	
3.4 Positioning Status Monitoring and Area K for Input and Output	3-49
3.4.1 Status Monitoring and Flag for Positioning	3-49
3.4.2 Flag for Positioning Instruction and Command	3-51

Chapter 4 Positioning Check4-1~4-4

4.1 The Sequence of Positioning Check	.4-1
4.2 Making of Operation Check Program	4-3

Cha	oter 5	5 Positioning	Instructions	
Unia			j	

5.1 Positioning Instruction List	5-1
5.2 Details of Positioning Instructions (In case of XBC/XBM)	5-3
5.2.1 Origin Return Instructions	5-3
5.2.2 Fixed Origin Setting Instruction	5-7
5.2.3 Direct Starting Instruction	5-9
5.2.4 Indirect Starting Instruction	5-12
5.2.5 Straight Interpolation Starting Instruction	5-15
5.2.6 Simultaneous Starting Instruction	5-18
5.2.7 Speed Position Switching Instruction	5-20
5.2.8 Position Speed Switching Instruction	5-22
5.2.9 Deceleration Stop Instruction	5-24
5.2.10 Position synchronous Instruction	5-26
5.2.11 Speed Synchronous Instruction	5-29
5.2.12 Position Override Instruction	5-32
5.2.13 Speed Override Instruction	5-34
5.2.14 Positioning Speed Override Instruction	5-36
5.2.15 Inching Starting Instruction	5-38
5.2.16 Starting Step Number Change Instruction	5-39
5.2.17 M Code Cancel Instruction	5-40
5.2.18 Current Position Preset Instruction	5-41
5.2.19 Emergency Stop Instruction	5-42
5.2.20 Error Reset, Output Inhibition, Inhibition Termination	5-43
5.2.21 Parameter/Operation Data Save	5-45
5.2.22 Pulse width Modulation	5-47
5.3 Positioning Function Blocks (In case of XEC)	5-49
5.3.1 General for Function Block	5-49
5.3.2 Function Block for Return to Origin	5-50
5.3.3 Function Block for Floating Origin Setting	5-53
5.3.4 Direct Start-up Function Block	5-55
5.3.5 Indirect Start-up Function Block	5-58
5.3.6 Linear Interpolation Start-up Function Block	5-61
5.3.7 Simultaneous Start-up Function Block	5-64
5.3.8 Velocity to Position Transfer Function Block	5-66
5.3.9 Position Velocity Transfer Function Block	5-68

5.3.10 Deceleration Stop Function Block	5-70
5.3.11 Position Synchronization Function Block	5-73
5.3.12 Speed Synchronization Function Block	5-77
5.3.13 Position Override Function Block	5-80
5.3.14 Speed Override Function Block	5-82
5.3.15 Positioning Speed Override Function Block	5-84
5.3.16 Inching Start Function Block	5-86
5.3.17 Start Step Number Change Function Block	5-87
5.3.18 M Code Release Function Block	5-88
5.3.19 Present Position Preset Function Block	5-89
5.3.20 Emergency Stop Function Block	5-90
5.3.21 Error Reset, Output Cut-off Release Function Block	5-91
5.3.22 Parameter/Operation Data Write Function Block	5-93
5.3.23 Pulse width Modulation	5-95

Γ

Chapter 6 Positioning Monitoring Package......6-1~6-9

6.1 Introduction to Positioning Monitoring Package	.6-1
6.1.1 Introduction of Positioning Monitoring Package	.6-1
6.2 Menus and Functions of Positioning Monitoring	.6-3
6.2.1 Monitoring and Command	.6-3
6.3 Parameter/Operation Data Setting Using Monitoring Package	. 6-8
6.3.1 Changing the Position Parameter	. 6-8
6.3.2 Change of Position Operation Data	.6-9

Chapter 7 Program Examples of Positioning......7-1~7-38

7.1 System Composition and Setting of Input and Output	7-1
7.2 Program Examples	7-3
7.2.1 Floating Origin Setting/Single Operation	7-3
7.2.2 Straight Interpolation Operation	7-5
7.2.3 Deceleration Stop	7-8
7.2.4 Setting of Operation Step/Single Operation	7-10
7.2.5 Setting of Operation Step/Speed Control	7-12

7.2.6 Simultaneous Start	.7-15
7.2.7 Position Synchronous Start	.7-17
7.2.8 Speed Synchronous Start	.7-20
7.2.9 Emergency Stop	.7-23
7.2.10 Jog Operation	.7-25
7.2.11 Speed Override	.7-27
7.2.12 Position Override	.7-29
7.2.13 Speed override with Position	.7-32
7.2.14 Speed, Position, and Parameter Teaching	.7-34

8.1 Basic Procedure of Troubleshooting	.8-1
8.2 Check by Using the LED	.8-2
8.2.1 LED Check	.8-2
8.3 Check by Error Code	.8-5
8.3.1 How to Check Error Codes	.8-5
8.4 Check of Motor Failures	.8-6
8.4.1 If the Motor Doesn't Work	.8-6

Appendix 1 List of Error Codes...... APP.1-1~APP.1-7

APP.1.1 List of PLC Error Codes	APP.1-1
APP.1.2 List of Positioning Error Codes	APP.1-2

Appendix 2 Positioning Instruction and K area List...... APP.2-1~APP.2-44

APP 2.1 Positioning instruction list	APP.2-1
APP 2.2 Positioning Dedicated K area List	APP.2-3
APP 2.2.1 K area of positioning basic parameter	APP.2-3
APP 2.2.2 K area of positioning home parameter	APP.2-4
APP 2.2.3 Positioning operation data K area	APP.2-5

Appendix 3 Motor	Wiring Exam	ple	APP.3-1~APP.3-7

Г

APP.3.1 Stepping Motor Wiring Example	APP.3-1
APP.3.2 Servo Motor Wiring Example	APP.3-2

Appendix 4 DimensionAPP.

Chapter 1 General

XGB series transistor output type contains 2 positioning axes. This manual describes the specifications and usage of positioning.

1.1 General

1.1.1 Purpose of position function

The purpose of position function is to exactly move an object from the current position to a designated position and this function executes highly precise position control by sending a position pulse string signal to types of servo drive or stepping motor control drive. For applications, it may be widely used; for instance, machine tools, semiconductor assembling machine, grinder, small machine center, lifter and etc.



< XGB positioning function general >



< Positioning system inner block diagram >

1.1.2 Features

Positioning function features the followings.

- (1) Max. two axis, 100kpps positioning
 - XGB PLC can execute positioning of up to 2 axes with up to 100kpps.
- (2) Diversity of positioning function
 - XGB PLC contains various functions necessary for position system such as position control at any temporary position or constant speed operation.
 - (a) Operation data containing position address, operation method and operation pattern may be set up to 80 steps per axis (based on "H" type). It executes position function by using this operation data.
 - (b) Linear control is available by using each operation data
 - The control can also perform single position control by one operation data and continuous position control by several operation data
 - (c) linear interpolation control is available.
 - (d) According to operation data and control types designated by parameters, position control, speed control, position/speed switching control and position/speed switching control are available
 - (e) It also provides various home return functions.1) Home return can be chosen among the following three.
 - Origin detection after DOG Off
 - When DOG On, Origin detection after deceleration
 - Origin detection by DOG

2) temporary position can be set as machine's origin by using floating origin setting function.

- (3) Easy maintenance
 - It saves data such as position data and parameter into flash memory of main unit permanently.
 - The modified data during positioning can be preserved in the flash memory by application instruction (WRT/APM_WRT instruction).
- (4) XG5000 can perform self-diagnosis, monitor and test.
 - (a) Diagnosing of I/O signal line.
 - (b) It can test all functions of built-in positioning or check the current operation status without program through special module monitoring
 - (c) It is easy to take action because the user can check error by error occurrence flag (Ch0: K4201, ,%KX6721 Ch1: K4301, %KX6881) and error code (Ch0: K427, %KW427 Ch1: K437, %KW437) easily.



1.2 Performance specifications

1.2.1 Performance specifications of XGB built-in positioning

The performance specifications of positioning function are as follows.

Here standard type indicates XBM-DN \Box S/XBC-DN \Box S(U) and high end type indicate XBC(XEC)-DN \Box H. Each type is indicated as 'S' type and 'H' type.

	Туре	XGB Basic Unit (Transistor output)			
Iten	1	Stan	dard type ("S" type)	High-end type ("H" type)	
No. o	f control axis	2 axes			
Interp	olation	2 axes lin	ear interpolation		
Pulse	output method	Open coll	ector (DC 24V)		
Pulse	output type	Pulse + D	virection	Pulse + Direction CW/CCW output	
Contr	ol type	Position switching	Position control, speed control, speed/position switching, position/speed switching		
Contr	ol unit	Pulse	Pulse		
		30 data a (operatior * XBC-DN data are	0 data areas per axis operation step no. $1 \sim 30$) XBC-DN \square S(U) supports 80 data areas per axis data areas per axis		
Positi	on data		Setting through Embedded parameter of XG5000 $ ightarrow$ permanent auto-preservation		
		Setting	Setting through dedicated monitoring package \rightarrow permanent preservation by PADT instruction		
		method	Setting through K area dedicated for positioning → permanent preservation by application instruction (WRT/APM_WRT instruction)		
Positioning monitor		Special m	Special module monitoring of XG5000 / monitoring by K area		
Back-up		Parameter, operation data \rightarrow Flash memory K area \rightarrow RAM (super capacitor back up for S type/ battery back up for H type) (Saving them in the flash memory is available by application instruction(WRT/APM_WRT))			
Po	Position method	Absolute	Absolute method / Incremental method		
sition	Position address range	-2,147,483,648 ~ 2,147,483,647(Pulse)			
	Speed range	1 ~ 100,000pps(1pps unit)			
	Acc/dec processing	Trapezoid-shaped			
	Acc/dec time	$1 \sim 10,000$ ms (selectable from 4 types of acc/dec patterns)			
Max. output pulse		100 kpps			
Max. connection distance		2 m			

< Performance specifications >

1.3 Operation Sequence of Positioning

1.3.1 Operation Sequence of Positioning

Operation sequence is as follows.



1.3.2 Flow of position signal

Flow of position signal is as follows.



< XGB Positioning signal flow >

1.4 I/O Signal Allocation

Г

1.4.1 Allocation of modular type input signal

In case of modular type, external I/O signal for built-in function is allocated as follows.

(1) Pin array of I/O connector

Pin array of I/O connector of XGB modular type transistor type basic unit is as follows.



(2) Allocation of external input signal

Signal name	Input contact point no.		Detail	-
External lower	X axis	P0000	detected at the falling edge of input contact point.	
(LimitL)	Y axis	P0002	detected at the falling edge of input contact point.	Normally closed contact point (B contact point)
External upper	X axis	P0001	detected at the falling edge of input contact point.	
limit signal (LimitH)	Y axis	P0003	detected at the falling edge of input contact point.	
DOG signal	X axis	P0004	When homing, detected at the rising edge	
	Y axis	P0006	When homing, detected at the rising edge	Normally open
ORIGIN signal	X axis	P0005	When homing, detected at the rising edge	(A contact point)
	Y axis	P0007	When homing, detected at the rising edge	
Input common	X/Y axis	СОМ	Input common	

(3) Example of wiring the external input signal Example of wiring the external input signal is as follows.



< Example of wiring the external input signal >

1.4.2 Allocation of modular type output signal

(1) Allocation of output signal

When using the positioning function, the output signal is allocated as shown below.

Signal name	Input point no	contact	Detail	-
Pulse output	X axis	P0020	Positioning X axis pulse string output contact point (Open collector output)	
	Y axis	P0021	Positioning Y axis pulse string output contact point (Open collector output)	Low Active and High Active is
Direction output	X axis	P0022	Positioning X axis direction output contact point (Open collector output)	selectable in parameter setting.
	Y axis	P0023	Positioning Y axis direction output contact point (Open collector output)	
External 24V	X/Y axis	DC12 /24V	For external power (12/24V) supply	
Output common	X/Y axis	СОМ	Output common	

(2) Example of wiring external input signal Example of wiring external output signal is as follows.



1.4.3 Allocation of compact type (S/H type) input signal

In case of compact standard/high-end type, external input signal for built-in positioning is allocated as follows

(1) I/O terminal block array

Γ

Array of XGB transistor output type basic unit is as figure below.





	Input co	ontact point no.				
Signal name	Axis	XBC-DN(P) □□S(U)/H	XEC-DN(P) □□H	Operation content	Reference	
External lower	X axis	P0008	%IX0.0.8	Detected at the falling edge of input contact point		
(LimitL)	Y axis P000A %IX0.0.10		%IX0.0.10	Detected at the falling edge of input contact point.	Normally closed	
External upper	X axis	P0009	%IX0.0.9	Detected at the falling edge of input contact point	(B contact point)	
(LimitH)	Y axis	P000B	Detected at the falling edge of input contact point			
	X axis	P000C	%IX0.0.12	When homing, detected at rising edge		
DOG signal	Y axis	P000E	%IX0.0.14	When homing, detected at rising edge	Normally opened	
	X axis	P000D	%IX0.0.13	When homing, detected at rising edge	(A contact point)	
ONGIN	Y axis	P000F	%IX0.0.15	When homing, detected at rising edge		
Input common	X/Y axis	СОМ		Input common terminal		

(2) Allocation of external input signal

(3) Wiring example of external input signal

In case of using positioning function of XGB compact main unit, wiring example of input signal is as follows.

(XBC-DN \square S(U)/H is used for example)



< XGB high-end positioning input signal wiring example >

1.4.4 Allocation of compact type (S/H type) output signal

(1) Allocation of output signal

Γ

In case of using built-in positioning of XGB compact standard/high-end type main unit, output signal is allocated as follows.

	ا ب م ما		4 m m		Operation content		
Signal name	Axis	XBC- DN	XBC- DN(P)	XEC- DN(P)	Pulse + Direction mode	CW/CCW mode	Reference
Pulse output	X axis	P00020	P00040	%QX0.0.0	Positioning X axis pulse string (Open collector output)	X axis CW pulse string output (Open collector output)	
(CW output)	Y axis	P00021	P00041	%QX0.0.1	Positioning Y axis pulse string (Open collector output)	Y axis CW pulse string output (Open collector output)	Low Active and
Direction output	X axis	P00022	P00042	%QX0.0.2	X axis direction output contact point (Open collector output)	X axis CCW pulse string output (Open collector output)	selectable in parameter setting
(CCW output)	Y axis	P00023	P00043	%QX0.0.3	Y axis direction output constant point (Open collector output)	Y axis CCW pulse string output (Open collector output)	
External 24V	X/Y axis	Ρ			Terminal for externation implement the trans	al power (12/24V) to sistor	
Input common	X/Y axis	COM0 ~ 7			Output common ter	minal	

* Standard type (XBC-DN(P) Supports only "pulse + direction mode".

(2) Wiring example of external input signal

In case of using positioning function of XGB high-end basic unit, wiring example is as follows.



1.5 I/O wiring by using Smart Link Board

1.5.1 Smart link board

When using positioning function, easy wiring is available by connecting the I/O connector with smart link board.

XGB	1	Smar	t link		Conn	ection cable
Classification	Model	Model	The no. of pin	Model	Length	Content
Main unit	XBM- DN32S XBM- DN16S	SLP- T40P	40	SLT- CT101- XBM	1m	For main unit connection (20Pin + 20Pin)
	XBE- DC32A	SLP- T40P	40	SLT- CT101- XBE	1m	For extension module
Extension module	VDE	SLP- T40P	40	SLT- CT101- XBE	1m	(40Pin)
	TN32A	SLP- RY4A	40	SLP- CT101- XBE	1m	For extension module connection (40Pin) Exclusive for relay built-in SLP type

The available smart link and I/O cable are as follows.

It describes wring of XGB, SLP-T40P and SLT-CT101-XBM.

For wring of other smart link boards or XGB extension module, refer to XGB user manual for hardware.

(1) SLT-T40P terminal array

Terminal array of SLP-T40P is as follows.



ltem	Specification
Rated voltage	AC/DC 125[V]
Rated current	Max. 1[A]
Withstanding voltage	600V 1min
Insulation resistor	100 ^M Ω (DC500V)
Cable specification	1.25[m ²] or below
Terminal/screw	M3 X 8L
Torque	6.2 kg f.cm or above
Terminal material	PBT, UL94V-0
Weight	186g

(2) Wiring of SLT-T40P and XGB main unit Wiring of XGB main unit through SLP-T40P and SLT-CT101-XBM is as follows

Γ



At this time, relationship of XGB I/O signal and Smart link board terminal number is as follows. The following figure describes signal allocation when SLT-CT101-XBM is used as connection cable. When the user makes the cable, make sure that wring is done as figure below.

	B	1	B2	B3	В	4	B5	B6	B7	в	8	B9	B10	B1	1 B	12	B13	B14	B1	5 В	16	B17	B18	B19	B20	
	A1	A2	2 A	3	A4	A5	A	6	A7	A8	AS	A	10	A11	A12	A1	3	A14	A15	A16	A1	7 A	18	A19	A20	
	name																									
Г					—													_	1	27						1
	PO	201	P003	P00	5 PC	07 (сомо	P00:	9 PO	OB P		POOF	COM	1 PC	21 P	023	P02	5 PO	27 2	4V F	029	P02E	P02		FCOM	
F	000	POC	12 PC	104	9006	СОМ	O PO	08 F	POOA	POOC	PO	DE CI	OM1 I	P020	P022	PO	124 F	9026	12/ 24V	P028	B PO2	2A P	œc I	902E	СОМ	
\subset								_					ブ									_				Τ
	Input Output																									

Chapter 2 General Specification

2.1 General Specification

General specification is as follows.

No.	ltem			Specification	S		Related standards		
1	Operating temperature			0 ~ 55 °C					
2	Storage temperature			–25 ~ +70 °C	;				
3	Operating humidity		5 ~ 95	%RH, no cond	ensation				
4	Storage humidity		5 ~ 95	%RH, no cond	ensation	1			
		I1							
		Frequency							
		$10 \leq f < 57Hz$		-	3.5mm				
F	Vibration	$57 \leq f \leq 150Hz$	9	.8m/s²	_	10 times to			
Э	immunity	li	continuous v	ibration exists		X, Y and Z	IEC61131-2		
		Frequency	Frequency Acceleration Amplitude directions,						
		$10 \leq f < 57Hz$	0 ≤ f < 57Hz – 1.75mm ea						
		$57 \le f \le 150$ Hz	4						
		Max. impact acce	leration : 147	′ m/s²					
6	Shocks	• Time allowed : 11	ms				IEC61131-2		
		Pulse waveform :	half sine wa	ve (3 times to >	K, Y and Z direction	s, each)			
		Rectangular		AC	: ±1,500 V		Test specifications		
		impulse noise		DC	: ±900 V		of LS ELECTRIC		
		Electrostatic			/ (a cinta at alia ah anna		IEC61131-2		
		discharge		voitage : 4kv	(contact discharge	<i>=)</i>	IEC61000-4-2		
-	NI · · ·	Radiating							
1	Noise immunity	electronic field		80 ~ 1,0	000 ^{MHz} , 10V/m		IEC61131-2,		
		noise					IEC61000-4-3		
			-	Power	Digital/Analogue	Input/Output,			
		Fast transient /	st transient / I ype module Communication interface						
		Burst noise	Voltage 2kV 1kV						
8	Environment	Free of corrosive g	as and dust		·				
9	Altitude	Lower than 2,000m	ı						
10	Pollution degree	2 and lower							
11	Cooling method	Natural air cooling	ype						

Note

1) IEC(International Electro technical Commission)

: International private group facilitating international cooperation of electric/electronic standardization, issuing international standards and operating the compliance evaluation systems.

2) Pollution degree

: As an index representing the pollution degree of an environment to determine the insulation of a device, pollution degree 2 generally means the status generating non-conductive contamination. However, it also contains the status generating temporarily conduction due to condensation.

2.2 Power Specification

Γ

Power specification of XGB series main unit is as follows.

2.2.1 Modular type(XBM-DN ... S) power specification

	Item	Specification
	Rated input voltage	DC24V
	Input voltage range	DC20.4~28.8V(-15%, +20%)
	Inrush current	70APeak or below
Input	Input current	Max. 1A (Typ. 550 ^{mA})
	Efficiency	60% or above
	Allowed temporary	1 ms or below
	cutoff	
	Output voltage	DC5V (±2%)
Output	Output current	Max 1.5 A
Volta	ge status display	When power is normal, PWR LED On
Cat	ble specification	0.75 ~ 2 mm²

2.2.2 Compact standard type (XB(E)C-DR/DN/DP□□S(U)) power specification

				Specification						
	ltem		XB(E)C- DR(N)(P)20S(U) /DR(N)(P)30S(U)	XB(E)C- DR/DN/DP40SU	XB(E)C- DR/DN/DP60SU					
	Rated inpu	t voltage	AC 100 ~ 240 V							
	Input volta	ge range	AC85~264V(-15%, +10%)							
	Inrush c	urrent	50APeak or below							
Input	Input cu	urrent	0.5A or below (220V),	0.5A or below (220V), 1A or below (110V)						
	Efficie	ency	65% or above							
	Allowed te	mporary off	10 ms or below							
	Output	DC5V	1.5A	2A	2.5A					
	voltage	DC24V	0.3A	0.3A	0.5A					
Output	Output	DC5V	DC 4.9 ~ 5.1V (±2%)	DC 4.9 ~ 5.15V (-2%, +	-3%)					
	voltage ripple	DC24V	DC21.6~26.4 V(±10%)							
Volta	ige status dis	splay	When power is normal, PWR LED On							
Ca	ole specificat	ion	0.75 ~ 2 mm ²							

* For protection of power supply, use power supplier which has maximum 4A fuse.

2.2.3 Compact high-end type (XB(E)C-DR/DN/DP - H) power specification

٦

				Spec	ification					
	ltem		XBC- /DR32H /DN32H	XEC- DR32H /DN32H /DP32H	XBC- DR64H /DN64H	XEC- DR64H /DN64H /DP64H				
	Ratec volt	l input age	AC 100 ~ 240 V							
	Input v rar	voltage nge	AC85~264V(-15%, +10%)							
Input	Inrush	current	50APeak or less							
mpat	Input o	current	0.5A or less (220\	/), 1A or less (110V)					
	Effici	ency	65% or above							
	Allo tempora	wed ry cutoff	10 ms or less (Checking is necessary)							
	Rated	DC5V	2A		ЗА					
	output	DC24V	0.4A		0.6A					
Output	Output	DC5V	DC 4.9 ~ 5.15V (-2	2%, +3%)						
	ripple	DC24V	DC21.6~26.4 V(±	10%)						
Voltag	je status o	display	In case output voltage is normal, LED On							
Cabl	e specific	ation	0.75 ~ 2 mm ² (Cł	0.75 ~ 2 mm ² (Checking is necessary)						

* For protection of power supply, use power supplier which has maximum 4A fuse.

2.3 I/O Specification

Γ

It describes I/O specification when P0000~P000F is used for built-in positioning. For using P0000~P000F as general I/O, refer to XGB user manual for hardware

2.3.1 Input Specification

(1) Modular type input contact point specification

Contac	X axis	P0000	P0001		P000	4	P0	005	Pof
no.	Y axis	P0002	P0003		P000	6	P0	007	Kei.
Signal	name	External lower limit	External upper limit		DOG	6	НО	ME	
Ratec volt	l input age	DC24V (DC20.4~28.8V (-1	5/20	%, rip	ole rate 5º	s))		
Ratec cur	l input rent	al	bout 7 mA/24V			About 4	nA /24V		
Insul met	ation thod		Photo cou	pler	insulat	tion			
Input im	pedance	Abou	t 3.3 kΩ			About 5	.6 kΩ		
O voltage/	n /current	DC 19V or a ab	bove/5.7 ^{mA} or	DC	C 19V o	or above /	3.4 mA (or above	
O voltage/	ff /current	DC 6V or less	s/1.8 ^{mA} or less		DC 6\	/ or less/1	.1 ^{mA} o	r less	
Respor	nse time	().5 ^{ms} or less (Whe	en us	sed for	positionir	ng)		
Min. inp	out width								
					Pin	Contact point	Pin	Contact point	
					B10	P00	A10	P08	
		Г			B09	P01	A09	P09	
					B08	P02	A08	P0A	B10 A10
Cir	cuit				B07	P03	A07	P0B	
configura	ation and				B06	P04	A06	P0C	
connect	tor array				B05	P05	A05	P0D	
			Circuit		B04	P06	A04	P0E	B1 A1
		L			B03	P07	A03	P0F	
					B02	COM	A02	COM	
					B01	COM	A01	COM	

(2) Compact standard type input contact point specification

Contact point	X axis X axis	P0008 %IX0.0.8 P000A	P0009 %IX0.0.9 P000B	P000 %IX0.0 P000	C .12 E	P00 %IX0 P00	00D .0.13 00F	Re	əf.		
Signal	name	%IX0.0.10 External lower limit	%IX0.0.11 External upper limit	DOG	.14	%IX0 HO	.0.15 ME				
Rated volta	input age	DC24	/ (DC20.4~28.8V	(-15/20%, ri	pple rate	5% or less	s))				
Rated curr	input ent		Abo	out 4 ^{mA} /24∖	1						
Insulatior	n method		Photo c	oupler insul	ation						
Input imp	bedance		Al	ວout 5.6 ^k Ω							
On voltag	e/current		DC 19V or above /3.4 ^{mA} or above								
Off voltag	e/current		DC 6V or less/1.1 mA or less								
Respon	se time	0.5	5 ms or less (when	used for inp	out for pos	itioning)					
Min. inp	ut width		200	^{µs} or abov	e		T				
				No.	Contact	No.	Contact	-			
						TB1	RX				
				TB2	485+	твз	тх				
				TB4	485-			TB2	TB1		
					P00	TB5	SG	TB4	TB3		
				186	IX0.0.0	тв7	P01	тв6	TB5		
				TB8	P02		IX0.0.1	TB8	TB7		
					P04	ТВ9	IX0.0.3	TB10	TB9		
				TB10	IX0.0.4	TB11	P05		TB11		
Circuit cor	figuration		[TB12	P06		IX0.0.5		TB13		
and termi	nal array		DC3.3V		P08	TB13	P07 IX0.0.7		TB15		
		<u>ا</u> سی ا		TB14	IX0.0.8	TB15	P09		TB17		
				TB16	P0A		IX0.0.9	TB18	TB19		
				cult	P0C	TB17	P0B IX0.0.11	TB20	TB21		
		DC24V			IX0.0.12		P0D	TB22	ТВ23		
				TB20	P0E	1819	IX0.0.13	TB24			
					IX0.0.14	TB21	P0F				
				TB22	IX0.0.16		P11				
				TB24	СОМ	TB23	IX0.0.17				
Eor X		S(LI) there is no	actual input poin		DOOODE	If you wo	nt to use th	om tur	on hy		

٦

For XBC-DN20S(U), there is no actual input point P0000C ~ P0000F. If you want to use them, turn on by user program.

(3) C	ompact hi	igh end type inp	ut contact point sp	ecification							
Contact point no.	X axis Y axis	P0008 %IX0.0.8 P000A %IX0.0.10	P0009 %IX0.0.9 P000B %IX0.0.11	P000 %IX0.0 P000 %IX0.0	C .12 E .14	P00 %IX0 P00 %IX0	00D .0.13 00F .0.15	Ref.			
Signal	name	External lower limit	External upper limit	DOG	i	НО	ME				
Rated volta	input age	DC24V	(DC20.4~28.8V (-	15/20%, rij	ple rate	5% or les	s))				
Rated curr	input ent		Abo	ut 4 ^{mA} /24V							
Insula meti	ation hod		Photo co	upler insula	ation						
Input imp	bedance		Abo	out 5.6 ^k Ω							
O voltage/	n ′current		DC 19V or abo	ove /3.4 mA	or abov	/e					
O ⁻ voltage/	ff 'current		DC 6V or le	ess/1.1 mA	or less						
Respon	se time	0.5	0.5 ms or less (when used for input for positioning)								
Min. inp	ut width		200 /	s or above	, 						
				No.	Conta	TB1	RX				
				TB2	485+	ТВЗ	TX SG	TB1			
				ТВ6	P00	TB5	SG	TB2 TB3 TB4 TD5			
					IX0.0.0 P02) ТВ7	P01 IX0.0.1	TB6 TB7			
			DC3.3V		IX0.0.2	2 TB9	P03	TB8 TB9			
Circ	suit	^{P8}		TB10	IX0.0.4	4 TB11	P05	TB10 TB12			
configura	ition and			TB12	P06 IX0.0.6	6	IX0.0.5 P07	TB12 TB14			
termina	ll array			TB14	P08	IB13	IX0.0.7	TB16			
		DC24V			P0A	5 TB15	P09 IX0.0.9	TB18 TB19			
					IX0.0.1 P0C	10 TB17	P0B IX0.0.11	TB20 TB21			
				TB18	IX0.0.1	12 TB19	P0D	TB22 TB23			
				ТВ20	P0E IX0.0.1	14	P0F				
				TB22	сом	1821	IX0.0.15				
				TB24	24\/	ТВ23	24G				

Γ

2.3.2 Output specification

	(1)	Modular	type	output	contact	point	specification
--	---	----	---------	------	--------	---------	-------	---------------

Conta	X axis	P0020		P0022			Ref.	
ct no.	Y axis	P0021 P0023						
Signal name		Pulse string output	Dir					
Rated load voltage Max. load current		DC5~24V (DC4.7						
		0.1A/1 point o						
Insulation method		Photo-coupler ir	Photo-coupler insulation					
Inrush	arush current 1A/10 ms or below							
Volta whe	ge drop en On	DC 0.3V or below						
Leakage when O	e current	0.1 ^{mA} or be	elow					
Respo	nse time	0.1 ms or below (Rated lo	load, resistor load)					
			No.	Contact	No.	Cont act		
			B10	P20	A10	P28		
			B09	P21	A09	P29	HOH	
	cuit		B08	P22	A08	P2A		
Ci			B07	P23	A07	P2B		
and co	onnector	ay rd type)	B06	P24	A06	P2C		
ar (stand)	ray		B05	P25	A05	P2D		
(Stanua	idard type)		B04	P26	A04	P2E		
			B03	P27	A03	P2F		
			B02	10/0.01	A02	со		
			B01	12/24V	A01	М		

٦

(2)	Compact	standard type output contact point	specification					
Conta ct no.	X axis	P00040 %QX0.0.0 P00041		P00042 %QX0.0 P00043	2 .2 3		Ref.	
	Y axis	%QX0.0.1		%QX0.0.3				
Signa	Il name	Pulse string output	Direction output					
Rate vol	d load tage	DC5~24V (DC4.75~26.4V)						
Maxim cui	um load rrent	(0.1A/1or less					
Insu me	lation thod	Photo						
Inrush	current	14	V10 ms or less					
Volta whe	ge drop en On	D						
Leakage when Of	e current ff	C).1 ^{mA} or less					
Respo	nse time	0.1 ms or less	or less (rated load, resistive load)					
			No.	Contact	No.	Contact		
					TB1	AC100		
			TB2	PE	твз	~240V		
			TB4	COM0		P40		
			TB6	COM 1	COM 1 COM 2 TB5 QX0.0.0 P41 QX0.0.1 P42 P42 P42		TB2 TB3	
							TB4 TB5 TB6	
			TB8	COM 2			TB7 TB8	
			TB10	P43 QX0.0.3		QX0.0.2	TB10 TB11	
Ci	Circuit guration and minal array	TB12	COM 3	TB11 P	TB12 TB13			
termin			P/15	TB13	P44 QX0.0.4	TB14 TB15		
1		Laser circuit P23 L P23 L D012/24V	TB14	QX0.0.5	TB15	P46	TB18 TB18 TB19	
1			TB16	P47		QX0.0.6	TB20 TB21	
			4V	QA0.0.7	TB17	NC	TB22 TB23	
			1818	COM 4	TB19	P48		
			TB20	P49 QX0.0.9		QX0.0.8 P4A		
			TB22	P4B	TB21	QX0.0.10		
				QX0.0.11	TB23	24V		
			TB24	24G				

Γ

Chapter 2 General Specification

(3) Compact high-end type output contact point specification

Cont X axis act no. Y axis	P00020 %QX0.0.0 P00021 %QX0.0.2 P00023 %QX0.0.1 %QX0.0.3				Ref.		
Signal name	Pulse string output / CW output	Direct	Direction output / CCW output				
Rated load voltage	DC5~24\	/ (DC4.75~2	26.4V)				
Maximum load current	0.4						
Insulation method	Photo c						
Inrush current	1A/1						
Voltage drop when On	DC						
Leakage current when Off	0.1						
Response time	0.1 ms or les (ra	ated load, re	sistive load)			
		No.	Contact	No.	Contact		
	Inner P20 L Linner P23 L OU12/24V OU12/24V	TDO	55	TB1	AC100		
		182	PE	~240V TB3	~240V		
		TB4	Р	TDE	P20	TB1	
		TB6	P21	185	IBS QX0.0.0 TB7 P22 QX0.0.2 QX0.0.2 TB9 COM0 TB11 P25 QX0.0.5 P25	TB2 TB3	
			QX0.0.1 P23	TB7		TB6 TB5	
		188	QX0.0.3	TB9		ТВ8 ТВ9	
] ТВ10	P24 QX0.0.4			TB10 TB10	
Circuit configuration and		, TB12	P26	TB11		TB12 TB13 TB14	
terminal array			QX0.0.6	TB13	P27 QX0.0.7	TB15 TB16 TB17	
		TB14	COM1	TB15	P28	TB18 TB19	
		TB16	P29 QX0.0.9		QX0.0.8 P2A	TB20 TB21 TB22	
		TB18	P2B	TB17	QX0.0.10	TB23	
			QX0.0.11	TB19	COM2		
		TB20	QX0.0.12	TDOA	P2D		
		TB22	P2E	1821	QX0.0.13		
			QX0.0.14	TB23	P2F		
		TB24	COM3		Q/(0.0.13		

٦
2.3.3 Output pulse level

Γ

Output pulse of XGB built-in positioning consists of Pulse + Direction or CW/CCW like figure below. At this time, output level of Low Active and High Active can be specified by positioning parameter and K area flag dedicated for positioning (X axis: K4871, %KX7793, Y axis: K5271, %KX8433).

			Output s	signal level		
Pulse output type	Output signal	High Act	tive mode	Low Ac	tive mode	Reference
calpartype	olgital	Forward	Reverse	Forward	Reverse	
Pulse +	Pulse					Supported
direction mode	Direction	Low	High	High	Low	at 3, m type
cw/ccw	cw				 	Supported
mode	ccw					at n type

Chapter 3 Before Positioning

It describes the function of position control, operation parameter setting, operation data setting, K area for positioning, servo driver setting and programming.

3.1 Positioning Function

3.1.1 Positioning function list

Positioning function of XGB built-in positioning is as follows. For more detail, refer to ch.5.2.

Positioning function		Operation description	Instruction	Ref.
Position control	Operation pattern	Setting speed On Start Signal	DST IST APM_DST APM_IST	Ch.5.2.3 Ch.5.2.4 Ch.5.3.4 Ch.5.3.5
	Operation	If the rising edge of start command is detected, it moves windesignated position and after dwell time, complete signal is	th designated on during one	speed to scan.
Speed control	Operation pattern	Speed Setting speed On Start signal DEC. stop	DST IST APM_DST APM_IST	Ch.5.2.3 Ch.5.2.4 Ch.5.3.4 Ch.5.3.5
	Operation	If the rising edge of start command is detected, it moves and stops after deceleration by stop command. At this tim not be not on.	with designate ne, complete s	ed speed ignal will
speed/position switching control	Operation pattern	Setting speed Speed Position control control Dwell time Time Start Signal Switching signal	VTP APM_VTP	Ch.5.2.7 Ch.5.3.8
	Operation	Speed control is executed by start command and it is swite by switching signal and it moves to designated position.	ched to positio	n control

Positioning function		Operation description	Instruction	Ref.
Position/speed switching control	Operation pattern	Setting Setting Setting Setting Setting Setting Setting On Conversion Signal Dec. stop	PTV APM_PTV	Ch.5.2.8 Ch.5.3.9
	Operation	Position control is executed by start command and control by switching signal and stops after deceleration	l it is switched tion by stop co	to speed ommand .
Linear interpolation control	Operation pattern	Y axis Y incremental Y incremental Y1 Y1 Y1 Y1 Y1 Y1 Y1 Y1 Y1 Y1	LIN APM_LIN	Ch.5.2.5 Ch.5.3.6
	Operation	2 axes linear interpolation control is executed b current position to target position.	y start comm	nand from
Simultaneous start	Operation pattern	X axis Setting speed Y axis Setting speed Y axis Setting speed Understand	SST APM_SST	Ch.5.2.6 Ch.5.3.7
	Operation	X axis and Y axis starts simultaneously by start con At this time, each operation data such as operation is applied to each axis.	nmand. n speed, targe	et position
Sync start	Operation pattern	Aux. axs	SSP SSS APM_SSP APM_SSSB	Ch.5.2.10 Ch.5.2.11 Ch.5.3.11 Ch.5.3.12
	Operation	If sync start is executed by command, subsidiary a main axis' position or speed. At this time, settin ignored and operates according to the operating sta	xis is synchro g of subsidia atus of main a	nized with Iry axis is xis

Г

Positioning function		Operation description	Instru ction	Ref.
Home return	Operation pattern	Home setting Home setting Direction Direction Direction Home command 	ORG APM_ ORG	Ch.5.2.1 Ch.5.3.2
	Operation	It goes to home direction and detects the mechanica At this time, home method can be specified by opera	l origin tion para	meter.
Position override	Operation pattern	Setting speed Original target polition Charged position Setting speed On Dwell time Charged position time time Position override command	POR APM_ POR	Ch.5.2.12 Ch.5.3.13
	Operation	It changes the target position by position override con	mmand.	
Speed override	Operation pattern	Speed override	SOR APM_ SOR	Ch.5.2.13 CH.5.3.1 4
	Operation	It changes the speed by speed override command.		
Speed override with position	Operation pattern	Speed verride command with position	PSO APM_ PSO	Ch.5.2.14 Ch.5.3.15
	Operation	It changes the speed at the designated position by s position command.	speed over	erride with

٦

3.1.2 Position control

Position control is to move the designated axis from start address (present position) up to target address (movement). There are two position control methods, absolute and incremental.

(1) Control by absolute coordinates (Absolute coordinates)

Object moves from start address to target address. Position control is performed, based on the address designated in Home Return (home address).

- Direction is determined by start address and target address.
 - Start address < target address: forward positioning
 - Start address > target address: reverse positioning

(a) example

 It assumes that operation data is specified as shown table 3-1. (For how to set operation parameter, refer to the Ch.3.3)

Step no.	Coord.	Pattern	Control	Method	Rep step	Address [Pulse]	M Code	A/D No.	Speed [pls/s]	Dwell [ms]
1	ABS	END	POS	SIN	0	8,000	0	1	100	10

<Table 3-1 operation data example of absolute coordinates type>

- In table 3-1, since coordinates is 'ABS', control method is 'POS', step no. 1 is position control by absolute coordinates.
- It assumes that the current poison is 1000. Since address in step no.1 is 8000, object moves to 8000 as shown figure and increment is 8000-1000=7000. Object moves forward because target address is larger than start address.



<Figure 3-1 operation example of absolute coordinates type>

Remark

- Every position/speed control is available as long as the origin is determined preliminarily.
- If it is executed while origin is not determined, error code 234 occurs and it doesn't move.
- In case error occurs, refer to App.1.2 and remove the cause of error.
- Complete signal is on during one scan.

(2) Control by incremental coordinates

Object moves from current position as far as the address set in operation data. At this time, target address is based on start address. Direction is determined by sign (+,-).

- In case Address is positive number: forward positioning (Direction increasing address)
- In case Address is negative number: reverse positioning (Direction decreasing address)

(a) Example

• It assumes that operation data is specified as shown table 3-2. (For how to set operation parameter, refer to the Ch.3.3)

Step no.	Coord.	Pattern	Control	Method	Rep step	Address [Pulse]	M Code	A/D No.	Speed [pls/s]	Dwell [ms]
1	INC	END	POS	SIN	0	-7,000	0	1	100	10

<Table 3-2 operation data example of incremental coordinates type>

- In table 3-1, since coordinates is 'INC', control method is 'POS', step no. 1 is position control by incremental coordinates.
- It assumes that current position is 5000. Since object moves as long as -7000, target stop at -2000 (absolute coordinates) as shown figure 3-2. At this time, increment is -7000 pulse and direction is reverse.



< Figure 3-2 operation example of incremental coordinates type>

3.1.3 Speed control

- Speed control means that object moves with steady speed (steady pulse string) until stop command.
- In case of speed control, direction is determined by sign of Address set in operation data. Forward : Address is positive number Reverse : Address is negative number In the speed control, direction is determined by sign of target address regardless of current position and target position. For example, current position is 100 and target position is 90, though target position is less than current position, since sign is positive, it moves forward.

• In case of speed control, some items as figure below doesn't affect the operation.



- If Control is specified as SPD, coordinates, pattern, method, M code, dwell time doesn't affect the operation.
- So in case of speed control, when object stops by STP command, it stops without dwell time and M code doesn't operate.

(1) Example

• It assumes that operation data is specified as shown table 3-3

Step no.	Coord	Pattern	Contr ol	Metho d	Rep step	Address [Pulse]	M Code	A/D No.	Speed [pls/s]	Dwell [ms]
1	INC	END	SPD	SIN	0	10	10	1	100	10

<Table 3-3 operation data example of speed control>

- In table 3-3, since Control is 'SPD', step no. 1 is operation data of speed control.
- Since Address is positive number and Speed is 100, target moves forward with 100 pls/s speed regardless of current position until stop command (DEC. stop or EMG stop).
- If object moves, flag (X axis: K4200, %KX6720, Y axis: K4300, %KX6880) is on. And if DEC. stop command is executed, it stops after deceleration without dwell time and flag turns off immediately.
- At this time, deceleration time conforms to that in operation data, not operand of instruction.



< Figure 3-3 Operation of speed control >

3.1.4 Speed/position switching control

- It change speed control to position control by switching command (VTP instruction).
- In case of speed/position switching control, items affecting the operation are different according to control method.



- First, object moves by speed control. If speed/position switching control is executed, target will move by position control.
- At this time, position control is executed by absolute coordinates with initializing the current position as 0. So coordinates item doesn't affect the operation.
- Since control method also changes by speed/position switching, control method in the operation data doesn't affect the operation.
- In case of speed/position switching, object keeps its previous direction.

(1) Example

• It assumes that operation data is specified as shown table 3-4.

Step no.	Coord	Pattern	Contr ol	Metho d	Rep step	Address [Pulse]	M Code	A/D No.	Speed [pls/s]	Dwell [ms]
1	INC	END	SPD	SIN	0	1000	11	1	500	100

<Table 3-4 operation data example of speed/position switching control>



< Figure 3-4 Operation of speed/position switching control >

- If step no. 1 in table 3-4 starts, object moves forward by speed control because Control is SPD and Address is positive number.
- If speed/position switching command (VTP instruction) is executed during speed control, current position will be initialized as 0 and object moves by position control until 1000.
- If object reaches target position, complete flag and M code occurrence flag will be on after dwell time. At this time, M code number 11 is displayed as set in operation data.
- Positioning complete flag will be on during one scan and M code occurrence flag keeps on status, until it is turned off by off command.

Remark

- M code occurrence flag is turned off by MOF instruction.
- Using MOF instruction, M code occurrence flag and M code number will be clear simultaneously.
- Speed/position switching command is executed only when each axis is operating. If it is executed during stop, it may cause error.
- If position/speed switching command is executed during operation by speed control, the command is ignored. But at this time, error is not occurred.

3.1.5 Position/speed switching control

- It change position control to speed control by switching command (VTP instruction).
- In case of position/speed switching control, items affecting the operation are different according to control method. In case position control, all items affect the operation but in case of speed, some items affect the operation as shown below.



- First, object moves by position control. If position/speed switching control is executed, object will
 move by speed control. At this time, the current position is not initialized. Only control method
 changes into speed control and it continues operation
- When control method changes, some items in operation data doesn't affect the operation.

(1) Example

• It assumes that operation data is specified as shown table 3-5.

Step no.	Coord	Pattern	Contr ol	Metho d	Rep step	Address [Pulse]	M Code	A/D No.	Speed [pls/s]	Dwell [ms]
1	INC	END	POS	SIN	0	10000	12	1	500	100

< Table 3-5 operation data example of position/speed switching control >

- If step no. 1 in table 3-5 starts, object moves by position control according to operation data in table 3-5 because Control is POS.
- If position/speed switching command (VTP instruction) is executed during position control, object moves by speed control until stop command.
- If object stops by stop command, it will stop without dwell time and positioning complete flag will not be on.





Remark

- Position/speed switching command is executed only when each axis is operating. If it is executed during stop, it may cause error.
- If speed/position switching command is executed during operation by position control, the command is ignored and causes error. But at this time, positioning doesn't stop.

3.1.6 Linear interpolation control

- Object moves by linear interpolation control from start address to target address using two axes, X,
 Y. There are two method in linear interpolation control, absolute coordinates and incremental coordinates.
- (1) Control by absolute coordinates

When linear interpolation control is executed, object moves based on the origin designated by Home return.

Direction is determined by start address and target address for each axis.

- start address < target address: Forward
- start address > target address: Reverse
- (a) How to set operation data

In the linear interpolation control, since two axes operates simultaneously, it needs attention The following is notice when setting the operation data.

- 1) Determining main axis
 - For linear interpolation, first you have to determine the main axis. In the XGB built-in positioning, main axis is determined automatically. The one which has a large moving amount becomes main axis.

2) Determining control method

 In the linear interpolation operation, control methods of both axes should be specified as "position". If not, error will occur and it will not be executed. 3) Setting of operation pattern

- In case of main axis, operation pattern should be specified as 'END' or 'KEEP'. In case it is specified as 'CONT', it operates as 'KEEP'.
- In case of subsidiary, pattern doesn't affect the operation, it operates according to main axis pattern.

(b) Example

 It assumes that operation data is specified as shown table 3-6 and current position are X=1000, Y=4000.

Step no.	Coord.	Pattern	Control	Method	Rep step	Address [Pulse]	M Code	A/D No.	Speed [pls/s]	Dwell [ms]	Step no.
Х	1	ABS	END	POS	SIN	0	8000	0	0	500	100
Y	1	ABS	KEEP	POS	REP	3	1000	0	0	2000	20

<Table 3-6 operation data example of linear interpolation control by absolute coordinates>



< Figure 3-6 linear interpolation operation by absolute coordinates >

- If linear interpolation starts, main axis is determined automatically based on moving amount of X and Y axis. In table 3-6, since moving amount of X axis is larger than Y axis X, X axis becomes main axis.
- So operation pattern, speed, A/D number, dwell time of Y axis is ignored and it is specified automatically according to operation data of X axis.
- Figure 3-7 indicates operation of linear interpolation control.



< Figure 3-7 operation of linear interpolation control >

(2) Control by incremental coordinates

It executes the linear interpolation control based on current position by incremental coordinates. At this time, Address of operation data means how long object moves from current position. Direction is determined sign of Address.

- In case Address is positive number: forward
- In case Address is negative number: backward

(a) Example

 It assumes that operation data is specified as shown table 3-7 and current position are X=1000, Y=4000.

Step no.	Coord.	Pattern	Control	Metho d	Rep step	Address [Pulse]	M Code	A/D No.	Speed [pls/s]	Dwell [ms]	Step no.
Х	1	INC	END	POS	SIN	0	6000	0	0	500	100
Y	1	INC	KEEP	POS	REP	3	-2000	0	0	2000	20

< Table 3-7 operation data example of linear interpolation control by absolute coordinates >



< Figure 3-8 linear interpolation operation by absolute coordinates >

- If linear interpolation is executed, main axis is determined according to moving amount of X and Y axis. In table 3-7, since moving amount of X axis is larger than Y, X axis becomes main axis.
- So subsidiary Y axis operation pattern, operation speed, ACC/DEC time, dwell time do not affect the operation and recalculated according to operation data of main axis. For example, if you execute the linear interpolation control with operation data such as table 3-7, subsidiary Y axis starts as END, SINGLE operation and operates with automatically calculated ACC/DEC speed and operation speed, as for Dwell time after stop, 100ms, dwell time of main axis X is applied. not 20ms, setting value.

Remark

- A special attention should be paid that linear interpolation start operates on 2 axes simultaneously.
- Pattern of main axis can specified as 'END', 'KEEP'. If it is specified as 'CONT', object moves as it is 'KEEP'.
- Available commands during linear interpolation are DEC. STOP, EMG. STOP.
- During linear interpolation operation, position/speed switching control, speed override, position override, speed override with position, If those are executed during liner interpolation operation, it may cause error.
- Operation method, operation pattern, speed limit, dwell time is specified as that of main axis.
- Speed, acceleration/deceleration time, bias speed of subsidiary axis is calculated again automatically.
- Backlash compensation amount, SW upper/lower limit is specified as it is for each axis.

3.1.7 Simultaneous start control

- It starts each step for each axis simultaneously by simultaneous start control (SST instruction).
- If SST instruction is used, it can remove delay of start caused by scan time delay.



• SST instruction can be executed when two axes stop. If SST instruction is executed again after stop, in case of incremental coordinates, the current position is initialized as 0.

3.1.8 Sync control

•In sync control, position or speed of subsidiary axis is synchronized with that of main axis. There are two types in sync control, speed sync control and position sync control.

(1) Position sync control

 Position sync control means starting the operation step of subsidiary at the time when position of main axis is same with position set in SSP instruction (Sync control)



- Position sync control can be executed when origin of both axes is determined. When executing the SSP instruction, if origin of main axis is not determined, error code 346 occurs and for subsidiary axis, error code 344.
- When using SST instruction, specify the main axis to be different with subsidiary axis. If not, error code 347 will occur.
- If synch control is executed, though pulse is not yielded until main axis goes to designated axis, flag indicating whether subsidiary axis moves or not, turns on (X axis: K4200, %KX6720, Y axis: K4300, %KX6880).
- After executing position sync control, if the user wants to cancel the execution of position sync control, execute the STP instruction (stop command).

(2) Speed sync control

 If main axis starts as figure below, subsidiary axis moves with speed of sync speed rate set in the SSS instruction (speed sync command).



- It can be executed when origin of subsidiary axis is not determined.
- Since subsidiary axis moves according to speed of main axis, whether main axis moves by speed control or position control doesn't matter. At this time, direction of subsidiary axis is same as that of main axis.
- When sync control is executed and main axis stops, though pulse is not outputted, flag indicating whether subsidiary axis moves or not, turns on (X axis: K4200, %KX6720, Y axis: K4300, %KX6880).
- In case of speed synch control, sync speed rate is 0.00% ~ 100.00%. If it is out of range, error code 356 occurs.
- After executing speed sync control, if the user wants to cancel the execution of speed sync control, execute the STP instruction (stop command).
- When executing speed sync control, if M code is on, error code 353 will occur.
- The user can set X axis, Y axis, channel 0~3 of High speed counter as main axis in the speed sync control. For more detail, refer to Ch.5.2.12.

3.1.9 Home return

• Home return is used to fine mechanical origin when starting machine. Home return is executed according to home parameter for each axis. In home parameter, items affecting homing are as follows. (For setting of each parameter, refer to Ch.3.2)

Туре	Items	Description	-
	Home Method	Setting home method	
	Home Direction	Start direction when homing	
	Home Address	Origin address when detecting origin	
Home parameter	Home High/Low speed	High/Low speed when homing	
	Homing ACC/DEC Time	ACC/DEC time when homing	
	DWELL time	Time required to remove offset pulse of remaining bias counter immediately after positioning ends	

• When origin is determined by homing, though the user inputs homing signal and DOG signal, those are ignored.

(1) Type of Home method

Generally, home method can be divided into one using DOG and another not using DOG. In the XGB built-in positioning, there are three methods using DOG.

Home method	Necessary input signal	Reference
Origin detection after DOG off (0: DOG/HOME(OFF))	DOG, Origin	Content of () is displayed in
Origin detection after DEC. when DOG on (1: DOG/HOME(On))	DOG, Origin	the Home Parameter of XG5000.
Origin detection by DOG (2: DOG)	DOG	

(2) Origin detection after DOG Off

The operations by Home Return instruction using DOG and origin signal are as follows.



- (a) If home return command (ORG instruction) is executed, it accelerates toward a preset home return direction and with Home high speed.
- (b) During operating with Home Return High speed, if rising edge of DOG signal occurs, it operates with Home Return Low speed and monitors if there is falling edge of DOG signal. At this time, though Origin signal is inputted while DOG signal is On, Origin is not determined.
- (c) If first origin signal is entered after DOG signal changes from "On" to "Off", it stops.

Remark

• While DOG signal is "On", origin is not determined by origin signal. That is, origin may be determined as soon as origin signal is inputted after DOG signal changes from "On" to "Off".



Remark

• In speed-decreasing section, origin is not determined. Though DOG changed from "On" to "Off" and Origin signal is inputted in speed-decreasing section, origin is not determined. Origin is determined at first Origin signal after speed-decreasing section



• If 'On' time of origin input signal is very short, XGB may not recognize the input signal. So 'On' time of origin should be larger than 0.2ms.







Operations by home return instruction using DOG and origin signal are as follows.

- (a) If homing command(ORG instruction) is executed, it accelerates toward a set home direction and operates at home high speed.
- (b) At the moment, if an external entry, DOG signal is entered, it decelerates and operates at home return low speed.
- (c) Origin is determined and it stops if it meets an external entry, origin signal with DOG set "On" while it operates at home return low speed.

Remark

•Origin is determined if origin signal is entered with DOG set "On" as long as home return speed is operating at low speed from high speed via decelerating section with DOG signal set "On". That is, when home return speed is decelerating, origin is not determined by origin signal.

• If it meets external upper/lower limit signal prior to origin after DOG signal is changed from "Off" to "On", it works backward direction.

(4) Origin detection by DOG

It is used when determining origin by using the only DOG.



(a) If homing command (ORG instruction) is executed, it accelerates to home direction set in Home Parameter and it homes with high speed.

(The above figure is example when homing direction is forward)

- (b) While target is homing with high speed, if rising edge of DOG occurs, target speed decreases and change its direction.
- (c) When it accelerates after changing direction, if rising edge of DOG occurs, it homes with low speed.
- (d) In the homing status with low speed, rising edge occurs of DOG third time, it stops and determines the origin.
- (e) When 'On' time of DOG signal is larger decreasing time, it changes the direction at the falling edge of DOG and moves with low speed and stops at the rising edge of DOG and determines the origin.



3.1.10 Position and speed override

 Override means changing target address or speed without stop during positioning. The XGB positioning provides three type of override, position override, speed override, speed override with position.

(1) Position override

If changing a target position during positioning operation with positioning data, it may be changed by using position override command (POR instruction).



- When using position override, be careful the followings.
- (a) That is, if passing a position to change during operation, it decelerates, stops and keeps positioning operation by the subsequent operation pattern; if not passing a position, it starts positioning operation as taking a Incremental position as much as override set in the start point of the step of position override instruction.
 - (Ex.) It assumes that current location is 20,000 and operation data is specified as table below. (It assumes that position override amount is 15,000)

Step no.	Coord.	Pattern	Contr ol	Metho d	Rep step	Address [Pulse]	M Code	A/D No.	Speed [pls/s]	Dwell [^{ms}]
3	ABS	END	POS	SIN	0	40,000	0	0	500	100

1) If operation step 3 starts, target moves to 40,000 by absolute coordinates forward.

- If override is executed at the time current position is 30,000 during operation, since it doesn't pass 15,000 based on operation start point 20,000 target position changes 35000 (20,000+15,000).
- 3) If override is executed at the time current position is 38,000 during operation, since it passes 15,000 based on operation start point 20,000, target speed decreases and stops.
- (b) Position override command is available in the ACC., KEEP, DEC. section among operation pattern. If position override command is executed during dwell, error code 362 occurs.
- (c) In case operation pattern is set as CONT, override is executed based on start position of operation step used at this time.
- (d) Position override ranges –2,147,483,648 \sim 2,147,483,647 Pulse.

(2) Speed override

While positioning by operation data, it is used to change operation speed by speed override command (SOR instruction).



- Speed override command is available during acceleration, constant speed operation section and executing speed override instruction in deceleration section during operation or dwell section may cause Error 377 but the operation continues.
- Speed override setting ranges 1~100,000pps (setting unit: 1pps).

Remark

- Note that if a sudden difference between the current speed used for operation and a new speed newly changed by speed override is excessive, it may cause a Step-over.
- During speed override, if target speed is smaller than bias speed. it will be operate by bias speed.

(3) Speed override with position

Positioning speed override instruction changes its speed and keeps operating once it reaches the set position during positioning operation by using speed override with position (PSO instruction).



• Positioning speed override instruction is available only in acceleration and regular speed sections among operation patterns while the available operation modes are end operation, continuous operation and sequential operation.

3.1.11 Positioning stop signal

- (1) Stop instruction and stop factors
- Stop instructions and factors are summarized as follows and divided into individual stop and simultaneous stop.

Individual axis stop instructions or the stop factors affect the only axis (axes) of which stop instruction is "On" or stop factor exists. However, interpolation control operation axis stops if an axis is with stop instruction or stop factor during linear/circular interpolation.

Operation status Stop factor		Positioning *1 Home *2 Joe		Jog operation	Axis operation status after stop instruction ⁺³	M code "On" Signal status
Stop by	Excess of soft upper limit	Immediate stop	Not detected	Immediate stop	Error status (Error 501)	No change
setting *4	Excess of soft lower limit	Immediate stop	Not detected	Immediate stop	Error status (Error 502)	No change
Stop by	Dec. stop instruction	Dec. stop	Dec. stop	Error 322 (keep running)	Decelerating	No change
sequence program ^{*5}	Emergency stop instruction		Immediate st	qq	Error status (Error 481) No output	Off
Stop by	External upper limit "On"	Immedia	ate stop	Forward immediate stop	Error status (Error 492) ^{*6}	No change
external signal	External lower limit "On"	Immedia	ate stop	Backward immediate stop	Error status (Error 493) ^{*6}	No change
Stop by monitoring package	Dec. stop instruction	Immediate stop	Immediate stop	Error 322 (keep running)	Stopping	No change

Remark

- *1: Positioning refers to position control, speed control, position/speed switching control and speed/position switching position by positioning data.
- *2: If Home Return is complete, DOG and Home Signal, which are external input signals, do not affect positioning control.
- *3: If axial operation is 'no output' after being stopped, run a instruction to cancel 'No Output'. Then, No output is cancelled and error number is reset.
- *4: Soft upper/lower limits by parameters are unavailable in speed control operation mode.
- *5: Sequence program refers to XGB program method.
- *6: Error 495 may occur depending on a rotation direction.

- (2) Stop Process and Priority
 - (a) Stop Process
 - Since positioning operation is not complete if it stops due to deceleration stop instruction, After Mode among M code modes is not "On" because it does not generate positioning completion signal.
 - After then, if indirect start instruction (step number = current step number) is generated, Absolute method operation operates as much as the remaining distance of the current operation step yet output while Incremental method operation operates as much as the target distance.
 - (b) Process of emergency stop and external input upper/lower limits
 - If emergency stop instruction or external input upper/lower limits are input during positioning control, it stops positioning control and turns 'No output', generating an error.
 - (c) Stop process priority

The priority of positioning module stop process is as follows.

Decelerating stop < Immediate stop

Remark

• In case of any immediate stop factor during decelerating stop, it processes as follow.



• Immediate stop factors: ①internal emergency stop, ②external input upper/lower limit, ③ Soft upper/lower limits

- (d) Interpolation stop
 - It decelerates and stops if it meets a stop instruction during interpolation operation.
 - If indirect start instruction is executed in the current step when re-starting after decelerating stop, it resumes operating the positioning operation data to the target position. At the moment, it operates differently depending on absolute coordinate and Incremental coordinate.
- (e) Emergency stop
 - It immediately stops if meeting emergency stop while performing start-related instructions (indirect start, direct start, simultaneous start, synchronic start, linear interpolation start, Home Return start, jog start and inching start).
 - Internal emergency stop generates Error 481.
 - Since it is subject to no output and un-defined origin once emergency stop is executed, it may run

positioning operation after executing origin determination (Home Return, floating origin and the current position preset) in case it is operated with absolute coordinate or in determined origin.

3.1.12 Manual operation

In general, manual operations refer to jog operation, inching operation which don't use operation data.

- (1) Jog operation
 - Jog operation means positioning by jog operation stat contact point or positioning monitoring package.

Classification		Jog forward start	Jog backward start	Jog high speed/low speed	
V ovio	XBM/XBC	K4291	K4292	K4293	
X axis	XEC	%KX6865	%KX6866	%KX6867	
Y axis	XBM/XBC	K4391	K4392	K4393	
	XEC	%KX7025	%KX7026	%KX7027	

- It is operated by jog speed set in positioning parameter.
- It can be executed when origin is not determined.
- Acceleration/deceleration process is controlled by the duration set in jog acceleration/deceleration time among parameter settings of this software package.
- If jog speed is set out of allowable range, it generates an error and operation is not available

_	High speed jog operation	1 ~ 100,000	
Range	Low speed jog operation	$1~\sim~$ jog high speed	(Unit: Ipps)

Remark

Make sure to follow the cautions

Bias speed \leq Jog high speed \leq Speed limit

(2) Inching operation

- As one of manual operations, it outputs as much as pulse set at the speed for origin/manual parameter inching speed.
- While operation by jog instruction may not exactly move to the start/end points, inching instruction
 may easily reach to a target point as much as desirable distance. Therefore, it is probable to move
 close to an operation position by jog instruction and then move to an exact target position by
 inching operation instruction.
- \bullet The available range is between –2,147,483,648 $~\sim~$ 2,147,483,647 Pulse.

3.1.13 Stroke Upper/Lower Limits

Positioning is subject to external input stroke limit (external input upper limit, external input lower limit) and software stroke limit (software upper limit, software lower limit).

- (1) External input stroke upper/lower limits
 - External input stroke limit is an external input connector of positioning; external input upper limit/external input lower limit.
 - It is used to immediately stop a positioning module before reaching to stroke limit/stroke end by setting up stroke limits of positioning module inside stroke limit/stroke end of drives. At the moment, if exceeding upper limit, it generates Error 492 while if exceeding lower limit, it generates Error 493.



• Note that positioning operation is not available if it stops out of positioning range.

If it stops due to external input stroke limit detection, move it into the controllable range of positioning by manual operation (jog operation, inching operation, manual pulse generator operation).

• External input stroke upper/lower limit error is detected by edge during positioning, so manual operation is available although it exceeds stroke range.

(2) Stroke upper/lower limits

- Stroke upper/lower limit function does not execute positioning operation if it is operated out of ranges
 of stroke upper/lower limits, which are set in positioning parameters.
- When it starts operation or is in operation, stroke upper/lower limits are checked.



Remark

· Software stroke upper/lower limits are not detected unless origin is determined.

3.1.14 Output of positioning completion signal

- Regarding positioning completion output time, the completion signal(X axis: 4202, %KX6722, Y axis: K4302, %KX6882) is on and it turns off after 'on' is maintained as much as 1 scan time after positioning is completed during single operation, repeat operation, continuous operation, sequential operation, linear interpolation operation, speed/position switching operation (with position indicated during constant speed operation) and inching operation.
- In case operation pattern is KEEP or CONT, positioning completion signal is yielded when operation pattern stops completely.
- The operations in single operation mode are as follows.



• The operations in continuous mode are as follows.



· The operations in sequential operation mode are as follows.



3.2 Positioning Parameter

I

It describes positioning parameter and operation data setting.

3.2.1 Positioning parameter setting sequence

- Positioning parameter can be set more than V1.2 (high end type can be set more than XG5000 V2.2) and it has the following sequence. (This manual is described by using XG5000 V2.2.)
- (1) Opening parameter setting window
 - Select [Parameter] -> [Embedded Parameter] -> [Positioning] and double-click to open positioning parameter setting window.

(If project is not displayed, press [View] -> [Project Window] to open project window [shortcut key: ALT + 1])



< Positioning parameter setting window >

- (2) Setting parameter
 - Positioning parameter setting window is classified into basic parameter and Home parameter.
 - Each item can be set independently.
 - For detail setting of basic parameter, refer to 3.2.3.
 - For detail setting of Home parameter, refer to 3.2.4.

Туре	Item	Description				
	Positioning	Set whether to use positioning function.				
	Pulse output level	Set pulse output mode (Low/High Active).				
	Bias speed	Set the initial start speed for early operation.				
	Speed limit	Set the max speed settable in positioning operation.				
	ACC/DEC No.1	Time setting of ACC/DEC section No.1				
	ACC/DEC No.2	Time setting of ACC/DEC section No.2				
	ACC/DEC No.3	Time setting of ACC/DEC section No.3				
Basic parameters	ACC/DEC No.4	Time setting of ACC/DEC section No.4				
Dasic parameters	S/W upper limit	Set upper limit within a machine's operation range				
-	S/W lower limit	Set lower limit within a machine's operation range				
	Backlash compensation	Set compensation amount of tolerance in which a machine is not operated due				
	amount	to wear when rotation direction is changed.				
	S/W upper/lower limits	Set whether to detect or not S/W upper/lower limits during constant speed				
	during constant speed	operation				
	operation					
	Use upper/lower limits	Use or not				
	Home Return method	Set home return method				
	Home Return direction	Set home return direction				
	Origin address	Set origin address				
	Origin compensation amount	Set origin compensation amount				
	Home Return high speed	Set high speed for home return				
	Home Return low speed	Set low speed for home return				
	Home Return accelerating	Set accelerating time for home return				
Origin/Manual	time					
parameters	Home Return decelerating	Set decelerating time for home return				
	time					
	Dwell time	Set a time required to remove remaining bias counter immediately after				
		positioning ends				
	Jog high speed	Set high speed for jog operation				
	Jog low speed	Set low speed for jog operation				
	Jog accelerating time	Set accelerating time for jog operation				
	Jog decelerating time	Set decelerating time for jog operation				
	Inching speed	Set speed for inching operation				

< Positioning parameter setting item >

(3) Operation data setting

Г

- If the user select 'X Axis Data' or 'Y Axis Data' tap on the positioning parameter setting window, the user can set operation data of 30 steps as show below.
- Standard type can set up to 30 steps, high-end type can set up to 80 steps.

	l Posit	ioning										? 🔀
		Coord.	Pattern	Control	Method	REP Step	Address (pulse)	M Code	A/D No.	Speed (pls/s)	Dwell (ms)	^
	1	ABS	END	POS	SIN	0	0	0	No.1	0	0	' II
	2	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	3	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	4	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	5	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	6	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	7	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	8	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	9	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	10	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	11	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	12	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	13	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	14	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	15	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	16	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	17	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	18	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	19	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	20	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	21	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	22	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	23	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	24	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	25	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	26	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	27	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	28	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	29	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	30	ABS	END	POS	SIN	0	0	0	No.1	0	0	~
Ľ.	- 11	400	- Carrier		CIN	0		0	No.1		0	
	Positio	n Parameter	X-Axis	Data 9.4	Operat	tion dat	a setti	na		01		
	Operation data setting											

< Position operation data setting window >

•Items of operation data is as table below.

•For detail of operation data, refer to 3.3.

Item	Description	Initial value
Coord.	Setting Cood. of each step (ABS/INC)	ABS
Pattern	Setting operation pattern of each step (END/KEEP/CONT)	END
Control	Setting control method of each step (POS/SPD)	POS
Method	Setting operation method of each step (SIN/REP)	SIN
REP step	In case of repeated operation, setting the next step no.	0
Address	Setting target address of each step	0[Pulse]
M Code	In case of using M code, number indicated when M code occurred (In case of setting as 0, M code function is not used)	0
A/D No.	Setting A/D no. of each step	No.1
Speed	Operation speed of each step	0[pps]
Dwell	After ending step, time necessary to remove remaining pulse of offset counter	O [ms]

- (4) Writing to PLC
 - •After setting of positioning parameter and operation data per each axis, download them to PLC •Selecting [Online] -> [Write], 'Write' dialog box is displayed.
 - In order to download parameter, select 'Parameter' and click 'OK'.

Write ?X	
NewPLC Comment Parameter Program	Click OK
Setting OK Cancel	

Remark

- If XG5000 is not connected with PLC, 'Write' menu is not activated. In case of this, select [Online] -> [Connect] to connect with PLC.
- When PLC is RUN mode, comment is available to download so only comment is displayed in the 'Write' dialog box. At this time, change PLC's mode to STOP and retry it.

XG5000	X
1	Change PLC mode to stop mode and write to PLC?
	Yes No

- If downloading parameter, basic parameter, I/O parameter, built-in parameter is transmitted.
- The downloaded positioning parameter is applied when turning on the power or changing operation mode. For more detail, refer to 3.2.2.

3.2.2 Relationship between positioning parameter and dedicated K area

XGB built-in positioning function executes the positioning control by using parameter and K area dedicated for positioning. Here describes relationship between positioning parameter and K area. Internal memory configuration related with XGB built-in positioning is as follows.



< Relationship between positioning parameter and K area >

- •XGB has a built-in parameter area to save operation data and parameter written in the XG5000 and a dedicated K area for use of real positioning operation.
- •If writing the embedded positioning parameter and operation data, the downloaded data is saved in the built-in parameter area permanently. And in case of reading, it reads built-in parameter area.
- •XGB executes the initialization by copying the parameter and operation data saved in the built-in parameter area to K area dedicated for positioning.
 - (1) In case of restarting after power cut
 - (2) In case of changing PLC operation mode
 - (3) In case of restarting PLC by reset command

•XGB built-in positioning is executed by using data of K area and Flags that indicate the current operation status and monitoring data are displayed in the K area. So the user can change operation data easily by changing the K area data

•In order to preserve the current K area data, K area data should be applied to built-in parameter area by using application command (WRT command)

•For detail list of K area, refer to A2.2.

Remark

After changing K area and not using WRT instruction, if restarting after power cut or changing PLC operation mode, K area is initialized.
For more detail of WRT instruction, refer to 5.2.21.

3.2.3 Setting basic positioning parameters

It describes the range of setting basic parameters and special K area for positioning.

٦

			K area for			
			X-axis	Y-axis		
Item	Range	Initial value	XBM/XBC	XBM/XBC	Data size	
			XEC	XEC		
Positioning	0: No use, 1 : use	0	K4870 %KX7792	K5270 %KX8432	Bit	
Pulse output level	0 : Low Active, 1 : High Active	0	K4871 %KX7793	K5271 %KX8433	Bit	
Pulse output mode	0 : CW/CCW 1 : PLS/DIR	0	K4873 %KX7795	K5273 %KX8435	Bit	
M code output mode	0 : NONE, 1 : WITH 2 : AFTER	0	K4681-2 %KX7489-90	K5081-2 %KX8129-30	Bit	
Bias speed	$1 \sim 100,000$ [pulse/sec]	1	K450 %KD225	K490 %KD245	Double word	
Speed limit	1 ~ 100,000[pulse/sec]	100,000	K452 %KD226	K492 %KD246	Double word	
ACC time 1	0 ~ 10,000[unit: ms]	500	K454 %KW454	K494 %KW494	word	
DEC time 1	0 ~ 10,000[unit: ms]	500	K455 %KW455	K495 %KW495	word	
ACC time 2	0 ~ 10,000[unit: ms]	1,000	K456 %KW456	K496 %KW496	word	
DEC time 2	0 ~ 10,000[unit: ms]	1,000	K457 %KW457	K497 %KW497	word	
ACC time 3	0 ~ 10,000[unit: ms]	1,500	K458 %KW458	K498 %KW498	word	
DEC time 3	0 ~ 10,000[unit: ms]	1,500	K459 %KW459	K499 %KW499	word	
ACC time 4	0 ~ 10,000[unit: ms]	2,000	K460 %KW460	K500 %KW500	word	
DEC time 4	0 ~ 10,000[unit: ms]	2,000	K461 %KW461	K501 %KW501	word	
S/W upper limit	-2,147,483,648 ~ 2,147,483,647 [pulse]	2,147,483,647	K462 %KD231	K502 %KD251	Double word	
S/W lower limit	-2,147,483,648 ~ 2,147,483,647 [pulse]	-2,147,483,648	K464 %KD232	K504 %KD252	Double word	
Backlash Compensation	0 ~ 65,535[pulse]	0	K466 %KW466	K506 %KW506	word	
S/W Limit Detect	0 : No detect1 : detect	0	K4684 %KX7492	K5084 %KX8132	Bit	
Upper/lower limits	0: no use, 1: use	1	K4872 %KX7794	K5272 %KX8434	Bit	

(1) Positioning

•Determine whether to use positioning.

- If not using positioning function, set it '0: no use' while for use, it should be set to '1: use'.
- If setting it as '1:use', though it doesn't execute the instruction related with positioning, it is controlled by positioning.

So in this case, though the user turns on this contact point by other application instruction, only output image data of XG5000 monitoring window is on and real output contact point doesn't turn on.

Remark

• Make sure to set it '1: use' to use positioning. If using the instruction related with positioning when it is set as '0: no use'', error code 105 occurs.

(2) Pulse output level

- •For pulse output level, select either of 'Low Active output' or 'High Active output'.
- •For Low Active output, set as 0, for High Active output, set as 1.
- •The following figure shows output pulse type in case of Low Active and High Active output based on X axis. (in case of Y axis, pulse string output: P21, direction output: P23)





- (3) Pulse output mode (For only high end type)
 - •XGB built-in positioning can select output mode as one between PLS/DIR mode and CW/CCW mode.
 - •If you use CW/CCW mode, select 0. If you use PLS/DIR mode, select 1.
 - •About output pulse shape according to each pulse output mode, refer to ch.2.2.3.
- (4) M code output mode (For only high end type)In case of using M code function, you can set output timing of M code.

•M code output mode set in the parameter is applied to all operation step of each axis.

- •The user can select one M code output mode among three modes, NONE, WITH, AFTER. According to each setting value, timing of M code output signal is as follows.
- (a) NONE mode
 - In case M code output mode is selected as NONE, though M code is set in operation data, M code doesn't occur like the following figure.
 - •If the user use this function, it can prohibit the M code function set per operation step, simultaneously.



(b) WITH mode

• In case M code output mode is set as WITH, like the following figure, it outpus M code on signal and M code number when each step runs.



< M code output timing in case of WITH mode >

- (c) AFTER mode
 - In case M code output mode is set as AFTER, like the following figure, if each operation of step is completed, it outputs M code On signal and M code number.



< M code output timing in case of AFTER mode >

- (5) Bias speed
 - Considering that torque of stepping motor is unstable when its speed is almost equal to 0, the initial speed is set during early operation in order to facilitate motor's rotation and is used to save positioning time. The speed set in the case is called 'bias speed'.
 - In case of XGB built-in positioning, setting range of bias speed is 0 ~ 100,000 (unit:pps).
 - · Bias speed may be used for
 - (1) Positioning operation by start instruction (IST,DST,SSTetc.)
 - (2) Home operation, JOG operation
 - (3) Main axis of interpolation operation(not available for sub axis)



< Operation when setting bias speed >

• The figure above shows operation when setting bias speed.

The entire operation time may be advantageously reduced if bias speed is highly set, but excessive value may cause impact sound at the start/end time and unreasonable operation on a machine.

- Bias speed should be set within the following range.
 - (a) Bias speed \leq Positioning speed
 - (b) Bias speed \leq Home Return low speed \leq Home Return high speed

- (c) Bias speed \leq JOG high speed
 - → (If home return speed is set lower than bias speed, it generates Error 133; if operation speed is set lower than bias speed during positioning, it generates Error 153; if JOG high speed is set lower than bias speed, it generates Error 121.)
- (6) Speed limit
 - It refers to the allowable max speed of positioning operation.
 - In Pulse unit, the range is between 1 \sim 1,000,000(unit: pps).
 - During position operation, operation speed, home return speed and jog operation speed are affected by speed limit, and if they are set higher than speed limit, it detects error.
 - (1) If home return speed is higher than speed limit : Error 133
 - (2) If positioning speed is higher than speed limit : Error 152
 - (3) If jog operation speed is higher than speed limit : Error 121
- (7) ACC/DEC time
 - It is applied to sequential operation instruction, speed override, positioning speed override during
 positioning operation as well as start/end time of positioning operation. At this time, ACC and DEC
 time is defined as shown below.
 - (a) ACC time: a duration required to reach from "0(stop)" speed to the speed limit set in parameter. Using bias would be a time consumed to reach from bias speed set to the speed limit set in parameter.
 - (b) DEC time: a duration required to reach from the speed limit set in parameter up to "0"(stop) speed.

Using bias would be a time consumed to reach from bias speed set to the speed limit set in parameter.





- The range is between 0 \sim 10,000 (unit: 1 ms) per axis.
- ACC/DEC time is set with 4 types and it can be set differently according to each operation data.

(8) S/W Upper/Lower Limit

• A range of a machine's move is called 'stroke limit', and it sets the upper/lower limits of stroke into software upper limit and software lower limit and does not execute positioning if it operates out of ranges set in the above.

Therefore, it is used to prevent against out-of-range of upper/lower limits resulting from incorrect positioning address or malfunction by program error and it needs installing emergency stop limit switch close to a machine's stroke limit.

•Except S/W upper limit and lower limit, install limit switch for emergency stop near stroke limit of machine.


- Range of S/W upper limit and lower limit is checked when starting positioning and operating.
- If an error is detected by setting software upper/lower limits(software upper limit error: 501, software lower limit error: 502), pulse output of positioning module is prohibited.
 Therefore, to resume operation after an error is detected, it is prerequisite to cancel 'No output'.
 (No output status is displayed at K4205(%KX6725), for X axis and K4305(%KX6885) for Y axis.
- It can be set according to each axis and range is as follows.
 - S/W upper limit address value range: -2,147,483,648 ~ 2,147,483,647 (unit: Pulse)
 - S/W lower limit address value range: -2,147,483,648 \sim 2,147,483,647 (unit: Pulse)

(9) Backlash Compensation Amount

- A tolerance that a machine does not operate due to wear when its rotation direction is changed if it is moving with motor axis combined with gear and screw is called 'backlash'.
- Therefore, when changing a rotation direction, it should output by adding backlash compensation amount to positioning amount.
- The range is between 0 \sim 65,535(unit: Pulse) per axis.
- It is available for positioning operation, inching operation and jog operation



• Backlash compensation outputs backlash compensation amount first and then, address of positioning operation, inching operation and jog operation move to the target positions. (At this time, output as many as backlash amount is not added to the current position address.)



- The above figure describes difference of backlash setting or no backlash setting. In case of not setting backlash compensation amount, it moves as many as 100,000 pulse forward and changes the direction and moves backward as many as 100,000 pulse. It may cause error by backlash. For example, it assumes that backlash is 500 pulse, in case of not setting backlash, final stop location is 500. To compensate this, setting backlash compensation as 500, when changing the direction, 100,500 pulse is yielded adding 500 pulse set as backlash compensation amount. So
- target stops at the precise stop position.The following table indicates real pulse output and stop position in case of setting backlash. (Absolute coordinates is used.)

Operation step	Backlash setting amount	Target address	Direction conversion	Real output pulse	Stop positio
1		10,000	Х	10,000	10,000
2	500	30,000	Х	20,000	30,000
3		0	0	-30,500	0



• Once backlash compensation amount is set or changed, home return should be executed otherwise there can be error at the current position by backlash compensation amount.

- (10) S/W upper/lower limits during constant speed operation
 - It is used to stop pulse output by S/W upper/lower limit detection during constant speed operation by speed control.

- In the case, S/W upper/lower limit detection is available as long as origin is set and the position mark during constant speed operation is "Mark"
- (11) Use of Upper/Lower Limits

Γ

- To use upper/lower limits during operation, it should be set as "Use".
- Upper/Lower limit input contact point is fixed as the table below and it can be used as normally closed contact point (B contact point).
- If 'No use' is set, it does not detect upper/lower limits and is available with general input contact.

Signal	Input cor	ntact point n	umber	Operation content	Poforonco		
name	Standard High end Operation content		Operation content	Relefence			
External low limit	X axis	P0000	P0008	Detects the X axis external lower limit at the rising edge of input contact point	Acts as		
signal (LimitL)	Y axis	P0002	normally closed				
External upper limit	X axis	P0001	P0009	Detects the X axis external upper limit at the rising edge of input contact point.	(B contact point)		
signal (LimitH)	Y axis	P0003	P0008	Detects the Y axis external upper limit at the rising edge of input contact point.			

3.2.4 Origin/Manual Parameter Setting for Positioning

Here describes setting range, method of origin/manual parameter for positioning, and special K area for positioning corresponding to each item. They are summarized as the table below.

			Dedi K a	cated area	
ltem	Setting range	Initial value	X axis XBM/XBC XEC	Y axis XBM/XBC XEC	Data size
Home Return method	 0 : origin detection after DOG off 1 : origin detection after deceleration when DOG is On 2 : origin detection by DOG 	0	K4780-81 %KX7648-49	K5180-81 %KX8288-89	2 Bit
Home Return direction	0 : forward, 1 : backward	1	K4782 %KX7650	K5182 %KX8290	Bit
Origin address	-2,147,483,648~2,147,483,647[pulse]	0	K469 %KD234	K509 %KD254	Double word
Home Return high speed	1 ~ 100,000[pulse/ s]	5,000	K471 %KD235	K511 %KD255	Double word
Home Return low speed	1 ~ 100,000[pulse/ s]	500	K473 %KD236	K513 %KD256	Double word
Home Return ACC time	0 ~ 10,000[unit: ms]	1,000	K475 %KW475	K515 %KW515	Word
Home Return DEC time	0 ~ 10,000[unit: ms]	1,000	K476 %KW476	K516 %KW516	Word
Dwell time	0 ~ 50,000[unit: ms]	0	K477 %KW477	K517 %KW517	Word
Jog high speed	1 ~ 100,000[pulse/s]	5,000	K479 %KD239	K519 %KD259	Double word
Jog low speed	1 ~ 100,000[pulse/s]	1,000	K481 %KD240	K521 %KD260	Double word
Jog ACC time	0 ~ 10,000[unit: ms]	1,000	K483 %KW483	K523 %KW523	Word
Jog DEC time	0 ~ 10,000[unit :ms]	1,000	K484 %KW484	K524 %KW524	Word
Inching speed	1 ~ 65,535[pulse/s]	100	K485 %KW485	K525 %KW525	Word

(1) Home Return method

There are three home return methods as follows.

- a) DOG/Origin(Off) :
- -If origin signal is inputted, it detects the origin signal after DOG changes On -> Off.
- b) DOG/Origin(On) : When DOG is on, it detects the origin after deceleration
- -If DOG signal is on and origin signal is inputted after deceleration, it detects the origin. c) DOG :
- -It detects the origin by using DOG signal.
- For more detail of home return method, refer to 3.1.9.

(2) Home Return direction

 Home Return direction is divided into CW(forward) and CCW(backward) depending on pulse output direction.

Setting value	Home Return direction	Pulse output operation of XGB positioning module
0	Forward	Executing forward home return.
1	Backward	Executing backward home return.

(3) Origin address

- It is used to change the current address to a value set in home return address when home return is completed by home return instruction.
- setting range: -2,147,483,648 ~ 2,147,483,647 (unit: Pulse)

(4) Home Return high speed

- As a speed when it returns home by home return instruction, it is divided into high speed and low speed.
- It refers to a speed operating in regular speed section via accelerating section by home return instruction.
- The range of home return high speed is between 1 \sim 100,000(unit: pps)

(5) Home Return low speed

- It refers to a speed operating in regular speed section via decelerating section from home return high speed by home return instruction.
- The range of home return low speed is between 1 \sim 100,000(unit: pps)

Remark

• When setting home return speed, it should be "speed limit ≥ home return high speed ≥ home return low speed".

• It is recommended to set home return low speed as low as possible when setting home return speed. Origin signal detection may be inaccurate if low speed is set too fast.

- (6) Home Return ACC/DEC time
- When it returns home by home return instruction, it returns home at the speed of home return high speed and home return low speed by ACC/DEC time.
- The range of home return ACC/DEC time is between 0 \sim 10,000(unit: 1 ms).

(7) Dwell time

- It sets Dwell time applied to Home Return
- Dwell time is necessary to maintain precise stop of servo motor when positioning by using a servo motor.
- The actual duration necessary to remove remaining pulse of bias counter after positioning ends is called 'dwell time'.
- The range of home return dwell time is between 0 \sim 50,000 (unit: 1 ms)

- (8) JOG high speed
- Jog speed is about jog operation, one of manual operations and is divided into jog low speed operation and jog high speed operation.
- Jog high speed operation is operated by patterns with accelerating, regular speed and decelerating sections. Therefore, job is controlled by ACC/DEC instruction in accelerating section and decelerating section.
- The range of jog high speed is between 1 \sim 100,000(unit: 1pps)
- (9) JOG low speed
- Jog low speed operation is operated with patterns of accelerating, regular speed and decelerating sections.
- The range of jog low speed is between 1 \sim 100,000 (unit: 1pps)

- When setting JOG high speed, it should be "Speed limit \geq JOG high speed \geq Bias speed".
- When setting JOG low speed, it should be smaller than JOG high speed.

(10) JOG ACC/DEC time

- It refers to JOG ACC/DEC time during jog high/low speed operation.
- The range of JOG ACC/DEC time is between 0 \sim 10,000 (unit: 1 $^{\rm ms})$

(11) Inching speed

- The inching operation speed is set.
- The range of inching speed is between 1 \sim 65,535 (unit: 1pps)
- For detail of inching operation, refer to 3.1.12.

3.3 Positioning Operation Data

It describes operation data for XGB positioning. If the user select 'X axis data' or 'Y axis data' tap in the positioning parameter setting window, the following figure is displayed. Each axis can have 30~80 (standard type: 30 steps, compact stand/high-end type: 80steps) steps of operation data.

1 2 3	ABS			method	HEP Step	(pulse)	M Code	No.	(pls/s)	(ms)	
2		END	POS	SIN	0	0	0	No.1	0	0	
3	ABS	END	POS	SIN	0	0	0	No.1	0	0	
-	ABS	END	POS	SIN	0	0	0	No.1	0	0	
4	ABS	END	POS	SIN	0	0	0	No.1	0	0	
5	ABS	END	POS	SIN	0	0	0	No.1	0	0	
6	ABS	END	POS	SIN	0	0	0	No.1	0	0	
7	ABS	END	POS	SIN	0	0	0	No.1	0	0	
8	ABS	END	POS	SIN	0	0	0	No.1	0	0	
9	ABS	END	POS	SIN	0	0	0	No.1	0	0	
10	ABS	END	POS	SIN	0	0	0	No.1	0	0	
11	ABS	END	POS	SIN	0	0	0	No.1	0	0	
12	ABS	END	POS	SIN	0	0	0	No.1	0	0	
13	ABS	END	POS	SIN	0	0	0	No.1	0	0	
14	ABS	END	POS	SIN	0	0	0	No.1	0	0	
15	ABS	END	POS	SIN	0	0	0	No.1	0	0	
16	ABS	END	POS	SIN	0	0	0	No.1	0	0	
17	ABS	END	POS	SIN	0	0	0	No.1	0	0	
18	ABS	END	POS	SIN	0	0	0	No.1	0	0	
19	ABS	END	POS	SIN	0	0	0	No.1	0	0	
20	ABS	END	POS	SIN	0	0	0	No.1	0	0	
21	ABS	END	POS	SIN	0	0	0	No.1	0	0	
22	ABS	END	POS	SIN	0	0	0	No.1	0	0	
23	ABS	END	POS	SIN	0	0	0	No.1	0	0	
24	ABS	END	POS	SIN	0	0	0	No.1	0	0	
25	ABS	END	POS	SIN	0	0	0	No.1	0	0	
26	ABS	END	POS	SIN	0	0	0	No.1	0	0	
27	ABS	END	POS	SIN	0	0	0	No.1	0	0	
28	ABS	END	POS	SIN	0	0	0	No.1	0	0	
29	ABS	END	POS	SIN	0	0	0	No.1	0	0	
30	ABS	END	POS	SIN	0	0	0	No.1	0	0	
	400	C	-	CIN			-	Ma 1		0	
osition P	Parameter	X-Axis	Data Y-A	xis Data							

Each of item can have a following data.

Sten	ltem	Range	Initial	Devic	e area	Remarks
Step	nem	Kange	values	X-axis	Y-axis	Kennarks
	Coord.	0 : ABS, 1 : Incremental	ABS	K5384 %KX8612	K8384 %KX13412	Bit
	Pattern	0 : end, 1 : continuous, 2 : sequential	End	K5382~3 %KX8610-11	K8382~3 %KX13410-11	Bit
	Control	0 : position control, 1 : speed control	Position	K5381 %KX8609	K8381 %KX13409	Bit
	Method	0: single, 1 : repeat	Single	K5380 %KX8608	K8380 %KX13408	Bit
1	REP	0~30(High end 0~80)	0	K539 %KW539	K839 %KW839	Word
I	Address(pulse)	-2,147,483,648 ~ 2,147,483,647 [pulse]	0	K530 %KD265	K830 %KD415	Double word
	M Code	0 ~ 65,535	0	K537 %KW539	K837 %KW837	Word
	A/D No.	0 : No.1, 1 : No.1, 2 : No.3 3 : No.4	0	K5386-87 %KX8614-15	K8386-87 %KX13414-15	Bit
	Speed	1 \sim 100,000[pulse/sec]	0	K534 %KD267	K834 %KD417	Double word
	Dwell time	0 ~ 50,000[unit: ms]	0	K536 %KW536	K836 %KW836	Word
2		Same item with No.1 step		K540~549 %KW540~549	K840~849 %KW840~849	
3~30		Same item with No.1 step		K550~829 %KW550~829	K850~1129 %KW850~1129	
31		Same item with No.1 step		K2340~2349 %KW2340~2349	K2840~2849 %KW2840~2849	Only for
32~80		Same item with No.1 step		K2350~2839 %KW2350~2839	K2850~3339 %KW2850~3339	high end type

(1) Step number

- The range of positioning data serial number is between 1 ~ 30. (compact standard/high-end type is 1~80)
- When executing indirect start, simultaneous start, linear interpolation operation, position synchronization and etc., if you designates the step number of data to operate, it operates according to positioning dedicated K area where operation data is saved.
- If step number is set as 0, operation step indicated at the current step number (X axis: K426(%KW426), Y axis: K436(%KW436)) of positioning monitor flag is operated.

Remark

• The user can use variable of dedicated K area per each step easily by using Register U Device. For detail of monitor registration of positioning, refer to XG5000 user manual.

(2) Coordinates

- Here sets the coordinates method of relevant operation step data.
- Coordinates methods selectable are absolute coordinate and Incremental coordinate.
- For more detail, refer to 3.1.2.
- (3) Operation pattern (END/KEEP/CONT) and operation method (SIN/REP)
 - The user can select one pattern among three operation patterns per step. It can configure how to use the positioning operation data.
 - Operation pattern can be set as follows according to Control and Method on the operation data.

Control	Method	Pattern	Reference
		END	
	SIN	KEEP	
DOS		CONT	Linear interpolation is not available
FU3		END	
	REP	KEEP	
		CONT	Linear interpolation is not available
		END	Linear interpolation is not available
SPD	SIN	KEEP	Linear interpolation is not available
		CONT	Not available
		END	Linear interpolation is not available
속도 제어	REP	KEEP	Linear interpolation is not available
		CONT	Not available

• In case Method is set as SIN, the next operation step become 'current operation step + 1'. And in case Method is set as REP, the next operation step become the step set in REP Step.

(a) END (SIN)

• It refers to execute the positioning to target address by using the data of operation step and complete the positioning after dwell time.



 Generally with END operation, position operation is executed according to pre-arranged speed and position like above picture as ladder shape with accelerated, constant, and decelerated intervals. However depending on position and speed settings, special shapes besides a ladder can be witnessed as below.



- 1) In case target address is far less than speed, it can't pass the acceleration regular speed deceleration section. In this case, the positioning is complete without regular speed section.
- 2) In case operation speed is same with bias speed, target moves with regular speed (bias speed) and it stops without deceleration section.

• It assumes that operation data is as follows to describe END/SIN operation.

Step no.	Coord	Pattern	Contr ol	Metho d	REP Step	Address [Pulse]	M code	A/D No.	Speed [pls/s]	Dwell [ms]
1	ABS	END	POS	SIN	0	10,000	0	1	1,000	100
2	ABS	END	POS	SIN	0	20,000	0	1	500	100
3	ABS	END	POS	SIN	0	30,000	0	1	1,000	100

• In the above table, operation pattern is set as END, target moves once by once start command and since Method is set as SIN, the next step becomes 'current operation step + 1'.

• To operate the next step, one more start command is necessary.



(b) END operation (Repetition)

In case END operation (repetition), operation of currently started operation is same with END operation (single).

But, The next step becomes the step set in the REP Step, which is different with END operation (single).

• It assumes that operation data is set as follows to describe END/Repetition.

Step No.	Coord	Pattern	Contr ol	Metho d	REP Step	Address [Pulse]	M code	A/D No.	Speed [pls/s]	Dwell [ms]
1	ABS	END	POS	SIN	0	10,000	0	1	1,000	100
2	ABS	END	POS	REP	1	20,000	0	1	500	100
3	ABS	END	POS	SIN	0	30,000	0	1	1,000	100

1) By first start command, target moves to 10,000 pulse with 1,000pps speed and stops. At this time, since Method is SIN, the next operation step becomes the no.2 step, current operation step +1.

2) By second start command, target moves to 20,000 with 500pps and stops. At this time, Method is REP, the next operation step becomes no.1 step set in REP Step, not no.3 step.

3) If third start command is inputted, target moves to 10,000 ABS coordinates with 1,000 pps.

4) Like this, no.1 step and no.2 step are repeated whenever start command is executed so no.3 step is not operated.



- •If the operation mode is set as single, set the operating step number in the IST at 0, then the step specified in the current step number (axis X: K426(%KW426), axis Y: K436 (%KW436)) in area K for positioning.
- •If the operation mode is set as Repeat and the Repeat step is set at 0, the step stops operating and the next step changes into 0.

In this case, the operating step gets out of the range of $1\sim30$ ($1\sim80$ for the compact standard/high-end type) and error code 512 comes out, so be careful of the repeating step setting when you set at the repeating operation.

(c) Continued Operation

•Continued operation refers to the operation which carried out positioning to the target position by using the data of the corresponding operating step by the operation instruction and continues the next operating steps without any additional operation instructions with the positioning not completed after the dwell time.

•The next operating steps differ according to the current operating mode of the steps.

A) The operation mode of the current step is single: current operating step + 1

B) The operation mode of the current step is repetition: the step designated as Repeat in the current operation step

•If you use the continued operation pattern, you can conduct the pattern operation that sequentially carried out multiple operating steps with only one operation instruction.

•The continued operation can be explained with the operation data in the following table.

Step No.	Coordina tes	Operation pattern	Control	Operation mode	Repeatin g step	Target position [Pulse]	M code	Acc./Dec. No.	Speed [pls/s]	Dwell time [^{ms}]
1	Absolute	Keep	Position	Single	0	10,000	0	0	1,000	100
2	Absolute	Keep	Position	Single	0	20,000	0	0	500	100
3	Absolute	End	Position	Single	0	30,000	0	1	1,000	0
4	Absolute	End	Position	Repeat	1	40,000	0	1	500	0

- 1) Steps 1 and 2 are continued in the operation pattern and single in the operation mode, so they operate at 1,000pps to the pulse of absolute coordinates 10,000 and then operates step 2, the next step, without waiting for the next operation instruction when the dwell time passes. If the dwell time passes after step 2, step 3 is operated.
- 2) Step 3, of which the operation pattern is end, operates up to absolute coordinates 30,000, and then stops right away because the dwell time is 0, and the positioning completion bit turns on for a scan.

- 3) Since the operation mode of step 3 is single, the next step is No. 4.
- 4) Step 4 has been set as end/repeat 1, it operates up to absolute coordinates 40,000 when step 4 operates by the second operation instruction, and stops without dwell time, and the next step points at step 1 which has been designated as the Repeat step.
- 5) The operation pattern can be illustrated as follows.



- (d) Incessant Operation
 - Incessant operation refers to the operation that continues the steps set as continued operation by the operation instruction.
 - The continued operation can be explained with the operation data in the following table.

St	ep No.	Coordina tes	Operation pattern	Control	Operation mode	Repeatin g step	Target position [Pulse]	M code	Acc./Dec. No.	Speed [pls/s]	Dwell time [^{ms}]
	1	INC	Continuous	Position	Single	0	10,000	0	1	500	100
	2	INC	End	Position	Repeat	1	20,000	0	1	1,000	0

- 1) Since the operation pattern of step 1 has been set as continued, it operates up to the incremental coordinates 10,000 pulse at 500pps by the first operation instruction, and changes the operation speed to 1,000pps without deceleration or stop and continues to operate step 2.
- 2) Because the operation pattern of step 2 is end, it moves to incremental coordinates 20,000 and the positioning ends after the dwell time.



• If the direction changes during the continued operation, error code 511 comes out and the operation stops. If the direction has to change, change "Continuous" into "End" or "Keep".

- (4) Repeat Step
 - Sets the step to repeat when the operation mode is set as Repeat.
 - The setting range is 1~30 (1~80 for the compact standard/high-end type).
- (5) Target Position
 - Sets the movement of the operation of the step.
 - The setting range is -2,147,483,648 ~ 2,147,483,647 (unit: Pulse).
 - The target position set in operation data setting can be freely changed in the program by changing the value of area K for positioning.
 - For the address of area K for positioning of each step number, see 2.2.
- (6) M Code
 - M code is for checking the current operation step or carrying out the auxiliary work such as tool change, clamp, and drill rotation.
 - In general, the output of M code divides into the 'With' mode, when M code is output with the step operating, and the 'After' mode when M code is output after the step operation is completed.
 For XGB built-in positioning, the standard type has only the After mode, and the advanced type has all modes.
 - For example, if M code output mode is set as the After mode, the positioning of the step is completed and at the same time, the M code On signal (axis X: K4203(%KX6723), axis Y: K4303 (%KX6883)) is set and the M code number set in the M code item of the step operation data is output in the M code output device (axis X: K428(%KW428), axis Y: K438(%KW438)).
 - M code can be set differently for the operation steps of the positioning operation data. The setting
 range is 1 ~ 65,535. If you don't want to use M code function for the step, just set it at 0. If you don't
 want to use M code function for any step, set the M code output mode parameter as NONE.
 - If there is the M code signal, you can reset it by using the M code Off instruction (MOF).
 - If there is the M code signal, the operation differs depending on the current operation pattern.
 - (a) End: Stops with M code coming out. For operation of the next operation step, the M code should be reset and the operation instruction should be executed.
 - (b) Continued: Enters the Stand-by status for operation of the next step with M code coming out. For operation of the next operation step, if the M code is reset, the next operation step is operated without additional operation instructions.
 - (c) Incessant: Does not stop and operates the next operation step although M code comes out. In this case, M code Off instruction can be carried out even during operation.
 - For example, the output timing of M code signals in case of After Mode can be illustrated as follows.



• With M code signal On, if you execute the next operation step number, error code 233 will come out and the operation will not happen.

Therefore, for positioning of the next operation step number with M code signal "On," you must reset M code signal as M code Off instruction (MOF).

- (7) Acceleration/Deceleration Numbers
 - Sets the Acc./Dec. numbers to be used in the step during the acceleration/deceleration time set in the basic positioning parameter.
 - The setting range is 1~4.
 - For details about the acceleration/deceleration time, see 3.2.3.
- (8) Operation Speed
 - Set the target speed at which to operate in the step.
 - The setting range is 1 ~ 100,000 pulse (unit:1pps).
 - The operation speed should be set higher than or equal to the bias speed set in the basic positioning parameter, and lower than or equal to the speed limit.
- (9) Dwell Time
 - The dwell time to be applied to the operation step.
 - The dwell time refers to the time needed to maintain the precise stop of the servo motor in controlling the positioning by using the servo motor, and also the standby time given before the next positioning operation when one positioning operation is finished.
 - Especially when the servo motor is used, it might not reach the target position or stay excessive even though the output of the positioning function has been stopped, so the dwell time is the data that set the standby time until the stable rest.
 - The operation status of the axis of the XGB positioning function during the dwell time maintains "Operation," and if the dwell time passes, the operation status signaling bit (axis X: K4200(%KX6720), axis Y: K4300(%KX6880)) turns Off and the positioning completion signal turns On.

3.4 Positioning Status Monitoring and Area K for Input and Output

The XGB built-in positioning function controls positioning by using area K for positioning and the parameters. This Chapter describes area K for positioning.

For the relations between the XGB built-in positioning parameters and area K, see 3.2.2.

XGB built-in positioning area K divides into the bit flag, word, and double word flag. The flag in turn divides into the status monitoring flag area (for read only) and the flag for instruction and command (for read and write).

3.4.1 Status Monitoring and Flag for Positioning

This chapter describes the XGB built-in status monitoring flag for positioning (for read only). The status monitoring flag divides into bit, word, and double word.

(1) Bit Area Flag

(a) XBM/XBC bit are	ea flag

	Device Area						
Variables		Axis)	x		Axis	Y	Status
	Word	Bit	Address	Word	Bit	Address	
In operation		0	K4200		0	K4300	0: stop, 1: operation
Error		1	K4201		1	K4301	0: no error, 1: error
Positioning completed		2	K4202		2	K4302	0: not completed, 1: completed
M code signal		3	K4203		3	K4303	0:M code Off, 1:M code On
Origin settled		4	K4204		4	K4304	0: origin not decided, 1: origin decided
No pulse output		5	K4205		5	K4305	0: output available, 1: no output
Stopped		6	K4206		6	K4306	0: not stopped 1: stopped
Upper limit detected		8	K4208		8	K4308	0: undetected, 1: detected
Lower limit detected	1/120	9	K4209	K130	9	K4309	0: undetected, 1: detected
Emergency stop	K42U	А	K420A	4 K430	А	K430A	0: normal, 1: abnormally stopped
Normal/backward rotation	В К420В		В	6 K430B	0: normal direction, 1: backward direction		
Operation (acceleration)		С	K420C		С	K430C	0: not accelerated, 1: accelerated
Operation (constant speed)		D	K420D		D	K430D	0: not constant speed, 1: constant speed
Operation (deceleration)		E	K420E		E	K430E	0: not decelerated, 1: decelerated
Operation (dwell)		F	K420F		F	K430F	0: not during dwell, 1: during dwell
Operation (positioning)		0	K4210		0	K4310	0: position not controlled 1: position controlled
Operation (speed control)		1	K4211		1	K4311	0: speed not controlled 1: speed controlled
Operation control (straight interpolation)	K421	2	K4212	K431	2	K4312	0: interpolation not controlled 1: interpolation controlled
Return to origin		5	K4215		5	K4315	0: not returning to origin 1: returning to origin
Position synchronization		6	K4216		6	K4316	0: position not synchronized 1: position synchronized

Speed synchronization	7	K4217	7	K4317	0: speed not synchronized 1: speed synchronized
Jog low speed	8	K4218	8	K4318	0: jog not at low speed 1: jog at low speed
Jog high speed	9	K4219	9	K4319	0: jog not at high speed 1: jog at high speed
Inching operation	A	K421A	А	K431A	0:not during inching operation 1: during inching operation

(a) XEC bit area flag

Г

	Dev	ice area	
Variables	Axis X	Axis Y	Status
	Address	Address	
In operation	%KX6720	%KX6880	0: stop, 1: operation
Error	%KX6721	%KX6881	0: no error, 1: error
Positioning completed	%KX6722	%KX6882	0: not completed, 1: completed
M code signal	%KX6723	%KX6883	0:M code Off, 1:M code On
Origin settled	%KX6724	%KX6884	0: origin not decided, 1: origin decided
No pulse output	%KX6725	%KX6885	0: output available, 1: no output
Stopped	%KX6726	%KX6886	0: not stopped 1: stopped
Upper limit detected	%KX6728	%KX6888	0: undetected, 1: detected
Lower limit detected	%KX6729	%KX6889	0: undetected, 1: detected
Emergency stop	%KX6730	%KX6890	0: normal, 1: abnormally stopped
Normal/backward rotation	%KX6731	%KX6891	0: normal direction, 1: backward direction
Operation (acceleration)	%KX6732	%KX6892	0: not accelerated, 1: accelerated
Operation (constant speed)	%KX6733	%KX6893	0: not constant speed, 1: constant speed
Operation (deceleration)	%KX6734	%KX6894	0: not decelerated, 1: decelerated
Operation (dwell)	%KX6735	%KX6895	0: not during dwell, 1: during dwell
Operation (positioning)	%KX6736	%KX6896	0: position not controlled 1: position controlled
Operation (speed control)	%KX6737	%KX6897	0: speed not controlled 1: speed controlled
Operation control (straight interpolation)	%KX6738	%KX6898	0: interpolation not controlled 1: interpolation controlled
Return to origin	%KX6741	%KX6901	0: not returning to origin1: returning to origin
Position synchronization	%KX6742	%KX6902	0: position not synchronized 1: position synchronized
Speed synchronization	%KX6743	%KX6903	0: speed not synchronized 1: speed synchronized
Jog low speed	%KX6744	%KX6904	0: jog not at low speed 1: jog at low speed
Jog high speed	%KX6745	%KX6905	0: jog not at high speed 1: jog at high speed
Inching operation	%KX6746	%KX6906	0:not during inching operation 1: during inching operation

(2) Status Monitoring Data Area

-		-	
((a)	XBM/XBC status	monitoring area

		Devid	e Area		
Variables	Axi	s X	Ax	is X	Status
	Address	Properties	Address	Properties	
Current position	K422	Double word	K432	Double word	Shows current position
Current speed	K424	Double word	K434	Double word	Shows current speed
Step No.	K426	Double word	K436	Word	Shows current operation step
Error code	K427	Word	K437	Word	Shows error code in case of an error
M code No.	K428	Word	K438	Word	Shows M code number when M code is on

(b) XBM/XBC status monitoring area

		Device	e Area			
Variables	Axi	is X	Axi	s Y	Status	
	Address	Properties	Address Properties			
Current position	%KD211	Double word	%KD216	Double word	Shows current position	
Current speed	%KD212	Double word	%KD217	Double word	Shows current speed	
Step No.	%KW426	Double word	%KW436	Word	Shows current operation step	
Error code	%KW427	Word	%KW437	Word	Shows error code in case of an error	
M code No.	%KW428	Word	%KW438	Word	Shows M code number when M code is on	

3.4.2 Flag for Positioning Instruction and Command

The flag for positioning instruction and command divides as follows. You can easily conduct positioning operation without positioning instruction using the flag. If you change the flag for instruction of area K, the scan ends and applies in the next scan.

(1) Bit Area Flag

(a) XBM/XBC	bit area flag
-------------	---------------

	Device Area						
Variables	Axis X			Axis Y			Status
	Word	Bit	Address	Word Bit Address		Address	
Start signal		0	K4290		0	K4390	Indirect start at rising edge
Normal direction jog		1	K4291	11 12 13	1	K4391	0: stop jog, 1: normal direction jog operation
Backward direction jog	K429	2	K4292		2	K4392	0: stop jog,, 1: normal direction jog operation
Jog high/low speed		3	K4293		3	K4393	0: jog low speed, 1: jog high speed
M code output mode	14400	1	K4681	K508	1 K5081		
	K468	2	K4682		2	K5082	U: NONE, 1: WITH, 2: AFTER

Chapter 3 Before Positioning

Upper/lower limit detection of S/W allowed during constant speed operation		4	K4684		4	K5084	0: detection not allowed, 1: detection allowed
Return-to-origin method	K478	0,1	K4780~1	K518	1	K5180~1	0: approximate origin/origin(OFF) 1: approximate origin/origin (On) 2: approximate origin
Return-to-origin direction		2	K4782		2	K5182	0: normal direction, 1: backward direction
Use for positioning		0	K4870		0	K5270	0: no use, 1: use
Pulse output level		1	K4871		1	K5271	0: low Active,1: high Active
Use of upper/lower limit	K487	2	K4872	K4872 K527	2	K5272	0: no use, 1: use
Pulse output mode		3	K4873		3	K5273	0: CW/CCW, 1: PLS/DIR

(b) XEC bit area flag

Γ

	Devid	ce area		
Variables	Axis X	Axis Y	Status	
	Address	Addreess		
Start signal	%KX6864	%KX7024	Indirect start at rising edge	
Normal direction jog	%KX6865	%KX7025	0: stop jog, 1: normal direction jog operation	
Backward direction jog	%KX6866	%KX7026	0: stop jog,, 1: normal direction jog operation	
Jog high/low speed	%KX6867	%KX7027	0: jog low speed, 1: jog high speed	
Maaada ay tay tayaada	%KX7489	%KX8129		
M code output mode	%KX7490	%KX8130	U. NONE, 1: WITH, 2: AFTER	
Upper/lower limit detection of S/W allowed during constant speed operation	%KX7492	%KX8132	0: detection not allowed, 1: detection allowed	
Return-to-origin method	%KX7648-49	%KX8288-89	0: approximate origin/origin(OFF) 1: approximate origin/origin (On) 2: approximate origin	
Return-to-origin direction	%KX7650	%KX8290	0: normal direction, 1: backward direction	
Use for positioning	%KX7792	%KX8432	0: no use, 1: use	
Pulse output level	%KX7793	%KX8433	0: low Active,1: high Active	
Use of upper/lower limit	%KX7794	%KX8434	0: no use, 1: use	
Pulse output mode	%KX7795	%KX8435	0: CW/CCW, 1: PLS/DIR	

(c) Starting Signals

1) The starting signals conducts positioning operation according to the current operation step number (axis X: K426(%KW426), axis Y: K436(%KW436)) without setting the step number unlike indirect or direct starting.

2) Since the current operation step area is for read only, if you want to change the operation step number, you need to use the starting step number change instruction (SNS, APM_SNS).

3) The following program is an example of the program that indirectly starts with the operation data displayed in the current step number (K426) on axis X by setting the starting signal whenever

the external input starting switch (P000F) turns On.

Ι	P000F	K04200	K04201			K04290
5	Starting switch	XAxis BUSY	XAxis Error			XAxis Start
	P000F			r		K04290
1	Starting switch					XAxis Start

Device	Description	Device	Description
P000F(%IX0.0.15)	Axis X starting external switch	K4201(%KX6721)	Axis X error
K4200(%KX6720)	Axis X signal during operation	K4290(%KX6864)	Axis X starting instruction flag

- The program above is an example of the program that indirectly starts with the operation data of the current step number (K426 word) on axis X by setting the starting signal whenever the external input starting switch (P000F) turns On.
- When the starting switch turns On, the starting commanding flag (K4290) is set and axis X starts, and when the starting switch turns Off, the starting contact point is reset.
- Note that the set coil is used for axis X starting commanding flag (K4290) instead of ordinary coil output.

For example, if a toggle switch is used for the starting switch, and if the starting commanding flag (K4290) is not set but ordinary coil output is used, there might be the problem that it is automatically restarted by the bit Off during operation when positioning is completed. To avoid this, use a push button switch for the external input switch, and use a set coil and reset coil according to the On/Off of the input switch for the starting commanding flag.

- (b) Jog Operation
 - The following program is an example of the program that carries out the jog operation of axis X by turning on/off the flag for commanding the normal/backward direction jog according to the external input signal.

XAxis JOG
Low Speed/High Speed
K04291
XAxis CW JOG START
K04292
XAxis CCW JOG START

Device	Description	Device	Description
P0008(%IX0.0.8)	External input of normal direction jog	K4201(%KX6721)	Flag displaying axis X error
P0009(%IX0.0.9)	External input of backward direction jog	K4291(%KX6865)	Flag commanding normal direction jog of axis X
P000A(%IX0.0.10)	External input of jog low speed/high speed	K4292(%KX6866)	Flag commanding backward direction jog of axis X
K4200(%KX6720)	Signal of axis X during operation	K4293(%KX6867)	Flag commanding jog low/high speed of axis X

- The program above is an example of the program that carries out the jog operation in the corresponding direction while the external input normal direction jog switch (P0008) or backward direction jog switch (P0009) in On.
- Then the operation speed is jog high speed if the jog low/high speed external input (P000A) is On, and high low if Off, and can be changed during jog operation, too.
- As the start and stop of jog operation is done by the level of the input signals, if the input signal (P0008, P0009) is On, it operates, and if Off, it carries out jog stop.
- If both jog normal direction operation and backward direction operation are On, there is no error code in XGB built-in positioning, but it stops if it is currently in operation.

 If you do jog operation by adding the signal (K4200(%KX6720), K4300(%KX6880)) during operation as the normally closed contact point (contact point B) for the jog operation input condition, it alternates starting and stopping according to the On/Off of the signal during operation.

(2) Data Area for Positioning Setting (a) In case of XBM/XBC

	Device Area				
Variables	A	Axis X Axis Y		Status	
	Address	Properties	Address	Properties	
Bias speed	K0450	Double word	K0490	Double word	Sets bias speed.
Speed limit	K0452	Double word	K0492	Double word	Sets maximum speed limit.
Acceleration time 1	K0454	Word	K0494	Word	Sets acceleration time 1.
Deceleration time 1	K0455	Word	K0495	Word	Sets deceleration time 1.
Acceleration time 2	K0456	Word	K0496	Word	Sets acceleration time 2.
Deceleration time 2	K0457	Word	K0497	Word	Sets deceleration time 2.
Acceleration time 3	K0458	Word	K0498	Word	Sets acceleration time 3.
Deceleration time 3	K0459	Word	K0499	Word	Sets deceleration time 3.
Acceleration time 4	K0460	Word	K0500	Word	Sets acceleration time 4.
Deceleration time 4	K0461	Word	K0501	Word	Sets deceleration time 1
Upper limit of software	K0462	Double word	K0502	Double word	Sets upper limit value of software.
Lower limit of software	K0464	Double word	K0504	Double word	Sets lower limit value of software.
Backlash correction	K0466	Word	K0506	Word	Sets backlash correction value.
Origin address	K0469	Double word	K0509	Double word	Sets origin address for origin return.
High speed of origin return	K0471	Double word	K0511	Double word	Sets high speed for origin return.
Low speed of origin return	K0473	Double word	K0513	Double word	Sets low speed for origin return.
Acceleration time for origin return	K0475	Word	K0515	15 Word Sets acceleration origin return	
Deceleration time for origin return	K0476	Word	K0516 Word Sets de origin ret		Sets deceleration time for origin return
Dwell time for origin return	K0477	Word	K0517	Word	Sets dwell time for origin return
Jog high speed	K0479	Double word	K0519	Double word	Sets high speed for jog operation.
Jog low speed	K0481	Double word	K0521	Double word	Sets low speed for jog operation
Jog acceleration time	K0483	Word	K0523	Word	Sets acceleration time for jog operation
Jog deceleration time	K0484	Word	K0524	Word	Sets deceleration time for jog operation
Inching speed	K0485	Word	K0525	Word	Sets operation speed for inching operation.

٦

(b) In case of XEC					
		Devic	e area		
Variables	A	xis X	А	xis Y	Status
	Address	Properties	Address	Properties	
Bias speed	%KD225	Double word	%KD245	Double word	Sets bias speed.
Speed limit	%KD226	Double word	%KD246	Double word	Sets maximum speed limit.
Acceleration time 1	%KW454	Word	%KW494	Word	Sets acceleration time 1.
Deceleration time 1	%KW455	Word	%KW495	Word	Sets deceleration time 1.
Acceleration time 2	%KW456	Word	%KW496	Word	Sets acceleration time 2.
Deceleration time 2	%KW457	Word	%KW497	Word	Sets deceleration time 2.
Acceleration time 3	%KW458	Word	%KW498	Word	Sets acceleration time 3.
Deceleration time 3	%KW459	Word	%KW499	Word	Sets deceleration time 3.
Acceleration time 4	%KW460	Word	%KW500	Word	Sets acceleration time 4.
Deceleration time 4	%KW461	Word	%KW501	Word	Sets deceleration time 1
Upper limit of software	%KD231	Double word	%KD251	Double word	Sets upper limit value of software.
Lower limit of software	%KD232	Double word	%KD252	Double word	Sets lower limit value of software.
Backlash correction	%KW466	Word	%KW506	Word	Sets backlash correction value.
Origin address	%KD234	Double word	%KD254	Double word	Sets origin address for origin return.
High speed of origin return	%KD235	Double word	%KD255	Double word	Sets high speed for origin return.
Low speed of origin return	%KD236	Double word	%KD256	Double word	Sets low speed for origin return.
Acceleration time for origin return	%KW475	Word	%KW515	Word	Sets acceleration time for origin return
Deceleration time for origin return	%KW476	Word	%KW516	Word	Sets deceleration time for origin return
Dwell time for origin return	%KW477	Word	%KW517	Word	Sets dwell time for origin return
Jog high speed	%KD239	Double word	%KD259	Double word	Sets high speed for jog operation.
Jog low speed	%KD240	Double word	%KD260	Double word	Sets low speed for jog operation
Jog acceleration time	%KW483	Word	%KW523	Word	Sets acceleration time for jog operation
Jog deceleration time	%KW484	Word	%KW524	Word	Sets deceleration time for jog operation
Inching speed	%KW485	Word	%KW525	Word	Sets operation speed for inching operation.

Г

(3) Status Monitoring and Commanding Flag by Operation Step (a) In case of XBM/XBC (Step 01)

	Device area			
Variables	Axis X	Axis Y	properties	Status
	Address	Address	properties	
Step 01 target position	K0530	K0830	Double word	
Step 01 operation speed	K0534	K0834	Double word	
Step 01 dwell time	K0536	K0836	Word	
Step 01 M code number	K0537	K0837	Word	
Step 01 operation method	K05380	K08380	Bit	
Step 01 control method	K05381	K08381	Bit	
Step 01 operation pattern (Low)	K05382	K08382	Bit	
Step 01 operation pattern (High)	K05383	K08383	Bit	
Step 01 coordinates	K05384	K08384	Bit	
Step 01 acc./dec. number (Low)	K05386	K08386	Bit	
Step 01 acc./dec. number (High)	K05387	K08387	Bit	
Step 01 coordinates	K0539	K0839	Word	

٦

		Device area		
Variables	Axis X	Axis X Axis Y properties		Status
	Address	Address	properties	
Step 01 target position	%KD265	%KD415	Double word	
Step 01 operation speed	%KD267	%KD417	Double word	
Step 01 dwell time	%KW536	%KW836	Word	
Step 01 M code number	%KW537	%KW837	Word	
Step 01 operation method	%KX8608	%KX13408	Bit	
Step 01 control method	%KX8609	%KX13409	Bit	
Step 01 operation pattern (Low)	%KX8610	%KX13410	Bit	
Step 01 operation pattern (High)	%KX8611	%KX13411	Bit	
Step 01 coordinates	%KX8612	%KX13412	Bit	
Step 01 acc./dec. number (Low)	%KX8614	%KX13414	Bit	
Step 01 acc./dec. number (High)	%KX8615	%KX13415	Bit	
Step 01 coordinates	%KW539	%KW839	Word	

(b) In case of XBM/XBC (Step 01)

Γ

• The table above shows the area K for positioning of the operation step #1. You can change the operation data without setting the parameters by changing the value of the corresponding area K.

 If you want to permanently preserve the operation data of the changed area K, apply the data of current area K to the built-in parameter area by using the applied instruction (WRT instruction, APM_WRT instruction).

Remark

- Note that area K for positioning is initialized if you cut the power and re-supply power or if you change the operation mode without executing the WRT instruction after changing the value of area K.
- The variable of area K for each step can be used more conveniently by using the variable registration function of XG5000. For the positioning monitor registration, see the manual of XG5000.

Chapter 4 Positioning Check

This Chapter describes how to test the operation test to check whether the positioning function is well performed before the XGB positioning function is used.

4.1 The Sequence of Positioning Check

This is for checking whether the XGB positioning operation is normally performed by carrying out normal and reverse direction jog operation. The sequence is as follows.

(1) Power Off

- Distribution is needed to check the XGB positioning operation. Before distribution, turn off XGB.
- Be sure to check whether the PWR LED of XGB is off before moving on to the next step.

(2) Input Signal Distribution

- Distribute the input signals needed to check the operation as follows.
- Do not connect the output signal line to the motor driver. If there is a problem with the PLC hardware, connecting to the motor driver might lead to malfunction or damage to the equipment.

Input Signal	Input Signal Contact Point		ontact Poi	nt No.	Remark
	туре		XBC	XEC	
Jog normal direction		Axis X	P0010	%IX0.0.16	Contact point randomly selected
switch	Contact point	Axis Y	P0011	%IX0.0.17	Contact point randomly selected
Jog reverse direction	normally open (A)	Axis X	P0012	%IX0.0.18	Contact point randomly selected
switch		Axis Y	P0013	%IX0.0.19	Contact point randomly selected

(3) Making the Program for Operation Check

- Make the program for checking the operation by using XG5000. For the details and making of the program, see '4.2 Making of the Program for Operation Check.'
- (4) Power Supply and Program Writing
 - If you have finished making the program, supply power to XGB PLC, and use XGB as the parameter and the program.
- (5) Input Contact Point Operation Check
 - Before switching the operation mode of the PLC to RUN, check the normal operation of the input contact point as follows.

Input Signal		Contact No).	Operation Check	
input Signai	XBC XEC		Operation Check		
Jog normal	Axis X	P0010	%IX0.0.16	Check whether the LED of the contact	
direction	Axis Y	P0011	%IX0.0.17	point turns on while the switch is ON and	
Jog reverse	Axis X	P0012	%IX0.0.18	the value of the contact point changes into	
direction	Axis Y P0013 %IX0.0.19	1 in the device monitor of XG5000.			

- If the device doesn't work as described in the table above, there might be a problem with the LED or the input hardware, so contact the customer center.
- (6) Operation Check through Jog Operation
 - Check the operation of XGB positioning doing jog operation in the following sequence.
 - This manual describes the axis X operation check when the pulse output mode is PLS/DIR mode and the pulse output level is set as Low Active. Check the operation of axis Y. in the same manner.
 - (a) Check of Normal Direction Rotation of Jog
 - Turn on the normal direction switch(P0010) of axis X, with the reverse direction switch of the jog set at Off.
 - Check whether the XGB positioning function normally generates jog normal direction output.
 - 1) Check of the output LED
 - P0020 (%QX0.0.0) : flashes quickly
 - P0022 (%QX0.0.2) : stays ON
 - 2) Check of area K
 - Check whether the current position address is increasing by checking the current position address area (axis X: K422 double word) with XG5000.
 - (b) Check of Normal Direction Stop of Jog
 - Turn Off the jog normal direction switch (P0010, %IX0.0.16) during jog normal direction operation, and check whether the output LED (P0020, %QX0.0.0, P0022, %QX0.0.2) is Off, the current position address area (axis X: K422, %KD211 double word) with XG5000, and whether the current position address has stopped increasing.

(c) Check of Reverse Direction Rotation of Jog

- Turn on the axis X jog reverse direction switch (P0012, %IX0.0.18)), with the normal direction switch of the jog Off.
- Check whether the XGB positioning function is generating jog reverse direction output normally.
 - 1) Output LED Check
 - P0020(%QX0.0.0) : flashes quickly
 - P0022(%QX0.0.2) : stays OFF
 - 2) Check of area K
 - Check whether the current position address is decreasing by checking the current position address area (axis X: K422, %KD211 double word) with XG5000
- (d) Check of Reverse Direction Stop of Jog
 - Turn Off the jog reverse direction switch (P0012, %IX0.0.18) during jog reverse direction operation, and check whether the output LED (P0020, %QX0.0.0, P0022, %QX0.0.2) is Off, the current position address area (axis X: K422, %KD211 double word) with XG5000, and whether the current position address has stopped decreasing
- (e) For compact standard type, there is not actual output P00040/P00044 and they are indicated by LED.
- (7) Finish of Positioning Check
 - When you have finished checking whether the jog normal and reverse operation is normally operating through the process above, end the check, make the positioning operation program to be actually used and conduct the positioning operation.

4.2 Making of Operation Check Program

The program for operation check used in this manual should be made as follows.

The positioning parameters should be set as follows. For setting the positioning parameters, see 3.2.

(1) Positioning Basic Parameters

Items	Range	Set Values	Data Size
Positioning	0 : not used, 1 : used	0	Bit
Pulse output level	0 : Low Active, 1 : High Active	0	Bit
Pulse output mode	0 : CW/CC, 1 : PLS/DIR	1	Bit
M code output mode	0 : NONE, 1 : WITH, 2 : AFTER	0	2 Bit
Bias speed	1 ~ 100,000[pulse/sec.]	1	Double word
Speed limit	1 \sim 100,000[pulse/sec.]	100,000	Double word
Acceleration time 1	0 ~ 10,000[unit: ms]	500	Word
Deceleration time 1	0 ~ 10,000[unit: ms]	500	Word
Acceleration time 2	0 ~ 10,000[unit: ms]	1,000	Word
Deceleration time 2	0 ~ 10,000[unit: ms]	1,000	Word
Acceleration time 3	0 ~ 10,000[unit: ms]	1,500	Word
Deceleration time 3	0 ~ 10,000[unit: ms]	1,500	Word
Acceleration time 4	0 ~ 10,000[unit: ms]	2,000	Word
Deceleration time 4	0 ~ 10,000[unit: ms]	2,000	Word
S/W upper limit	-2,147,483,648 ~ 2,147,483,647 [pulse]	2,147,483,647	Double word
S/W lower limit	-2,147,483,648 ~ 2,147,483,647 [pulse]	-2,147,483,648	Double word
Backlash correction	$0\sim 65,535$ [pulse]	0	Word
SW upper and lower limit during constant speed operation	0 : not detected, 1 : detected	0	Bit
Use of upper and lower limit	0 : not used, 1 : used	1	Bit

(2) Home return/Manual Operation Parameter

ltems	Range	Initial Values	Data Size
Home return method	0~2	0	Bit
Home return direction	0 : normal direction, 1 : reverse direction	1	Bit
Origin address	-2,147,483,648~2,147,483,647[pulse]	0	Double word
Home return high speed	1 ~ 100,000[pulse/sec.]	5,000	Double word
Home return low speed	1 \sim 100,000[pulse/sec.]	500	Double word
Home return acceleration time	0 ~ 10,000[unit: ms]	1,000	Word
Home return deceleration time	0 ~ 10,000[unit: ms]	1,000	Word
Dwell time	0 ~ 50,000[unit: ms]	0	Word
JOG high speed	$1 \sim 100,000$ [pulse/sec.]	5,000	Double word
JOG low speed	1 ~ 100,000[pulse/sec.]	1,000	Double word
JOG acceleration time	0 ~ 10,000[unit: ms]	1,000	Word

JOG deceleration time	0 ~ 10,000[unit: ms]	1,000	Word
Inching speed	1 \sim 65,535[pulse/sec.]	100	Word

Γ

(3) Example of the ProgramThe following is an example of the program for positioning check.(a) In case of XBM, XBC

P0011 K0	4201 K04870	K04291
YAxis JOG XAx CW	s Error XAxis Position Enable	XAxis CW JOG START
P0011 K0	4301 K05270	K04391
YAxis JOG YAx CW	s Error YAxis Position Enable	YAxis CW JOG START
P0012 K0	4201 K04870	K04291
XAxis JOG XAx CCW	s Error XAxis Position Enable	XAxis CW JOG START
P0013 K0	4301 K05270	K04391
YAxis JOG YAx CCW	s Error YAxis Position Enable	YAxis CW JOG START
		END
	P0011 K0	P0011 K04201 K04870 Image: I

(b) In case of XEC

%IXO.0.16	XKX6721	%KX7792	XKX6865
XAxis JOG CW	XAxis Error	XAxis Position Enable	XAX IS CW JOG START
%IXO.0.18	%KX6721	*KX7792	%KX6866
XAxis JOG CCW	XAxis Error	Axis Position Enable	XAXIS CCW JOG START
%IX0.0.17	XKX6881	XKX8432	*KX7025
YAxis JOG C₩	VAxis Error	VAxis Position Enable	YAXIS CU JOG START
%IXO.0.19	XKX6881	%KX8432	*KX7026
YAxis JOG CCW	YAxis Error	VAxis Position Enable	YAXIS CCW JOG START

Chapter 5 Positioning Instructions

This chapter describes the definitions, functions, use of the positioning instructions used in XGB positioning functions and the program examples.

5.1 Positioning Instruction List

The positioning instructions used for XGB positioning are as follows.

(1) In case of XBC/XBM

Instructions	Description	Conditions	Remark
ORG	Start return to the origin	Slot, instruction axis	5.2.1
FLT	Set floating origin	Slot, instruction axis	5.2.2
DST	Direct starting	Slot, instruction axis, position, speed, dwell time, M code, control word	5.2.3
IST	Indirect starting	Slot, instruction axis, step number	5.2.4
LIN	Linear interpolation starting	Slot, instruction axis, step number, axis information	5.2.5
SST	Simultaneous starting	Slot, instruction axis, axis X step, axis Y step, axis Z step, axis information	5.2.6
VTP	Speed/position switching	Slot, instruction axis	5.2.7
PTV	Position/speed switching	Slot, instruction axis	5.2.8
STP	Stop	Slot, instruction axis, deceleration time	5.2.9
SSP	Position synchronization	Slot, instruction axis, step number, main axis position, main axis setting	5.2.10
SSS	Speed synchronization	Slot, instruction axis, synchronization rate, delay time	5.2.11
POR	Position override	Slot, instruction axis, position	5.2.12
SOR	Speed override	Slot, instruction axis, speed	5.2.13
PSO	Positioning speed override	Slot, instruction axis, position, speed	5.2.14
INCH	Inching starting	Slot, instruction axis, inching amount	5.2.15
SNS	Change starting step number	Slot, instruction axis, step number	5.2.16
MOF	Cancel M code	Slot, instruction axis	5.2.17
PRS	Preset current position	Slot, instruction axis, position	5.2.18
EMG	Emergency stop	Slot, instruction axis	5.2.19
CLR	Reset error, cancel output inhibition	Slot, instruction axis, inhibit/allow pulse output	5.2.20
WRT	Save parameter/operation data	Slot, instruction axis, select the storage area	5.2.21
PWM	Pulse width modulation	Slot, instruction axis, output cycle, off duty rate	5.2.22

• XGB positioning instructions are activated at the rising edge. That is, when the execution contact point is On, it carried out the instruction only once. (PWM insturction is activated at the "On" level)

(2) In case of XEC

Г

Function Block	Description	Conditions	Remark
APM_ORG	Start return to the origin	Req, Base, Slot, Axis	5.3.2
APM_FLT	Set floating origin	Req, Base, Slot, Axis	5.3.3
APM_DST	Direct starting	Req, Base, Slot, Axis, Position, speed, dwell time, M code, position/speed, absolute/incremental, ACC/DEC time	5.3.4
APM_IST	Indirect starting	Req, Base, Slot, Axis, step number	5.3.5
APM_LIN	Linear interpolation starting	Req, Base, Slot, Axis, step number	5.3.6
APM_SST	Simultaneous starting	Req, Base, Slot, Axis, X axis step, Y axis step, Z axis step	5.3.7
APM_VTP	Speed/position switching	Req, Base, Slot, Axis	5.3.8
APM_PTV	Position/speed switching	Req, Base, Slot, Axis	5.3.9
APM_STP	Stop	Req, Base, Slot, Axis, ACC/DEC time	5.3.10
APM_SSP	Position synchronization	Req, Base, Slot, Axis, Step number, main axis, Main axis position	5.3.11
APM_SSSB	Speed synchronization	Req, Base, Slot, Axis, main axis, rate of sub-axis, delay time	5.3.12
APM_POR	Position override	Req, Base, Slot, Axis, position	5.3.13
APM_SOR	Speed override	Req, Base, Slot, Axis, speed	5.3.14
APM_PSO	Positioning speed override	Req, Base, Slot, Axis, position, speed	5.3.15
APM_INC	Inching starting	Req, Base, Slot, Axis, inching amount	5.3.16
APM_SNS	Change starting step number	Req, Base, Slot, Axis, step number	5.3.17
APM_MOF	Cancel M code	Req, Base, Slot, Axis	5.3.18
APM_PRS	Preset current position	Req, Base, Slot, Axis, position	5.3.19
APM_EMG	Emergency stop	Req, Base, Slot	5.3.20
APM_RST	Reset error, cancel output inhibition	Req, Base, Slot, Axis, Enable/Disable pulse output	5.3.21
APM_WRT	Save parameter/operation	Req, Base, Slot, Axis, Select area to save	5.3.22
APM_PWM	Pulse width modulation	Reg, Slot, Axis, output cycle, off duty rate	5.3.23

5.2 Details of Positioning Instructions (In case of XBC/XBM) 5.2.1 Origin Return Instructions

• Origin return is sued to check the origin of the machine when power is supplied to the machine in general. If the origin return instruction is given, it is executed depending on the setting of the origin return parameter. (for setting of the origin return parameter, refer to 3.2.4.)

Туре	Items	Description	Remark
	origin return method	Set origin return method	
	origin return direction	Starting direction during origin return operation	
	Origin address	origin address in detecting origin	
origin return	origin return speed	high/low speed during origin return operation	
parameter	origin return dec./acc. time	dec./acc. time during origin return operation	
	origin return deceleration time	Set deceleration time during origin return operation	
	DWELL time	Time it takes to remove remaining pulse of the deviation counter right after origin return is finished	

• In general, the origin return divides into two ways, one of which is using the DOG and the other is not using it. In XGB positioning function, the following three ways can be used that use the DOG. (for details of the origin return method, refer to 3.1.9.)

Origin return method	Necessary input signals	Remark
Detect origin after DOG turns Off (0: DOG/origin (OFF))	DOG signal, origin signal	
When DOG is On, detect the origin after deceleration . (1: DOG/origin (On))	DOG signal, origin signal	() is what is displayed in the positioning origin/manual parameter.
Detect the origin by DOG (2: DOG)	DOG signal	

• The following diagram is an example of origin detection by DOG among the three ways of origin return.



(1) Origin return Instruction (ORG)

	Available areas										Flag								
Instruc	tion	PMK	F	L	т	С	S	z	D.x	R.x	con stan t	U	N	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)
ORG	sl	-	-	-	-	-	-	-	-	-	0	-	-	-	-	4~7	0	-	-
	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	-				
ORG				∮	_	С	оми —		2						[OR	G	sl ax]

Α

[Area seting]

Operand	Description	Setting range	Data size
sl	Slot number where positioning modules are mounted	XGB is fixed at 0.	WORD
ax	The axis to give instructions	0(axis X) or 1(axis Y)	WORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is for carrying out the origin return of the XGB built-in positioning function.
- It gives the origin return instruction to the axis designated as the ax of positioning built in XGB at the rising edge of the input condition.
- When origin return is completed, the origin setting bit (axis X:K4204,axis Y:K4304) turns On and the current address is preset at the address value set in the origin return parameter.

(s) Error

- If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.
- This is an error of instruction execution, so the error flag (axis X:K4201,axis Y: K4301) of area K for positioning does not turn On.

(2) Related Device Alarm

• The parameters and area K devices related to ORG instructions are as follows.

Pa	rameter		Data sizo			
Item	Setting range	axis X	axis Y	Properties	Data Size	
origin return method	0 : DOG/Home(Off) 1 : DOG/Home(On) 2 : DOG	K4780 K4781	K5180 K5181	Read/write	2 bit	
origin return direction	0 : CW, 1 : CCW	K4782	K5182	Read/write	Double word	
Origin address	-2,147,483,648~ 2,147,483,647[pulse]	K469	K509	Read/write	Double word	
origin return high speed	1 ~ 100,000[pps]	K471	K511	Read/write	Double word	

Pa	rameter		Area K				
ltem	Setting range	Data size	axis Y	Properties	Data size		
origin return low speed	1 ~ 100,000[pps]	K473	K513	Read/write	Double word		
origin return acceleration time	0 ~ 10,000[ms]	K475	K515	Read/write	Word		
origin return deceleration time	0 ~ 10,000[ms]	K476	K516	Read/write	Word		
Dwell time	0 ~ 50,000[ms]	K477	K517	Read/write	Word		

(3) Examples of Instructions

- The origin return instructions are described as follows with the examples of the parameters and programs.
- The examples of the ORG instructions are described on the basis of axis X.

Param	leter			
ltem	Value			
origin return	1: DOG		Home Method	1: DOG/HOME(ON)
method	/origin(On)		Home Direction	1: CCW
origin return	1: reverse		Home Address	0 pls
direction	direction		Home High Speed	5000 pls/s
direction	direction		Home Low Speed	500 pls/s
Origin address	0	11	Homing ACC Time	100 ms
oriain return hiah		Home Parameter	Homing DEC Time	100 ms
speed	50,000[pps]		DWELL Time	100 ms
origin return low speed	500[pps]			
origin return acceleration time	100[ms]			
origin return deceleration time	100[ms]			
Dwell time	100[ms]			

(a) Parameter Setting

(b) Examples of the Program

	M0000	к04200 — /	K04201					ORG	0	0
_	Home Detrue Dure	XAxis BUSY	XAxis Error							
0	Retrun Run									
										END
-										
										-
				Rung	Step	Instruction	OP 1	OP 1	OP 2	
				0	0	LOADP	M0000	Home Retrun Run		
		II prog	ram		2	AND NOT	K04200	XAxis BUSY		
		in prog			3	AND NOT	K04201	XAxis Error		
					4	ORG	0		0	
				1	7	END				

(c) Devices Used

Device	Description
M0000	Starting signal of axis X origin return
K4200	Signal during axis X operation
K4201	axis X error
r	

- (d) Program Operation
 - The ORG instruction is executed when there is the rising edge of M0000 which was used as the starting signal of the axis X origin return.
 - (It doesn't work if axis X is operating or in error)
 - 1) If the origin return instruction (ORG instruction) is executed, it is decelerated in the reverse direction as set in the origin return parameter and operates at origin return high speed (50,000pps).
 - 2) If there is the rising edge of the DOG signal during origin return high speed operation, it is decelerated and operates at origin return low speed (500pps). The deceleration time is 100ms, set in the parameter.
 - 3) If the origin signal is input, which is the external input signal, after switch to the origin return low speed, the output immediately stops, and the origin determining status flag (K4204 bit) turns On after the dwell time (100ms).

(There may be a delay as long as 'dwell time + 1 scan time' until the origin determining status flag (K4204 bit) turns On after the output stops.)

4) Then the current address is preset at 0, which is the origin address set in the parameter.



• The DOG signal and origin signal are respectively fixed as the following contact points.

	Standa	rd	Compact standard/high-end type						
	DOG	origin	DOG	origin					
axis X	P0004	P0005	P000C	P000D					
axis Y	P0006	P0007	P000E	P000F					

 If the contact points of the DOG and the origin input are used together as the external preset input of the high speed counter, or together as the starting signal of the external contact point task, the origin detection might be inaccurate.

• The current position address does not change during origin return.

5.2.2 Floating Origin Setting Instruction

• Floating origin setting refers to setting the current position as the origin by force with the instruction without carrying out the actually mechanical origin return.

(1) Floating origin Setting Instruction (FLT)

			Areas available															Flag			
Instruc	tion	PMK	F	L	т	С	S	z	D.x	R.x	con stan t	U	N	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)		
FLT	sl	-	-	-	-	-	-	-	-	-	0	-	-	-	-	4~7	0	-	-		
	ax	0	I	0	-	I	-	0	-	-	0	I	-	0	-						
FLT				ſ	_	С	OMN 		D							FL	Г	sl ax]		

[Area Setting]

Operand	Description	Setting range	Data size
sl	Slot number where positioning module is mounted	XGB is fixed at 0	WORD
ax	Axis to give instruction	0(axis X) or 1(axis Y)	WORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is for setting the floating origin to the XGB built-in positioning.
- The instruction of setting the floating origin is given to the axis designated as ax of XGB positioning at the rising edge of the input condition.
- If the instruction is carried out, the current position address becomes 0, and the origin determining bit (axis X: K4204,axis Y:K4304) turns On.

(b) Error

• If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed

- Floating origin setting presets the current position at 0 and only fixs the origin, so you need to note the following when you use the instruction of setting the floating origin.
 - → Check whether there is an error before carrying out the floating origin setting instruction. If there is an error, remove the cause of the error, reset the error (CLR instruction) and terminate the output inhibition.
 - → Now set the floating origin, change the step number to operate into the starting step change instruction (SNS), and then get it started.

(2) Example of Use of the Instruction

• The floating origin setting instruction is described with the example of the following program.

• The example of use of the FLT instruction is described on the basis of axis X.

(a) Example of the Program

Γ



(b) Device Used

Device	Description
M0000	axis X floating origin instruction signal
K4200	Signal during axis X operation
K4201	axis X error

(c) Operation of the Program

• The FLT instruction is executed when there is the rising edge of M0000, which was used as axis X floating origin instruction signal.

(Not if axis X is operating or in error)

• If the FLT instruction is executed, the origin is fixed right away at the current position differently from the origin return, the origin determining signal (axis X:K4204) turns On, and the current address is preset at 0.

5.2.3 Direct Starting Instruction

• Direct starting refers to designating the operation data of the target position and speed from the positioning instruction (DST instruction) for operation without using the setting of the step set in the positioning operation data.

(1) Direct Starting Instruction (DST)

							Area	as av	vailab	le							Flag			
Instruc	tion	PMK	F	L	Т	С	S	z	D.x	R.x	con stan t	U	N	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)	
	sl	-	1	-	1	1	-	-	-	-	0	1	-	-	-					
	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	-		0			
	n1	0	-	0	-	-	-	0	-	-	0	-	-	0	-			-	-	
DST	n2	0	-	0	-	-	-	0	-	-	0	-	-	0	-	4~7				
	n3	0	-	0	-	-	-	0	-	-	0	-	-	0	-	1				
	n4	0	-	0	-	-	-	0	-	-	0	-	-	0	-					
	n5	0	-	0	-	-	-	0	-	•	0	-	-	0	-					
								[DST		sl	ax	n1	n2	n3 r	14 n5			

[Area Setting]

Operand	Description	Setting range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ax	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD
n1	Target position	-2,147,483,648~2,147,483,647[Pulse]	DINT
n2	Target speed	1~100,000[pps]	DWORD
n3	dwell time	0~50,000[ms]	WORD
n4	M code number	M code (0~65,535)	WORD
n5	Control word	See '(a) function'	WORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is for directly ordering the start to XGB built-in positioning.
- This instruction carries out direct starting of the axis designated as ax of XGB positioning at the rising edge of input condition.
- If the instruction is executed, positioning operation is started by using the target position set in n1, the target speed set in n2, the dwell time set in n3, and the M code number set in n4 instead of the operation data set in the step number (axis X:K426, axis Y:K436 word) of area K.
- The absolute/Incremental coordinates, position/speed control and acceleration/deceleration pattern number are fixed by the setting of each bit of the control word set as n5.

Bit	F	Е	D	С	В	A	9	8	7	6	5	4	3	2	1	0
Setting	Not used							Acc./de	ec. time	coordinates setting	N	ot use	ed	control method		
Setting	-						0: 1, 2:3	1:2	0: absolute		-		0: position			
- The instruction only sets the item of the operation data, and the basic parameter items related to the operation such as the bias speed and speed limit are fixed in the positioning basic parameters.
- If you use the DST instruction, the operation pattern is fixed as End operation, and the operation method is fixed as the single operation. But if continued operation or repeated operation is needed, use indirect starting (IST instruction).

(b) Error

Γ

- If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.
- This case if an error of execution of the instruction, so the error of positioning area K flag (axis X:K4201, axis Y: K4301) does not turn On.

(2) Example of Use of the Instruction

- Direct starting instruction is described with the example of the following program.
- The example of use of the DST instruction is described on the basis of axis X.

(a) Example of the Program

0	M0000 P Home Return Run	K04200	K04201								_[ORG		0		0	
7	M0001 P Direct Start	K04200 // XAxis BUSY	K04201													•	0
			DST	0		0	DO	000	D	0002		D0004		D0005		D000	6
							Tai pos	get ition	T s	arget peed	D	well tin	ne I	M code	•	Contro word	ol j
18															_(END	<u> </u>
	IL pro	gram		L040# L040# A/0 N0# 013 013 0140 A/0 N0# A/0 N0# 017 017 017 017 017	G# 1 M0000 454300 454301 9 M0001 454301 454301 2	1991 second 1993 Receive and Receive and Name Receive Devertised Xame Receive Xame Receive Xame Receive Constituent Xame Receive Constituent Xame Receive Constituent Xame Receive Constituent Xame Receive Xame Rece	(9-140-P	083	CP 3 con	00002	SP 1400	00004	Of Baser	09 8 Docos	OF Econ	00008	Control Control

(b) Device Used

Device	Description	Data size	Example of setting
M0000	axis X origin return instruction signal	BIT	-
M0001	axis X direct starting instruction signal	BIT	-
K4200	signal during axis X operation	BIT	-
K4201	axis X error	BIT	-
D0000	Target position	DINT	100,000
D0002	Target speed	DWORD	30,000
D0004	Dwell time	WORD	100
D0005	M code number	WORD	123
D0006	Control word	WORD	H'20 [%]

※ H`20 : Bit5~6 : 1 (No.2 acceleration/deceleration pattern), Bit 4 : 0 (absolute coordinates), Bit0 : 0(position control)

- (c) Operation of the Program
 - If there is the rising edge of M0001 used as the direct starting instruction signal of axis X, the DST instruction is executed.
 - (Not if axis X is operating or in error.)
 - If the origin is not fixed when the DST is started, error code 224 will appear and operation will not occur. In such a case, turn on M0000, execute the ORG instruction and thereby carry out the origin return, and start the DST instruction.
 - 1) If the DST instruction is executed, the positioning operation gets started as set in the operand as follows.
 - Since sl and ax are 0, built-in positioning axis X is started.
 - The target position will be 100,000 pulse set as double word in D0002.
 - The target speed will be 30,000 pps set as double word in D0002.
 - After positioning is finished, the dwell time becomes 100ms set in D0004, and No.123 designated in D0005 will be output as the M code.
 - Since the control word of D0006 is H`20, the acceleration/deceleration pattern will follow the acceleration time 2 and deceleration time 2 of the basic parameter, and the positioning operation will be done as the absolute coordinates. If the DST instruction is started, the position control will be executed in the absolute coordinates, it will operate up to the 100,000 pulse at 30,000 pps, then stop, and after the dwell time of 100 ms passes, the positioning is finished, and M code outputs 123.
 - 2) If positioning is finished by direct starting, positioning finish signal (axis X:K4202) turns on for a scan.



5.2.4 Indirect Starting Instruction

• Indirect starting refers to execution of the positioning operation by using the operation step data set in the positioning operation data.

							Area	as av	vailab	le								Flag	
Instruc	tion	РМК	F	L	т	С	S	Z	D.x	R.x	con stan t	U	N	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)
	sl	-	-	-	-	-	-	-	-	-	0	-	-	-	-				
IST	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	-	4~7	0	-	-
	n1	0	-	0	-	-	-	0	-	-	0	-	-	0	-				
IST			_			(сом —	MAN	D					[ST	sl	ax n1]

(1) Indirect Starting Instruction (IST)

[Area Setting]

Operand	Description	Setting range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ax	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD
n1	Step number to start	0~30(standard), 0~80(advanced)	WORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is giving indirect starting instruction to XGB built-in positioning.
- The indirect starting is executed to the axis designated as ax of XGB positioning at the rising edge of the input condition.
- If the instruction is executed, the positioning operation is carried out by the operation data set in the step number of area K designated in n1. If n1 is set at 0, the operation step is executed which is displayed in the step number of current positioning area K (axis X:K426, axis Y:K436 word).
- Various operation patterns such as end, continued, and incessant operation, and single and repeated operation can be made and executed by using the indirect operation instruction.

(b) Error

- If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.
- In this case, execution of instruction is error. so K area error ocurrence Flag(X axis:K4201, Y axis:K4301) doesn't turn On
- If the set value of the starting step number gets out of the settable range, instruction Error Flag(F110) is not set, the error flag of positioning area K (axis X:K4201, axis Y: K4301) turns On, and the operation does not occur.

(2) Example of Use of the Instruction

- The indirect starting instruction is described with the example of the following program.
- The example of use of the IST instruction is described on the basis of axis X.

(a) Example of the Program

	K04200	K04	201					ORG	0	0
0 Return R	XAxis BUSY un	XAxis	Error							
M0001	K04200	K04	201				IST	0	0	D0000
7 Start	XAxis BUSY	XAxis	Error							Start Step
15										END
		Rung	Step	Instruction	OP 1	OP 1	OP 2	OP 2	OP 3	OP 3
			0					_		
		0	•	LOADP	M0000	Home Return Run				
		0	2	AND NOT	M0000 K04200	Return Run XAxis BUSY	1			
			2 3	AND NOT AND NOT	M0000 K04200 K04201	Home Return Run XAxis BUSY XAxis Error				
			2 3 4	AND NOT AND NOT ORG	M0000 K04200 K04201 0	Home Return Run XAxis BUSY XAxis Error	0			
IL progra	am	1	2 2 3 4 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	AND NOT AND NOT ORG LOADP	M0000 K04200 K04201 0 M0001	Home Return Run XAxis BUSY XAxis Error Indirect Start	0			
IL progra	am	1	2 3 4 7 9	AND NOT AND NOT ORG LOADP AND NOT	M0000 K04200 K04201 0 M0001 K04200	Home Return Run XAxis BUSY XAxis Error Indirect Start XAxis BUSY	0			
IL progra	am	1	2 3 4 7 9 10	LOADP AND NOT AND NOT ORG LOADP AND NOT AND NOT	M0000 K04200 K04201 0 M0001 K04200 K04201	Home Return Run XAxis BUSY XAxis Error Indirect Start XAxis BUSY XAxis Error	0			
IL progra	am	1	2 3 4 7 9 10 11	AND NOT AND NOT ORG LOADP AND NOT AND NOT IST	M0000 K04200 K04201 0 M0001 K04200 K04201 0	Home Return Run XAxis BUSY XAxis Error Indirect Start XAxis BUSY XAxis Error	0		D0000	Start Step

(b) Device Used

Device	Description	Data size	Example of setting
M0000	axis X origin return instruction signal	BIT	-
M0001	axis X indirect starting instruction signal	BIT	-
K4200	signal during axis X operation	BIT	-
K4201	axis X error	BIT	-
D0000	Starting step number	WORD	3

Step No.	coordin ates	Operatio n pattern	Control method	Operatio n mode	Repeat ed Step	Target position [Pulse]	M code	Acc./dec . No.	Operation speed[pls/s]	Dwell time [ms]
3	Increm ental	end	position	single	0	7,000	0	1	100	10

(c) Operation of the Program

• If there is the rising edge of M0001 used as the axis X indirect starting instruction signal, the IST instruction is executed.

(Not if axis X is operating or in error.)

- If the origin is not fixed when the DST is started, error code 224 will appear and operation will not occur. In such a case, turn on M0000, execute the ORG instruction and thereby carry out the origin return, and start the DST instruction.
 - 1) If the direct starting instruction (IST instruction) is executed, positioning operation starts as set in the operand as follows.
 - Since sl and ax are 0, built-in positioning axis X of the basic unit is started.
 - Because the starting step number is set as 3, positioning operation is carried out by the data of No. 3 step of the positioning operation data. That is, if the IST instruction is started, positioning control is conducted in the Incremental coordinates as set in operation data No. 3 step, moves up to 7,000 pulse at 100pps, stops, and when the dwell time of 10ms passes, positioning is finished.

2) Since M code is set at 0, it does not appear and as the operation pattern is End, the step number (axis X:K426) of area K is changed into 4, which is step + 1.



- In addition to executing indirect operation by using the IST instruction, indirect starting can also be started by using the starting signal instruction contact point (axis X:K4290, axis Y:K4390) of area K.
 - → If starting is done by using the starting signal instruction contact point, the operation step is fixed at the current operation step number (axis X:K426, axis Y:K436).
 - → Therefore if you want to change the operation step when starting by using the starting signal instruction contact point, change the operation step by using the Starting step number changing instruction and turn on the starting instruction contact point.
- For details, refer to 3.4.2.

Γ

5.2.5 Straight Interpolation Starting Instruction

- Straight interpolation starting refers to the operation so that the path of axes X and Y is straight from the starting address (current stop location) to the target address (target address).
- Straight interpolation control divides into control by absolute coordinates and Incremental coordinates. For details, refer to 3.1.2.
- When the instruction of straight interpolation starting is given, the axis where there is more movement is designated as the main axis. If the movements are equal, axis X is the main axis.
- The speed of the auxiliary axis does not follow the setting of the operation data, but conducts operation by calculating the operation speed, acceleration time, deceleration time, and bias speed automatically by the following operations.



 The operation pattern that can use straight interpolation operation is limited to End and Continued operation. If the main axis is set as Continued and the interpolation operation is started, no error is issued in XGB built-in positioning but the operation pattern of the main axis is changed into Continued. If the auxiliary axis is set as Continued, it does not affect the straight interpolation.

							Area	as av	vailab	le								Flag	
Instruc	tion	РМК	F	L	т	С	S	z	D.x	R.x	con stan t	U	N	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)
	sl	-	-	-	-	-	-	-	-	-	0	-	-	-	-				
1 181	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	-	4 7			
LIN	n1	0	-	0	-	-	-	0	-	-	0	-	-	0	-	4~1	0	-	-
	n2	0	-	0	-	-	-	0	-	-	0	-	-	0	-				
LIN				₽	_	С	ЮММ)				-	LIN	1	sl	ax r	n1 n2	

[Area Setting]

Operand	Description	Setting range	Data size
sl	Slot number of positioning module	XGB is fixed at 0	WORD
ax	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD
n1	Step number to carry out straight interpolation	0~30(standard), 0~80(advanced)	WORD
n2	Set the axis to carry out straight interpolation	XGB is set at 3	WORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is giving the straight interpolation starting instruction to XGB built-in positioning.
- The two axes of XGB positioning conduct straight interpolation starting at the rising edge of input condition.
- If the instruction is executed, the two axes of XGB positioning carried out the straight interpolation operation according to the axis setting designated in n2. The step number to be operated is the step number set in n1.
- In setting of the axis of n2, the axis to carry out the straight interpolation operation as follows.

Bit number	15 ~ 3	2	1	0
Setting	Not used	Axis Z (XGB is not	axis Y	axis X
		used)		

- Each bit refers to the axis to start the straight interpolation. In the case of XGB built-in positioning, n2 should be fixed as 3 since only axis X and axis Y are available. Otherwise, error code 253 is issued and it does not operate.

(b) Error

- If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.
- Since this case if an error of execution of the instruction, the error in positioning area K error flag(axis X:K4201, axis Y: K4301) does not turn On..
- If the set value of the starting step number gets out of the settable range, instruction Error Flag(F110) is not set, the error flag of positioning area K (axis X:K4201, axis Y: K4301) turns On, and the operation does not occur.

(2) Example of Use of the Instruction

(a) Example of the Program

	M0000	K04200	K04201			ORG	0	0
0	Home Return Run	XAxis BUSY	XAxis Error					
	M0001	K04200	K04201	LIN	0	0	D0000	D0001
7	Liner intepolation	XAxis BUSY	XAxis Error				Operation step	Axis data
								END

	Run	Step	Instruction	OP 1	OP 1 comm	OP 2	OP 2	OP 3	OP 3	OP 4	OP 4
	0	0	LOADP	M0000	Home Return Run						
		2	AND NOT	K04200	XAxis BUSY						
		3	AND NOT	K04201	XAxis Error						
		4	ORG	0		0					
	1	7	LOADP	M0001	Liner intepolation						
II program		9	AND NOT	K04200	XAxis BUSY						
		10	AND NOT	K04201	XAxis Error						
		11	LIN	0		0		D0000	Operation step	D0001	Axis data
P	2	16	END								

(b) Device Used

Device	Description	Data size	Example of setting
M0000	axis X origin return instruction signal	BIT	-
M0001	Interpolation starting instruction signal	BIT	-
K4200	signal during axis X operation	BIT	-
K4201	axis X error	BIT	-
D0000	Operation step number	WORD	10
D0001	Axis information	WORD	3

Axis	Step No.	coordi nates	Operatio n pattern	Control method	Operatio n mode	Repeat ed Step	Target position [Pulse]	M code	Acc./dec. No.	Operation speed[pls/s]	Dwell time [^{ms}]
х	10	Rel.	End	positio n	Single	0	7,000	0	1	100	10
Y	10	Rel.	End	positio n	Single	0	2,000	0	2	300	10

(c) Operation of the Program

• The LIN instruction is executed if the rising edge of M0001 is generated which was used as the instruction signal of the straight interpolation starting.

(If it is in operation of axis X or in error, it does not operate. If axis Y is in operation, error code 242 is issued and it does not operate)

- 1) If the straight interpolation instruction (LIN instruction) is executed, the straight interpolation operation is started as set in operand.
- 2) Since sl is 0, built-in positioning of the basic unit operates straight interpolation.
- Because the starting step number is set as 3, positioning operation is carried out by the data of No. 3 step of the positioning operation data. That is, if the IST instruction is started, positioning control is conducted in the Incremental coordinates as set in operation data No. 3 step, moves up to 7,000 pulse at 100pps, stops, and when the dwell time of 10ms passes, positioning is finished.
- 3) As the ax is set at 0, the straight interpolation instruction for axis X is started. (For actual zero, the main and auxiliary axes of axis X and axis Y are calculated according to the size of the target position for starting, to the ax operand does not affect the operation)
- 4) Since the step number of n1 operation is set at 10, the main and auxiliary axes are automatically selected by No. 10 operation data of axis X and axis Y. (In this example, because the target position of axis X is larger, axis X is the main axis and axis Y is the auxiliary axis.)
- 5) The acceleration and deceleration time and speed of axis Y, which is the auxiliary axis, does not follow the set value but automatically calculated for operation.
- 6) That is, axis X and axis Y are designated as the main and auxiliary axes respectively by starting of the LIN instruction, it moves by (7000,2000) to the relative position and the operation ends.

5.2.6 Simultaneous Starting Instruction

• The simultaneous starting instruction (SST instruction) is for simultaneously starting the steps of the axes set in the instruction. For details, refer to 3.1.7.

							Area	as av	vailab	le								Flag	
Instruc	tion	PMK	F	L	Т	с	Ś	z	D.x	R.x	con stan t	U	Z	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)
	sl	-	-	-	-	-	-	-	-	-	0	-	-	-	-				
	ax	0	1	0	-	-	1	0	-	-	0	-	1	0	1				
0.07	n1	0	-	0	-	-	-	0	-	-	0	-	-	0	-	4 7	_		
551	n2	0	-	0	-	-	-	0	-	-	0	-	-	0	-	4~1	0	-	-
	n3	0	-	0	-	-	-	0	-	-	0	-	-	0	-				
	n4	0	-	0	-	-	-	0	-	-	0	-	-	0	-				<u> </u>
SST	-		_	C	омм Н		1					SST		sl	ax	n1	n2 r	13 n4]

(1) simultaneous starting instruction (SST)

[Area Setting]

Operand	Description	Setting range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ax	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD
n1	axis X Step No.	0~30(standard), 0~80(advanced)	WORD
n2	axis Y Step No.	0~30(standard), 0~80(advanced)	WORD
n3	axis Z Step No.	Not used	WORD
n4	Axis setting	XGB is set at 3	WORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This function is for giving the simultaneous starting instruction to XGB built-in positioning simultaneous starting.
- The two axes of XGB positioning are simultaneously started at the rising edge of the input condition. (For the difference between using the simultaneous starting instruction and starting the two axes consecutively in the PLC ladder program, refer to 3.1.7.)
- When the instruction is executed, axis X and axis Y simultaneously start by using the operation data of the step number set in n1 and n2 respectively. XGB built-in positioning does not have axis Z, so the set value of n3 does not affect the operation.
- Axis setting of n4 sets the axis to carry out simultaneous starting by bit as follows.

Bit No.	15 ~ 3	2	1	0
Setting	Not used	Axis Z (XGB not used)	axis Y	axis X

- Each bit refers to the axis to start straight interpolation. In the case of XGB built-in positioning, only axis X and axis Y are available, so n4 should be fixed at 3. Otherwise, error code 296 is issued and operation does not occur.

(b) Error

- If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.
- Since this case if an error of execution of the instruction, the error in positioning area K error flag(axis X:K4201, axis Y: K4301) does not turn On..
- If the set value of the starting step number gets out of the settable range, instruction Error Flag(F110) is not set, the error flag of positioning area K (axis X:K4201, axis Y: K4301) turns On, and the operation does not occur.

(2) Example of Use of the Instruction

• The instruction is described with the example of the following program simultaneous starting instruction.

(a) Example of the Program





(b) Device Used

Device	Description	Data size	Example of setting
M0001	simultaneous starting instruction signal	BIT	-
K4200	signal during axis X operation	BIT	-
K4201	axis X error	BIT	-
K4300	signal during axis Y operation	BIT	-
K4301	axis Y Error	BIT	-
D0000	axis X operation Step No.	WORD	1
D0001	axis Y operation Step No.	WORD	2
D0002	axis Z operation Step No.	WORD	-
D0003	Axis setting	WORD	3

Axis	Step No.	coordin ates	Operatio n pattern	Control method	Operat ion mode	Repeat ed Step	Target position [Pulse]	M code	Acc./dec. No.	Operation speed[pls/s]	Dwell time [^{ms}]
х	1	Rel.	End	position	Singl e	0	7,000	0	1	100	10
Y	2	Rel.	End	Position	Singl e	0	2,000	0	2	300	10

(c) Operation of the Program

- SST instruction is executed it the rising edge of M0001, which was used as the instruction signal of the simultaneous starting is generated.
 - 1) If the simultaneous starting instruction (SST) is executed, the two axes are simultaneously started as set in the operand as follows.
 - 2) Since sl is 0, built-in positioning of the basic unit operates simultaneous starting.
 - 3) If the set value of ax does not exceed the setting range, it does not affect the operation.
 - 4) Since the step numbers of axis X and axis Y are set 1 and 2 respectively, the two axes are simultaneously started by using the operation data of the operation step.
 - 5) Since there is no axis Z in XGB built-in positioning, even if a random value is input as the step number of axis Z operation, the operation is not affected.

5.2.7 Speed Position Switching Instruction

• This is positioning according to the target position by switching the axis operated by speed control to position control through speed/position switching instruction (VTP instruction). For details, refer to 3.1.4.

							Area	as av	/ailab	le								Flag			
Instruc	tion	PMK	F	L	т	с	S	z	D.x	R.x	con stan t	U	N	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)		
VTD	sl	-	-	-	-	•	-	•	-	•	0	-	-	-	-	47	0				
VIF	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	-	4~1	0	-	-		
VTP											sl ax]									
- [Area S	Settir	ng]																			
Opera	and	Ind Description Setting range										Data	a size								
sl		Slot	No. (of po	sitio	ning	mod	dule	Х	XGB is fixed at 0								WORD			
ax	[Axis to give instruction 0 (axis X) or 1 (axis Y)								WORD											

(1) Speed/Position Switching Instruction (VTP)

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is giving the speed/position control switching instruction to XGB built-in positioning.
- The axis designated as ax at the rising edge in the input condition is switched from the speed operation to position operation.
- The current position which was output during the previous speed control operation is initialized to 0 and operated to the target position by absolute coordinates method.

(b) Error

• If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.

(2) Example of Use of the Instruction

- The program speed/position control switching instruction is described with the following example.
- (a) Example of the Program

٦	M0001	K04211	K04201					VTP 0	0
2	VTP command	XAxis Control Pattern(Spe ed)	XAxis Error						
4									END
	-			0	0	LOADP	M0001	VTP	:
	IL	progran	n		2	AND	K04211	command XAxis Control Pattern(Spe ed)	
					3	AND NOT	K04201	XAxis Error	
			F		4	VTP	0		0
				1	7	END			

(b) Device Used

Device	Description	Data size	Example of setting
M0001	speed/position switching instruction signal	BIT	-
K4211	Signal during axis X speed control	BIT	-
K4201	axis X error	BIT	-

(c) Operation of the Program

• VTP instruction is executed when there is the rising edge of M0001, which was used as the speed/position switching instruction signal.

- It the speed control is going on currently, it is switched into position control, the current position is preset to 0, and position control is carried out up to the target position. Now the target position divides into the following cases according to the direct and indirect starting.
 - 1) In case of indirect starting, the target position of the operating step becomes the target position after the speed position switching.
 - 2) In case of direct starting, the target position set as the operand in the DST instruction becomes the target position after the speed position switching
- When using the speed/position switching instruction, make sure that the instruction is not executed during the position operation by using the display flag (axis X:K4211, axis Y:K4311) during speed control as the program example above.

5.2.8 Position Speed Switching Instruction

• This is operation by switching the axis operating by the current position control into speed control by the position/speed switching instruction (PVT instruction). For details, refer to 3.1.5.

(1) Position/Speed Switching Instruction (PTV)

			Areas available														Flag		
Instruc	tion	PMK	F	L	т	С	S	z	D.x	R.x	Cons tant	U	Ν	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)
DTV	sl	-	-	-	-	-	-	-	-	-	0	-	-	-	-	4 7			
PIV	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	-	4~7	0	-	-
PTV											PT۱	/	sl ax]					

[Area Setting]

Operand	Description	Setting range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ax	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is giving the position/speed control switching instruction to XGB built-in positioning.
- The axis designated as ax at the rising edge in the input condition is switched from the position operation to speed operation.
- The current position which was output during the previous speed control operation is not initialized to 0 and only the control method is switched to speed control with the operation continued.
- (b) Error
 - If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.
- (2) Example of Use of the Instruction
 - The position/speed control switching instruction is described with the example of the following program.
 - (a) Example of the Program



(b) Device Used

Device	Description	Data size	Example of setting
M0001	position/speed switching instruction signal	BIT	-
K4210	signal during axis X position control	BIT	-
K4201	axis X error	BIT	-

(c) Operation of the Program

• PVT instruction is executed when there is the rising edge of M0001, which was used as the position/speed switching instruction signal.

• It the position control is going on currently, it is switched into speed control, and the current position is not preset but only the control method is switched to speed control.

• When using the position/speed switching instruction, make sure that the instruction is not executed during the speed operation by using the display flag (axis X:K4210, axis Y:K4310) during position control as the program example above.

• To stop the operation after switching to speed control, use the stop instruction (STP).

5.2.9 Deceleration Stop Instruction

• The currently operating axis is decelerated and stopped at the speed designated by the deceleration stop instruction (STP instruction). For details, refer to 3.1.11.

	Areas available														Flag				
Instruc	tion	PMK	F	L	т	С	Ś	Z	D.x	R.x	con stan t	U	Z	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)
	sl	-	-	-	-	-	-	-	-	-	0	-	-	-	-				
STP	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	-	4~7	0		-
	n1	0	-	0	-	-	-	0	-	•	0	-	-	0	•				
STP									S	TP	sl	ax n1							

(1) Deceleration Stop Instruction (STP)

[Area Setting]

Operand	Description	Setting range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ax	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD
n1	deceleration time	0(immediate stop) 1~65,535(default)	WORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is giving the deceleration stop instruction to XGB built-in positioning.
- The designated axis of instruction works at the rising edge of the input signal.
- In case n1 is 0
 - It stops right away without deceleration in XGB internal positioning.
- In this case, note that there might be shock noise or damage to the motor.
- In case n1 is 1~65535
- the deceleration time do not follow by n1 setting.
- It stops according to the operation data of the acceleration/deceleration number.

(For example, In DST operation STP deceleration time is followed by Acc./dec. number in DST. In IST operation, STP deceleration time is followed by Acc./dec. number in operation data.)

(b) Error

• If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.

(2) Example of Use of the Instruction

- The deceleration stop instruction is described with the example of the following program.
- (a) Example of the Program

M0000	K04210	K04201						ORG	0	0
Home Return Run	XAxis Control Pattern(Pos ition)	XAxis Error								
M0001	К04200	K04201				[IST	0	0	1
IST command	XAxis BUSY	XAxis Error								
M0002	K04200	K04201				[STP	0	0	0
STP command	XAxis BUSY	XAxis Error								
										END
			_				Hama			
			0	0	LOADP	M0000	Return Run			
				2	AND NOT	K04210	XAxis Control Pattern(Position)			
11	progra	22		3	AND NOT	K04201	XAxis Error			
	progra			4	ORG	0		0		
						v				
			1	7	LOADP	M0001	IST			
			1	7 9	LOADP AND NOT	M0001 K04200	IST command XAxis BUSY			
			1	7 9 10	AND NOT AND NOT	M0001 K04200 K04201	IST command XAxis BUSY XAxis Error			
			1	7 9 10 11	AND NOT AND NOT IST	M0001 K04200 K04201 0	IST command XAxis BUSY XAxis Error	0	1	
			1	7 9 10 11 15	LOADP AND NOT AND NOT IST LOADP	M0001 K04200 K04201 0 M0002	IST command XAxis BUSY XAxis Error STP command	0	1	
			1	7 9 10 11 15 17	LOADP AND NOT AND NOT IST LOADP AND NOT	M0001 K04200 K04201 0 M0002 K04200	IST command XAxis BUSY XAxis Error STP command XAxis BUSY	0	1	
			2	7 9 10 11 15 17 18	LOADP AND NOT IST LOADP AND NOT AND NOT	M0001 K04200 K04201 0 M0002 K04200 K04201	IST command XAxis BUSY XAxis Error STP command XAxis BUSY XAxis Error	0	1	
			2	7 9 10 11 15 17 18 19	LOADP AND NOT IST LOADP AND NOT AND NOT STP	M0001 K04200 K04201 0 M0002 K04200 K04201 0	IST command XAxis BUSY XAxis Error STP command XAxis BUSY XAxis Error	0	1	

(b) Device Used

Device	Description	Data size	Example of setting
M0000	origin return instruction signal	BIT	-
M0001	Indirect starting instruction signal	BIT	-
M0002	Deceleration stop instruction signal	BIT	-
K4200	signal during axis X position control	BIT	-
K4201	axis X error	BIT	-

(c) Operation of the Program

- IST instruction is executed when there is the rising edge of M0001, which was used as the indirect starting instruction signal.
 - In the program above, the indirect starting of No. 1 step of axis X is executed.
- If there is the rising edge of M0002, which is the deceleration stop instruction signal during operation, the deceleration stop instruction is executed according to the setting of STP instruction.
 - Since sl (first Operand) and ax(second Operand) are set at 0, the deceleration stop is executed for axis X of basic unit built-in positioning.
 - Since the deceleration time is set at 0, if the STP instruction is executed, it stops right away without deceleration.
- Note the following in executing the STP instruction.
 - If it has been stopped by the deceleration stop instruction, because the positioning operation has not been finished to the set target position, no positioning completion signal (axis X:K4202, axis Y:K4302) is generated, and if M code is set, the M code signal does not turn On either.
 - In this case, the operation step number maintains the current step.
 - If the indirect starting instruction is executed again afterwards, the operation methods differs according to the coordinates type.
 - 1) Absolute coordinates: The remaining position output which has not been output from the current operation step is output.
 - 2) Incremental coordinates: Operation is conducted as much as the new target position.
 - For example, if the target value of the corresponding step is 20,000 and it has been stopped at 15,000 by the deceleration stop instruction, and if the indirect starting is executed again, in case of absolute coordinates, operation is done as much as 5,000 and stops at 20,000, and in case of Incremental coordinates, it newly moves 20,000 and stops at 35,000.

5.2.10 Main axis position synchronous Instruction

• As follows, this is the instruction for synchronous starting according to the current position of the main axis with the axis set in the SSP being the auxiliary axis. For details, refer to 3.1.8.



(1) Main axis position synchronous Starting Instruction (SSP)

							Area	as av	vailab	le							Flag			
Instruc	tion	PMK	F	L	Т	С	S	Z	D.x	R.x	Cons tant	U	Ν	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)	
	sl	-	1	1	1	1	1	I	-	-	0	-	1	-	1					
	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	-			-	-	
SSP	n1	0	-	0	-	-	-	0	-	-	0	-	-	0	-	4~7	0			
	n2	0	1	0	1	1	1	0	-	-	0	-	•	0	-					
	n3	0	-	0	-	-	-	0	-	-	0	-	-	0	-					
SSP	_	COMMAND												0	sl	ax	n1 n	2 n3]	

[Area Setting]

Γ

Operand	Description	Setting range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ax	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD
n1	Position value of the main axis position synchronous main axis	-2,147,483,648 ~ 2,147,483,647	DINT
n2	Operation step number of auxiliary axis	0~30(standard), 0~80(advanced)	WORD
n3	Setting of the main axis of position synchronous	0 (axis X) or 1 (axis Y)	WORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is executing main axis position synchronous starting for the XGB built-in positioning.
- The main axis position synchronous instruction is executed with the axis set in the axis designated as ax at the rising edge of the input condition auxiliary axis, n3 being the main axis.

- If the instruction is executed, the auxiliary axis stands by without generating actual pulse (the operation status flag of the auxiliary axis (axis X:K4200, axis Y:K4300) turns On), and n2 step of the auxiliary axis is started when n3 axis, which is the main axis, is positioned as set in n1.
- The position synchronous starting instruction can be executed only when the origins of both the main axis and auxiliary axis are fixed. If the origin of the main axis is not decided when the main axis position synchronous instruction (SSP) is started, error code 346 is issued, and if the origin of the auxiliary axis is not decided when the main axis position synchronous instruction (SSP) is started, error code 346 is issued.
- When you use the main axis position synchronous instruction, set the main axis and auxiliary axis at different axes. If they are set at the same axis, error code 347 is issued.
- If you want to cancel the main axis position synchronous instruction after you executed it, execute the stop instruction of the auxiliary axis (STP).

(b) Error

- If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.
- (2) Example of Use of the Instruction
 - The main axis position synchronous starting instruction is described with the example of the following program.
 - (a) Example of the Program
 - The following program example is starting No.1 step operation data of the auxiliary axis when axis Y is the auxiliary axis and axis X is the main axis, and the position of the main axis is 10,000.



(b) Device Used

Device	Description	Data size	Example of setting
M0001	main axis position synchronous instruction signal	BIT	-
M0002	main axis instruction signal	BIT	-
K4300	Signal during auxiliary axis (axis Y) position control	BIT	-
K4301	auxiliary axis(axis Y) Error	BIT	-
K4204	axis X origin fixed	BIT	-
K4304	axis Y origin fixed	BIT	-
K4200	Signal during the main axis(axis X) position control	BIT	-
K4201	main axis(axis X) Error	BIT	-

(c) Operation of the Program

- The SSP instruction is executed if there is the rising edge of M0001, which was used as the main axis position synchronous instruction signal.
- Since the second operand is 1 (axis Y), axis Y is the auxiliary axis, and as the fifth operand is 0(axis X), so the main axis is axis X.
- No.1 step of axis X is indirectly started if there is the rising edge of M0002, which is the indirect starting instruction signal of the main axis.
- When the current position of the main axis during operation becomes 10,000[Pulse], set in the third operand of the SSP instruction, axis Y, which is the auxiliary axis, starts No. 1 step, which is the operation step set in the fourth operand of the SSP instruction.

• When you use the main axis position synchronous instruction, if the axis set as the main axis has already been started as the main axis position synchronous auxiliary axis, error code 349 is issued and it is not executed. If the following example, axis Y becomes the auxiliary axis and axis X becomes the main axis at the rising edge of M0001 and the main axis position synchronous instruction is executed. If there is the rising edge of M0100, the position synchronous instruction is issued with axis X being the auxiliary axis and axis Y being the main axis. In this case, since axis Y used as the main axis, is already being started as the auxiliary axis of the main axis position synchronous instruction, axis X generates error code 349 and is not started.

	M0001	SSP	0	1	10000	1	0
0	Y axis SSP command						
8	M0100 P X axis SSP command	SSP	0	0	10000	1	1
16							END

5.2.11 Speed Synchronous Instruction

• The speed synchronous instruction (SSS instruction) is for speed synchronization at the set synchronous speed rate and operation when the main axis is started with the axis set in the instruction being the auxiliary axis. For details, refer to 3.1.8.

							Area	as av	vailab	le							Flag			
Instruc	tion	РМК	F	L	т	С	S	z	D.x	R.x	con stan t	U	N	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)	
	sl	-	-	-	-	-	1	-	-	-	0	-	-	-	-					
	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	1				-	
SSS	n1	0	-	0	-	1	-	0	-	-	0	-	-	0	1	4~7	0	-		
	n2	0	-	0	-	1	-	0	-	-	0	-	-	0	1					
	n3	0	-	0	-	1	-	0	-	-	0	-	-	0	1				<u> </u>	
SSS	-		-	C	omn H)					_	SS	S	sl	ax	n1 r	n2 n3]	

(1) Speed Synchronous Starting Instruction (SSS)

[Area Setting]

Operand	Description	Setting range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ax	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD
n1	speed synchronous ratio	1 ~ 10,000(0.01% ~ 100.00%)	WORD
n2	Delay time	1 ~ 10[ms]	WORD
n3	Speed delay main axis setting	See 0 ~ 9 '(1) Function'	WORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is for executing the speed synchronous starting for synchronous starting.
- The axis set in the axis designated as ax at the rising edge of the input condition auxiliary axis, n3 becomes the main axis and the speed main axis position synchronous starting instruction is executed.
- If the instruction is executed, the auxiliary axis stands by without generating actual pulse (the operation status flag of the auxiliary axis (axis X:K4200, axis Y:K4300) turns On), and nn3 axis, which is the main axis, it is started according to the speed synchronous ratio set in n1.
- The synchronous ratio settable in n1 is 0.01% ~ 100.00% (set value 1 ~ 10,000). If the set speed ratio gets out of this range, error code 356 is issued.
- The delay time of n2 refers to the delay time it takes for speed of the auxiliary axis to reach the current main axis speed. In XGB built-in positioning, when controlling the speed synchronization, the speed of the current main axis is detected every 500 μ s, and thereby the speed of the auxiliary axis is adjusted. If the speed of the auxiliary axis is synchronized to the current main axis speed without a delay time and immediately changed, there might be damage or shock noise to the motor due to the sudden change of the auxiliary axis speed.

For example, assuming the speed ratio is 100.00% and the delay time is 5[ms], if the speed of the main axis is 10,000[pps], the XGB built-in positioning adjusts the speed of the auxiliary axis according to the speed of the main axis every $500[\mu s]$ by adjusting the current speed for the speed of the auxiliary axis to reach 10,000[pps].

The longer the delay time, the longer the delay time between the main axis and auxiliary axis, but the output pulse is stably output. If there is likely to be step out of the motor, lengthen the delay time.

- The delay time settable for n2 is 1 ~ 10[ms]. If it gets out of the settable range, error code 357 is issued.
- The main axis of n3 is settable between 0 and 9. If it gets out of the settable range, error code 355 is issued

Set value	Main axis setting	Remark
0	axis X	
1	axis Y	
2	High speed counter Ch0	
3	High speed countCh1	
4	High speed countCh2	
5	High speed countCh3	
6	High speed counter Ch4	
7	High speed counter Ch5	Only the advanced type is
8	High speed counter Ch6	settable.
9	High speed counter Ch7	

- If you want to cancel the speed synchronous instruction after you execute it, execute the stop instruction (STP) for the auxiliary axis.
- The speed synchronous control is executable even when the origin is not fixed.
- The speed synchronous control is synchronized to the speed of the main axis for operation of the auxiliary axis, so even if the control method of the auxiliary axis is set as position control, starting and stop are alternated by the operation of the main axis, with the rotation of the auxiliary axis being in the same direction as the main axis.
- If the M code of the auxiliary axis is On when you execute the speed synchronous instruction, error code 353 is issued.

(b) Error

- If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.
- (2) Example of Use of the Instruction
 - The speed synchronous starting instruction is described with the example of the following program.
 - (a) Example of the Program
 - The following program example is about speed synchronous starting with the synchronization ratio 100.00[%] and the delay time being 10[ms] when the main axis is started if axis Y is the auxiliary axis and axis X is the main axis.

0	M0001 P Yaxis SSS command	K04300	K04301	K04204 XAxis Origin Fix	SSS	0	1		10000	10	0
	M0002						IS	r	0	0	1
10	start										
15											END

	0	•	LOADP	M0001	Yaxis SSS command				
		2	AND NOT	×04300	YAxis BUSY				
		3	AND NOT	×04301	YAxis Error				
		4	AND	X04204	XAxis Orgin Fix				
		5	\$\$\$	0		1	10000	10	0
IL program	1	10	LOAD	M0002	Main axis start				
		11	157	0		0	1		
	2	15	END						

(b) Operation of the Program

- SSS instruction is executed if there is the rising edge of M0001, which was used as the speed synchronous instruction signal. Since the second operand is 1(axis Y), axis Y becomes the auxiliary axis, and because the fifth operand is 0(axis X), the main axis is axis X.
- If there is the rising edge of M0002, which is the indirect starting instruction signal of the main axis, No. 1 step of axis X is indirectly started.
- When the main axis is started, axis Y is started at the synchronous ratio speed of 100.00[%] set in the third operand of SSS instruction, and is synchronized to the main axis with the delay time of 10[ms] set in the fourth operand for operation.

5.2.12 Position Override Instruction

• The position override instruction (POR) is for changing the target position of the axis being operated for the current positioning into the target position set in the instruction. For details, refer to 3.1.10.

							Area	as av	vailab	le							Flag			
Instruction		PMK	F	L	т	с	S	z	D.x	R.x	con stan t	U	N	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)	
POR	sl	-	-	-	-	-	-	-	-	-	0	-	-	-	-					
	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	-	4~7	0	-	-	
	n1	0	-	0	-	-	-	0	-	-	0	-	-	0	-					
POR	ł												Ρ	OR	sl	ax n1				

(1) position override instruction (POR)

[Area Setting]

Operand	Description	Settable range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ax	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD
n1	Target position to change	-2,147,483,648 ~ 2,147,483,647	DINT

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is giving the position override instruction to the XGB built-in positioning.
- This is changing the target position to the position set in n1 during the operation of the axis designated as ax at the rising edge of the input condition.
- The position override instruction is available in the acceleration and deceleration sections and if the position override is executed during dwell, error code 362 is issued.

(b) Error

• If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.

(2) Example of Use of the Instruction

- The position override instruction is described with the example of the following program.
- (a) Example of the Program

M0000	K04200	K04	1201 /			IST	0	0	1
IST command	XAxis BUSY	XAxis	Error						
	K04200	K04	120F			POR	0	0	1000
command		Statu	s(Dwe II)						END
4		0	0	LOADP	M0000	IST command	1		
4		0	0	LOADP AND NOT	M0000 K04200	IST command XAxis BUSY			
4		0	0 2 3	LOADP AND NOT AND NOT	M0000 K04200 K04201	IST command XAxis BUSY XAxis Error			
4	•	0	0 2 3 4	LOADP AND NOT AND NOT IST	M0000 K04200 K04201 0	IST command XAxis BUSY XAxis Error	0		1
	ram	0	0 2 3 4 8	LOADP AND NOT AND NOT IST LOAD	M0000 K04200 K04201 0 M0001	IST command XAxis BUSY XAxis Error POR command	0		1
IL progi	ram	0	0 2 3 4 8 9	LOADP AND NOT AND NOT IST LOAD AND	M0000 K04200 K04201 0 M0001 K04200	IST command XAxis BUSY XAxis Error POR command XAxis BUSY	0		1
L progr	ram	0	0 2 3 4 8 9 10	LOADP AND NOT AND NOT IST LOAD AND AND NOT	M0000 K04200 K04201 0 M0001 K04200 K0420F	IST command XAxis BUSY XAxis Error POR command XAxis BUSY XAxis Move Status(Dwel I)	0		1
L progr	ram	0	0 2 3 4 8 9 10 11	LOADP AND NOT AND NOT IST LOAD AND AND NOT POR	M0000 K04200 K04201 0 M0001 K04200 K0420F 0	IST command XAxis BUSY XAxis Error POR command XAxis BUSY XAxis BUSY XAxis Move Status(Dwel I)	0		1

(b) Operation of the Program

- The positioning axis X is indirectly started with operation step 1 when there is the rising edge of M0000 used as the indirect starting instruction signal.
- If there is the rising edge of M0001 used as the instruction signal of the position override instruction before the current position during operation reaches 100,000 [Pulse], operation continues by changing the target position of the currently operating step into 100,000. (Note that the value of the target position of No. 1 step set in the positioning parameter is not changed)
- If the position override instruction is executed when the current position has passed 100,000[Pulse], it is decelerated and stops.
- If the position override instruction is executed during dwell operation, error code 362 is issued. To prevent this, make the program by connecting the axis X dwell flag to the starting contact point with the normally closed contact point (contact point B).

5.2.13 Speed Override Instruction

• The speed override instruction (SOR) is for changing the operation speed of the axis during current positioning operation into the speed set in the instruction. For details, refer to 3.1.10.

							Area	as av	vailab	le							Flag		
Instruction		PMK	F	L	т	с	S	z	D.x	R.x	con stan t	U	N	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)
	sl	-	-	-	-	-	-	-	-	-	0	-	-	-	-				-
SOR	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	-	4~7 ○	0	-	
	n1	0	-	0	-	-	-	0	-	-	0	-	-	0	-				
									S	OR	sl	ax n1							

(1) Speed Override Instruction (SOR)

[Area Setting]

Operand	Description	Setting range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ax	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD
n1	Operation speed to change	0 ~ 100,000[pps]	DWORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is giving the speed override instruction to XGB built-in positioning.
- This is for changing the operation speed into the speed set in n1 during the operation of the axis designated as ax at the rising edge of the input condition.
- The speed override instructions available in the acceleration and constant speed sections and if the speed override is executed during deceleration or dwell, error code 377 is issued and the currently operating operation step continues.

(b) Error

• If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.

(2) Example of Use of the Instruction

• The speed override instruction is described with the example of the following program.

(a) Example of the Program

ŀ	M0000	K04200	KO	4201 1∕/──				IST		0	0	1
2	IST command	XAxis BUSY	XAx	is Error	104005							
L		K04200	KU	420F	K0420E			SOR		0	0	10000
	SOR	XAxis BUSY	XAxis Move Status(Dwe II)		XAxis Move Status(Dec eleration)							
L												END
1								IST				
			0	0	LOA	DP	M0000	command				
				2	AND	NOT	K04200	XAxis BUSY				
				3	AND	NOT	K04201	XAxis Error				
				4	IST		0		0			1
L	. prog	ram	1	8	LOA	DP	M0001	SOR command				
				10	AND		K04200	XAxis BUSY				
				11	AND	NOT	K0420F	XAxis Move Status(Dwel I)				
				12	AND	NOT	K0420E	XAxis Move Status(Dece leration)				
				13	SOF		0		0			10000
			2	18	END							

- (b) Operation of the Program
- The positioning axis X is indirectly started with operation step 1 if there is the rising edge of M0000 used as the indirect starting instruction signal.
- If there is the rising edge of M0001 used as the instruction signal of the speed override instruction during operation, operation continues by changing the speed of the currently operating step into 10,000[pps]. (Note that the value of the operation speed of No. 1 step set in the positioning parameter is not changed)
- If the speed override instruction is executed during deceleration or dwell, error code 377 is issued. To prevent this, make the program by connecting the axis X dwell flag to the starting contact point with the normally closed contact point (contact point B).

5.2.14 Positioning Speed Override Instruction

- The positioning speed override instruction (PSO) is changing the operation speed of the axis during current positioning operation at the specific position set in the instruction. For details, refer to 3.1.10.
- (1) Positioning speed override instruction (PSO)

							Area	as av	vailab	le							Flag			
Instruc	tion	PMK	F	L	т	С	S	Z	D.x	R.x	con stan t	U	Ν	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)	
	sl	-	-	-	-	-	-	-	-	-	0	-	-	-	-				-	
DSO	ax	0	-	0	-	-	-	0	-	-	0	-	1	0	1	4 7				
P30	n1	0	1	0	-	-	I	0	-	-	0	-	1	0	1	4~1	0	-		
	n2	0	1	0	-	-	1	0	-	-	0	-	1	0	1					
										С	sl	ax r	n1 n2]						

[Area Setting]

Γ

Operand	Description	Setting range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ax	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD
n1	Position to change the speed	-2,147,483,648 ~ 2,147,483,647	DINT
n2	Operation speed to change	0 ~ 100,000[pps]	DWORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is giving the positioning speed override instruction to XGB built-in positioning.
- The positioning speed override is executed at the axis designated as ax at the rising edge of the input condition, and if the current position reaches the position set in n1 during operation, the current operation speed is overridden to the speed set in n2.
- The positioning speed override instruction is available in the deceleration and acceleration sections and if the positioning speed override is executed during deceleration or dwell, no error code is issued, but the instruction is not executed either.

(b) Error

• If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.

- (2) Example of Use of the Instruction
 - (a) Example of the Program

	M0000	K04200	K0420	1				IST	0	0	1
	IST	XAxis BUSY	XAxis Er	ror							
0	command M0001	K04200	K0420		205						
				F KU4	/L		PSO	0	0	50000	15000
	PSO command	XAxis BUSY	XAxis Mo Status(D	we XAxis we Statu	Move s(Dec						
			-10	elera	adony						END
19											
			0 0		LOADP	M0000	IST command				
			1		AND NOT	K04200	XAxis BUSY				

		2	AND NOT	K04200	XAxis BUSY	r		
		3	AND NOT	K04201	XAxis Error			
		4	IST	0		0	1	
	1	8	LOADP	M0001	PSO command			
II program		10	AND	K04200	XAxis BUSY	r		
		11	AND NOT	K0420F	XAxis Move Status(Dwei I)			
		12	AND NOT	K0420E	XAxis Move Status(Dece leration)			
		13	PSO	0		0	50000	15000
	2	19	END					

(b) Operation of the Program

- If there is the rising edge of M0000 used as the indirect starting instruction signal, positioning axis X is indirectly started with operation step 1.
- If there is the rising edge of M0001 used as the instruction signal of the positioning speed override instruction during operation, operation continues by changing the operation speed to 15,000[pps] when the position of the currently operating step reaches 50,000.

5.2.15 Inching Starting Instruction

• The inching starting instruction (INCH) is moving to the position set in the instruction at the inching speed set in the origin/manual parameter. For details, refer to 3.1.12.

							Area	as av	vailab	le								Flag	
Instruc	tion	PMK	F	L	т	с	S	z	D.x	R.x	con stan t	U	N	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)
	sl	-	1	1	-	-	-	-	-	-	0	1	-	-	-				
INCH	ax	0	1	0	-	-	-	0	-	-	0	1	-	0	-	4~7	0	-	-
	n1	0	I	0	-	-	-	0	-	-	0	-	-	0	-				
				_		(COM	MAN	D					_					
INCH	1		_	_≜				-							IN	СН	sl	ax n1	

(1) inching starting instruction (INCH)

[Area Setting]

Operand	Description	Setting range 줄	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ax	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD
n1	Position to move by inching	-2,147,483,648 ~ 2,147,483,647	DINT

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is giving the inching operation instruction to XGB built-in positioning.
- It moves to the position set in n1 at the inching speed set in the positioning parameter with respect to the axis designated as ax at the rising edge of the input condition.
- (b) Error
 - If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.

(2) Example of Use of the Instruction

(a) Example of the Program

	M0001	K04200	K0420	15			INCH	0	0	150
0	command		Outpu Inhibi	t t						
9										END
			Rung	Step	Instruction	OP 1	OP 1 comm	OP 2	OP 2	OP 3
			0	0	LOADP	M0001	INCH command			
				2	AND NOT	K04200	XAxis BUSY			
I	IL prog	gram		3	AND NOT	K04205	XAxis Output Inhibit			
_				4	INCH	0		0		150
		r	1	9	END					

- (b) Operation of the Program
- I there is the rising edge of M0001 used as the inching starting instruction signal, positioning axis X moves to position 150 at the inching speed set in the positioning origin/manual parameter.
- If the axis is in operation or inhibited from output during inching starting, it generates error code 401 and 402 respectively and no operation takes place.

5.2.16 Starting Step Number Change Instruction

• The starting step number change instruction is for changing the number of the step to be operated currently by force.

							Are	as a\	/ailab	le								Flag	
Instruc	ction	РМК	F	L	т	с	s	z	D.x	R.x	con stan t	U	N	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)
	sl	-	-	-	-	-	-	-	-	-	0	-	-	-	-				
SNS	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	-	4~7	0	-	-
	n1	0	-	0	-	-	-	0	-	-	0	-	-	0	-				
SNS	6		_			(ID						S	NS	sl	ax n1	

(1) Starting Step Number Change Instruction (SNS)

[Area Setting]

Operand	Description	Setting range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ax	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD
n1	Step number to change	1~30(standard), 1~80(advanced)	WORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is giving the starting step instruction to XGB built-in positioning.
- The current step number of the axis designated as ax at the rising edge of the input condition changes into the step set in n1.
- If the corresponding axis is operating when the starting step change instruction is executed, error code 441 is issue and the instruction is not executed. If the set value of n1 gets out of the settable range, error code 442 is issued and the instruction is not executed either.

(b) Error

• If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.

(2) Example of Use of the Instruction

(a) Example of the Program

	K04200	K042	205			SNS	0	0	D0100
SNS command	XAxis BUSY	XAx Outp Inhi	is eut bit						
									END
		0	0	LOADP	M0001	SNS command			
		0	0	LOADP AND NOT	M0001 K04200	SNS command XAxis BUSY			
ll pro	gram	0	0 2 3	LOADP AND NOT AND NOT	M0001 K04200 K04205	SNS command XAxis BUSY XAxis Output Inhibit			
IL pro	gram	0	0 2 3 4	LOADP AND NOT AND NOT SNS	M0001 K04200 K04205 0	SNS command XAxis BUSY XAxis Output Inhibit	0		D0100

- (b) Operation of the Program
- If there is the rising edge of M0001 used as the starting step change instruction signal, the current operation step number of positioning axis X changes into the step number set in D0100.

5.2.17 M Code Cancel Instruction

• M code cancel instruction (MOF) is for cancelling the M code generated during operation. For details, refer to 3.3.

(1) M code cancel instruction (MOF)

							Area	as av	vailab	le								Flag	
Instruc	tion	PMK	F	L	т	с	S	z	D.x	R.x	con stan t	U	N	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)
MOF	sl	-	-	-	-	-	1	-	-	-	0	-	-	-	-	4 7			
NOF	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	-	4~7	0	-	-
MOF				₽	_	С)						[МО	F	sl ax]

[Area Setting]

Operand	Description	Setting range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ах	Axis to cancel M code	0 (axis X) or 1 (axis Y)	WORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is giving the instruction of cancelling the M code to XGB built-in positioning.
- The M code On signal (axis X: K4203, axis Y: K4303 bit) of the axis designated as ax at the rising edge of the input condition and M code number (axis X : K428, axis Y:K438 word) are simultaneously cancelled.

(b) Error

- If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.
- (2) Example of Use of the Instruction
- (a) Example of the Program

M0001	K04200	K04201	K04	203			MOF	0	0
MOF	XAxis BUSY	XAxis Error	XAxis Code	s M e On					_
			0	0	LOADP	M0001	MOF		
				2	AND NOT	K04200	Command XAvia BLISY		
				3	AND NOT	K04200	XAxis Error		
				4	AND	K04203	XAxis M Code On		
L prog	gram j	· · · · · · · · · · · · · · · · · · ·							
L prog	gram			5	MOF	0		0	

- (b) Operation of the Program
- If there is the rising edge of M0001 used as the M code cancel instruction signal and if there is an M code in positioning axis X, the M code On signal and M code number are cancelled.

5.2.18 Current Position Preset Instruction

• The current position preset instruction (PRS instruction) is for changing the current position by force.

(1) Current Position Preset Instruction (PRS)

							Area	as av	vailab	le							Flag		
Instruc	tion	PMK F L T C S Z D.x R.x stan U N D						R	Step	Error (F110)	Zero (F111)	Carry (F112)							
	sl	-	-	-	-	-	-	-	-	-	0	-	-	-	-				
PRS	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	-	4~7	0	-	-
	n1	0	-	0	-	-	-	0	-	-	0	-	-	0	-				
PRS	5		_	Ĵ L	-		P									RS	sl	ax n1	

[Area Setting]

Operand	Description	Setting range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ax	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD
n1	Current position value to change	-2,147,483,648 ~ 2,147,483,647	DINT

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is giving the instruction of changing the current position to XGB built-in positioning.
- The current position of the axis designated as ax at the rising edge of the input condition is changed to the position set in n1 of the instruction by force.
- If the origin is not fixed, the origin fixed status (axis X:K4202, axis Y:K4304) turns On and the origin is fixed.
- If the current position preset instruction is executed, and if the axis is currently operating, error code 451 is issued and the instruction is not executed.

(b) Error

• If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.

(2) Example of Use of the Instruction

(a) Example of the Program



- (b) Operation of the Program
 - If there is the rising edge of M0001 used as the current position preset, the current position of the positioning axis X changes into 0, which has been set in the instruction, and the origin determining bit turns On.

5.2.19 Emergency Stop Instruction

• The emergency stop instruction is immediately stopping the current positioning operation and the output. For details, refer to 3.1.11.

							Are	as av	vailab	le							Flag		
Instruction		РМК	F	L	т	с	s	z	D.x	R.x	con stan t	U	N	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)
EMC	sl	-	-	-	-	-	-	-	-	-	0	-	-	-	1	4 7			
EIVIG	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	I	4~7	0	-	-
EMG					_	С			C							EM	G	sl ax	

[Area Setting]

Operand	Description	Setting range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ах	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This is for giving the emergency stop instruction to XGB built-in positioning.
- With respect to the positioning of the axis designated as ax at the rising edge of the input condition, the output immediately stops, the output stop status flag (axis X : K4205, axis Y:K4305) turns On, and error code 481 is issued.
- If the emergency stop instruction is executed, output is inhibited and the origin gets undecided, so in order to resume operation, set the origin return or floating origin or preset the current position to decide the origin.

(b) Error

• If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.

(2) Example of Use of the Instruction

(a) Example of the Program



- (b) Operation of the Program
- If there is the rising edge of M0001 used as the emergency stop instruction signal, the positioning axis X immediately stops the current operation, issues error code 481 and inhibits output.

5.2.20 Error Reset, Output Inhibition, Inhibition Termination

• The error reset instruction is resetting the current error and terminating the output inhibition.

(1) Error Reset Instruction (CLR)

							Are	as av	/ailab	le							Flag		
Instruc	tion	PMK	F	L	Т	С	S	z	D.x	R.x	Cons tant	U	Ν	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)
	sl	-	-	-	-	-	-	-	-	-	0	-	-	-	1				
CLR	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	1	4~7	0	-	-
	n1	0	-	0	-	-	-	0	-	-	0	-	-	0	-				
CLR	ł										С	LR	sl	ax n1]				

[Area Setting]

Operand	Description	Setting range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ax	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD
n1	Whether output inhibition is terminated	0 ~ 65,535	WORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is giving the error reset instruction to XGB built-in positioning.
- At the rising edge of the input condition, the error code generated in the axis designated as ax is cancelled, and if the value set in n1 is 0, only the error code is cancelled, with the output inhibition maintained. If the value set in n1 is other than 0, the output inhibition is also cancelled.

(b) Error

• If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.

(2) Example of Use of the Instruction

(a) Example of the Program

Г

	M0001	K04870					CLR	0	0	0	1
0	EMG command	XAxis Position Enable									-
	M0002	К04870					CLR	0	0	0]
7		XAxis Position Enable									
14										END]
			Rung	Step	Instruction	OP 1	OP 1	OP 2	OP 2	OP 3	٦
			0	0	LOADP	M0001	EMG				1
				2	AND	K04870	XAxis Position Enable				
	II pro	ogram		3	CLR	0		0		0	
_ 1		gram	1	7	LOADP	M0002					
							Xávie				
				9	AND	K04870	Position Enable				
				9 10	AND CLR	K04870	Position Enable	0		0	

- (b) Operation of the Program
- If the error and output inhibition are simultaneously generated due to the emergency stop, when there is the rising edge of M0001 used as the error cancel instruction signal, only the error code of axis X is cancelled but the output inhibition is not cancelled.
- If there is the rising edge of M0002 used as the error termination/output inhibition termination instruction signal, the error code of axis X and output inhibition are cancelled together.

5.2.21 Parameter/Operation Data Save

• The parameter save instruction (WRT) is permanently preserving the operation data of positioning area K changed during operation in the XGB built-in flash memory. For the relations between positioning area K and the positioning parameter, refer to 3.2.2.

(1) Parameter Save (WRT)

							Area	as av	vailab	le							Flag			
Instruc	tion	PMK	F	L	т	С	S	z	D.x	R.x	cons tant	U	Ν	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)	
	sl	-	-	-	-	-	-	-	-	-	0	I	-	-	-					
WRT	ax	0	-	0	-	-	-	0	-	-	0	-	-	0	-	4~7	4~7 0	-	-	
	n1	0	-	0	-	-	-	0	-	-	0	-	-	0	-					
WRT	WRTCOMMAND								W	/RT	sl	ax n1]							

[Area Setting]

Operand	Description	Setting range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ax	Not used in XGB	0 ~ 1(Dummy Operand)	WORD
n1	Set the parameter to save	0~2	WORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- The instruction is for permanently preserving the operation data of positioning area K in the XGB built-in flash memory.
- The operation data of positioning area K are permanently preserved in the XGB built-in flash memory according to the setting of n1 at the rising edge as follows.

Set value	0	1	2
Area k to be permanently preserved	Positioning data	High speed counter data	PID control function data

- If n1 has been set at 0, the current operation data of area K of axis X and axis Y for positioning are
 permanently preserved as the positioning parameter. If set at 1, the data of area K of all the
 channels of the high speed counter are permanently preserved as the positioning parameter. If
 set at 2, the data set in area K of 16 loop of the built-in PID are permanently preserved as the PID
 parameter.
- Although the value set as ax is the operand that does not affect the execution of WRT instruction, if it gets out of the setting range, instruction execution error flag (F110) turns On and the instruction is not executed.

(b) Error

• If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.
(2) Example of Use of the Instruction

(a) Example of the Program

Γ

0 command					WRT	0	1	0
6								END
	0	0	LOADP	M0001	WRT			
IL program	1	2 6	WRT	0		1		0

- (b) Operation of the Program
- If there is the rising edge of M0001 used as the parameter save instruction signal, the operation data of area K of positioning axis X and axis Y are permanently preserved as the positioning parameter of XGB built-in flash memory.
- If WRT instruction is executed, the previously saved positioning parameter is deleted and the parameter is changed to the operation data of the current area K.
- Be careful that if WRT instruction is executed, the scan time of the scan where the instruction has been executed because the previous positioning parameter of the flash memory is deleted and the operation data of area K is written.

5.2.22 Pulse Width Modulation

• Pulse Width Modulation is to operate On/Off output in designated Off duty rate and Output cycle.

(1) Pulse width Modulation (PWM)

							Area	as av	/ailab	le							Flag		
Instruc	tion	PMK	F	L	т	С	s	Z	D.x	R.x	cons tant	U	Ν	D	R	Step	Error (F110)	Zero (F111)	Carry (F112)
	sl	-	-	-	-	-	-	-	-	-	0	-	1	-	-				
WDT	ax	0	-	0	-	-	-	0	-	-	0	-	1	0	-	4~7 o	0	-	-
WKI	n1	0	-	0	-	-	-	0	-	-	0	-	I	0	-				
	n2	0		0				0			0			0					
PWM			ſ	l		(сомі	MAN	D				-	PWN	1	sl	ax	n1 n2]

[Area Setting]

Operand	Description	Setting range	Data size
sl	Slot No. of positioning module	XGB is fixed at 0	WORD
ax	Axis to give instruction	0 (axis X) or 1 (axis Y)	WORD
n1	Output Cycle	1~20,000(ms)	WORD
n2	Off duty rate	0~100(%)	WORD

[Flag Set]

Flag	Description	Device number
Error	If the value of ax gets out of the range	F110

(a) Function

- This instruction is for PWM output.
- While the input condition is On state, XGB postioning outputs pulse train in designated cycle time in n1 and designated Off duty rate in n2 at designated axis in ax
- During PWM output, current address don't change. Constant speed bit(X axis: K0420D, Y axis: K0430S) and Operation bit(X axis: K04200 Y axis: K4300) set On.

(b) Error

• If the value designated as ax (instruction axis) is other than 0 and 1, the error flag (F110) is set and the instruction is not executed.

- If PWM instruction is executed, other instruction do not operate. And upper/lower limit does not work
- If PWM instruction is executed, STP, EMG instruction doesn't operate. To stop output, Off the Start-up contact

• If output cycle is changed, when operating APM_PWM, it cannot be applied.

- PWM applicable version
- -XBM-DNxxS: H/W from V2.0, O/S V3.10
- -XBC-DN/DPxxH: O/S from V2.03
- -XBC-DN/DPxxSU: O/S from V1.10

(2) Example of Use of the Instruction

(a) Example of the Program

Γ

	M00000	K04201	 	 PWM	0	0	500	30
0	PWM set	XAxis Error						
								END
6			 	 				-(<u> </u>

(b) Used Device

Device	설 명
M00000	PWM output reference signal
K04201	X-axis error state

(c) Operation of the Program

• While M00000 is On which is used as output reference signal, PWM is operated.

(At this time, the X-axis is in operation or errorstatus, the instruction will not be executed.)

• If PWM executed, designated output cycle(500ms for this picture) and designated Off duty rate(30% for this picture)



5.3 Positioning Function Blocks (In case of XEC)

5.3.1 General for Function Block

In the XEC PLC, the input/output variables and their functions which are applied commonly for all the function blocks used for internal positioning are as follows..

Classification	Variable	Data Type	Description
	Iname		Request for function block execution
			- If the condition in connection with this area is
	REQ	BOOL	satisfied during the software running and $0\rightarrow 1$
			(edge or level), the function block is executed.
Input Variables	BASE USINT		 Base Number This area is for setting up the number of the base where the positioning module is mounted. (In the internal positioning of XGB, fix this to 0.)
			•Slot Number
	SLOT	USINT	- This area is for setting up the number of the slot
			where the positioning module is mounted. (In the
			internal positioning of XGB, fix this to 0.)
	AXIS	USINT	•Number of the axis in use - X-axis: 0, Y-axis: 1
			 Indicates completion of the function block execution
	DONE	DOOL	- If the function block is executed without error,
	DONE	BOOL	"1" is outputted and maintained until the next
			execution. If erroneous, "0" is outputted.
Output			•Error State Indication
Variables			- This area indicates the number of the error
	OTAT		occurred in the start-up of the function block.
	STAT	UINT	(The errors occurred during operation are
			indicated in the K area which outputs error
			codes.)

Other I/O variables excluding the common variables presented in the above table are described below.

(1) Common Error Codes for Function Block

The types and description of the common error codes which may occur in the starting up of the function blocks related with internal positioning are as follows.

Error Code	Error Type	Countermeasures
0	Function block normally executed	-
1	Base No. exceeded setting range	Set the base No. to "0" for internal positioning.
3	Slot No. exceeded setting range	Set the slot No. to "0" for internal positioning.
6	Axis range No. exceeded setting range	Adjust the axis No. within the allowable range of the function block (0: X-axis, 1: Y-axis)
10	A new function block was executed while the previous instruction has not been completed	Modify the program so that a new function block can be executed after completion of the previous instruction.
11	Set-up auxiliary input value exceeded allowable range	Adjust the value within the allowable range.

For other error code, see "Appendix 1. Error Code List."

5.3.2 Function Block for Return to Origin

•Return to Origin instruction is usually used to confirm the Origin of machine when applying power. This instruction is executed in accordance with the set-up parameters shown below (see 3.2.4 for setting-up of the return-to-Origin parameters).

(1) Return to Origin Function Block (APM_ORG)

Form	Description
- REQ DONE - -BASE STAT - -SLOT -AXIS	 This instruction is for the execution of the Origin return of the XEC-DN**H internal positioning function. At the ascending edge of the input condition, the return to Origin instruction is given to the axis defined to be the axis of the internal positioning decision. After completing Origin return, the Origin determination bit (X-axis: %KX6724,Y-axis: %KX6884) turns on and the present address is preset to the address setup with the Origin return parameter.

(2) Related Device List

Г

•The parameters related with the APM_ORG instruction and the exclusive K area devices are presented in the table below.

Pa	rameter	Exc	clusive K Ar	ea	Doto Tyroo
Title	Setting Range	X-axis	Y-axis	Attribute	Data Type
Origin returning	0: DOG/ Origin (Off)	%KX7648	%KX8288	Read/Writ	Bool
method	1: DOG/ Origin (On) 2: DOG	%KX7649	%KX8289	е	Bool
Origin returning direction	0: normal, 1: reverse	%KX7650	%KX8290	Read/Writ e	Bool
Origin address	-2,147,483,648~ 2,147,483,647[pulse]	%KD234	%KD254	Read/Writ e	DINT
Origin return high speed	1 ~ 100,000[pps]	%KD235	%KD255	Read/Writ e	UDINT
Origin return low speed	1 ~ 100,000[pps]	%KD236	%KD256	Read/Writ e	UDINT
Origin return accelerating time	0 ~ 10,000[ms]	%KW475	%KW515	Read/Writ e	UINT
Origin return decelerating time	0 ~ 10,000[ms]	%KW476	%KW516	Read/Writ e	UINT
Dwell time	0 ~ 50,000[ms]	%KW477	%KW517	Read/Writ e	UINT

(4) Exemplary Instruction

- •An example of return to Origin instruction execution is explained with the exemplary parameters and sample program as presented below.
- •The example of the APM_ORG instruction is with reference to the X-axis.
- (a) Parameter Setting

Para	meter		
Title	Value		
Origin returning method	1:DOG/HOME (On)		
Origin returning direction	1: reverse		Home Method
Origin address	0		Home Direction
Origin return at			 Home High Speed
high speed	50,000 [pps]		Home Low Speed
Origin return at	500 [au a]	Home	 Homing ACC Time
low speed	500 [pps]	Parameter	 Homing DEC Time
Origin return accelerating time	100[ms]		 DWELLTIMe
Origin return decelerating time	100[ms]		
Dwell time	100[ms]		

(b) Sample Program

	XMXO P StartHomin 9	%KX6720 ↓/↓ _POS_X_Bus y	%KX6721 / _POS_X_Err	INST APM_ORG REQ DONE -	XMX123 Done
			%MB10 BASE	BASE STAT-	XMW321 Stat
_			XMB11 Slot	SLOT	
			XMB12 AXIS	AXIS	

(c) Devices Used

Device	Description
StartHoming	Signal for X-axis Origin return start-up
%KX6720	Signal for X-axis in operation
%KX6721	X-axis in error status

(d) Program Operation

At the ascending edge of the 'starting-up Origin return' used for the Origin return start-up signal for X-axis, the APM_ORG instruction is executed. At this time, the X-axis is in operation or error status, the instruction will not be executed.

- 1) When the Origin return instruction (APM_ORG) is executed, the operation will be
- 'Origin return at high speed (50,000 pps)' accelerated reversely as set up in the Origin return parameter.
- 2) If an ascending edge of DOG signal occurs during the operation of Origin return at high speed, it will be decelerated and operated at the Origin return at low speed (500 pps) set up in the parameter. The decelerating time will be 100 ms set up in the parameter.
- 3) If the Origin signal which is an external signal enters after being changed to Origin return at low speed, the output is immediately stopped, and the Origin determination status flag (%KX6724) is turned on after the dwell time (100ms) set up in the parameter. From the interruption of the output to the turning On of the Origin determination status flag (%KX6724), there may be (dwell time + 1 scan time) of delay.
- 4) Here, the present address will be preset to '0' which is the address of the Origin set up in the parameter.



•The DOG signal and Origin signal are fixed to the contact points shown below.

	XEC-DNxxH					
	DOG Origin point					
X-axis	%IX0.0.12	%IX0.0.13				
Y-axis	%IX0.0.14	%IX0.0.15				

•Take care that, if both the DOG and Origin input contact are used as the external preset inputs of the high speed counter or as the start up signals for the external contact, the Origin detection may become incorrect.

•During returning to Origin, the present position address is not changed.

5.3.3 Function Block for Floating Origin Setting

- •In floating Origin setting, the present position is set up as the Origin by instruction, without executing mechanical operation of Origin return.
- (1) Floating Origin setting instruction (APM_FLT)

Form Description	Form
INST1 •This is the instruction for floating Origin setting in the XGB internal positioning. •APM_FLT •This is the instruction for floating Origin setting in the XGB internal positioning. •BASE_STAT •At the ascending edge of the input condition, floating Origin instruction is given the axis selected as the axis for the XGB positioning. •BASE_STAT •When this instruction is executed, the present position address becomes 0 and the Origin determination bit (X-axis: %KX6724,Y-axis: %KX6884) becomes On.	INST1 APM_FLT - REQ DONE -BASE STAT -SLOT -AXIS

•For floating Origin setting, the present position is preset to 0 and only Origin is determined. Therefore, following cautions should be taken for this instruction.

- → Before executing this instruction, check it an error has been occurred. If occurred, correct the cause of the error and reset the error with APM_RST instruction to lift the output interruption.
- → Then, set up the floating Origin and change the step No. for operation to the start-up step change instruction (APM_SNS) and start-up.

- (2) Example of Instruction
 - •The floating Origin setting instruction is explained with a sample program shown below.
 - •This exemplary APM_FLT instruction is with reference to the X-axis.
- (a) Sample Program

Γ

FixFloatin gOrigin P -	%KX6720 / _P0S_X_Bus y	%KX6721 // _POS_X_Err	INST1 APM_FLT REQ DONE -	XMX123 Done
		%MB10 BASE	BASE STAT-	XMW321 Stat
		%MB11 SLOT	SLOT	
		XMB12 AXIS	AXIS	

(b) Used Devices

Device	Description				
Floating Origin	X-axis floating reference instruction				
Instruction	signal				
%KX6720	X-axis in-operation signal				
%KX6721	X-axis error state				

(c) Program Operation

When the rising edge of the 'floating reference instruction' which was used as the X-axis floating reference instruction signal is generated, the APM_FLT instruction is executed. (However, the instruction is not executed if the X-axis is in operation or error.)
When the APM_FLT instruction is executed, the Origins is determined at the present position different from return to reference, and the Origin determination signal (X-axis: %KX6724) turns on and the present address is preset to 0.

5.3.4 Direct Start-up Function Block

- In direct start-up, the operation data such as target position or velocity is specified in the exclusive positioning instruction (APM_DST instruction), not using the setting for operation steps set up in the positioning operation data.
- (1) Direct Start-up Instruction (APM_DST)

Form	Variable	Data Type	Description
APM_DST REQ DONE	ADDR	DINT	Target address (position) • Setting range: -2,147,483,648 ~ 2,147,483,647
-BASE STAT - -SLOT -AXIS	SPEED	UDINT	Operation velocity • Setting range: 0 ~ 100,000
ADDR	DWELL	DINT	Dwell time • Setting range: 0 ~ 50,000
-SPEE	MCODE	UINT	M Code No. • Setting range: 0 ~ 65,635
-DWEL L -MCOD	POS_SPD	BOOL	Position/velocity control selectionSetting range: 0 ~ 1(0: position, 1: velocity)
- POS_ SPD	ABS_INC	BOOL	Absolute/Incremental coordinates selection • Setting range: 0 ~ 1(0: absolute, 1: Incremental)
ABS_ INC _TIME _SEL	TIME_SEL	USINT	Acceleration/deceleration time numbering • Setting range: 0 ~ 3 0: Accl./Dec. time 1, 1: Accl./Dec. time 2, 2: Accl./Dec. time 3, 3: Accl./Dec. time 4

(2) Sample Instruction

Γ

•Direct start-up instruction is explained with the sample program below.

- •This exemplary APM_DST instruction is with reference to the X-axis.
- (a) Sample Program



(b) Used Devices

Device	Description	Data Size	Exemplary Setting
Reference Decision	X-axis reference return instruction signal	BOOL	-
Direct Start	X-axis direct start-up instruction signal	BOOL	-
%KX6720	X-axis in-operation signal	BOOL	-
%KX6721	X-axis error state	BOOL	-
ADDR	Target position	DINT	100,000
SPEED	Target velocity	UDINT	30,000
DWELL	Dwell time	DINT	100
MCODE	M code No.	UINT	123
POS_SPD	Position/velocity control selection	BOOL	0
ABS_INC	Absolute/Incremental coordinates selection	BOOL	0
TIME_SEL	Acce/dec. time numbering	BOOL	0

(d) Program Operation

•APM_DST instruction is executed when the rising edge of the direct start-up used as the Xaxis direct start-up instruction signal is generated. However, if X-axis is in operation or error state, the instruction is not executed.

•If reference has not been defined at the start of DST, error code 224 is outputted to STAT_1 and the instruction is not executed.

In such case, turn on the 'reference determination' signal ON and perform reference return with APM_ORG instruction before starting-up the APM_DST instruction.

- 1) When the direct start-up instruction (APM_DST instruction) is executed, positioning operation is started as set up in the operand as shown below.
 - Because the BASE, SLOT and AXIS are 0, the built-in positioning X-axis of the base unit is started.
 - The target position is the 100,000 pulse set up in ADDR as DINT.
 - The target velocity is 30,000 pps set up in SPEED as UDINT.
 - After the positioning, the dwell time is 100ms set up in the DWEELL, and as for M code, the 123 stored in the MCODE is stored in the %KW428.
 - Because POS_SPD and ABS_INC are 0, positioning control operation is based on absolute coordinates. Since TIME_SEL is 0, the acceleration/deceleration pattern follows 1 which is the acceleration time in the basic parameters.

In particular, when the APM_DST instruction is started, positioning is controlled in absolute coordinates, operated at 30,000 pps up to 100,000 pulse position and stopped, and positioning is completed after 100ms of dwell time and the M code outputs 123.

2) When the position has been determined by direct start-up, the position determination completion signal (X-axis: %KX6722) turns on for one scan.

5.3.5 Indirect Start-up Function Block

- •In the indirect start-up, position determination operation is performed with the operation step data set up in the position determination operation data.
- (1) Indirect Start-up Instruction (APM_IST)

Form	Variable	Data Type	Description
INST - REQ DONE - -BASE STAT - -SLOT -AXIS -STEP	STEP	UINT	Operation step No. • Setting range: 0 ~ 80

(a) Function

Γ

- •This instruction provides an indirect start-up reference to the XGB built-in positioning.
- •At the rising edge of input condition, indirect start-up is executed in the axis defined to be the axis of XGB positioning.
- •When the instruction is executed, positioning is performed using the operation data in the K area according to the step No. designated to the STEP. If the STEP is 0, the operation step indicated at the step No. (X-axis: %KW426, Y-axis: %KW436 word) in the exclusive K area is executed.
- •With indirect operation instruction, diversified composition and execution of operation patterns can be implemented, such as termination, continue, continuous, single, or repeated operation, etc.

(2) Sample Instruction

•Indirect start-up instruction is explained with the sample program shown below.

1

- •The sample IST instruction is described with reference to X-axis.
- (a) Sample Program

			INST	2	
XMXO P StartHomin 9	*KX6720 // POS_X_Bus y	*KX6721 // POS_X_Err	APM_O REQ I)rg Done -	XMX123 Done
		0	-BASE 3	STAT	%MW321 Stat
		0	SLOT		
		0	AXIS		
%MX321 Р	%KX6720	%KX6721	INST APM_I REQ I	IST DONE -	XMX123
art	_PUS_X_BUS	_PUS_X_Err			DUNE
		0	-BASE 3	STAT-	XMW321 STAT
		0	SLOT		
		0	AXIS		
		XMW123 STEP	STEP		

(b) Used Devices

Device	Description	Data Size	Setting Examples
Reference Determination	X-axis reference return instruction signal	BOOL	-
Indirect Start	X-axis indirect start-up instruction signal	BOOL	-
%KX6720	X-axis in-operation signal	BOOL	-
%KX6721	X-axis error state	BOOL	-
STEP	Start-up step No.	UINT	3

Step	Coordi	Op.	Contro	Ор.	Rep.	Target	M	Accl/de	Op. Speed	Dwell
No.	nate	Pattern	I Type	Туре	Step	Pos. [Pulse]	Code	c. No.	[pls/s]	Time [ms]
3	Rel.	Term.	Pos.	Sing.	0	7,000	0	1	100	10

(c) Program Operation

 When the rising edge of the 'Indirect Start-up' uses as the X-axis indirect start reference signal is generated, the APM_IST instruction is executed. However, if X-axis is in operation or error state, the instruction is not executed.

•If the Origin has not been defined at the start-up of the APM_IST, error code 224 is outputted to the STAT_1 and the operation is not executed.

In such case, turn the 'Reference Decision' on to execute APM_ORG instruction to return to reference before starting the APM_IST instruction.

- 1) When direct start-up instruction (APM_IST instruction) is executed, positioning operation is started as set up in the instruction line operand as set forth below.
 - Since the BASE, SLOT and AXIS are 0, the built-in positioning X-axis of the base unit is started up.
 - Because the start-up step No. was appointed by 3, positioning operation is carried out with the data in the No. 3 step of the positioning operation data.

In particular, when the APM_IST instruction is stated, positioning is carried out as set up in the operation data No. 3 step in Incremental coordinates, move to 7,000 pulse position at 100 pps velocity and stop, and after 10ms of dwell time, the positioning is completed.

2) Here, as the M code was set to 0, it is not generated, and as the operation pattern is terminated, the step No. X-axis: %KW426 of the exclusive K area is changed to 4 which is the (present operation step + 1).



•In addition to using indirect start instruction, indirect start can be done using the start signal reference contact (X-axis: %KX6864, Y-axis: %KX7024) in the K area.

- → In the start-up using the start signal reference contact, the operation step is fixed to the present operation step number which is X-axis: %KW426, Y-axis: %KW436.
- → Therefore, to change operation step in starting –up using start signal reference contact, change the operation step with starting step number change instruction (APM_SNS) and then turn the start reference contact ON.

•For the details of the starting method using starting signal reference, see 3.4.2.

5.3.6 Linear Interpolation Start-up Function Block

- •In linear interpolation start-up, both X and Y axes are used in the manner that the movement paths of the 2 axes, from the start address (present stationary position) to the target address (position), is linear.
- •This method can be classified into absolute coordinates control and Incremental coordinates control. For details, see 3.1.2.
- •At the linear interpolation start-up instruction, the axis having greater movement for positioning becomes the main axis automatically. If the 2 axes move the same distance, X-axis is set up as the main axis.
- •Here, the velocity of the subsidiary axis does not follow the setting of the operation data. The operation velocity, accelerating and decelerating times, and bias velocity are calculated automatically with the formula below to perform the operation.



•The operation patterns available for linear interpolation are termination and continuous operation only. If the interpolation operation is started when the main axis is set up to be continuous, the XGB internal positioning does not trigger error and performs the operation of the main axis by changing it to be continuous. If the sub-axis is set to be continuous, it does not affect linear interpolation.

Form	Variable	Data Type	Description			
INSTT APM_LIN - REQ DONE - BASE STAT -	LIN_ AXIS	USINT	• Interpolation operation axisAxis informationY-X-axis(BIT1)axis(BIT0)ON(1)ON(1)	Operation axis X,Y		
-SLUT -LIN_ AXIS -STEP	STEP	UINT	Operation step No. • setting range: 0 ~ 80			

(1) Linear Interpolation Start-up Instruction (APM_LIN)

(2) Sample Instruction

Г

(a) Sample Program

٦				INST2	
	XMXO	%KX6720	%KX6721	APM_ORG	9WV100
	StartHomin 9	_POS_X_Bus	_POS_X_Err		DONE
_			0	-BASE STAT-	XMW321 Stat
			0	SLOT	
_			0	AXIS	
	XMX111 P Interpolca tionStart	*KX6720 // _POS_X_Bus	%KX6721	INST5 APM_LIN REQ DONE -	%MX123 Done
			0	BASE STAT	XMW321 Stat
			0	SLOT	
			%MB100 LIN_AXIS	LIN_ AXIS	
			XMW123 STEP	STEP	

(b) Used Device

Device	Description	Data Size	Example
Reference Decision	X-axis reference return instruction signal	BOOL	-
Interpolation Start	Interpolation start reference signal	BOOL	-
%KX6720	X-axis in-operation signal	BOOL	-
%KX6721	X-axis error state	BOOL	-
LIN_AXIS	Axis information	USINT	3
STEP	Operation step No.	UINT	10

Axis	Step No.	Coord inate	Op. Pattern	Contr ol Type	Ор. Туре	Rep. Step	Target Pos. [Pulse]	M Code	Accl/de c. No.	Op. Speed [pls/s]	Dwell Time [ms]
Х	10	Rel.	Term.	Pos.	Sing.	0	7,000	0	1	100	10
Y	10	Rel.	Term.	Pos.	Sing.	0	2,000	0	2	300	10

(d) Program Operation

•At the rising edge of the 'Interpolation Start-up' used as the linear interpolation start-up reference signal, the APM_LIN instruction is executed. If X-axis is in operation or error condition, it is not executed. If Y-axis is in operation, error code 242 is outputted to STAT_1 and operation is not performed.

- 1) When linear interpolation instruction (APM_LIN) is executed, linear interpolation operation is carried out as set up in the instruction operand as set forth below.
- 2) Since the BASE and SLOT are 0, the internal positioning of the base unit performs linear interpolation operation.
- 3) Since the STEP operation step No. was set to 10, main and sub-axes are automatically selected with the No. 10 operation data of the X-axis and Y-axis. In this example, since the target position of the X-axis is larger, X-axis becomes the main the Y-axis becomes the sub-axis.
- 4) Here, the velocity and the accelerating and decelerating times of the sub-axis Y do not follow the set up values but automatically calculated for operation.
- 5) in particular, with the APM_LIN instruction, the X-axis and Y-axis become main and sub-axes, respectively, and travels by (7000, 2000) in elative position basis before operation stopped.

5.3.7 Simultaneous Start-up Function Block

•Simultaneous start-up instruction (APM_SST) starts the steps of the 2 axes designated in the instruction simultaneously. For details, see 3.1.7.

(1) Simultaneous Start-up Instruction(APM_SST)

Form	Variable	Data Type	Description				
INST - REQ GASNE - -BASE STAT -	SST_ AXIS	USINT	• Simultaneous start-up operation axisAxis informationSetting ValueOperation axisY-X- axis(BIT1)ValueOperation axisON(1)ON(1)3X,Y				
-SST AXIS	X_STEP	UINT	Operation step No. • Setting range: 0 ~ 80				
-Y_ST EP	Y_STEP	UINT	Operation Step No. • Setting range: 0 ~ 80				
-Z_ST - EP	Z_STEP	UINT	Dummy variable				

(a) Function

Γ

- •This instruction gives simultaneous start-up reference to the XGB internal positioning.
- •At the rising edge of the input condition, the 2 axes of the XGB positioning are started up simultaneously. See 3.1.7 for the difference between using simultaneous start up instruction and continuous start up of 2 axes continuously with PLC ladder programming.
- •When this instruction is executed, of the XGB's positioning axes, X and Y axes are simultaneously started up using the operation data set up at X_STEP and Y_STEP for X-axis and Y-axis, respectively. Here, since the XGB internal positioning has no Z-axis, the set value of Z_STEP does not have influence on the operation.

(2) Exemplary Instruction

- •The sample program below is provided to explain the operation of the simultaneous start-up instruction.
- (d) Sample Program



(e) Used Devices

Device	Description	Data Size	Exemplary Setting
Simultaneous Start	Simultaneous start reference signal	BOOL	-
%KX6720	X-axis in-operation signal	BOOL	-
%KX6721	X-axis error state	BOOL	-
%KX6880	Y-axis in-operation signal	BOOL	-
%KX6881	Y-axis error state	BOOL	-
SST_AXIS	Axis setting	USINT	3
X_STEP	X-axis operation step No.	UINT	1
Y_STEP	Y-axis operation step No.	UINT	2
Z_STEP	Z-axis operation step No.	UINT	-

Axis	Step No.	Coord inate	Op. Pattern	Contr ol Type	Ор. Туре	Rep. Step	Target Pos. [Pulse]	M Code	Accl/de c. No.	Op. Speed [pls/s]	Dwell Time [ms]
Х	1	Coor.	Term.	Pos.	Sing.	0	7,000	0	1	100	10
Y	2	Coor.	Term.	Pos.	Sing.	0	2,000	0	2	300	10

(f) Program Operation

- •At the occurrence of the rising edge of the simultaneous start-up used for the simultaneous start-up reference signal, the APM_SST instruction is executed.
 - 1) When the simultaneous start-up instruction (APM_SST) is executed, the 2 axes start up simultaneously as set up in the instruction operands set forth below.
- 2) Since the BASE and SLOT are 0, the internal positioning of the base unit performs simultaneous start-up.
- 3) Since the operation step numbers of the X and Y axes are set to 1 and 2 respectively, the 2 axes start up simultaneously using the operation data set up in the operation steps.
- 4) Since the XGB internal positioning has no Z-axis, the Z-axis operation step No. has no influence on the operation.

5.3.8 Velocity to Position Transfer Function Block

- •Velocity/Position transfer instruction (APM_VTP) changes the axis presently in velocity control to position control and determines position to the target position. For details, see 3.1.4.
- (1) Velocity/Position Transfer (APM_VTP)

Form	Description
INST APM_VTP - REQ DONE - BASE STAT - -SLOT - AXIS	 This instruction provides XGB internal positioning with velocity/position transfer reference. At the rising edge of the input condition, the axis designated as the AXIS is transferred from velocity operation to position operation. At this time, the present position outputted from the previous velocity control operation is initialized to 0 and the system operates in absolute coordinates system to the target position.

(2) Sample Instruction

Γ

•The sample program below shows the operation of the velocity/position control transfer instruction.

(a) Sample Program



(b) Used Devices

Device	Description	Data Size	Exemplary Setting
Velocity/Position Transfer	Velocity/Position Transfer reference signal	BOOL	-
%KX6737	X-axis in-velocity-control signal	BOOL	-
%KX6721	X-axis error state	BOOL	-

(c) Program Operation

•At the occurrence of the rising edge of the velocity to position transfer used as the velocity to position transfer reference signal, the VTP instruction is executed.

•if presently under velocity control, the mode is changed to position control and the present position is preset to 0 and position control is carried out until the target position. At this time, the target position is classified as follows according to being in the indirect or direct start-up.

- 1) If presently in indirect start up, the target position of the step in operation becomes the target position after transfer from velocity to position control.
- 2) If presently in direct start up, the target position value set up as the operand with the APM_DST instruction becomes the target position after transfer from velocity to position control.
- •When using this velocity/position transfer instruction, as shown in the sample program above, use the indicator flag (X-axis: %KX6737, Y-axis: %KX6897) during velocity control to prevent instruction from being executed during position operation.

5.3.9 Position Velocity Transfer Function Block

•This APM_PTV instruction changes the axis presently in position control to velocity control. For details, see 3.1.5.

(1) Position/Velocity Transfer Instruction (APM_PTV)

Form	Description
INST1 - REQ DONE - -BASE STAT - -SLOT -AXIS	 This instruction provides position/velocity transfer reference to the XGB internal positioning. At the rising edge of the input condition, the axis designated as the AXIS is transferred from position operation to velocity operation. At this time, the present position obtained from the previous velocity control operation is not initialized to 0, and only the control mode is changed from position to velocity to continue to operate.

(2) Sample Instruction

Γ

•The sample program below shows the operation of the position/velocity control transfer instruction.

(a) Sample Program



(b) Used Devices

Device	Description		Data Size	Exemplary Setting
Position/Velocity Transfer	Position/Velocity reference signal	transfer	BIT	-
%KX6736	X-axis in-position signal	control	BIT	-
%KX6721	X-axis error state		BIT	-

(c) Program Operation

- •At the occurrence of the rising edge of the position/velocity transfer signal used as the position/velocity transfer reference signal, the PTV instruction is executed.
- •Present position control mode is changed to velocity control mode. The present position is not preset and only control mode is changed.

•After changed to velocity control, to stop operation, used the stop instruction (APM_STP).

•When using this position/velocity transfer instruction, as shown in the sample program above, use the position control indicator flag (X-axis: %KX6736, Y-axis: %KX6896) to prevent instruction from being executed during velocity operation.

5.3.10 Deceleration Stop Function Block

•This APM_STP instruction decelerates a running axis at the rate specified in the instruction to stop it. For the details of the stop function in positioning operation including deceleration stop, see 3.1.11.

(1) Decelerate to Stop Instruction (APM_STP)									
Form	Variable	Data Type	Description						
INST1 - REQ DONE - -BASE STAT - -SLOT -AXIS -DEC_ TIME	DEC_TIME	UINT	Deceleration time • Setting range: 0 ~ 65,535						

(a) Function

•This instruction executes deceleration stop to XGB internal positioning.

•At the rising edge of the input condition, the axis designated to be the AXIS decelerates and stops at the deceleration time set up in the respective operation step.

ſ

- •It the deceleration time setting is 0, the XGB positioning stops immediately without waiting the time for deceleration. In this case, the motor may make impact sound by shock, which requires caution.
- •If the DEC_TIME setting is 0, the positioning stops immediately without deceleration process. For other setting values, it stops according to the acceleration/deceleration number set up in the operation data of the respective operation step or in the APM_DST instruction, in case of indirect start-up or direct start-up, respectively.

(2) Sample Instruction

•The sample program below show the exemplary operation of the deceleration stop.

٦

(a) Sample Program

			INST	
Homing	%KX6720	%KX6721	APM_ORG	
₽	XAxis BUSY	XAxis Error	- REQ DONE	DONE
		0	BASE STAT	STAT
		0	SLOT	
		0	AXIS	
IndirectSt art	%KX6720	%KX6721	APM_IST	
₽	XAxis BUSY	XAxis Error	REQ DONE	DONE
		0	-BASE STAT-	STAT
		0	SLOT	
		0	AXIS	
		1	STEP	
	%KX6720	XKX6721	APM_STP	DOME
	XAxis BUSY	XAxis Error		DONE
		0	BASE STAT	STAT
		0	SLOT	
		0	AXIS	
		0	-DEC TIMĒ	

Device	Description	Data Size	Exemplary Setting
Return to Reference	Return to Home instruction signal	BIT	-
Indirect starting	Indirect start-up reference signal	BIT	-
Deceleration stop	Deceleration stop reference signal	BIT	-
%KX6720	X-axis in position control signal	BIT	-
%KX6721	X-axis error state	BIT	-

(b) Used Devices

(d) Program Operation

•At the rising edge of the 'Indirect Start-up' signal used as the indirect start-up reference signal, the Installation instruction is executed.

- In the above program, indirect start-up for the No. 1 step of the X-axis is executed.

•At the rising edge of the 'Deceleration Stop' signal used as the deceleration stop during operation reference signal, the deceleration stop instruction is executed in accordance with the setting of the STP instruction.

- Since the BASE, SLOT and AXIS are set to 0, deceleration stop is executed to the X-axis of the internal positioning of the base unit.

- At this time, since the deceleration time setting is 0, the STP instruction will result in immediate stop without deceleration time.

• For APM_STP instruction execution, take care of followings;

 When stopping by deceleration stop instruction, positioning operation is not completed until the set up target position. Therefore, position determination completed signal (X-axis: %KX6722, Yaxis: %KX6882) is not created, and if M code was set up, the M code signal is not turned on, neither.

- In this case, the present operation step No. is maintained.

- If indirect start-up instruction is executed again later, operation method varies by coordinate system.
 - 1) In absolute coordinate system: output the residual position output not outputted in the present operation step.

2) In Incremental coordinate system: operates for the new target position value.

- For example, if the target value of the respective step is 20,000 and was stopped at position of 15,000 by deceleration stop instruction, and if the indirect start-up instruction is executed again; in absolute coordinate system, the system travels for the rest value of 5,000 and stops at position 20,000, and; in Incremental coordinate system, the system travels 20,000 again and stops at 35,000.

5.3.11 Position Synchronization Function Block

•As shown below, this is a synchronous start-up instruction with the axis set up by the position synchronization instruction (APM_SSP) as the sub-axis according to the present position of the main axis. For details, see 3.1.8.



(1) Position Synchronization Start-up Instruction (APM_SSP)

Form	Variable	Data Type	Description
INST4 - REQ DONE - -BASE STAT -	STEP	UINT	Operation step No. • Setting range: 0 ~ 80
-SLOT -AXIS -STEP	MST_ AXIS	USINT	Main axis • Setting range: 0 ~ 1(0: X-axis, 1: Y-axis)
-MST_ AXIS -MST_ ADDR	MST_ ADDR	DINT	Target position of main axis • Setting range: -2,147,483,648 ~ 2,147,483,647

(a) Function

 This instruction executes position synchronization start-up to the XGB internal positioning.

•At the rising edge of the input condition, synchronized start-up instruction is executed, where, the axis designated as AXIS is the sub-axis and that designated in the MST_AXIS is the main axis.

- •When the instruction is executed, the sub-axis does not out real pulses (at this time, the inoperation-state flag (X-axis: %KX6720, Y-axis: %KX6880) of the sub-axis is ON), and the STEP of the sub-axis starts up when the main axis MST_AXIS is at the position set up in the MST_ADDR.
- •The position synchronization instruction can be executed only when the Origins for both of the main axis and sub-axis have been determined. if the Origin of the main axis or sub-axis has not been determined at the start of the APM_SSP instruction, error code 346 or 344, respectively, will be outputted to STAT.
- •When using this instruction, set up the main axis and sub-axis with different axis. Otherwise, error code 347 will be outputted to STAT.
- •To cancel the execution of position synchronization instruction after it is given, execute the stop instruction (APM_STP) to the sub-axis.

(2) Sample Instruction

Γ

•the sample program below shows the operation of the position synchronization start-up instruction.

(a) Sample Program

 In the sample program below, where the Y-axis is the sub-axis and X-axis is the main axis, when the main axis position is at 100,000, the operation data in the No. step of the sub-axis is started up.

						INS	ST3	
	PositionSy nchronizat ion P	XKX6880 ↓/↓ YAxis BUSY	XKX6881 ──┤/├── YAxis Error	%KX6724 │	XKX6884 ──┤	APM_ REQ	.SSP DONE -	DONE
					0	BASE	STAT	STAT
					0	SLOT		
					1	AXIS		
					1	STEP		
					0	MST AXIS		
					100000	-MST ADDR		
_	1.11.10			INST4				
	art P	XKX6720 / XAxis BUSY	%KX67 21 │/│ XAxis Error	APM_IST — REQ DONE -	DONE1			
			0	-BASE STAT	STAT1			
			0	SLOT				
			0	AXIS				
			1	STEP				

(b) Used Devices

Device	Description	Data Size	Exemplary Setting
Position Sync.	Position synchronization reference signal	BIT	-
Indirect start	Main axis indirect start reference signal	BIT	-
%KX6880	Sub-axis (Y-axis) position being controlled signal	BIT	-
%KX6881	Sub-axis (Y-axis) in error state	BIT	-
%KX6724	X-axis reference determined state	BIT	-
%KX6884	Y-axis reference determined state	BIT	-
%KX6720	Main axis (X-axis) position being controlled signal	BIT	-
%KX6721	Main axis (X-axis) in error state	BIT	-

(c) Program Operation

•At the rising edge of the 'position synchronization' signal used as the position synchronization reference signal, APM_SSP instruction is executed.

At this time, since the AXIS is 1 (Y-axis), Y-axis is the sub-axis and as the MST_AXIS is 0 (X-axis), X-axis is the main axis.

•At the rising edge of the 'indirect start-up' signal which is the indirect start-up reference signal of the main axis, No. 1 step of the X-axis starts indirectly.

•During operation, when the present position of the main axis reaches 100,000 [Pulse] set up in the MAST_ADDR of the APM_SSP instruction, the Y-axis which is the sub-axis starts up the operation step (No. 1) set up in the STEP of the APM_SSP instruction.

•If the axis set up as the main axis has been started up as the sub-axis of position synchronization, error code 349 is outputted to STAT and the position synchronization instruction is not executed.

In the example shown below, at the rising edge of the 'Y-axis position synchronization,' position synchronization instruction is executed with the Y-axis as the sub-axis and the X-axis as the main axis. In this state, if a rising edge of the 'X-axis position synchronization' signal occur, the position synchronization instruction reference is generated with the X-axis as the sub-axis and the Y-axis as the main axis. In this case, because the Y-axis which is used as the main axis has already been started up as the sub-axis of the position synchronization instruction, the X-axis outputs error code 349 to the STAT1 and is not started.

	INS	ST5
AxisYposit ionSynchro nization P	APM_ REQ	.SSP DONE -
0 -	BASE	STAT -
0 -	SLOT	
1 -	AXIS	
1	STEP	
0 -	MST AXIS	
100000 -	MST ADDR	
		TC
AxisXPosit ionSynchro nization P	INS APM_ REQ	ST6 .SSP DONE -
AxisXPosit ionSynchro nization P	INS APM_ REQ BASE	STG .SSP .DONE - .STAT -
AxisXPosit ionSynchro nization P 0 -	INS APM_ REQ BASE SLOT	STG SSP DONE - STAT -
AxisXPosit ionSynchro nization P 0 0	INS APM REQ BASE SLOT AX1S	STG SSP DONE - STAT -
AxisXPosit ionSynchro nization P 0 - 0 - 0 - 1	APM_ REQ BASE SLOT AX1S STEP	ST6 SSP DONE - STAT -
AxisXPosit ionSynchro nization P 0 0 0 0 1	APM_ REQ BASE SLOT AXIS STEP	STAT -
AxisXPosit ionSynchro nization P 0 0 0 1 1 1 100000	INS APM_ REQ BASE SLOT AXIS STEP MST ADDR	STAT -

Γ

5.3.12 Speed Synchronization Function Block

•This instruction (APM_SSSB) is for the operation at synchronized speed at the preset rate with the axis set up in the instruction as the sub-axis when the main axis is started up. For details of speed synchronization function, see 3.1.8.

Form	Variable	Data Type	Description				
			Main axis setting range				
INST8				Setting Value	Main Axis Setting	Setting Value	Main Axis Setting
APM_SSS REQ DONE		USINT		0	X-axis	5	High Speed Counter Ch3
	MST_			1	Y-axis	6	High Speed Counter Ch4
-DACE STATE	AXIS			2	High Speed Counter Ch0	7	High Speed Counter Ch5
-SLOT				3	High Speed Counter Ch1	8	High Speed Counter Ch6
-AXIS				4	High Speed Counter Ch2	9	High Speed Counter Ch7
-MST AXIS -MST_ RAT -SLV_ RAT	SLV_RAT	UINT	Sp • \$	beed ratio of s Setting range:	ub-axis 1 ~ 10,000(0.01	~ 100.00%	6)
	DELAY	USINT	Su • S	ıb-axis delay t Setting range:	ime 1 ~ 10(1 ~ 10m	s)	

(1) Speed Synchronization Start-up Instruction (APM_SSSB)

(a) Function

- •This is the instruction for executing speed synchronized start-up to the XGB internal positioning.
- •At the rising edge of the input condition, speed position synchronized start-up instruction is executed with the AXIS as the sub-axis and the axis designated in the MST_AXIS as the main axis.
- •When the instruction is executed, the sub-axis does not output real pulse (at this time, the inoperation-state flag (X-axis: %KX6720, Y-axis: %KX6880) of the sub-axis is ON), and when the main axis MST_AXI starts, the sub-axis starts at the speed synchronization ratio set up in the AXIS.
- •The synchronization ratio which can be set up in the SLV_RAT is $0.01\% \sim 100.00\%$ (setting value 1 ~ 10,000). If the setting exceeds this range, error code 356 is created.
- •The DELAY time is the time required for the speed of the sub-axis to reach the present speed of the main axis. In the XGB internal positioning function, for speed synchronization control, the present speed of the main axis is detected at every 500 μ s to control the speed of the sub-axis. Here, if the speed of the sub-axis is synchronized to that of the main axis without delay time, the motor and drive may receive excessive impact.

For example, when the speed synchronization ratio is 100.00% and delay time is 5[ms], and if the present speed of the main axis is 10,000[pps], XGB internal positioning adjusts the speed of the sub-axis so that it's speed is the same as that of the main axis after 5[ms] at every $500[\mu s]$.

When the delay time is longer, the synchronization time delay between the main and sub-axes is longer but the output pulse is more stable. If there is the possibility that the motor may lose synchronism, set the delay time longer.

•The range of the delay time that can be set up in DELAY n2 is 1 ~ 10[ms]. If this range is exceeded, error code 357 is generated.

- •The range of the main axis setting of MST_AXIS is 0 ~ 9 as shown below. If this range is exceeded, error code 355 is generated.
- •To cancel the execution of speed synchronization instruction, run the stop instruction (APM_STP) for the sub-axis.
- •Speed synchronization control can be executed even when the Origin of the sub-axis has not be determined.
- In speed synchronization, the sub-axis is synchronized to the main axis. Therefore, even if the control mode of the sub-axis is set up position control, it repeats start and stop according to the operation of the main axis, and the direction of rotation of the sub-axis is the same as that of the main axis.
- •If the M code of the sub-axis is ON at the execution of the speed synchronization instruction, error code 353 is outputted to STAT.

(2) Sample Instruction

Γ

•The program below is to show exemplary operation of speed synchronization start instruction.

(a) Sample Program

•In the sample program below with the Y-axis as the sub-axis and the X-axis as the main axis, the speed synchronization start-up is executed at the synchronization ratio of

100.00[%] and delay time of 10[ms] when the main axis is started-up.



(b) Program Operation

- •At the rising edge of the 'Y-axis speed synchronization' signal used as the speed synchronization reference signal, the APM_SSSB instruction is executed. Here, since the AXIS is 1 (Y-axis), Y-axis is the sub-axis and as the MST_AXIS is 0 (X-axis), X-axis is the main axis.
- •At the rising edge of the 'indirect start-up' signal which is the indirect start-up reference signal, the No. 1 step of the X-axis starts indirectly.
- •When the main axis starts up, Y-axis is started-up at the synchronization ratio of 100.00[%] set up in the third operand of the APM_SSSB instruction and synchronized to the main axis by 10[ms] of delay time.

5.3.13 Position Override Function Block

- •The position override instruction (APM_POR) changes the target position of the axis which is presently in positioning operation to the target position set up in the instruction. For details, see 3.1.10.
- (1) Position Override Instruction (APM_POR)

Form	Variable	Data Type	Description
INST2 APM_POR - REQ DONE - -BASE STAT - -SLOT -AXIS -POR_ ADDR	POR_ ADDR	DINT	Position • Setting range: -2,147,483,648 ~ 2,147,483,647

(a) Function

Γ

- •This instruction provides position override reference to the XGB internal positioning.
- •At the rising edge of the input condition, the axis designated as AXIS changes its target position to the position set up in the POR_ADDR during operation.
- •Position override instruction is available for the acceleration, constant speed, and deceleration sections of operation patterns. If position override instruction is executed during dwelling, error code 362 is outputted to STAT.

(2) Sample Instruction

•The sample program below show exemplary operation of position override.

(c) Sample Program



- (d) Program Operation
- •At the rising edge of the 'indirect start-up' signal which is the reference signal for indirect start-up, positioning X-axis is started up indirectly by operation step No. 1.
- •If the rising edge of the 'position override reference' signal used as the reference signal for the position override instruction occurs before the present position reaches 100,000[Pulse] during operation, the operation continues by changing the target position of the step presently in operation to 100,000. Take care that the target position value of the No.1 step set up with the positioning parameter itself is not changed.
- If position override instruction is executed after the present position has passed 100,000[Pulse], deceleration stop occurs.
- •If position override instruction is executed while the operation state is in dwelling, error code 362 is outputted to STAT. To prevent this, the start-up contact should be connected with the X-axis dwell status flag as normally closed (B contact) in the program.
5.3.14 Speed Override Function Block

•Speed override instruction (APM_SOR) changes the operating speed of the axis presently in positioning operation to the speed set up in the instruction line. For the details of speed override function, see 3.1.10.

Form	Variable	Data Type	Description
INST3 APM_SOR - REQ DONE - -BASE STAT - -SLOT -AXIS -SOR_ SPD	SOR_ SPD	UDINT	Operating Speed • Setting range: 1~100,000

(1) Speed Override Instruction (APM_SOR)

(a) Function

Γ

- •This instruction provides speed override reference to the XGB internal positioning.
- •At the rising edge of the input condition, the axis designated to be AXIS changes its operating speed to the speed set up in SOR_SPD.
- •Speed override instruction is available for the acceleration, constant speed, and deceleration sections of operation patterns. If speed override instruction is executed during deceleration or dwelling, error code 377 is outputted to STAT, and the present operating step does not stop and continues running.

(2) Sample Instruction

•The sample program below shows exemplary operation of speed override instruction.

(c) Sample Program



- (d) Program Operation
- •At the rising edge of the indirect start-up signal used as the reference for indirect start up signal, positioning X-axis is started up indirectly by the operating step No. 1.
- If the rising edge of the 'speed override reference' signal used as the reference signal for the speed override instruction occurs during operation, the operation continues by changing the operating speed of the present operation step to 10,000[pps]. Take care that the speed value of the No.1 step set up with the positioning parameter itself is not changed.
- If speed override instruction is executed while the operation state is in deceleration or dwelling, error code 377 is outputted to STAT. To prevent this, the start-up contact should be connected with the X-axis dwell status flag as normally closed (B contact) in the program.

5.3.15 Positioning Speed Override Function Block

•This instruction (APM_PSO) changes the operating speed of the axis which is presently in positioning operation, at the position specified in the instruction line. For the details of this function, see 3.1.10.

(1)	Positioning	Speed	Override	Instruction	(APM_	_PSO)
-----	-------------	-------	----------	-------------	-------	-------

Form	Variable	Data Type	Description
INST - REQ DONE - -BASE STAT - -SLOT	PSO_ADDR	DINT	Target position • Setting range: -2,147,483,648 ~ 2,147,483,647
- AXIS - PSO_ ADDR - PSO_ SPD	PSO_SPD	UDINT	Operating Speed • Setting range: 1~100,000

(a) Function

Γ

- •This instruction provides positioning speed override reference to the XGB internal positioning.
- •At the rising edge of the input condition, the axis designate as the AXIS executes positioning speed override. When the present position reaches the points set up in the PSO_ADDR during operation, present speed is overridden by the speed set up by the PSO_SPD.
- •This instruction is available in the acceleration and constant speed sections of the operation patterns. If this override is executed during deceleration or dwelling, no error code is generated but the instruction is not executed.

(3) Sample Instruction

(a) Sample Program



(b) Program Operation

•At the rising edge of the 'Indirect Start-up' signal used as the indirect start-up reference signal, the positioning X-axis is started indirectly by operation step No.1.

•If the rising edge of the 'PSO start reference signal, which is used as the reference signal for the positioning speed override instruction, occurs during operation, operation continues by changing the speed to 15,000[pps] at the moment when the position of the present operation step reaches 50,000.

5.3.16 Inching Start Function Block

Γ

•This instruction (APM_INC) is for the movement at the inching speed set up by the positioning Origin/manual parameter in the instruction. For details about inching operation, see 3.1.12.

Form	Variable	Data Type	Description
INST - REQ DONE - -BASE STAT - -SLOT -AXIS - INCH _VAL	INCH_VAL	DINT	Inching Distance • Setting range: -2,147,483,648 ~ 2,147,483,647

(1) Inching Start Instruction (APM_INC)

(a) Function

- •This instruction provides inching operation reference to the XGB internal positioning.
- •At the rising edge of the input condition, the axis designated as AXIS moves by the distance and speed set up by the INCH_VAL and positioning parameter, respectively.

(2) Sample Instruction

(a) Sample Program

٦				INST2	
	Start INCHI NG P	XKX6720 ↓/↓ XAxis BUSY	XKX6725 ──┤/├── XAxis Output	APM_INC REQ DONE	DONE
_			Inhibit		
			0	BASE STAT	STAT
			0	SLOT	
			0	AXIS	
			150		

- (b) Program Operation
- •At the rising edge of the inching start signal used as the reference signal for inching start, the positioning X-axis moves by 150 at the inching speed in Incremental coordinate set up in the positioning Origin/manual parameter.
- •At inching start, if the axis is in operation or being prohibited from output, error codes 401 and 402, respectively, are outputted to STAT and does not operate.

5.3.17 Start Step Number Change Function Block

•This instruction (APM_SNS) changes the number of the step to be operated.

Form	Variable	Data Type	Description
INST APM_SNS - REQ DONE - -BASE STAT - -SLOT -AXIS -STEP	STEP	UINT	Operation Step No. • Setting range: 1 ~ 80

(1) Start Step No. Change Instruction (APM_SNS)

(a) Function

- •This instruction provides start step change reference to the XGB internal positioning.
- •At the rising edge of the input condition, the present step number of the axis designated to be AXIS is changed to the step set up in the STEP.
- •If the axis has been in operation when this instruction is given, error code 441 is generated and the instruction is not executed. If the setting value in the STEP exceeds allowable range, error code 442 is generated and the instruction is not executed.

(2) Sample Instruction

(a) Sample Program

-		0			
	ChangeStep P	%KX6720 ↓/↓ XAxis BUSY	XKX6725 ──┤/├── XAxis Output Inhibit	INST3 APM_SNS REQ DONE -	DONE
			0	-BASE STAT-	STAT
			0	SLOT	
			0	AXIS	
			STEP	STEP	

(b) Program Operation

•At the rising edge of the 'operation step change' signal used as the reference signal, the present operation step No. of the positioning X-axis is changed to the step No. set up in the STEP.

5.3.18 M Code Release Function Block

Г

- •This instruction (APM_MOF) cancels the M code generated during operation. For details of the M code, see 3.3.
- (1) M Code Release Instruction (APM_MOF)

Form	Description
INST1 - REQ DONE - -BASE STAT - -SLOT -AXIS	 This instruction provides M code release reference to the XGB internal positioning. At the rising edge of the input condition, the M code On signal (X-axis: %KX6723, Y-axis: %KX6883) and the M code number (X-axis: %KW428, Y-axis: %KW438) of the axis designated as AXIS are cancelled.

(2) Sample Instruction

(a) Sample Program

CancelMood				INST4	
e	XKX6720	%KX6721	%KX6723	APM_MOF	
1r	XAxis BUSY	XAxis Error	XAxis M Code On		DONE
			0	BASE STAT	STAT
			0	SLOT	
			0	AXIS	

(b) Program Operation

•At the rising edge of the 'M code release' signal used as the reference signal, and if M code is generated to the positioning X-axis, the ON signal and the number of the M code are cancelled.

5.3.19 Present Position Preset Function Block

•This instruction (APM_PRS) changes present position.

(1) Present Position Preset Instruction (APM_PRS)

Form	Variable	Data Type	Description
INST - REQ DONE - -BASE STAT - -SLOT -AXIS -PRS_ ADDR	PRS_ADDR	DINT	Preset Value • Setting range: -2,147,483,648 ~ 2,147,483,647

(a) Function

- •This instruction provides position change reference to the XGB internal positioning.
- •At the rising edge of the input condition, the present position of the axis designated to be AXIS is changed to the position set up at the PRS_ADDR in the instruction line.
- •At this time, if the Origin has not been defined, the Origin determination status (X-axis: %KX6724, Y-axis: %KX6884) becomes ON.
- •It the axis has been in operation when this instruction is given, error code 451 is outputted to STAT and the instruction is not executed.
- (2) Sample Instruction
- (a) Sample Program

Preset Preset	%KX6720 ↓/↓ XAxis BUSY	IN: APM <u>.</u> REQ	ST5 _PRS _DONE	- Done
	0	BASE	STAT	STAT
	0	SLOT		
	0	AXIS		
	0	-PRS ADDR		

- (b) Program Operation
- At the rising edge of the 'preset' signal, the position of the positioning X-axis is changed to 0 set up in the instruction and the reference determination state bit is ON.

5.3.20 Emergency Stop Function Block

Γ

•Emergency stop instruction immediately stops present operation and cuts off output. For details of this function, see 3.1.11.

(1) Emergency Stop Instruction (APM_EMG)

Form	Description
INST1 - REQ DONE - -BASE STAT - -SLOT	 Provides emergency stop reference to the XGB internal positioning. At the rising edge of the input condition, both internal positioning X-axis and Y-axis are stopped without deceleration process, status flag (X-axis: %KX6725, Y-axis: %KX6885) is On, and error code 481 is outputted to STAT. When this instruction has been executed, output is cut off and Origin is undetermined. To resume operation, Origin must be determined by reference return, floating reference setting, or present position preset function.

(2) Sample Instruction

(a) Sample Program

EMGStop P	XKX6720	IN: APM REQ	ST6 _EMG DONE -	DONE
	0	BASE	STAT-	STAT
	0	SLOT		

(b) Program Operation

•At the rising edge of the 'emergency stop' signal used as the reference signal, both X-axis and Yaxis of the XEC internal positioning stop operation immediately. Error code 481 is generated and output is cut off.

5.3.21 Error Reset, Output Cut-off Release Function Block

•This instruction reset present error and releases output cut-off.

(1) Error Reset Instruction (APM_RST)

Form	Variable	Data Type	Description
INST - REQ DONE - -BASE STAT - -SLOT -AXIS - INH_ OFF	INH_OFF	BOOL	Output cut-off release • Setting range: 0 ~ 1 (0: output cut-off not released, 1: output cut-off released)

(a) Function

- •This instruction provides error reset reference to the XGB internal positioning.
- •At the rising edge of the input condition, the error code applied to the axis designated as the AXIS is released. At this time, if the setting value of the INH_OFF is 0, only the error code is released but the output cut-off is maintained, and it the value is 1. output cut-off is released too.

(2) Sample Instruction

Γ

(a) Sample Program

		INST7	
CancelErro r P	XKX7792	APM_RST	DONE
1' 1	XAxis Position Enable		
	0	BASE STAT	STAT
	0	SLOT	
	0	AXIS	
	0	- INH_ OFF	
Error Cape			
elProhibit ingOutput IP	%KX7792 ↓↓ XAxis Position Enable	APM_RST - REQ DONE -	DONE1
	0	BASE STAT	STAT1
	0	SLOT	
	0	AXIS	
	1	- INH_ OFF	

- (b) Program Operation
- •When error and output cut-off have been applied by emergency stop, at the rising edge of the 'error reset' signal which is used as the reference signal for error reset, the error code of the positioning X-axis only is released and the output cut-off is not released.
- •At the rising edge of the 'Error_Output Cut-off Release' signal used as the reference signal, both the error code and output cut-off of the positioning X-axis are released.

5.3.22 Parameter/Operation Data Write Function Block

•Parameter Write instruction (APM_WRT) writes the operation data, which is changed during operation, of the positioning exclusive K area permanently in the built-in flash memory of the XGB. For the relation between the positioning exclusive K area and the positioning parameter, see 3.2.2.

Form	Variable	Data Type	Description												
INST			 This instruction positioning for positioning for positioning for position of the exclusive At the rising edge saves the operation of the n1 settir permanently. 	on provides reference to the XGB interna or permanent preservation of the operation data ive K area. edge of the input condition, as shown below peration data of the exclusive K area respective etting in the flash memory device of the XGB											
APM_WRT			Setting Value	0	1	2									
-BASE STAT												K area to be Position preserved Da	Positioning Data	High Speed Counter Data	PID Control Data
-SLOT -AXIS -WRT AXIS	WRT_AXIS	USINT	•If WRT_AXIS is exclusive K area axis are permane If it is set to 1, the the high speed of the high speed of If it is set to 2, the internal PID's 10 parameters.	set to 0, the a of the pos ently stored a he setting da counter chan ounter param he setting da 6 loop are s	set to 0, the present operation data in the of the positioning functions X-axis and Y- ntly stored as the positioning parameters. e setting data in the exclusive K area of all ounter channels are stored permanently as ounter parameters. e setting data in the exclusive K area in the b loop are stored permanently as the PID										
			•At this time, although the value set up with AXIS is operand which does not have influence on the executi the APM_WRT instruction, however, be careful that, exceeds the setting range $(0 \sim 1)$, 11 is outputted to 3 and the instruction is not executed.												

(1) Parameter Write Instruction (APM_WRT)

(2) Sample Instruction

Γ

(a) Sample Program



- (b) Program Operation
- •At the rising edge of the 'store positioning data' signal used as the parameter saving reference signal, the operation data in the exclusive K area of the positioning functions X-axis and Y-axis are permanently stored as the parameters in the XGB's flash memory.

•Take care that, when the APM_WRT instruction is executed, the positioning parameters previously stored are replaced with the operation data of the exclusive K area.

•Take care that when APM_WRT instruction is executed, the existing positioning parameters in the flash memory are replaced with the operation data in the exclusive K area, therefore, the scan time of the scan in which the instruction has been executed becomes longer.

5.3.23 Pulse Width Modulation

• Pulse Width Modulation is to operate On/Off output in designated Off duty rate and Output cycle.

Form	Variable	Data Type	Description
INST1 -REQ DONE- -SLOT STAT-	FREQ	WORD	Output cycle • Setting rage: 1~20,000(ms)
-FREQ -DUTY	DUTY	WORD	Off duty rate • Setting range: 1 ~100(%)

(1) Pulse Width Modulation (APM_PWM)

- (a) Fuction
 - This instruction is for PWM output.
 - While the input condition is On state, XGB postioning outputs pulse train in designated cycle time in FREQ and designated Off duty rate in DUTY at designated axis in AXIS
 - During PWM output, current address don't change. Constant speed bit(X-axis: %K%6733, Y-axis: %KX6893) and Operation bit(X-axis: %KX6720, Y-axis:%KX6880) set On.
- (2) Example of Use of the Instruction
 - (a) Sample Program

	 	INST	
%MX0 PWM set	%KX6721	APM_PWM REQ_DON- E	DONE
	0	SLO STAT	STAT
	0	AXIS	
	500	FRE	
	30	DUT Y	

(b) Used Device

Device	설명
MX0	PWM output reference signal
%KX6721	X-axis error state

(c) Operation of the Program

• While MX0 is On which is used as output reference signal, PWM is operated.

(At this time, the X-axis is in operation or errorstatus, the instruction will not be executed.)

• If PWM executed, designated output cycle(500ms for this picture) and designated Off duty rate(30% for this picture)



- If APM_PWM instruction is executed, other instruction do not operate. And upper/lower limit does not work
- If APM_PWM instruction is executed, STP, EMG instruction doesn't operate. To stop output, Off the Start-up contact

• If output cycle is changed, when operating APM_PWM, it cannot be applied.

- · PWM applicable version
- -XEC-DN/DPxxH: O/S from V1.50
- -XEC-DN/DPxxSU: O/S from V1.00

Chapter 6 Positioning Monitoring Package

6.1 Introduction to Positioning Monitoring Package

You can monitor the status of XGB PLC built-in positioning and carry out test operation without the program by changing the parameters and operation data if you use the XGB monitoring package.

6.1.1 Introduction of Positioning Monitoring Package

- You can easily and conveniently monitor the current positioning operation or change the parameter or operation data by using the following positioning monitoring package with XGB PLC connected to XG5000.
- If you use the positioning monitoring package, you can easily carry out test operation without the program, adjust the parameter and operation data, and permanently save it in PLC after the adjustment.
- This chapter describes how to run the XGB positioning monitoring package.
- XGB positioning monitoring package is available with over XG5000 V1.2 (over V2.2 for XBCH, over V3.0 for XECH, over V3.4 for XBCS, over V3.7 for XECS), and it is carried out in the following sequence. (This manual has been made by using XG5000 V2.2)
- (1) Opening the Monitoring Package
 - Select 'Monitoring' → 'Special Module Monitoring' with XGB PLC connected to XG5000, the special module monitoring display is invoked as follows.

(If XGB is not connected to XG5000, 'Special Module Monitoring' is inactivated in the 'Monitoring' menu. Thus make sure that XGB is connected to XG5000 before using positioning monitoring.)



• When you want to carry out the positioning monitoring package, double click on the positioning module or select the positioning module, and then click on the 'Monitoring' button at the bottom. And the positioning monitoring package is started as follows.

			-	Survey and				- A A A A A A A A A A A A A A A A A A A
/								
Command	🖌 X-Axis	🗌 Y4	lucis	^	Signal/Axis	🗹 X-Axis	V-Axis	A 1
Indirect Start	Step	1	Run		Position			
Error Reset	1: Reset/Output	it Enable	Run		Speed			
	Pos	0 pls			Step No.			
	Spd	1 pls/s			Error Code			
	Dwell	0 ms	1		M Code			
Direct Start	Mcode	0	Bun		BUSY Decition Complete			
	Acc/Dec No.	No.1			M Code ON			
	Cordinate	ARS			M Lode UN Origin Fix			
	Control	POS			Output Johibit			
M Code OFF	Consor	100	Bun		Stop			
Dee Stee	Time	0.00			Upper Limit			
EMC Stop	THIPS	0 IIIS	- Num		Lower Limit			
EMG Stop	Cod	1 als de			EMG			
Spd Uvernde	Spa	1 pis/s	Hun		CW/CCW			
Pos Override	Pos	U pls	Hun		Operation Status			
Spd Override with	Pos	0 pls	Run	_	Control Pattern			
Position	Spd	1 pls/s			Home Return			
Home Return			Run		Position Sync			
FLT			Run		Speed Sync			
Position Preset	Pos	0 pls	Run		JOG High Speed			
Start Step No.	Step	1	Run		JOG Low Speed			
Inching	Value	0 pls	Run		Inching			
JOG	(()		>>		Ext. Signal/Axis	X-Axis Signal	Y-Axis Signal	
IOG Stop				~	Upper Limit (P1/P3)			≤/
Monitoring Position	Parameter X-Axi	s Data Y-A	xis Data	Y				
	Position command window Status monitoring window							

• The menu and function of the positioning monitoring package are as follows.

Items	Functions	Remark
Monitoring	Monitors the positioning of the axis or gives commands.	
Position Parameter	Checks and modifies the positioning parameter of each axis.	
X-Axis Data	Checks and modifies the operation data of axis X.	
Y-Axis Data	Checks and modifies the operation data of axis Y.	
Start Monitor	Carried out positioning monitoring.	
Stop Monitor	Stops positioning monitoring.	
Write PLC	Permanently saves the changed parameter and operation data in PLC.	WRT function
Save Project	Saves the changed parameter and operation data in XG5000 project.	

• For details of each menu, refer to 6.2.

Γ

6.2 Menus and Functions of Positioning Monitoring

The following is the function and use of the menus of the XGB monitoring package.

6.2.1 Monitoring and Command

- The positioning monitoring package consists of the command window for positioning test operation and positioning monitoring window as shown above.
- If you click on the 'Start Monitor' button at the left bottom of the package, the monitoring and command function is activated to make various commands and current status monitoring functions available.
- If you start the command on the left, the corresponding functions are activated without the program and the status is displayed on the monitoring window on the right.

-	Positioning								? 🛛
					_				
	Command	🗹 X-Axis	🗌 🗌 Y-4	ixis	^	Signal/Axis	🗹 X-Axis	Y-Axis	<u>></u>
	Indirect Start	Step	1	Run		Position	0	0	
	Error Reset	1: Reset/Outpu	it Enable	Run		Speed	0	0	
		Pos	0 pls	\square		Step No.	1	1	
		Spd	1 pls/s			Error Code	0	492	
		Dwell	0 ms			M Lode	U	U	
	Direct Start	Mcode	0	Run		BUST Position Complete			
		Acc/Dec No.	No.1			M Code ON			
		Cordinate	ABS			Origin Eix			
		Control	POS			Output Inhibit		ON	
	M Code OFF			Run		Stop			Ξ
	Dec. Stop	Time	0 ms	Run		Upper Limit		ON	
	EMG Stop	<u>.</u>		Run		Lower Limit		ON	
	Spd Override	Spd	1 pls/s	Run		EMG			
	Pos Override	Pos	O pls	Run		CW/CCW	CW	CW	
	Spd Querride with	Pos	0 pls	m		Uperation Status			
	Position	Spd	1 pls/s	Run		Lontrol Pattern			
	Home Beturn			Bun		Position Sunc			
	FLT			Bun		Sneed Sync			
	Position Preset	Pos	0 pls	Bun		JOG High Speed			
	Start Sten No	Sten	1	Bun		JOG Low Speed			
	Inchina	Value	0 pls	Bun		Inching			
	.106					Ext. Signal/Axis	X-Axis Signal	Y-Axis Signal	
	IOG Stop			<u> </u>	~	Upper Limit (P1/P3)	ON	OFF	
-	Monitoring Position Parameter X-Axis Data Y-Axis Data								
	Start Monitor Stop Monitor Write PLC Save Project Close								

(1) Positioning Command

- The commands available in the positioning monitoring package are as follows.
- To execute an command, enter the setting of the command, and click on the 'Run' button (「<<」, 「<」, 「||」, 「>」, 「>」, 「>>」 during jog operation).

Item	Description	Command	Remark
Indirect start	Direct start with the operation step set in the monitoring window	IST	5.2.4
		APM_IST	5.3.5
Error reset	Resets the error code and output inhibition in case of an error	CLR	5.2.20
		APM_RST	5.3.21
Direct start	Directly starts with the position, speed, dwell, M code, acc./dec. number, coordinates and control method set in the monitoring window	DST APM_DST	5.2.3 5.3.4
M code OFF	Cancels the M code On signal and M code number	MOF APM_MOF	5.2.17 5.3.18
Dec. stop	Carries out deceleration stop in the set deceleration time	STP APM_STP	5.2.9 5.3.10
EMG stop	Stops the operation of the axis and inhibits pulse output	EMG APM_EMG	5.2.19 5.3.20

Item	Description		Command	Remark
Spd override	Overrides the speed at the set speed value		SOR APM_SOR	5.2.13 5.3.14
Pos override	Overrides the position at the set position value		POR APM_POR	5.2.12 5.3.13
Spd override with position	Changes the operation speed at the speed value set in the position	set	PSO APM_PSO.	5.2.14 5.3.15
Home return	Conducts home return as the home return method set in positioning parameter	the	ORG APM_ORG	5.2.1 5.3.2
FLT	Sets the current position as the fixed home		FLT APM_FLT	5.2.2 5.3.3
Position preset	Presets the current position with the set value		PRS APM_PRS	5.2.18 5.3.19
Start step No.	Changes the start step with the set step		SNS APM_SNS	5.2.16 5.3.17
Inching	Conducts inching operation to the set position (inching amoun the inching speed set in the positioning parameter	t) at	INCH APM_INC	5.2.15 5.3.16
Jog	Conducts jog operation at the jog speed set in the parameter Image: Conducts jog operation at the jog speed set in the parameter Image: Conducts jog operation at the jog speed set in the parameter Image: Conducts jog operation at the jog speed set in the parameter Image: Conducts jog operation at the jog speed set in the parameter Image: Conducts jog operation at the jog speed set in the parameter Image: Conducts jog operation at the jog speed set in the parameter Image: Conducts jog operation at the jog speed set in the parameter Image: Conducts jog operation at the jog speed set in the parameter Image: Conducts jog operation at the jog speed set in the parameter Image: Conducts jog operation at the jog speed set in the parameter Image: Conducts jog operation at the jog speed set in the parameter Image: Conducts jog operation at the jog speed set in the parameter Image: Conducts jog operation at the jog speed set in the parameter Image: Conducts jog operation at the jog speed set in the parameter jog operation at the jog speed set in the jog speed set in the parameter jog operation at the jog speed set in the jog se	1	-	
Spd position conversion	Changes from speed control to position control		VTP APM_VTP	5.2.7 5.3.8
Position spd conversion	Changes from position control to speed control		PTV APM_PTV	5.2.8 5.3.9
Spd synchronous operation	Speed synchronous operation at the set main axis, speed ra and delay time	ition	SSS APM_SSS	5.2.11 5.3.12
Position synchronous operation	Speed synchronous operation at the set main axis, step position	and	SSP APM_SSP	5.2.10 5.3.11
Simultaneous start	Simultaneous start with the operation step set for each axis		SST APM_SST	5.2.6 5.3.7
Straight interpolation operation	Straight interpolation operation for axes X and Y with the operation step	set	LIN APM_LIN	5.2.5 5.3.6

Γ

Remark

• Note that the positioning command through the XGB positioning monitoring package is executed regardless of the operation mode of PLC.

• If the PLC operation mode is Run mode, the positioning command is executed in the positioning monitoring package, and if a different command is executed in the instruction of the program, XGB PLC executes them both.

Therefore, in such a case, it might operate differently from the intent of the user or an error might occur.

Note that if you use the positioning monitoring package, positioning by the instruction in the program is not executed.

(2) Positioning Monitoring Window

• The monitoring window on the right of the monitoring package displays the current status according to the positioning command.

• The information displayed in the positioning monitoring window is as follows.

(a) In case of XBM/XBC

lterre	Displays	Relate	Pomark	
item	Displays	Axis X	Axis Y	Remark
Current position	Current position of each axis	K422	K432	DINT
Current speed	Current speed of each axis	K424	K434	DINT
Step No.	Currently operating step of each axis	K426	K436	WORD
Error code	Error code in case of an error of the axis	K427	K437	WORD
M code	M code of the currently operating step	K428	K438	WORD
Busy	Whether the axis is operating	K4200	K4300	BIT
Positioning complete	Whether the positioning has been completed for the axis	K4202	K4302	BIT
M code On	M code On/Off of the currently operating step	K4203	K4303	BIT
Origin fix	Whether the origin has been fixed		K4304	BIT
Output inhibit	Whether output is inhibited	K4205	K4305	BIT
Upper limit detection	Whether the upper limit is detected	K4208	K4308	BIT
Lower limit detection	Whether the lower limit is detected	K4209	K4309	BIT
EMG stop	Emergency stop	K420A	K430A	BIT
Normal/reverse rotation	Normal and reverse rotation	K420B	K430B	BIT
Operation status	The operation status of each axis (acc., dec., constant speed, and dwell)	K420C~ K420F	K430C~ K430F	BIT
Control pattern Operation control pattern of each axis (position, speer interpolation)		K4210~ K4212	K4310~ K4312	BIT

Chapter 6 Positioning Monitoring Package

ltore	Displays	Relate	Demerle	
item	Displays	Axis X	Axis Y	Remark
Home return	Whether home return is being conducted	K4215	K4315	BIT
Position Sync	Whether position synchronization is being conducted	K4216	K4316	BIT
Speed Sync	Whether position synchronous operation is being conducted	K4217	K4317	BIT
Jog high speed	Whether jog high speed operation is being conducted	K4219	K4319	BIT
Jog low speed	Whether jog low speed operation is being conducted	K4218	K4318	BIT
Inching	Whether inching operation is being conducted	K421A	K431A	BIT

(b) In case of XEC

Γ

ltom	Displays	Relate	Remark			
nem	Displays	Axis X	Axis Y	Remark		
Current position	Current position of each axis	%KD211	%KD216	DINT		
Current speed	Current speed Current speed of each axis					
Step No.	Currently operating step of each axis	%KW426	%KW436	WORD		
Error code	Error code in case of an error of the axis	%KW427	%KW437	WORD		
M code	M code of the currently operating step	%KW428	%KW438	WORD		
Busy	Whether the axis is operating	%KX6720	%KX6880	BIT		
Positioning complete	Whether the positioning has been completed for the axis	%KX6722	%KX6882	BIT		
M code On	M code On/Off of the currently operating step	%KX6723	%KX6883	BIT		
Origin fix	Whether the origin has been fixed	%KX6724	%KX6884	BIT		
Output inhibit	Whether output is inhibited	%KX6725	%KX6885	BIT		
Upper limit detection	Whether the upper limit is detected	%KX6728	%KX6888	BIT		
Lower limit detection	Whether the lower limit is detected	%KX6729	%KX6889	BIT		
EMG stop	Emergency stop	%KX6730	%KX6890	BIT		
Normal/reverse rotation	Normal/reverse Normal and reverse rotation rotation		%KX6891	BIT		
Operation status	Operation status speed, and dwell)		%KX6892 ~ %KX6895	BIT		
Control pattern	%KX6736 ~ %KX6738	%KX6896 ~ %KX6898	BIT			

Chapter 6 Positioning Monitoring Package

lte m	Displays	Relate	Description	
Item	Displays	Axis X	Axis Y	Remark
Home return	Whether home return is being conducted	%KX6741	%KX6901	BIT
Position Sync	Whether position synchronization is being conducted	%KX6742	%KX6902	BIT
Speed Sync	Whether position synchronous operation is being conducted	%KX6743	%KX6903	BIT
Jog high speed	Whether jog high speed operation is being conducted	%KX6744	%KX6904	BIT
Jog low speed	Whether jog low speed operation is being conducted	%KX6905	BIT	
Inching	Whether inching operation is being conducted	%KX6746	%KX6906	BIT

٦

(3) Positioning External Input Signal Monitoring

• The external signal monitoring at the bottom of the monitoring window displays the status of the external input contact point, which is the fixed input contact point for the axes as follows.

ltom	Dieploye	Turne	Contact No.		Romark
nem	Displays	туре	Axis X	Axis Y	Remark
		XBM	P00001	P00003	
Upper limit signal	External upper limit signal status of the axes	XBC	P00009	P0000B	
J		XEC	%IX0.0.9	%IX0.0.11	
		XBM	P00000	P00002	
Lower limit signal	External lower limit signal status of the axes	XBC	P00008	P0000A	
		XEC	%IX0.0.8	%IX0.0.10	
		XBM	P00004	P00006	
Approximate	Approximate origin signal status of the axes	XBC	P0000C	P0000E	
ongin orginal		XEC	%IX0.0.12	%IX0.0.14	
		XBM	P00005	P00007	
Origin signal	Origin signal status of the axes	XBC	P0000D	P0000F	
		XEC	%IX0.0.13	%IX0.0.15	

6.3 Parameter/Operation Data Setting Using Monitoring Package

You can change the positioning parameter and operation data of XGB PLC and do test operation by using the XGB monitoring package.

6.3.1 Changing the Position Parameter

- (1) How to Change the Parameter
 - You can change the position parameter by using the position monitoring package. Note that the change of the parameter is applied when the next operation is started after the currently operating step ends.
 - If you select 'Position Parameter' tab in the positioning monitoring package, the window appears where you can change the positioning basic parameter and the origin/manual parameter and the parameter saved in XG5000 is displayed as well.

	Item	X Axis	Y Axis
	Positioning	0: Not Use	0: Not Use
	Pulse Output Level	0: Low Active	0: Low Active
	Bias Speed	1 pls/s	1 pls/s
	Speed Limit	100000 pls/s	100000 pls/s
	ACC No.1	500 ms	500 ms
	DEC No.1	500 ms	500 ms
	ACC No.2	1000 ms	1000 ms
	DEC No.2	1000 ms	1000 ms
Basic	ACC No.3	1500 ms	1500 ms
Parameter	DEC No.3	1500 ms	1500 ms
	ACC No.4	2000 ms	2000 ms
	DEC No.4	2000 ms	2000 ms
	S/W Upper Limit	2147483647 pls	2147483647 pls
	S/W Lower Limit	-2147483648 pls	-2147483648 pls
	Backlash Compensation	0 pls	0 pls
	S/W Limit Detect	0: No Detect	0: No Detect
	Upper/Lower Limit	1: Use	1: Use
	Home Method	1: DOG/HOME(ON)	0: DOG/HOME(OFF)
	Home Direction	1: CCW	1: CDw
	Home Address	0 pls	0 pls
	Home High Speed	5000 pls/s	5000 pls/s
	Home Low Speed	500 pls/s	500 pls/s
Hama	Homing ACC Time	100 ms	1000 ms
Parameter	Homing DEC Time	100 ms	1000 ms
Granierer	DWELL Time	100 ms	0 ms
	JOG High Speed	5000 pls/s	5000 pls/s
	JOG Low Speed	1000 pls/s	1000 pls/s
	JOG ACC Time	1000 ms	1000 ms
	JOG DEC Time	1000 ms	1000 ms
	Inching Speed	100 pls/s	100 pls/s
Monitoria	Inching Speed Position Parameter Axis De	100 pis/s	100 pls
Start Monit	or Stop Monitor Write PLC	Save Project	Close

 To change the parameter, first of all, change the parameter value to change, and select 'Write PLC'. Then the changed parameter is transferred to PLC, the position parameter saved in PLC is changed, and the parameter and operation data that have been changed are applied when the next operation step is started.

Remark

- If you execute 'Write PLC,' the position parameter set in the positioning monitoring package and the operation data of each axis are all transferred to XGB.
- The parameter and operation data displayed when the positioning monitoring package is executed are not the data read from XGB but the parameter and operation data currently saved in XG5000. Therefore if you change the parameter or operation data in the positioning monitoring package and save them in the XGB PLC, be sure to press the 'Save Project' button to save them in the XG5000 project. Otherwise the settings of XG5000 might be different from XGB.

6.3.2 Change of Position Operation Data

- (1) How to Change the Position Operation Data
 - You can change the operation data of each axis during operation by using the positioning monitoring package. Note that the change of the operation data is applied when the next operation is started after the currently operating step ends.
 - If you select the 'axis X data' or 'axis Y data' tabs in the positioning monitoring package, the window is invoked where you can set the operation data of each axis as follows along with the operation data saved in XG5000.

	Coord.	Pattern	Control	Method	REP Step	Address (pulse)	M Code	A/D No.	Speed (pls/s)	Dwell (ms)
1	ABS	END	POS	SIN	0	0	0	No.1	0	0
2	ABS	END	POS	SIN	0	0	0	No.1	0	0
3	ABS	END	POS	SIN	0	0	0	No.1	0	0
4	ABS	END	POS	SIN	0	0	0	No.1	0	0
5	ABS	END	POS	SIN	0	0	0	No.1	0	0
6	ABS	END	POS	SIN	0	0	0	No.1	0	0
7	ABS	END	POS	SIN	0	0	0	No.1	0	0
8	ABS	END	POS	SIN	0	0	0	No.1	0	0
9	ABS	END	POS	SIN	0	0	0	No.1	0	0
10	ABS	END	POS	SIN	0	0	0	No.1	0	0
11	ABS	END	POS	SIN	0	0	0	No.1	0	0
12	ABS	END	POS	SIN	0	0	0	No.1	0	0
13	ABS	END	POS	\$IN	0	0	0	No.1	0	0
14	ABS	END	POS	SIN	0	0	0	No.1	0	0
15	ABS	END	POS	SIN	0	0	0	No.1	0	0
16	ABS	END	POS	SIN	0	0	0	No.1	0	0
17	ABS	END	POS	\$IN	0	0	0	No.1	0	0
18	ABS	END	POS	SIN	0	0	0	No.1	0	0
19	ABS	END	POS	SIN	0	0	0	No.1	0	0
20	ABS	END	POS	SIN	Û	0	0	No.1	0	0
21	ABS	END	POS	\$IN	0	0	0	No.1	0	0
22	ABS	END	POS	SIN	0	0	0	No.1	0	0
23	ABS	END	POS	SIN	0	0	0	No.1	0	0
24	ABS	END	POS	SIN	0	0	0	No.1	0	0
25	ABS	END	POS	\$IN	0	0	0	No.1	0	0
26	ABS	END	POS	SIN	0	0	0	No.1	0	0
27	ABS	END	POS	SIN	0	0	0	No.1	0	0
28	ABS	END	POS	SIN	0	0	0	No.1	0	0
29	ABS	END	POS	SIN	0	0	0	No.1	0	0
30	ABS	END	POS	SIN	0	0	0	No.1	0	0
Vonito Start N	ing Posi Nonitor S	ton Parameter Rop Monitor	Wite		Axis Data	J			C	Close
				+						

 To change the operation data, first of all, change the operation data value to change, and select 'Write PLC'. Then the changed operation data is transferred to PLC, the operation data saved in PLC is changed, and the parameter and operation data that have been changed are applied when the next operation step is started

Remark

- If you execute 'Write PLC,' the position parameter set in the positioning monitoring package and the operation data of each axis are all transferred to XGB.
- The parameter and operation data displayed when the positioning monitoring package is executed are not the data read from XGB but the parameter and operation data currently saved in XG5000. Therefore if you change the parameter or operation data in the positioning monitoring package and save them in the XGB PLC, be sure to press the 'Save Project' button to save them in the XG5000 project. Otherwise the settings of XG5000 might be different from XGB.
- For details, refer to 3.2. and 3.3.

Chapter 7 Program Examples of Positioning

This chapter describes the program examples of the instructions of XGB positioning function.

7.1 System Composition and Setting of Input and Output

• This section describes the setting of the positioning system and the input and output signals for the program example of XGB positioning. If there is no separate description, all the example programs addressed in Chapter 7 were made according to the settings of the input and output signals described in this chapter.



(1) XBM-DNxxS system configuration

Remark

• Be sure to set the basic parameter positioning as '1:Use' when you use the positioning function.

	Item	X Axis	Y Axis
	Positioning	1: Use 💙	0: Not Use
	Pulse Output Level	0: Low Active	0: Low Active
	Bias Speed	1 pls/s	1 pls/s
	Speed Limit	100000 pls/s	100000 pls/s
	ACC No.1	500 ms	500 ms
	DEC No.1	500 ms	500 ms
	ACC No.2	1000 ms	1000 ms
_ ·	DEC No.2	1000 ms	1000 ms
Basic	ACC No.3	1500 ms	1500 ms
arameter	DEC No 3	1500 ms	1500 ms



(2) XBC(XEC)-DNxxH system configuration

Γ

7.2 Program Examples

7.2.1 Floating Origin Setting/Single Operation

• The example program of the single operation after the floating origin setting by using the XGB positioning function is as follows.

٦

(1) XBM/XBC

<u> </u>									
	P00040	KO42O1 XAxis			CLR	0	0	1	When error occurs, resets error and cancels output
0	reset SW POOO41	Error KO4200	K04201						minorcion
							U		Sets Axis X floating
8	floating origin SW	AMAIS DUGT	Error						origin
	P00047	K04200	K04201					K04290	Starts axis X current
5	Axis X start SW	XAxis BUSY	XAxis Error					XAxis Start	step
								END	
0									

(a) Devices Used

Device	Description
P0040	Axis X error reset, output inhibition cancel switch
P0041	Axis X axis X floating origin switch
P0047	Start switch of axis X
K4200	Signal during axis X operation
K4201	Error signal of axis X
K4290	Axis X start

(2) XEC

1	\$IX0.1.0	%KX6721		INST10		
	P ErrorReset Switch	XAxis Error		- RÊQ DONE -	RST_DONE	
2			0	-BASE STAT-	RST_STAT	
}			0	SLOT		
1			0	AXIS		
5			1	- INH_		
8						
omment	Sets floatin	g origin				
3	XIXO.1.1 FloatingOr iginSwitch	%KX6720 ↓/ XAxis BUSY	XKX6721 ──┤/├── XAxis Error	INSTI1 APM_FLT REQ DONE-	FLT_DONE	
9			0	BASE STAT	FLT_STAT	
10			0	SLOT		
11			0	AXIS		
.12						
Comment	Starts axis	X current ste	эр			
11	\$120.1.7	%K%6720	XKX6721			%KX6864

(a) Devices Used

Г

Device	Description					
%IX0.1.0	Axis X error reset, output inhibition cancel switch					
%IX0.1.1	Axis X axis X floating origin switch					
%IX0.1.7	Start switch of axis X					
%KX6720	Signal during axis X operation					
%KX6721	Error signal of axis X					
%KX6864	Axis X start					

(3) Operation Data Setting

Step No.	coordi nates	Control pattern	Operatio n pattern	Operatio n type	Repeat step	Target position [pulse]	M code	Acc./Dec. No.	Operation speed [pls/s]	Dwell time [^{ms}]
1	Abso lute	Position control	End	Single	0	10,000	0	1	1000	100
2	Abso lute	Position control	End	Single	0	20,000	0	1	1500	100
3	Abso lute	Position control	End	Single	0	30,000	0	1	2000	100

(4) Operation Sequence

- P0041/%IX0.1.1 (floating origin) switch On : set as the floating origin at the current position
- 3 times of P0047/%IX0.1.7 (start) switch On : 3 times of single operation (steps 1~3). If it is operating now, the start instruction is not executed.



7.2.2 Straight Interpolation Operation

• The example program of the straight interpolation operation after the floating origin is set is as follows. (1) XBM/XBC

٦



Device	Description
P0008	Axis X error reset, output inhibition cancel switch
P0009	floating origin switch
P000F	Straight interpolation start switch
K4200	Signal during operation of axis X
K4201	Signal of axis X error
K4300	Signal during operation of axis Y
K4301	Signal of axis Y error

(2) XE	C			.,	,			
Comment	When error o	ccurs, resets	s error and	cancels out;	out inhibition			
L1	xIX0.1.0	%KX6721					INST1 APM_RST REQ DONE	X_RST_DONE
	ErrorReset SW	XAxis Error						
12		XKX6881		APM_RST	V RST DONE	n	BASE STAT	X RST STAT
		VAxis Error		new bone	1_NOT_BONE		bride offici	
13			0	-BASE STAT	- V_RST_STAT	0	SLOT	
4			n	SLOT		n	AXIS	
5				1910		····		
8				-4413			OFF	
7			1	OFF				
Comment	Sets axis X	floating orig	gin					
LØ	%IX0.1.1	%KX6720	%KX6721				INST3	
	Floating origin SW	XAxis BUSY	──┤/├── XAxis Error					X_FLT_DONE
L 10		%KX6880	%KX6881	INST2				
		VAxis BUSY		- RÊQÎ DONE	- Y_FLT_DONE	0	-BASE STAT	X_FLT_STAT
.11			Crior	BASE STAT	V ELT STAT	0	TOIR	
.12				-DHOL OTHI	- Y_FET_STAT	U	-3201	
. 13			0	SLOT		0	AXIS	
			1	AXIS				
.14								
Comment	Starts axis	X-Y linear in	nterpolatio	n			1107	
L18	%IX0.1.7	XKX6720	XKX6721	XKX6880	%KX6881	_	INST4 APM_LIN REDDONE	
	Linear interpolat	XAxis BUSY	XAxis Error	YAxis BUSY	VAxis Error			CTM_DONC
L17	ion start							
18						0	-BASE STAT	LIN_STAT
10						0	SLOT	
19						1		
120						3	STEP	
121								

Γ

(a) Devices Used

Device	Description
%IX0.1.0	Axis X error reset, output inhibition cancel switch
%IX0.1.1	floating origin switch
%IX0.1.7	Straight interpolation start switch
%KX6720	Signal during operation of axis X
%KX6721	Signal of axis X error
%KX6880	Signal during operation of axis Y
%KX6881	Signal of axis Y error

1

(3) Operation Data Setting

Axis	Step No.	coordinat es	Control pattern	Operation pattern	Operation type	Repeat step	Target position [pulse]	M code	Acc./Dec. No.	Operation speed [pls/s]	Dwell time [^{ms}]
х	1	Absolute	Position control	End	Single	0	10,000	0	1	1000	100
Y	1	Absolute	Position control	End	Single	0	5,000	0	1	1000	100

(4) Operation Sequence

- P0009/%IX0.1.1 (floating origin) switch On : set as the floating origin at the current position.
- P000E/%IX0.1.7 (straight interpolation start) switch On : the straight interpolation start of axes X-Y is started.



7.2.3 Deceleration Stop

• The example program of deceleration stop during operation is as follows.

(1) XBM/XBC

Γ

0	P0008 P Error reset SW	K04201		[CLR	0	0	1	In case of error, error reset, output inhibit cancel
8	P0009 FLT command	K04200	K04201			FLT	0	0	set Floating origin
15	P000F X axis start SW	K04200	K04201					K04290	X Axis current start
20		K04201		 (STP	0	0	1	DEC. Stop
28								END	

Device	Description
P0008	Axis X error reset, output inhibition cancel switch
P0009	axis X floating origin switch
P000A	axis X deceleration stop switch
P000F	axis X start switch
K4200	Signal during axis X operation
K4201	Error signal of axis X



٦

Device	Description
%IX0.1.0	Axis X error reset, output inhibition cancel switch
%IX0.1.1	axis X floating origin switch
%IX0.1.2	axis X deceleration stop switch
%IX0.1.7	axis X start switch
%KX6720	Signal during axis X operation
%KX6721	Error signal of axis X

(3) Operation Data Setting

ſ

Step No.	coordina tes	Control pattern	Operatio n pattern	Operatio n type	Repeat step	Target position [pulse]	M code	Acc./Dec. No.	Operation speed [pls/s]	Dwell time [ms]
1	Absolute	Position control	End	Single	0	10,000	0	1	1000	100

(4) Operation Sequence

•P0009/%IX0.1.1 (floating origin) switch On : set as the floating origin at the current position.

•P000F/%IX0.1.7 (start) switch On : indirect start of axis X is started.

•P000A/%IX0.1.2 (deceleration stop) switch On : Since the deceleration time is not 0 when the deceleration stop instruction is given, it does deceleration stop for the deceleration time (100ms) of the currently operating step.

7.2.4 Setting of Operation Step/Single Operation

• The example program of conducting the single operation by setting the operation step is as follows.

(1) XBM/XBC



Device	Description
P0008	Error reset, output inhibition cancel switch
P0009	Floating origin switch
P000C	Operation step change switch
P000F	axis X start switch
K4200	Signal during axis X operation
K4201	Error signal of axis X

,					INST2		
	XIX0.1.0	%KX6721			APM_RST REQ DONE	- X RST DONE	
	ErrorReset SW	XAxis Error					
				0	BASE STAT	- V_RST_STAT	
				Π	SI OT		
1				, ,	4710		
				U	- 1010		
				1	- INH_ OFF		
mment	Sets axis X	floating ori	gin		INST		
	XIX0.1.1	%KX6720	%KX6721		APM_FLT REQ DONE	- X FLT DONE	
	Floating origin SW	XAxis BUSY	XÁxis Error				
				0	BASE STAT	- X_FLT_STAT	
)				0	SLOT		
1				0	AXIS		
?]	
3	\$IX0.1.4	%KX6720	% KX6721			(BCD_TO_+++)	
	Position	XAxis BUSY	XAxis			EN ENO ENO	
1	teaching		Error		«υщο 1 1		
ī					BCD SW		
ſ							
,					0	RASE STAT V SNS STAT	
}					, ,		
7					U	-3201	
)					0	AXIS	
,					STEP	STEP	
,							
nment	Starts axis	X current st	ер				
}	XIX0.1.7	%KX6720	XKX6721				XKX6864
	Parameter teaching	XAxis BUSY	XAxis Error				XAxis Start

٦

Device	Description
%IX0.1.0	Error reset, output inhibition cancel switch
%IX0.1.1	Floating origin switch
%IX0.1.4	Operation step change switch
%IX0.1.7	axis X start switch
%KX6720	Signal during axis X operation
%KX6721	Error signal of axis X

(a) Devices Used

ſ

(3) Operation Data Setting

Step No.	coordi nates	Control pattern	Operatio n pattern	Operatio n type	Repeat step	Target position [pulse]	M code	Acc./Dec. No.	Operation speed [pls/s]	Dwell time [^{ms}]	
1	Abs olute	Position control	End	Single	0	10,000	0	1	1,000	100	
2	Abs olute	Position control	End	Single	0	20,000	0	1	1,500	100	
3	Abs olute	Position control	End	Single	0	30,000	0	1	2,000	100	
10	Abs olute	Position control	End	Single	0	50,000	0	1	1,000	100	
11	Abs olute	Position control	End	Single	0	60,000	0	1	1,500	100	
12	Abs olute	Position control	End	Single	0	70,000	0	1	2,000	100	

(4) Operation Sequence

- P0009/%IX0.1.1 (floating origin) switch On : set as the floating origin at the current position.
- BCD/SNS_STEP switch input: enters the operation step to change in P004(enters 10 in this example).
- P000C/%IX0.1.4(operation step change) switch On : the currently operating step changes into 10.
- P000F/%IX0.1.7(axis X start) On : indirect start is conducted with the changed step (10).

7.2.5 Setting of Operation Step/Speed Control

• The program example of conducting speed control by setting the operation step is as follows. (1) XBM/XBC

	P0008	K04201 XAxis Error			CLR	0	0	1	In case of error, error reset, output inhibit cancel
0	P0009	K04200	K04201	 		FLT	0	0	set Floating origin
8	Command P000C	K04200	K04201	 		BIN	P004	D0050	Convert BCD input of
15	step change			 	SNS	0	0	D0050	Change start step by
26	P000A	K04200	K04201	 	STP	0	0	1	DEC. stop with DEC time of current step
20	P000F	K04200 XAxis BUSY	K04201	 				K04290	Start XAxis current step
<u>36</u> 41	SW			 				END	
Device	Description								
--------	--	--	--	--	--	--	--	--	
P0008	Error reset, output inhibition cancel switch								
P0009	floating origin switch								
P000C	Operation step changing switch								
P000F	axis X start switch								
P000A	Deceleration stop switch of axis X								
K4200	Signal during axis X operation								
K4201	Error signal of axis X								

٦

(a) Devices Used

(2) XEC

Comment	When error o	ccurs, resets	error and car	ncels ouptut inhib	ition				
11	XIXO.1.0	%KX6721 ↓↓ XAxis			INS APM_ REQ	T2 RST DONE	X_RST_DONE		
12	2₩	Error		0	BASE	STAT	V RST STAT		
L3				Ű.	SLOT				
L4					AXIS				
15				1	INH				
18					OFF				
Comment	Sets axis X	floating orig	in						
18	XIXO.1.1 Floating origin S [™]	XKX6720	XKX6721		APM_ REQ	ST FLT DONE -	X_FLT_DONE		
19	or igni ow		Error	0	BASE	STAT	X_FLT_STAT		
L10				0	SLOT				
L11				0	AXIS				
L12									
Comment	Changes BCD	SW input into	BIN Chang	es start step numb	er by valu	e of S	TEP		
L14	%IXO.1.4 Position teaching	%KX6720 │/│ XAxis BUSY	XKX6721				BCD_TO_*** - EN ENO	ENO	
L15					%1W0 BCD	.1.1 SW	- IN OUT	STEP	
L18									
L17							INST1 APM_SNS REQ DONE	X_SNS_DONE	
L18)	-BASE STAT	X_SNS_STAT	
L19					()	-SLOT		
L20)	AXIS		
L21					ST	EP	STEP		
122									
	1								

Comment	Deceleration	stop with c	urrent DEC.	time			
L24	%IXO.1.2 	XKX6720	%KX6721 ┤∕┞ XAxis Error		APM REQ	NST3 IM_STP } DONE_	
L25				0	BASE	e stat-	
L26				0	SLOT	т	
L27				0	AXIS	S	
L28				1		Ē	
L29]	
Comment	Starts axis >	(current st	ер				
L31	%IX0.1.7	XKX6720	%KX6721			XKX6864	
L32	Parameter teaching	XAxis BUSY	XAxis Error			XAxis Start	

(a) Devices Used

Γ

Device	Description
%IX0.1.0	Error reset, output inhibition cancel switch
%IX0.1.1	floating origin switch
%IX0.1.4	Operation step changing switch
%IX0.1.7	axis X start switch
%IX0.1.2	Deceleration stop switch of axis X
%KX6720	Signal during axis X operation
%KX6721	Error signal of axis X

(3) Operation Data Setting

Step No.	coordi nates	Control pattern	Operatio n pattern	Operatio n type	Repeat step	Target position [pulse]	M code	Acc./Dec. No.	Operation speed [pls/s]	Dwell time [^{ms}]	
1	Abs olute	Position control	End	Single	0	10,000	0	1	1,000	100	
2	Abs olute	Position control	End	Single	0	20,000	0	1	1,500	100	
3	Abs olute	Position control	End	Single	0	30,000	0	1	2,000	100	
											-
10	Abs olute	Speed control	End	Single	0	50,000	0	1	1,000	100	
11	Abs olute	Position control	End	Single	0	60,000	0	1	1,500	100	
12	Abs olute	Position control	End	Single	0	70,000	0	1	2,000	100	

(4) Operation Sequence

P0009/%IX0.1.1 (floating origin) switch On : set as the floating origin at the current position.
BCD/SNS_STEP switch input: enters the operation stop to change in P004 (enters 10 in this example).

•P000C/%IX0.1.4 (operation step change) switch On : the current operating step changes into 10.

•P000F/%IX0.1.7(axis X start) On : indirect start is conducted with the changed step (10).

•P000A/%IX0.1.2 (deceleration stop) switch On : axis X, which is being operated with speed control, is decelerated and stopped by the deceleration time of the current step.

7.2.6 Simultaneous Start

• The program example of simultaneous start of axes X, Y is as follows.

(1) XBM/XBC

	P0008	K04201					CLR	0	0	1	In case of error, error
0	Error reset SW	XAxis Error									reset, output inhibit cancel
		K04301					CLR	0	1	1	
15	P0009	K04200	K04201					FLT	0	0	set Floating origin
	Command	K04300	K04301					FLT	0	1	
29	P000E	K04200	K04201	K04300	K04301					▶ 0	
	0 🕨			SST	0	0	1	2	0	3	X-Y SST
41										END	

٦

Device	Description
P0008	axes X and Y error reset, output inhibition cancel switch
P0009	axes X and Y floating origin switch
P000E	simultaneous start switch of axes X and Y
K4200	Signal during axis X operation
K4201	Error signal of axis X
K4300	Signal during axis Y operation
K4301	Axis Y error signal

ment	When error o	ccurs, resets	s error and	cancels oupt	ut inhibitio	n			
	\$IX0.1.0	% KX6721						INST8	
	P ErrorReset	XAxis						- RÊQ ^{®®} DÔNE	- X_RST_DONE
	SW	Error			INST7				
		XKX6881 ───┤			APM_RST REQ DONE	Y_RST_DONE	0	BASE STAT	- X_RST_STAT
		YAxis Error							
				0	BASE STAT	V_RST_STAT	0	SLOT	
				0	SLOT		0	AXIS	
				1	AXIS		1	INH	
				• • • • • • • • • • • • • • • • • • • •			· ·	ÖFF	
				1	- INH_ OFF				
	l								
mment	Sets axis X,	Y floating	origin						
0	%IX0.1.1	%KX6720	%KX6721					INST10 APM_FLT	
	Floating	XAxis BUSY	∕ XAxis					REQ DONE	- X_FLT_DONE
t	origin SW	W/VC000	Error WVC001		INST11				
			⊼KADOOI ──┤/ ├── Vávic		- REQ DONE	Y_FLT_DONE	0	BASE STAT	- X_FLT_STAT
1		18213 0001	Error						
1				0	-BASE STAT	V_FLT_STAT	0	-SLOT	
;				0	SLOT		0	AXIS	
r				1	AXIS				
i									
	· · · · · ·								
mment	X-Y Simultan	eous start					INST12		
, 	%IX0.1.6	%KX6720	%KX6721	%KX6880	%KX6881		APM_SST REO DONE	- SST DONE	
	Simultaneo us start	XAxis BUSY	XAxis Error	YAxis BUSY	VÁxis Error				
!	SW								
,						U	-BASE STAT	- 22172191	
1						0	SLOT		
						3	-SST AXIS		
1						1	-X_ST		
,						2	Y ST		
						_	ĒĎ		
						· 0	4Z ST – L		

Γ

Device	Description
%IX0.1.0	axes X and Y error reset, output inhibition cancel switch
%IX0.1.1	axes X and Y floating origin switch
%IX0.1.6	simultaneous start switch of axes X and Y
%KX6720	Signal during axis X operation
%KX6721	Error signal of axis X
%KX6880	Signal during axis Y operation
%KX6881	Axis Y error signal

(a) Devices Used

(3) Operation Data Setting

Axis	Step No.	coordinat es	Control pattern	Operation pattern	Operation type	Repeat step	Target position [pulse]	M code	Acc./Dec. No.	Operation speed [pls/s]	Dwell time [ms]
х	1	Absolu te	Position control	End	Single	0	10,000	0	1	1000	100
Y	2	Absolu te	Position control	End	Single	0	20,000	0	1	2000	100

(4) Operation Sequence

P0009/%IX0.1.1 (floating origin) switch On : set as the floating origin at the current position.
P000F/%IX0.1.6 (simultaneous start) switch On : axis X simultaneously starts step 1, and axis Y does step 2.

7.2.7 Position Synchronous Start

• The program example of position synchronous start is as follows.

(1) XBM/XBC



Device	Description
P0008	axes X and Y error reset, output inhibition cancel switch
P0009	axes X and Y floating origin switch
P000D	Axis X position synchronous switch
P000F	Indirect start switch f axis Y
K4200	Signal during axis X operation
K4201	Error signal of axis X
K4300	Signal during axis Y operation
K4301	Axis Y error signal

(a) Devices Used

Γ

(2) XEC

Comment	When error o	ccurs, resets	s error and c	ancels oup	tut inhibition				
Lf	%IX0.1.0	%KX6721						INST8	V DST DONE
	ErrorReset SW	XAxis Error						- KEY DUNE	- X_KST_DUNE
12		XKX6881 YAxis Error			APM_RST REQ DONE - 1	/_RST_DONE	0	-BASE STAT	- X_RST_STAT
L3				0	BASE STAT	/_RST_STAT	0	SLOT	
14				0	SLOT		0	AXIS	
15				1	AXIS		1	INH_	
18				1					
L7									
LB									L
Comment	Sets axis X,	Y floating	prigin						
L10	XIXO.1.1	XKX6720 I/I XAxis BUSY	XKX6721					INSTIO APM_FLT REQ DONE	X_FLT_DONE
Lff	ongin ow	XKX6880 I/I YAxis BUSY	XKX6881 /// VAxis Error		INST11	/_FLT_DONE	0	-BASE STAT	X_FLT_STAT
112				0	BASE STAT	/_FLT_STAT	0	SLOT	
L13				0	SLOT		0	AXIS	
L14				1	AXIS				
L15									
	1								

Comment	When axis Y	is 2000, sta	rts axis X st	ep 1	
L17	%IXO.1.5	%KX6720	%KX6721		INST13
	PositionSy nc.Start	XAxis BUSY	XAxis Error		- REQ DURE - SSP_DURE
L18				0	-BASE STAT - SSP_STAT
L19				0	SLOT
120				0	AXIS
L21				1	-STEP
122				1	-MST_
L23				2000	AXIS
L24					ADDR
L25	XIXO.1.7	XKX6880 ↓/↓ YAxis BUSY	XKX6881 //- YAxis Frror		INST15 APM_IST REQ_DONE - IST_DONE
1.26	Start ow		LITO	0	-BASE STAT - IST_STAT
L27				0	-SLOT
L28				1	AXIS
L29				1	-STEP
<i>L30</i>					

(a) Devices Used

Device	Description							
%IX0.1.0	axes X and Y error reset, output inhibition cancel switch							
%IX0.1.1	xes X and Y floating origin switch							
%IX0.1.5	xis X position synchronous switch							
%IX0.1.7	Indirect start switch f axis Y							
%KX6720	Signal during axis X operation							
%KX6721	Error signal of axis X							
%KX6880	%KX6880 Signal during axis Y operation							
%KX6881	Axis Y error signal							

(3) Operation Data Setting

Axis	Step No.	coordinat es	Control pattern	Operation pattern	Operation type	Repeat step	Target position [pulse]	M code	Acc./Dec. No.	Operation speed [pls/s]	Dwell time [ms]
х	1	Absolu te	Position control	End	Single	0	10,000	0	1	1000	100
Y	1	Absolu te	Position control	End	Single	0	20,000	0	1	2000	100

(4) Operation Sequence

Γ

- •P0009/%IX0.1.1 (floating origin) switch On : set as the floating origin at the current position.
- •P000D/%IX0.1.5 (synchronous start) switch On : axis X tarts position synchronous start with axis Y being the main axis.
- •P000F/%IX0.1.7 (Axis Y start) switch On : axis Y starts the step operation. If the position of axis Y reaches 2,000, axis X is synchronized to this, starting step 1.

7.2.8 Speed Synchronous Start

• The program example of speed synchronous start is as follows.

(1) XBM/XBC



Device	Description						
P0008	axes X and Y error reset, output inhibition cancel switch						
P0009	-loating origin switch of axes X and Y						
P000A	axis X deceleration stop switch						
P000B	deceleration stop switch of axis X						
P000C	axis X speed synchronous start switch						
P000F	indirect start switch of axis Y						
K4200	Signal during axis X operation						
K4201	Error signal of axis X						
K4300	Signal during axis Y operation						
K4301	Axis Y error signal						

(2) XE	С									1
Comment	When error o	ccurs, resets	s error and ca	ancels our	≎tut inhibitic	n				
11	XIXO.1.0	%KX6721						INST8 APM_RST REQ DONE	X_RST_DONE	
12	SW	Error			INST7				1	
12		%KX6881 ──┤			APM_RST REQ DONE	- Y_RST_DONE	0 -	BASE STAT	- X_RST_STAT	
L3		Error		0	BASE STAT	- Y_RST_STAT	0 -	SLOT		
14				0	SLOT		0 -	AXIS		
15				1	AXIS		1 -	INH_ OFF		
18				1						
L7										
Comment	Sets axis X,	Y floating o	prigin							
L10	%IX0.1.1	%KX6720	%KX6721					INSTIO]	
	Floating origin SW	XAxis BUSY	──┤/├── XAxis Error					- REQ DUNE	- X_FLT_DONE	
L11		%KX6880	%KX6881				0		N FLT OTAT	
		VAxis BUSV	────// VAxis Error			F Y_FLI_UUNC	U	-DHOE OTHI	- X_FLI_STAT	
112				0	BASE STAT	V_FLT_STAT	0	SLOT		
L13				0	SLOT		0	AXIS		
L14				1	AXIS]	
L15										
Comment	Axis X DEC.	stop								
L17	%IX0.1.2	%KX6720	%KX6721			INST16 APM_STP				
1.10	DEC. Sto	XAxis BUSY	XAxis Error			- RËQ DONE -	- X_STP_DONE			
110					0	BASE STAT	- X_STP_STAT			
L19					0	SLOT				
120					0	AXIS				
L21					1	-DEC_				
1.22						TIME				
Comment	Axis Y DEC.	stop								
124	XIX0.1.3	XKX6880	XKX6881 ──┤╱┝───			INST17 APM_STP REQ DONE	+ V_STP_DONE			
1.75	Axis Y DEC. stop	VAxis BUSY	VAxis Error							
120					0	BASE STAT	- V_STP_STAT			
120					0	SLOT				
L27					1	AXIS				
L28					1	-DEC_ TIME				
129										

Comment	Axis X speed	sync. start	Sync.:50%	Delay:	1ms			
L31	%IX0.1.4	%KX6720	%KX6721			INS	81T	
	Speed sync.	XAxis BUSY	XAxis Error			RÊQ	DONE -	SSS_DONE
132	start				0	BASE	STAT-	SSS_STAT
L33					0	SLOT		
134					0	AXIS		
L35					1	MST		
L38					5000	SLV. RAT		
L37					1	DEL		
L38						-	_	
L33	XIXO.1.7 Axis V start SW	%KX6880 ──┤╱┝── YAxis BUSY	XKX6881 			IN: APM REQ	ST19 - IST - DONE -	V_IST_DONE
134					0	-BASE	STAT	V_IST_STAT
135					0	SLOT		
L36					1	-AXIS		
137					1	STEP		
1.38						-		

(a) Devices Used

Γ

Device	Description						
%IX0.1.0	exes X and Y error reset, output inhibition cancel switch						
%IX0.1.1	loating origin switch of axes X and Y						
%IX0.1.2	xis X deceleration stop switch						
%IX0.1.3	Jeceleration stop switch of axis X						
%IX0.1.4	axis X speed synchronous start switch						
%IX0.1.7	indirect start switch of axis Y						
%KX6720	Signal during axis X operation						
%KX6721	Error signal of axis X						
%KX6880	0 Signal during axis Y operation						
%KX6881	Axis Y error signal						

Axis	Step No.	coordina tes	Control pattern	Operatio n pattern	Operatio n type	Repeat step	Target position [pulse]	M code	Acc./Dec. No.	Operation speed [pls/s]	Dwell time [ms]
X(auxiliary axis)	1	Absol ute	Position control	End	Single	0	10,000	0	1	1000	100
Y(main axis)	1	Absol ute	Speed control	End	Single	0	15000	0	1	1000	100

(3) Operation Data Setting

(4) Operation Sequence

•P0009/%IX0.1.1 (floating origin) switch On : set as the floating origin at the current position.

•P000C/%IX0.1.4 (synchronous start) switch On : axis X starts speed synchronous start with axis Y being the main axis.

•P000F/%IX0.1.7 (Axis Y start) switch On : axis Y starts step 1 operation. Axis X is synchronized to the speed of 50,00% of axis Y and started.

7.2.9 Emergency Stop

• The program example of emergency stop during operation is as follows.

(1) XBM/XBC

<u> </u>		-							
0	P0008	K04201		[CLR	0	0	1	In case of error, error reset, output inhibit cancel
8	P0009 FLT command	K04200	K04201			FLT	0	0	set X axis Floating origin
15	P000A	K04200	K04201	[IST	0	0	1	X indirect start
23	P000B	K04200	K04201			EMG	0	0	X axis emergency stop
30								END	

Device	Description
P0008	Error reset, output inhibition cancel switch in case of emergency stop
P0009	axis X home return switch
P000B	emergency stop switch during home return
K4200	Signal during axis X operation

(2) XEC

Γ

_) /(_0							
When error occurs, rese	ts error and ca	ancels ou	ptut inhibitio	n			
% X0.1.0 %KX6721						INST8 APM DST	
PI ErrorReset XAxis SW Error						- RÊQ ^{MI} DONE	- X_RST_DONE
					0	-BASE STAT	- X_RST_STAT
					0	SLOT	
					0	AXIS	
					1	- INH_ OFF	
Gets axis X floating or	igin						
VIV0 1 1 VVV2300	9KA6201					INST10	
Floating XAxis BUSY	XAxis Error						- X_FLT_DONE
					0	-BASE STAT	- X_FLT_STAT
					0	SLOT	
					0	AXIS	
xis X indirect start							
%IXO.1.2 %KX6720 → I IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	%KX6721 ┤╱┝ XAxis Error		INST20 REQDONE	- X_IST_DONE			
		0	-BASE STAT	- X_IST_STAT			
		0	SLOT				
		0	-AXIS				
		1	STEP				
XIXO.1.3 XKX6720 H H H EMG STOP XAxis BUSY	XKX6721 // XAxis Error		INST21 APM_EMG REQ DONE	- X_EMG_DONE			
		0	-BASE STAT	- X_EMG_STAT			
		0	SLOT				

Device	Description
%IX0.1.0	Error reset, output inhibition cancel switch in case of emergency stop
%IX0.1.1	axis X home return switch
%IX0.1.7	emergency stop switch during home return
%KX6720	Signal during axis X operation

(3) Operation Data Setting

Step No.	coordinat es	Control pattern	Operation pattern	Operation type	Repeat step	Target position [pulse]	M code	Acc./Dec. No.	Operation speed [pls/s]	Dwell time [^{ms}]
1	Absolut e	Speed control	End	Single	0	10000	0	1	1000	100

(4) Operation Sequence

•P0009/%IX0.1.1 (floating origin) switch On : set as the floating origin at the current position.

P000A/%IX0.1.2 (indirect start) switch On : axis X indirectly starts step 1 and starts speed control.
P000B/%IX0.1.7 (emergency stop) switch On : axis X does emergency stop without deceleration and the output is inhibited.

7.2.10 Jog Operation

• The program example of jog operation is as follows.

(1) XBM/XBC



Device	Description					
P0008	Axis X error reset, output inhibition cancel switch					
P0009	axis X floating origin switch					
P000D	P000D axis X jog normal direction start switch					
P000E	axis X jog reverse direction start switch					
P000F	Switch for low/high speed selection of axis X jog					
K4200 Signal during axis X operation						
K4201 Error signal of axis X						

(2) XEC

Γ

%IX0.1.0 %KX6721			INST8 APM RST	
─────────────────────────────────────				
		0	-BASE STAT X_RST_STAT	
		0	SLOT	
		0	AXIS	
		1	- INH	
Gets axis X floating or	igin			
%IXO.1.1 %KX6720	xKx6721		INSTIO APM_FLT REQONEX_FLT_DONE	
Floating origin SW	XÁxis Error			
		0	-BASE STAT - X_FLT_STAT	
		0	SLOT	
		0	AXIS	
Start CW JOG				
%IX0.1.5				XKX6865
JOG CW				XAxis CW JOG START
XIXO.1.6				XKX6866
JOG CCW				XAxis CCW JOG START
Select JOG low speed/hi	gh speed			
%IX0.1.7				XKX6867
JOG speed				XAxis JOG Low Speed/High Speed

Device	Description						
%IX0.1.0	Axis X error reset, output inhibition cancel switch						
%IX0.1.1	axis X floating origin switch						
%IX0.1.5	axis X jog normal direction start switch						
%IX0.1.6	axis X jog reverse direction start switch						
%IX0.1.7	Switch for low/high speed selection of axis X jog						
%KX6880	Signal during axis X operation						
%KX6881	%KX6881 Error signal of axis X						

(3) Operation Sequence

•P0009/%IX0.1.1 (floating origin) switch On : set as the floating origin at the current position.

•P000D/%IX0.1.5 (jog normal direction) switch On : axis X starts normal direction jog operation.

1

•P000F/%IX0.1.7 (jog speed) switch On : axis X is converted to jog high speed.

•P000D/%IX0.1.5 (jog normal direction) switch Off : axis X does jog stop.

•P000E/%IX0.1.6 (jog reverse direction) switch On : axis X starts reverse direction jog operation. •P000E/%IX0.1.6 (jog reverse direction) switch Off : axis X does jog stop.

7.2.11 Speed Override

• The program example of speed override during operation is as follows.

(1) XBM/XBC

0	P0008	K04201			CLR	0	0	1	In case of error, error reset, output inhibit cancel
8	P0009 PIP FLT command	K04200	K04201			FLT	0	0	set X axis Floating origin
16	P000A P Indirect start	K04200	K04201		IST	0	0	1	X axis indirect start
	P000C PP Speed override	K04200	K04201	K0420C XAxis Move Status(Acce	SOR	0	0	1000	Override current speed to 1000pps
				K04200 XAxis BUSY					
38								END	

Device	Description						
P0008	Axis X error reset, output inhibition cancel switch						
P0009	axis X floating origin switch						
P000A	axis X indirect start switch						
P000C	axis X speed override switch						
K4200	Signal during axis X operation						
K4201	Error signal of axis X						
K420C	axis X acceleration signal						
K420D	axis X constant speed signal						

(2) XEC

Γ

When error o	ccurs, resets	s error and	cancels oupt	ut inhibitio	n			ото	
%IX0.1.0	XKX6721							ST8 _RST	V DOT DOUE
ErrorReset	XAxis Error							DOME	- A_KST_DONE
						0	BASE	STAT	- X_RST_STAT
						0	SLOT		
						0	AXIS		
						1			
						· · · · · · · · · · · · · · · · · · ·	OFF		
Sets axis X ·	floating oris	ain							
WUVD 1 1	91/VC700	W/VCT01					INS	ST10	
Floating	XAXIS BUSY	XAXIS					REQ	-FLI DONE	- X_FLT_DONE
origin SW		Error					DYOL	от. т	
						U -	-DASE	SIAI	- X_FET_STAT
						0	-SFOL		
						0	AXIS		
Axis X indir	ect start]	
W1V0 1 0	WWYCROO	W/VCR04		INST23					
Indirect start	XAxis BUSY	XKX6721 /// XAxis Error		- REQ DONE	X_IST_DONE				
			0	BASE STAT	X_IST_STAT				
			0	SLOT					
			0	AXIS					
			1	STEP					
Override cur	rent speed in	nto 1000pps							
%IX0.1.4	%KX6720	%KX6721	%KX6732		INST24				
P P Speed	XAxis BUSY	— ∕ — XAxis	XAxis Move		- RËQ ^{®-} DÖNE-	SOR_DONE			
overriue			eleration)						
			XAxis Move Status(Con stant)	Jo	-BASE STAT -	SOR_STAT			
				0	SLOT				
				0	AXIS				
				1000	-SOR_				
					SPD				

Device	Description						
%IX0.1.0	Axis X error reset, output inhibition cancel switch						
%IX0.1.1	axis X floating origin switch						
%IX0.1.2	axis X indirect start switch						
%IX0.1.4	axis X speed override switch						
%KX6720	Signal during axis X operation						
%KX6721	Error signal of axis X						
%KX6732	axis X acceleration signal						
%KX6733	axis X constant speed signal						

(a) Devices Used

(3) Operation Data Setting

Step No.	coordinat es	Control pattern	Operation pattern	Operation type	Repeat step	Target position [pulse]	M code	Acc./Dec. No.	Operation speed [pls/s]	Dwell time [ms]
1	Absolut e	Position control	End	Single	0	100000	0	1	5000	100

(4) Operation Sequence

•P0009/%IX0.1.1 (floating origin) switch On : set as the floating origin at the current position.

•P000A/%IX0.1.2 (indirect start) switch On : axis X indirectly starts step 1.

•P000C/%IX0.1.4 (speed override) switch On : overrides the current speed to 1000pps during acceleration or constant speed operation of axis X.

7.2.12 Position Override

• The program example of position override during operation is as follows.

(1) XBM/XBC



(a) Devices Used

Γ

Device	Description					
P0008	Axis X error reset, output inhibition cancel switch					
P0009	axis X floating origin switch					
P000A	axis X indirect start switch					
P000C	axis X position override switch					
K4200	Signal during axis X operation					
K4201	Error signal of axis X					
K420D	axis X constant speed signal					

(2) XEC

When error o	ccurs, resets	error and cancels	ouptut inhibition		
%IX0.1.0	% KX6721				
ErrorReset SW	XAxis Error				- REQ DONE - X_RST_DONE
				0	BASE STAT X_RST_STAT
				0	-SLOT
				0	AXIS
				1	- INH_ DFF
Sets axis X 1	floating orig	iin			
XIXO.1.1 Floating origin SW	XKX6720 // XAxis BUSY	XKX6721 // XAxis Error			INSTIO APM_FLT REQ DONE - X_FLT_DONE
				0	BASE STAT X_FLT_STAT
				0	SLOT
				0	AXIS

Axis X indir	ect start								
XIXO.1.2 P Indirect start	¥KX6720 ↓/↓ XAxis BUSY	XKX6721 ────// ─── XAxis Error		INST APM_ REQ	IST DONE -	X_IST_DONE			
			0	BASE	STAT	X_IST_STAT			
			0	SLOT					
			0	AXIS					
			1	STEP					
Override pos	ition into 60	0000							
XIXO.1.4 Position Override	%KX6720 ↓↓ XAxis BUSY	XKX6721 │/│ XAxis Error	XKX6733 XAxis Move Status(Con stant)	INST APM_I REQ	POR DONE -	POR_DONE			
			0	BASE	STAT	POR_STAT			
			0	SLOT					
			0	AXIS					
			60000	- POR ADDR					

(a) Devices Used

Device	Description
%IX0.1.0	Axis X error reset, output inhibition cancel switch
%IX0.1.1	axis X floating origin switch
%IX0.1.2	axis X indirect start switch
%IX0.1.4	axis X position override switch
%KX6720	Signal during axis X operation
%KX6721	Error signal of axis X
%KX6733	axis X constant speed signal

(3) Operation Data Setting

Step No.	coordinat es	Control pattern	Operation pattern	Operation type	Repeat step	Target position [pulse]	M code	Acc./Dec. No.	Operation speed [pls/s]	Dwell time [ms]
1	Absolut e	Position control	End	Single	0	100000	0	1	5000	100

(4) Operation Sequence

•P0009/%IX0.1.1 (floating origin) switch On : set as the floating origin at the current position.

•P000A/%IX0.1.2 (indirect start) switch On : axis X indirectly starts step 1.

[•]P000C/%IX0.1.4 (position override) switch On : overrides the current position to 60,000 when the current position is below 60,000.

7.2.13 Speed Override with Position

• The program example of positioning speed override during operation is as follows

(1) XBM/XBC

Γ

	P0008	K04201				CLR	0	0	1	In case of error, error reset, output inhibit
0	SW									cancel
	P0009	K04200	K04201				FLT	0	0	eet X avia Floating
8	FLT command	XAxis BUSY	XAxis Error							origin
	P000A	K04200	K04201			IST	0	0	1	
16	Indirect start	XAxis BUSY	XAxis Error							X axis indirect start
	P0000	K04200	K04201	K0420D	PSO	0	0	50000	5000	
25	PSO	XAxis BUSY	XAxis Error	XAxis Move Status(Con stant)						position to 60000
37									END	

Device	Description
P0008	Axis X error reset, output inhibition cancel switch
P0009	axis X floating origin switch
P000A	axis X indirect start switch
P000D	axis X positioning speed override switch
K4200	Signal during axis X operation
K4201	Error signal of axis X
K420D	axis X constant speed signal

(2) XEC

						·		INST8		
%IXO.1.0 —IP	%KX6721							APM_RST REQ DONE	X_RST_DONE	
ErrorReset SW	XÁxis Error									
							0	BASE STAT	X_RST_STAT	
							0	SLOT		
							0	AXIS		
							1	- INH_ OFF		
Gets axis X	floating ori	gin								
WINO 1 1	W/VCDO0	WI/VCE01						INST10		
Floating origin SW	XAxis BUSY	XKX6721 ————————————————————————————————————						APM_FLT REQ DONE	X_FLT_DONE	
							0	-BASE STAT	X_FLT_STAT	
							0	SLOT		
							0	AXIS		
xis X indir	ect start									
	AII (VOTO)			INS	T23					
XIXU.1.2 P Indirect start	XKX672U / XAxis BUSY	XKX6721 —— / — XAxis Error		- REQ	DONE -	X_IST_DONE				
		2.101	0	BASE	STAT-	X_IST_STAT				
			0	SLOT						
			0	AXIS						
			1	STEP						
				L						
)verride spe	ed into 5000	when curre	nt postion be	COMES	50000 T26					
%IX0.1.5	%KX6720	XKX6721	XKX6733	APM	PSO	DSU DONE				
Speed override with position	XAxis BUSY	XAxis Error	XAxis Move Status(Con stant)			PS0_DONE				
			0	BASE	STAT-	PS0_STAT				
			0	SLOT						
			0	AXIS						
			50000	-PSO ADDR						

٦

(a) Devices Us	sea
Device	Description
%IX0.1.0	Axis X error reset, output inhibition cancel switch
%IX0.1.1	axis X floating origin switch
%IX0.1.2	axis X indirect start switch
%IX0.1.5	axis X positioning speed override switch
%KX6720	Signal during axis X operation
%KX6721	Error signal of axis X
%KX6733	axis X constant speed signal

(a) Devices Used

Г

(3) Operation Data Setting

Step No.	coordinat es	Control pattern	Operation pattern	Operation type	Repeat step	Target position [pulse]	M code	Acc./Dec. No.	Operation speed [pls/s]	Dwell time [^{ms}]
1	Absolut e	Position control	End	Single	0	100000	0	1	10000	100

(4) Operation Sequence

•P0009/%IX0.1.1 (floating origin) switch On : set as the floating origin at the current position. •P000A/%IX0.1.2 (indirect start) switch On : axis X indirectly starts step 1.

•P000D/%IX0.1.5 (positioning speed override) switch On : overrides the current speed to 5000 when the current position reaches 50,000.

7.2.14 Speed, Position, and Parameter Teaching

• The program example of teaching of speed, position, and operation parameter is as follows (1) XBM/XBC

P0008	K04201		CLR	0	0	1	In case of error, erro reset, output inhibit cancel
0 P0009 PLT	K04200	K04201 / XAxis Error		FLT	0	0	set X axis Floating origin
8 P000A P Indirect	K04200	K04201 / XAvis Error	 IST	0	0	1	X axis indirect start
16 P000E P Speed teaching	K04200	K04201 / XAxais Error		DMOV	D0100	K0534 XAxis Step01	
25 P0008 P position teaching	K04200 XAxis BUSY	K04201 // XAxis Error	 	DMOV	D0102	Speed K0530 XAxis Step01	
31 P000F P parameter	K04200	KD4201		MOV	D0104	Position K0452 XAxis	
37				MOV	D0106	Speed Limit K0454	
			 	MOV	D0107	Acceleratio n Time 1 K0455	
_						XAxis Deceleratio n Time 1	

Device	Description
P0008	Axis X error reset, output inhibition cancel switch
P0009	axis X home return switch
P000A	axis X start switch
P000E	axis X speed teaching switch
P000B	axis X position teaching switch
P000F	axis X parameter teaching switch
K4200	Signal during axis X operation
K4201	Error signal of axis X
K534 ~ K535	axis X step 1 operation speed
D0100 ~ D0101	axis X speed change data (3000)
K530 ~ K531	axis X step 1 target position
D0100 ~ D0101	axis X speed change data (5000)
K452 ~ K453	axis X speed limit
K454	axis X deceleration time
K455	axis X acceleration time
D0100 ~ D0101	axis X speed limit setting data (10000)
D0102	axis X deceleration time 1 setting data (50)
D0103	axis X deceleration time 1 setting data (50)

(2) XEC

%IXO.1.0 %KX672	21	
ErrorReset XAxis SW Erroi	-	
		0 -BASE STAT X_RST_STAT
		0 -SLOT
		0 -AXIS
		1 - INHOFF
ets axis X floating	origin	
XIXO.1.1 XKX672	20 %KX6721	
Floating XAxis B origin SW	USV XAxis Error	
		0 -BASE STAT X_FLT_STAT
		0 -SLOT
		0 AXIS

∧ Indi	rect start			TMS	123				
(0.1.2 P irect tart	XKX6720 XAxis BUSV	XKX6721 / XAxis Error		APM REQ	-IST DONE -	X_IST_DONE			
			0	BASE	STAT	X_IST_STAT			
			0	SLOT					
			0	AXIS					
			1	STEP					
(O.1.6 ∤P ⊨−−− peed	%KX6720 ↓/↓ XAxis BUSY	XKX6721 // XAxis Error					EN MO	VE ENO -	ENO
						AxisX_Step O1_speed -	IN	OUT -	%KD267 XA×is StepO1 Speed
(0.1.3	%KX6720	% KX6721					мо	VE	
P ition aching	XAxis BUSY	XAxis Error					EN	'ENO -	ENO_1
						AxisX_Step O1_positio n -	IN	OUT -	%KD265 XAxis Step01 Position
X0.1.7	XKX6720	%KX6721							ENO 2
ameter aching	XAxis BUSY	XAxis Error							LHO_C
						AxisX_Spee d_limit -	. IN	OUT -	%KD226 XAxis Speed Limit
							EN MO	VE ENO -	EN0_3
						AxisX_Acce leration_T ime1	IN	оυт	%KW454
									XAxis Accelerati on Time 1
							MO EN	VE ENO	ENO_4
						Axis_Xdece leration_T	T KI	пп	≪VШ4EE
						(mei -	1 114		XAxis Decelerati

Γ

Device	Description
%IX0.1.0	Axis X error reset, output inhibition cancel switch
%IX0.1.1	axis X home return switch
%IX0.1.2	axis X start switch
%IX0.1.6	axis X speed teaching switch
%IX0.1.3	axis X position teaching switch
%IX0.1.7	axis X parameter teaching switch
%KX6720	Signal during axis X operation
%KX6721	Error signal of axis X
%KD267	axis X step 1 operation speed
AxisX_Step01_Speed	axis X speed change data (3000)
%KD265	axis X step 1 target position
AxisX_Step01_Position	axis X speed change data (5000)
%KD266	axis X speed limit
%KW454	axis X acceleration time
%KW455	axis X deceleration time
AxisX_Speed_limit	axis X speed limit setting data (10000)
AxisX_acceleration_time1	axis X acceleration time 1 setting data (50)
AxisX_deceleration_time1	axis X deceleration time 1 setting data (50)

(a) Devices Used

(3) Operation Data Setting

Step No.	coordinates	Control pattern	Operation pattern	Operation type	Repeat step	Target position [pulse]	M code	Acc./Dec. No.	Operation speed [pls/s]	Dwell time [ms]
1	Relative	Position control	End	Repeat	1	10,000	0	1	1000	100

(4) Positioning Basic Parameter Setting

Parameter	Set value			
Speed limit	100,000			
Acceleration time 1	100			
Deceleration time 1	100			

(5) Operation Sequence

•P0009/%IX0.1.1 (floating origin) switch On : set as the floating origin at the current position.

•P000A/%IX0.1.2 (indirect start) switch On : axis X indirectly starts step 1.

- speed : 1,000[pps]
- target position : 10,000[Pulse]

- acceleration/deceleration time : 100[ms]

•P000E/%IX0.1.6 (speed teaching) switch On after positioning is completed: speed of step 1 changes to 3,000[pps].

•P000A/%IX0.1.2 (indirect start) switch On : axis X indirectly starts step 1 again.

- speed : changes to 3,000[pps] and operates.

- target position : 10,000[Pulse]
- acceleration/deceleration time : 100[ms]

• P000B/%IX0.1.3 (position teaching) switch On after positioning is completed: the target position of step 1 changes to 5,000.

•P000A/%IX0.1.2 (indirect start) switch On : axis X indirectly starts step 1 again.

- speed : 3,000[pps]

- target position : changes to 5,000[Pulse] and operates.

- acceleration/deceleration time : 100[ms]

• P000F/%IX0.1.7 (parameter teaching) switch On after positioning is completed: positioning basic parameter is changed.

•P000A/%IX0.1.2 (indirect start) switch On : axis X indirectly starts step 1 again.

- speed : 3,000[pps]
- target position : 5,000[Pulse]
- acceleration/deceleration time : changes to $50 \ensuremath{\left[\text{ms}\right]}$ and

operates.

Remark

- Permanent Storage of Teaching Data
- If you have changed the operation data and parameter by using the DMOV instruction, you need to use the WRT instruction to save the changed value in the flash memory. Otherwise, it is initialized to the value saved in the previous flash memory when the power is off or the mode is changed.

Chapter 8 Troubleshooting Procedure

This chapter describes the errors that occur during the use of XGB PLC and the built-in positioning function, the method of finding the cause of the error, and the actions to take.

8.1 Basic Procedure of Troubleshooting

Although t is important to use a highly reliable device for normal operation of the system, it is important as well how to deal with a trouble quickly.

In case of a trouble, if you want to restart the system, it is critical to find the cause of the trouble and take an action as soon as possible. The basic troubleshooting points you need to keep in mind are as follows.

(1) Check with Naked Eye

- Check the following with your naked eye.
- Operation of the machine (in motion, not in motion)
- Power supply whether the rated voltage is normally supplied to XGB PLC
- Condition of the input and output devices
- Distribution (input and output lines, communication cables, expansion)
- Check the Indicators (PWR LED, RUN LED, STOP LED, input and output LED), and access the peripheral devices to check the PLC operation and program contents.

(2) Trouble Check

When you manipulate the device as follows, observe how the trouble develops.

- Turn the operation mode switch to STOP and turn On / Off.
- (3) Supposition of the Cause of Trouble
 - Suppose which of the following the cause of the trouble is.
 - Whether the cause is in the PLC or an external device
 - If the trouble is in the PLC, decide whether it is the trouble of the basic unit or other expansion modules.

• In the former is the case, decide whether there is a problem with the PLC parameter/program or hardware.

8.2 Check by Using the LED

If there is trouble in using the XGB built-in positioning function, you can roughly presume the cause of the trouble by checking the LED of XGB PLC. This chapter describes the LED related to the trouble of the positioning function. With respect to the trouble that occurs during use of other functions of the basic unit, refer to 'Hardware section of the XGB Manual.'

8.2.1 LED Check

Γ

If there is trouble during use of the positioning function, check the status of PWR LED, RUN LED and ERR LED of XGB PLC, and check the LED of the input and output contact point related to positioning.



(1) PWR LED Check

Check the PWR LED status and take the following actions.

LED	PLC trouble	Actions to take
On	 Rated voltage is normally supplied to XGB. 	 The power supply is normal, so check whether there is another cause.
Flashing	 One of the following might be the cause. Rated voltage/current set for the XGB is not being supplied. Problem with the PLC hardware Problem with external lines 	 Check the voltage and current of the power supply. Remove the input and output lines, re-supply power and check again. If there still is the same problem, contact the A/S office or customer center.
Off	 Power is not being supplied. Supplied voltage is lower than the rated voltage. The cable is severed. There is a problem with the PLC hardware. 	 Check whether rated voltage is being normally supplied to the PLC. If normally supplied, contact an A/S office or customer center.

(2) RUN LED Check

LED	PLC trouble	Actions to take
On	 The program is being normally operated. 	 Check whether there is another cause.
Off	 The running of the program has stopped. 	 The program has stopped. Check the ERR LED to find whether it is because of an error or the operation mode is STOP.

1

(3) ERR LED Check

LED		PLC trouble	Actions to take		
On	• A proble	m with the PLC hardware	 There is a problem with the PLC hardw so contact an A/S office or customer center 		
Flashing	Quick flashing (0.1 sec)	 Serious trouble that makes operation impossible 	 Access XGB with XG5000, execute 'Online' → 'PLC error/warning'. check the error and 		
, idoning	Slow flashing (0.5 sec) • A minor problem with operation continuing		warning, and remove the cause.`		
On	• The pro	gram is being normally run.	 The program is being normally run, so check whether there is another problem. 		

(4) Positioning Output LED Check

If no problem is found as a result of the check of the LED, check the LED of the output contact point related to the positioning function, and take the following actions.

(a) When the pulse output mode is the PLS/DIR mode

Signal	Contact point	LED status	Error and actions to take
	P20,P21	Fast flashing	 Pulse is being normally output by the positioning function. Check whether there is a problem with the lines of the XGB and motor driver.
Pulse output	(XBM, XBCH) P40,P41 (XBCS) Q00,Q01 (XECH,XECS)	Off	 Pulse is not being normally output. Positioning operation has finished (normal). → Start the next operation instruction. There is an error that makes positioning operation impossible. → Check the positioning error code and remove the cause. For the method of check the error code, refer to Appendix 1.1.

Signal	Contact point	LED status	Output level	Error and actions to take
			Low Active	• Direction signals are being output in the normal direction (normal).
Direction output	P22,P23 (XBM, XBCH) P42,P43	On	HIGH Active	 Direction signals are being output in the reverse direction (normal). Pulse is not being normally output Positioning operation has finished (normal) → Start the next operation instruction. There is an error that makes positioning operation impossible → Check the positioning error code and remove the cause.
	(XBCS) Q02,Q03 (XECH,XECS)	Off	Low Active	 Direction signals are being output in the reverse direction (normal) Pulse is not being normally output Positioning operation has finished (normal) → Start the next operation instruction. There is an error that makes positioning operation impossible → Check the positioning error code and remove the cause.
			HIGH Active	 Direction signals are being output in the normal direction (normal).

(b) When the pulse output mode is the CW/CCW mode

Signal	CW contact point	CCW contact point	Error and actions to take		
	Flashing	Off	 CW pulse is being normally output (normal). 		
		Flashing	 The pulse is being abnormally output. → Contact an A/S office or customer center. 		
CW output	Off	Off	 Pulse is not being output (normal). Positioning operation has finished (normal). → Start the next operation instruction. There is an error that makes positioning operation impossible. → Check the positioning error code and remove the cause 		
		Flashing	 CCW pulse is being normally output (normal). 		

Remark

Γ

• If PWR, RUN, and ERR LED are all off, there is a problem with the internal operation system of XGB. In such a case, XGB PLC cannot normally operate, so inquire of the customer center.

8.3 Check by Error Code

If there is found to be an error as a result of the check of the LED related to positioning, access XGB with XG5000, check the positioning error code, and remove the cause.

This chapter only describes how to check the positioning error codes. With respect to the details of error codes and actions to take, refer to Appendix 1.1.

8.3.1 How to Check Error Codes

The built-in positioning error code can be checked by using the XGB positioning monitoring package or the positioning error code device of area K in the following procedure.

- (1) Positioning Monitoring Package
- (a) Access PLC with XG5000.
- (b) Select 'Monitor' → 'Special Module Monitor' → 'Positioning Module,' the following monitoring package is executed. Select 'Start Monitor' at the left bottom, you can check the error code.



(2) Positioning Area K

- (a) You can check the error code by using the device monitor function of XG5000.
- (b) To check the error code of the XGB positioning function, monitor the following device. About how to use the device monitor, refer to the manual of XG5000.

	Area K address	Data size
Axis X	K427(%KW427)	Word
Axis Y	K437(%KW437)	Word

8.4 Check of Motor Failures

ſ

If the motor does not work despite there being no problem after the check according to the procedure described above, check the following.

8.4.1 If the Motor Doesn't Work

(1) Lines between the XGB and Motor Driver

- Check whether the lines between XGB and servo motor driver are connected rightly.
- For the specifications of the input and output of XGB, refer to Chapter 2.
- For examples of wiring between XGB and the motor driver, refer to Appendix 3.
- If you use a motor driver that is not addressed in this manual, refer to the manual of that motor driver.

(2) Setting of the Motor Driver

- If there is no problem with the wiring, check whether the input pulse of the motor driver is the same as that of the XGB.
- XGB only supports the open collector type. Check whether the motor driver you are using can accommodate the type, and check the setting of the motor driver.

(3) Check of the Motor Driver

• If no problem is found as a result of the procedure above, check whether pulse is actually supplied to the motor driver by using the oscilloscope. If the motor driver isn't working despite the pulse actually being supplied, refer to the manual of the motor driver and check whether there is an error of the driver.

Appendix 1 List of Error Codes

1.1 List of PLC Error Codes

The general error codes that might occur during XGB operation are as follows. To check the error codes, access XGB with XG5000 and execute 'online' \rightarrow 'PLC error/warning' menu.

1

Code	Cause	Action to take	Туре	LED status	Detected during
23	There is a problem with the program to run	Re-download and run the project	Minor	0.5 second Flicker	RUN
24	Over I/O parameter	Check the preservation by reading I/O parameter or basic	Minor	0.5 second Flicker	Reset RUN mode conversion
25	Over basic parameter	problem, correct it to Write with PLC and check the operation. If the problem still goes on, replace the basic unit.	Minor	0.5 second Flicker	Reset RUN mode conversion
30	The module set in I/O parameter does not match the actually mounted module.	Correct the I/O parameter for it to match the actually mounted module and write with PLC.	Minor	0.5 second Flicker	RUN mode conversion
31	Module is removed or another module is mounted during operation	Turn OFF -> ON.	Serious	0.1 second Flicker	Every scan
33	Data of input and output modules during operation are not normally collected	Replace the module and restart it after checking the input and	Serious	0.1 second Flicker	Scan end
34	Data of special/comm module during operation are not normally collected	output where the error took place by using XG5000.	Serious	0.1 second Flicker	Scan end
38	Number of additionally mounted modules exceeded	No more than 7 layer can be added, remove the excessively added modules and restart.	Serious	0.1 second Flicker	Every scan
39	PLC CPU operation overload or failure due to noise or hardware	 If repeated when resupply power, call A/S. Carry out noise action. 	Serious	0.1 second Flicker	Any time
40	Program scan time during operation exceeds the set scan delay monitoring time	Check the scan delay monitoring time of the basic parameter, and modify it or the program and restart.	Minor	0.5 second Flicker	Program running
41	Operation error during sequence program	Check the step where the operation error took place, remove the cause and restart.	Minor	0.5 second Flicker	Program running
44	Timer index use error	Modify the timer index program, write the program and restart.	Minor	0.5 second Flicker	Scan end
50	Serious failure is detected in external device due to sequence program	Refer to the serious failure detecting error flag of external device, repair it and restart.	Serious	0.1 second Flicker	Scan end
60	E_STOP function performed	Remove the cause of error that started the E-STOP function in the program and re-supply power.	Serious	0.1 second Flicker	Program running
500	Data memory backup error	Re-supply power. (converted to STOP mode in remote mode)	Warning	1 second Flicker	Power On

1.2 List of Positioning Error Codes

Γ

Error code that can be occurred in the XGB positioning is as follows.

The user can check error code through XGB dedicated positioning monitoring package or K area (X axis: K427, Y axis: K437). Error code occurs according to dedicated K area applied at starting.

For checking the relationship between positioning parameter and dedicated K area, refer to ch.3.2.

Error code	Description	Operation	Countermeasures
101	Exceeding the max speed range of basic parameter	Stop	Change the max speed value
102	Exceeding the bias speed of basic parameter 1) bias speed ≥ Speed limit 2) bias speed = 0	Stop	Re-adjust it lower then the max speed of basic parameter.
103	ACC time setting error 1) ACC time > 10,000 2) Jog ACC time > 10,000	Stop	Re-adjust ACC time of basic parameter lower than 10,000
104	DEC time setting error 1) DEC time > 10,000 2) Jog DEC time > 10,000	Stop	Re-adjust DEC time of basic parameter lower than 10,000
105	Setting non use dedicated positioning at parameter	Stop	Setting dedicate positioning.
111	Expansion parameter soft upper/lower limit error • S/W upper > S/W lower	Stop	Re-adjust S/W upper limit equal to or larger than the lower limit.
121	Manual operation parameter jog high speed range exceeding error 1) Jog high speed < bias speed 2) Jog high speed > > max speed 3) Jog high speed = 0	Stop	Re-adjust to be max speed≥jog high speed≥bias speed
	4) Jog high speed < Jog low speed		
122	 ivalual operation parameter jog low speed range exceeding error 1) Jog low speed < bias speed 2) Jog low speed > max speed 3) Jog low speed = 0 	Stop	Re-adjust to be jog high speed≥jog low speed≥ 1.
	4) Jog low speed > Jog high speed		
123	Manual operation parameter inching speed range exceeding error 1) inching speed < bias speed 2) inching speed > > max speed	Stop	Re-adjust to be max speed ≥ inching speed ≥ bias speed
131	Home return parameter home return mode value range exceeding error	Stop	Re-adjust to be $0 <$ home return parameter ≤ 3 . (1:Dog/origin(On) 2:upper/lower limit/origin 3:DOG)
132	Home return parameter home return address range exceeding error	Stop	Re-adjust to be S/W upper limit ≥ home return address≥ S/W lower limit
133	Home return parameter home return high speed range exceeding error 1) home return high speed < bias speed 2) home return high speed > max speed	Stop	Re-adjust to be max speed \geq home return high speed \geq bias speed
134	Home return parameter home return low speed range exceeding error 1) home return low speed < bias speed 2) home return low speed > home return high speed	Stop	Re-adjust to be home return high speed ≥home return low speed≥ bias speed
135	Home return dwell time out error of home return parameter • Home return dwell time > 50,000	Stop	Re-adjust dwell time lower than 50000.

Error code	Description	Operation	Countermeasures
136	Home return ACC time setting error • Home return ACC time > 10,000	Stop	Re-adjust home return ACC time lower than 10,000
137	Home return DEC time setting error • Home return DEC time > 10,000	Stop	R-adjust home return Dec time lower than 10,000.
151	Operation speed '0' setting error of operation data	Stop	Set operation speed over '0'.
152	Operation speed of operation data exceeding the max speed	Stop	Re-adjust to be max speed ≥ operation speed.
153	Operation speed of operation data set lower than bias speed.	Stop	Re-adjust to be operation speed ≥ bias speed.
154	Exceeding dwell time setting range of operation data	Stop	Set dwell time lower than 50000.
155	Exceeding end/continuous/sequential setting range of operation data	Stop	Re-set operation pattern of operation data as one of 0:end, 1:continuous or 2:sequential
201	Home return command is unavailable during operation	Stop	Check whether command axis was not operating at the time of home return command.
202	Home return command is unavailable in case of 'no output' status.	Stop	Check whether command axis was not in 'no output' status at the time of home return command.
211	Floating origin setting command is unavailable during operation.	Stop	Check whether command axis was not operating at the time of floating origin setting command.
221	Direct start command is unavailable during operation.	Stop	Check whether command axis was not operating at the time of direct start command
222	Direct start command is unavailable in case of 'no output ' status.	Stop	Check whether command axis was not in 'no output' status at the time of direct start command.
223	Direct start command is unavailable in case of M code On	Stop	Check whether M code of command axis was not On at the time of direct start command.
224	Direct start command is unavailable without origin set in absolute coordinate.	Stop	Absolute coordinate operation is not available without origin set. Check whether operation data to operate and the current origin set.
231	Indirect start command is unavailable during operation	Operati on	Check whether command axis was not operating at the time of indirect start command.
232	Indirect start command is unavailable in case of 'no output' status.	Stop	Check whether command axis was not in 'no output' status at the time of indirect command.
233	Indirect start command is unavailable in case of M code On.	Stop	Check whether M code signal of command axis was not On at the time of indirect start command.
234	Indirect start command is unavailable without origin set in absolute coordinate.	Stop	Absolute coordinate operation is not available without origin set. Check whether operation data to operate and the current origin set.
236	Continuous operation of indirect start is unavailable in speed control.	Stop	Re-set single or continuous operation if operation data control method is speed
241	Linear interpolation start is unavailable when main axis of linear interpolation s operating.	Operati on	Check whether main axis was not operating at the time of linear interpolation command.
242	Linear interpolation start is unavailable when sub axis of linear interpolation is operating.	Operati on	Check whether sub axis was not operating at the time of linear interpolation command.

Error code	Description	Operation	Countermeasures
244	Linear interpolation start is unavailable when main axis of linear interpolation is in 'Output disabled' status.	Stop	Check whether main axis was not in 'Output disabled' status at the time of linear interpolation command.
245	Linear interpolation start is unavailable when sub axis of linear interpolation is in 'Output disabled' status.	Stop	Check whether a sub axis was not in 'Output disabled' status at the time of linear interpolation command.
247	Linear interpolation start is unavailable when the M code signal of linear interpolation's main axis is On.	Stop	Check whether M code signal of main axis was not On at the time of linear interpolation command.
248	Linear interpolation start is unavailable when M code signal of linear interpolation's sub axis is On.	Stop	Check whether M code signal of sub axis was not On at the time of linear interpolation.
250	Absolute coordinate positioning operation is unavailable when the origin of linear interpolation sub axis is not set.	Stop	Absolute coordinate operation is not available without origin set. Check whether operation data to operate and the current origin set.
251	Absolute positioning operation is unavailable when the origin of linear interpolation's sub axis is not set.	Stop	Absolute coordinate operation is not available without origin set. Check whether operation data to operate and the current origin set.
253	Main axis and sub axis of linear interpolation are set incorrectly.	Stop	Re-set the axis date as 3 of linear interpolation command.
257	Linear interpolation is not available when the target position of main axis does not have a target position.	Stop	Check whether the target position of operation data of a step for linear interpolation was not the present status in case of absolute coordinate or set to '0' in case of Incremental coordinate.
258	Linear interpolation is unavailable when main axis is controlling speed.	Stop	Check whether the control method of main axis operation data step for linear interpolation operation was not set by speed control.
259	Linear interpolation is unavailable when sub axis is controlling speed.	Stop	Check whether the control method of sub axis operation data step for linear interpolation was not set by speed control.
291	Concurrent start command is unavailable during operation.	Operatio n	Check whether an axis with error was not contained in concurrent start command and whether there wasn't any operating axis at the time of the command
292	Concurrent start command is unavailable in 'no output' status.	Stop	Check whether an axis with error was not contained in concurrent start command and whether it was not in 'no output' status at the time of the command.
293	Concurrent start command is not available with M code On	Stop	Check whether an axis with error was not contained in concurrent start command and whether M code signal was not On at the time of the command.
294	Concurrent start command is unavailable without origin set	Stop	Concurrent start command with origin set
296	When concurrent start command axis is incorrectly set.	Stop	Re-set the axis date as 3 of concurrent start command
301	Speed/position switching command is unavailable while not operating.	Stop	Check whether an axis did not stop at the time of speed/position switching command.
302	Speed/position switching command is unavailable while not controlling speed.	Stop	Check whether an axis was not in speed control status at the time of speed/position switching command.
304	Speed/position switching command is unavailable without target position.	Stop	Check whether operation had a move(amount) at the time of speed/position switching command.

Γ
Error code	Description	Operation	Countermeasures
311	Position/speed switching command is unavailable while not operating.	Stop	Check whether an axis did not stop at the time of position/speed switching command.
312	Position/speed switching command is unavailable On a sub axis of synchronic operation.	Stop	Check whether an axis was operating as a synchronic operation sub axis at the time of position/speed switching command.
314	Position/speed switching command is unavailable during linear operation.	Operation	Check whether an axis was not in linear interpolation operation at the time of position/speed switching command.
321	DEC stop command is unavailable while not operating.	Stop	Check whether it was not operating at the time of DEC stop command.
322	DEC stop command is not available during jog operation.	Operation	Check whether it was not jog-operating at the time of DEC stop command.
341	Position synchronic command is not available during operation	Operation	Check whether an axis was not in operating at the time of position synchronic command
342	Position synchronic command is unavailable in 'no output' status.	Stop	Check whether an axis was not in 'no output' status at the time of position synchronic command.
343	Position synchronic command is unavailable with M code On.	Stop	Check whether M code signal of an axis was not On at the time of position synchronic command.
344	Position synchronic command is unavailable without origin set.	Stop	Absolute coordinate operation is not available without origin set. Check whether operation data to operate and the current origin set.
346	Position synchronic command is unavailable without origin of main axis set.	Stop	Check whether main axis was without origin set at the time of position synchronic command.
347	There is an error of setting main/sub axis of position synchronic command.	Stop	Check whether main axis of position synchronic command was not set equally with command axis.
351	Speed synchronic command is unavailable during operation.	Operation	Check whether an axis was not operating at the time of speed synchronic command.
352	Speed synchronic command is unavailable in 'no output' status.	Stop	Check whether an axis was not in 'no output' status at the time of speed synchronic command.
353	Speed synchronic command is unavailable with M code On	Stop	Check whether M code signal of an axis was not On at the time of speed synchronic command.
355	There is an error of main/sub axis setting of speed synchronic command.1) main/ sub axis were set equally2) set of main axis >5	Stop	Check whether the main axis of speed synchronic command was not set equally with command axis.
356	There is an error of synchronization ratio setting of speed synchronic command	Stop	Check whether the synchronization ratio of speed synchronic command was not set between 0~10,000.
357	Delay time setting error	Stop	Check whether delay time was set between 1 ~ 10ms.
361	Position override command is unavailable in any other status but 'busy'	Stop	Check whether an axis did not stop at the time of position override command.
362	Position override command is unavailable during dwelling	Stop	Check whether an axis was not dwelling at the time of position override command.
363	Position override command is unavailable in any other status but positioning operation.	Operation	Check whether an axis was not operating by position control at the time of position override command.
364	Position override command is unavailable for an axis of linear interpolation operation.	Operation	Check whether an axis was not in linear-interpolation operation at the time of position override command.

Error code	Description	Operation	Countermeasures
366	Position override command is unavailable for a synchronic operation sub axis.	Operation	Check whether an axis was not operating as a sub axis of synchronic operation at the time of position override command.
371	Speed override command is unavailable in any other status but 'busy'.	Stop	Check whether an axis did not stop at the time of speed override command.
372	Out-of speed override range error	Stop	Re-set the speed of speed override command equal to or lower than the max speed set in the basic parameter.
373	Speed override command is unavailable to an sub axis of linear interpolation operation.	Operation	Check whether an axis was not operating as a sub axis of linear interpolation at the time of speed override command.
375	Speed override command is unavailable to an sub axis of synchronic operation	Operation	Check whether an axis was not operating as a sub axis of synchronic operation at the time of speed override command.
377	Speed override command is unavailable in a DEC section	Operation	Check whether an axis was not decelerating for stoppage at the time of speed override command.
381	Positioning speed override command is unavailable in any other status but 'operation'.	Stop	Check whether an axis did not stop at the time of positioning speed override command.
382	Positioning speed override command is unavailable in any other operation but 'positioning operation'	Stop	Check whether an axis was not in speed control operation at the time of positioning speed override.
383	Out of speed override range error of positioning sped override command	Stop	Check whether the speed of positioning speed override command was not equal to or lower than the max speed set in parameter.
384	Positioning speed override command is unavailable to an sub axis of linear interpolation operation.	Operation	Check whether an axis was not operating as a sub axis of linear interpolation at the time of positioning speed override command.
386	Positioning speed override command is unavailable to an sub axis of synchronic operation.	Operation	Check whether an axis was not operating as a sub axis of synchronic operation at the time of positioning speed override command.
401	Inching command is unavailable during operation.	Operation	Check whether an axis was not operating at the time of inching command.
402	Inching command is unavailable in 'no output' status.	Stop	Check whether an axis was not in 'no output' status at the time of inching command.
411	Jog start command is unavailable during operation.	Operation	Check whether an axis was not operating at the time of jog start command.
412	Jog start command is unavailable in 'no output' status.	Stop	Check whether an axis was not in 'no output' status at the time of jog start command.
441	Start step number change/repeat operation start step number designation command is unavailable during operation.	Operation	Check whether an axis was not operating at the time of start step number change command.
442	Start step number change/repeat operation start step number command is unavailable during operation. 1) Step = 0 2) Step > 30(80 for high end)	Stop	Check whether the step number of start step number change command or repeat operation start step number designation command is equal to or higher than 1 and lower and 30(80 for high end) or within the range.
451	Present position preset command is unavailable during operation.	Operation	Check whether an axis was not operating at the time of present position present command.
452	Sub position data may not be set exceeding soft upper/lower limits at the time of present position preset command.	Stop	Check whether the position of present position present command was within the soft upper/lower limits.

Error code	Description	Operation	Countermeasures
481	emergency stop error	Stop	Remove emergency stop causes and clear the error by executing CLR command.
491	External emergency stop error	Stop	Remove emergency stop causes and clear the error with CLR command.
492	Hard upper limit error	Stop	Escape from external upper signal range by using jog command and clear the error with CLR command.
493	Hard lower limit error	Stop	Escape from external upper signal range by using jog command and clear the error with CLR command.
501	Soft upper limit error	Stop	Escape from soft upper limit range by using jog command and clear the error with CLR command.\
502	Soft lower limit error	Stop	Escape from soft lower limit range by using jog command and clear the error with CLR command.
511	Direction turning error during sequential operation	Stop	Check whether the direction are turned during sequential operation.
512	Step number error during indirect start.	Stop	A step over 30 was set in a command. Re-set step number between 1 ~ 30.
513	Address error during indirect start.	Stop	Check whether it repetitively operates a step of which address is '0' during indirection start.
601	PWM command is unavailable during operation.	Operation	Check whether an axis was not operating at the time of present position present command.
602	PWM command is unavailable in 'no output' status	Stop	Check whether an axis was not in 'no output' status at the time of inching command.
603	PWM Output Cycle setting error	Stop	Check whether PWM Output Cycle was set between 1 ~ 20,000.
604	PWM Off duty rate setting error	Operation / Stop	Check whether PWM Off duty rate was set between 1 ~ 100.
605	Speed override command is unavailable during PWM operation	Operation	Check whether an axis was not in PWM operation at the time of speed override command.
606	Position/speed switching command is unavailable during PWM operation	Operation	Check whether an axis was not in PWM operation at the time of position/speed switching command.

Appendix 2 Positioning Instruction and K area List

٦

Appendix 2.1 Positioning instruction list

Instruction used in the XGB positioning is as follows. For detail, refer to ch.5.2 \sim ch5.3

(1) In case of XBC/XBM.

Instructi ons	Description	Conditions	Remark
ORG	Home starting	Slot, command axis	5.2.1
FLT	Float origin setting	Slot, command axis	5.2.2
DST	Direct starting	Slot, command axis, position, speed, dwell time, M code, control word	5.2.3
IST	Indirect starting	Slot, command axis, step no.	5.2.4
LIN	Linear interpolation starting	Slot, command axis, step no., axis information	5.2.5
SST	Simultaneous starting	Slot, command axis, X step, Y step, Z step, axis information	5.2.6
VTP	Speed/position change	Slot, command axis	5.2.7
PTV	position/speed change	Slot, command axis	5.2.8
STP	Stop	Slot, command axis, DEC. time	5.2.9
SSP	Position synchronization	Slot, command axis, step no., main axis position, main axis setting	5.2.10
SSS	Speed synchronization	Slot, command axis, synchronization rate, delay time	5.2.11
POR	Position override	Slot, command axis, position	5.2.12
SOR	Speed override	Slot, command axis, speed	5.2.13
PSO	Speed override with position	Slot, command axis, position, speed	5.2.14
INCH	Inching starting	Slot, command axis, inching amount	5.2.15
SNS	starting step no. change	Slot, command axis, step no.	5.2.16
MOF	M code cancel	Slot, command axis	5.2.17
PRS	Current position preset	Slot, command axis, position	5.2.18
EMG	EMG stop	Slot, command axis	5.2.19
CLR	Error reset, output inhabit cancel	Slot, command axis, pulse output inhabit/allowed	5.2.20
WRT	Parameter/operation data saving	Slot, command axis, storage area selection	5.2.21
PWM	Pulse width modulation	Slot, instruction axis, output cycle, off duty rate	5.2.22

Remark

Γ

• XGB positioning instructions are activated at the rising edge. That is, when the execution contact point is On, it carried out the instruction only once. (PWM instruction is activated at the "On" level).

(2) In case of X	EC		
Function Block	Description	Conditions	Remark
APM_ORG	Start return to the origin	Req, Base, Slot, Axis	5.3.2
APM_FLT	Set floating origin	Req, Base, Slot, Axis	5.3.3
APM_DST	Direct starting	Req, Base, Slot, Axis, Position, speed, dwell time, M code, position/speed, absolute/incremental, ACC/DEC time	5.3.4
APM_IST	Indirect starting	Req, Base, Slot, Axis, step number	5.3.5
APM_LIN	Linear interpolation starting	Req, Base, Slot, Axis, step number	5.3.6
APM_SST	Simultaneous starting	Req, Base, Slot, Axis, X axis step, Y axis step, Z axis step	5.3.7
APM_VTP	Speed/position switching	Req, Base, Slot, Axis	5.3.8
APM_PTV	Position/speed switching	Req, Base, Slot, Axis	5.3.9
APM_STP	Stop	Req, Base, Slot, Axis, ACC/DEC time	5.3.10
APM_SSP	Position synchronization	Req, Base, Slot, Axis, Step number, main axis, Main axis position	5.3.11
APM_SSSB	Speed synchronization	Req, Base, Slot, Axis, main axis, rate of sub-axis, delay time	5.3.12
APM_POR	Position override	Req, Base, Slot, Axis, position	5.3.13
APM_SOR	Speed override	Req, Base, Slot, Axis, speed	5.3.14
APM_PSO	Positioning speed override	Req, Base, Slot, Axis, position, speed	5.3.15
APM_INC	Inching starting	Req, Base, Slot, Axis, inching amount	5.3.16
APM_SNS	Change starting step number	Req, Base, Slot, Axis, step number	5.3.17
APM_MOF	Cancel M code	Req, Base, Slot, Axis	5.3.18
APM_PRS	Preset current position	Req, Base, Slot, Axis, position	5.3.19
APM_EMG	Emergency stop	Req, Base, Slot	5.3.20
APM_RST	Reset error, cancel output inhibition	Req, Base, Slot, Axis, Enable/Disable pulse output	5.3.21
APM_WRT	Save parameter/operation data	Req, Base, Slot, Axis, Select area to save	5.3.22
APM_PWM	Pulse width modulation	Reg. Slot. Axis, output cycle, off duty rate	5.3.23

Appendix 2.2 Positioning Dedicated K area List

				K ar			
ltem	Setting range	Initial value	Туре	posit	ioning	Data size	
				X axis	Y axis		
Positioning		0	XBM/XBC	K4870	K5270	hit	
Fositioning	0. Not use, 1. use	0	XEC	%KX7792	%KX8432	Dit	
Pulse output level	0 : Low Active,	0	XBM/XBC	K4871	K5271	bit	
r uise output level	1 : High Active	0	XEC	%KX7793	%KX8433	Dit	
Pulse output mode	0 · CW/CCW 1 · PLS/DIR	0	XBM/XBC	K4873	K5273	Bit	
		0	XEC	%KX7795	%KX8435	Dit	
M Code Output			XBM/XBC	K4681 K4682	K5081		
Mode	2 : AFTER	0		%KX7489	%KX8129	2bit	
			XEC	%KX7490	%KX8130		
Disa su sad	1 . 100.000[pulpe/e]	4	XBM/XBC	K450	K490	Daublaumad	
Blas speed	$1 \sim 100,000$ [puise/s]	1	XEC	%KD225	%KD245	Double word	
	1 - 100 000[pulse/c]	400.000	XBM/XBC	K452	K492	Deuble werd	
Speed limit	$1 \sim 100,000$ [pulse/s]	100,000	XEC	%KD226	%KD246	Double word	
	0 ~ 10,000[unit: ms]	500	XBM/XBC	K454	K494))/(and	
ACC NO.1		500	XEC	%KW454	%KW494	VVord	
DEC No.1	0 ~ 10,000[unit: ms]	500	XBM/XBC	K455	K495	Word	
			XEC	%KW455	%KW495		
ACC No.2	0 ~ 10,000[unit: ms]	1,000	XBM/XBC	K456	K496		
			XEC	%KW456	%KW496	Word	
DEC No.2	0 ~ 10,000[unit: ms]	1,000	XBM/XBC	K457	K497	Word	
			XEC	%KW457	%KW497		
			XBM/XBC	K458	K498		
ACC No.3	0 ~ 10,000[unit: ms]	1,500	XEC	%KW458	%KW498	Word	
DEC No.3			XBM/XBC	K459	K499		
	0 ~ 10,000[unit: ms]	1,500	XEC	%KW459	%KW499	Word	
ACC No.4		0.000	XBM/XBC	K460	K500		
	0 ~ 10,000[unit: ms]	2,000	XEC	%KW460	%KW500	Word	
DEC No.5			XBM/XBC	K461	K501		
	0 ~ 10,000[unit: ms]	2,000	XEC	%KW461	%KW501	Word	
	-2,147,483,648 ~		XBM/XBC	K462	K502		
S/W Upper Limit	2,147,483,647 [pulse]	2,147,483,647	XEC	%KD231	%KD251	Double word	
0 M M H H H	-2,147,483,648 ~	-	XBM/XBC	K464	K504		
S/W Lower Limit	2,147,483,647 [pulse]	2,147,483,648	XEC	%KD232	%KD252	Double word	
Backlash			XBM/XBC	K466	K506		
Compensation	$0 \sim 65,535$ [puise]	0	XEC	%KW466	%KW506	Word	
CAN/ Limit Data at		0	XBM/XBC	K4684	K5084	4 Bit	
S/W LIMIT Detect	U. NO DETECT, 1 : DETECT	U	XEC	%KX7492	%KX8132		
	0 · No Detect 4 · Detect		XBM/XBC	K4872	K5272		
opper/Lower limit	U. NO DETECT, 1 : DETECT	1	XEC	%KX7794	%KX8434	Bit	

٦

Appendix 2.2.1 K area of positioning basic parameter

ltem	Setting range	Initial	Type	Dedic ar	Data size	
	eening range	value	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	X axis	Y axis	
Home Mathed	0.2	0	XBM/XBC	K4780 K4781	K5180 K5181	Di+
	0~2	0	XEC	%KX7648 %KX7649	%KX8288 %KX8289	Bit
Home Direction	0 : CW. 1 : CCW	1	XBM/XBC	K4782	K5182	Bit
			XEC	%KX7650	%KX8290	-
Home Address	-2.147.483.648~2.147.483.647[pulse]	0	XBM/XBC	K469	K509	Double word
	_,,,	Ŭ	XEC	%KD234	%KD254	
Home High Speed	$1 \sim 100000$ [pulse/s]	5 000	XBM/XBC	K471	K511	Double word
	1 100,000[puise/3]	5,000	XEC	%KD235	%KD255	
Home Low Speed	1 ~ 100,000[pulse/s]	500	XBM/XBC	K473	K513	Double word
Home Low Speed			XEC	%KD236	%KD256	
	0 ~ 10,000[unit: ms]	1,000	XBM/XBC	K475	K515	Word
			XEC	%KW475	%KW515	
		1,000	XBM/XBC	K476	K516	Word
	0 ~ 10,000[unit. ms]		XEC	%KW476	%KW516	
		0	XBM/XBC	K477	K517	
DWELL TIME	0 ~ 50,000[unit. ms]	0	XEC	%KW477	%KW517	vvoru
IOC Llink Croad	1 . 100.000[pulpo/o]	F 000	XBM/XBC	K479	K519	Devila word
JOG Fligh Speed	1 ¹⁰ 100,000[pulse/s]	5,000	XEC	%KD239	%KD259	Double word
	4 400 000[]	4 000	XBM/XBC	K481	K521	
JOG Low Speed	$1 \sim 100,000$ [pulse/s]	1,000	XEC	%KD240	%KD260	Double word
		4	XBM/XBC	K483	K523	
JOG ACC Time	0 ~ 10,000[unit: ms]	1,000	XEC	%KW483	%KW523	VVord
		4	XBM/XBC	K484	K524	
JOG DEC Time	0 ~ 10,000[unit: ms]	1,000	XEC	%KW484	%KW524	Word
la shina O		400	XBM/XBC	K485	K525	
inching Speed	$1 \sim 00,030$ [puise/s]	100	XEC	%KW485	%KW525	Word

Appendix 2.2.2 K area of positioning home parameter

Ston	Itom Sotting range		Initial	Dedicated K area		Doto cizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		ADC	K5484	K8484	
	Coold.	U. ABS, T. INC	ADS	%KX8772	%KX13572	Bit
	Pattorn			K5482~83	K8482~83	
	Fallem	0. END, 1. REEF, 2. CONT	END	%KX8770~71	%KX13570~71	Bit
	Control		POS	K5481	K8481	D
	Control		100	%KX8769	%KX13569	Bit
	Mathad		CINI	K5480	K8480	Dit
	Method			%KX8768	%KX13568	DIL
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K549	K849	Word
				%KW549	%KW849	
1	Address	Address [pulse] -2,147,483,648~2,147,483,647 [pulse]	0	K540	K840	Double word
	[pulse] -2,14			%KD270	%KD420	
	M Code	0 65 525	0	K547	K847	Word
	W Code	0~65,535	0	%KW547	%KW847	vvora
	A/D No.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	K5486~87	K8486~87	Bit
				%KX8774~75	%KX13574~75	
	Speed	$1 \sim 100.000$ [pulso/s]	0	K544	K844	
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD272	%KD422	Double word
	Dwell	0 - 50 000[upit:ms]	0	K546	K846	Word
	Dweil	0 ~ 50,000[unit: ^{ms}]	0	%KW546	%KW846	VVord

Appendix 2.2.3 Positioning operation data K area

Ston	Itom	m Sotting range		Dedicate	Doto cizo	
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		400	K5484	K8484	
	Coord.	U. ABS, T. INC	AD3	%KX8772	%KX13572	Bit
	Pattern			K5482~83	K8482~83	
	rattern	U. END, T. REEF, Z. CONT	LIND	%KX8770~71	%KX13570~71	Bit
	Control		POS	K5481	K8481	D'/
	Control		100	%KX8769	%KX13569	Bit
	Mathad	0 : SIN, 1 : REP	SIN	K5480	K8480	Bit
	Method		SIN	%KX8768	%KX13568	DIL
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K549	K849	Word
				%KW549	%KW849	
2	Address	-2,147,483,648~2,147,483,647 [pulse]	0	K540	K840	Double word
	[pulse]			%KD270	%KD420	
	M Code	0 - 65 535	0	K547	K847	Word
	M Code	0~00,000	0	%KW547	%KW847	word
	A/D No.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	K5486~87	K8486~87	Bit
				%KX8774~75	%KX13574~75	
	Speed	$1 \sim 100.000$ [pulse/s]	0	K544	K844	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD272	%KD422	Double word
	Dwoll	0 50 000[upit:ms]	0	K546	K846	Word
	Dwell		0	%KW546	%KW846	vvoru

Ston	ltom	Sotting range	Initial	Dedicate	Data aira	
Step	nem	Setting range	value	X axis	Y axis	Dala Size
	Coord			K5584	K8584	
	Coora.	U: ABS, 1: INC	ABS	%KX8932	%KX13732	Bit
	Dottorn			K5582~83	K8582~83	
	Pallem	0. END, T. KEEP, Z. CONT	END	%KX8930~31	%KX13730~31	Bit
	Control		POS	K5581	K8581	
	Control	0.100, 1.010	100	%KX8929	%KX13729	Bit
	Method		CIN	K5580	K8580	Dit
		U. SIN, I. KEP	SIN	%KX8928	%KX13728	BI
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K559	K859	Word
				%KW559	%KW859	
3	Address	$2147492649 \sim 2147492647$ [pulco]	0	K550	K850	Double word
	[pulse]	-2,147,483,848°2,147,483,847 [pulse]	0	%KD275	%KD425	
	M Code	0 - 65 535	0	K557	K857	Word
	IN CODE	0~00,000		%KW557	%KW857	word
	A/D No.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	K5586~87	K8586~87	Bit
				%KX8934~35	%KX13734~35	
	Speed	$1 \sim 100000$ [nulse/s]	0	K554	K854	Double word
	Opeed		0	%KD277	%KD427	
	Dwall		0	K556	K856	Word
	Dwell (0 ~ 50,000[unit: ^{ms}]	U	%KW556	%KW856	vvord

Stop	Itom	Item Setting range		Dedicat	Doto cizo	
Step	nem	Setting range	value	X axis	Y axis	Dala Size
	Coord			K5684	K8684	
	Coord.	U. ABS, T. INC	ADS	%KX9092	%KX13892	Bit
	Pattorn			K5682~83	K8682~83	
	Fallem	0. END, 1. REEF, 2. CONT	END	%KX9090~91	%KX13890~91	Bit
	Control		DOS	K5681	K8681	
	Control	0. FO3, T. 3FD	F03	%KX9089	%KX13889	Bit
	Method		SIN	K5680	K8680	Bit
				%KX9088	%KX13888	DIL
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K569	K869	Word
				%KW569	%KW869	
4	Address	-2,147,483,648~2,147,483,647 [pulse]	0	K560	K860	Double word
	[pulse]			%KD280	%KD430	
	M Code	0 ~ 65 535	0	K567	K867	
	M Oode	0 - 00,000	0	%KW567	%KW867	Word
	A/D No.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	K5686~87	K8686~87	Bit
				%KX9094~95	%KX13894~95	
	Speed	1 - 100 000[pulco/o]	0	K564	K864	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD282	%KD432	Double word
	Durall		0	K566	K866	\\/ord
	Dwell		U	%KW566	%KW866	vvora

Ston	ltom	Sotting rongo	Initial	Dedicat	Dedicated K area	
Step	nem	Setting range	value	X axis	Y axis	Dala Size
	Coord			K5784	K8784	
	Coord.	U. ABS, T. INC	ADS	%KX9252	%KX14052	Bit
	Dottorn			K5782~83	K8782~83	
	Fallem	0. END, 1. REEF, 2. CONT	END	%KX9250~51	%KX14050~51	Bit
	Control		DOS	K5781	K8781	
	Control	0. FOS, 1. SFD	FU3	%KX9249	%KX14049	Bit
	Method	0 : SIN, 1 : REP	SIN	K5780	K8780	Dit
			SIN	%KX9248	%KX14048	זום
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K579	K879	Word
				%KW579	%KW879	
5	Address	$2 147 492 649 \sim 2 147 492 647 [pulse]$	0	K570	K870	Double word
	[pulse]	-2,147,403,048 -2,147,403,047 [pulse]		%KD285	%KD435	Double word
	M Code	0 - 65 535	0	K577	K877	Word
	M Code	0~00,000	0	%KW577	%KW877	word
	A/D No.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	K5786~87	K8786~87	Bit
				%KX9254~55	%KX14054~55	
	Speed	1 - 100 000[pulse/s]	0	K574	K874	Double word
	Speed	$1 \sim 100,000$ [puise/s]	0	%KD287	%KD437	
	Dwell	0 - 50 000[upit:ms]	0	K576	K876	Word
	Dweil	0 ~ 50,000[unit:118]	0	%KW576	%KW876	vvord

Ston	ltom	Sotting rongo	Initial	Dedicate	ed K area	Dete cire
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord			K5884	K8884	
	C0010.	U. ABS, T. INC	AD3	%KX9412	%KX14212	Bit
	Pattorn			K5882~83	K8882~83	Bit
	Fallem	0. END, 1. REEF, 2. CONT	LIND	%KX9410~11	%KX14210~11	
	Control		DO0	K5881	K8881	Bit
	Control	0. FO3, 1. 3FD	FU3	%KX9409	%KX14209	
	Method		CINI	K5880	K8880	Bit
		U. SIN, T. REF	SIN	%KX9408	%KX14208	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K589	K889	
			0	%KW589	%KW889	Word
6	Address	-2,147,483,648~2,147,483,647 [pulse]	0	K580	K880	Deuble word
	[pulse]			%KD290	%KD440	Double word
	M Code	0 65 525	0	K587	K887	
	M Code	0~ 65,555	0	%KW587	%KW887	word
	A/D No.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	K5886~87	K8886~87	Bit
				%KX9414~15	%KX14214~15	
	Speed	1 a. 100 000[pulse/c]	0	K584	K884	Double word
	Speed	1 ~ 100,000[pulse/s]	0	%KD292	%KD442	
	Dwell	0 ~ 50,000[unit:ms]	0	K586	K886	Word
			U	%KW586	%KW886	

Stop	Itom	Setting range	Initial	Dedicate	ed K area	Data sizo
Step	nem	Setting range	value	X axis	Y axis	Dala Size
	Coord			K5984	K8984	
	Coold.	U. ABS, T. INC	ADS	%KX9572	%KX14372	Bit
	Pattorn			K5982~83	K8982~83	Bit
	Fallem	0. END, 1. REEF, 2. CONT	END	%KX9570~71	%KX14370~71	
	Control		DOG	K5981	K8981	
	Control	10 : POS, 1 : SPD	P05	%KX9569	%KX14369	Bit
	Method	0 · SIN 1 · REP	SIN	K5980	K8980	Bit
	Method		SIN	%KX9568	%KX14368	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K599	K899	
			0	%KW599	%KW899	Word
7	Address	Address -2 147 483 648 ~ 2 147 483 647 [pulse]	0	K590	K890	Double word
	[pulse]	-2,147,403,040 2,147,403,047 [puise]	U	%KD295	%KD445	Double word
	M Code	0 ~ 65 535	0	K597	K897	Word
	M Couc	0.00,000	Ŭ	%KW597	%KW897	Word
	A/D No.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	K5986~87	K8986~87	Bit
				%KX9574~75	%KX14374~75	
	Speed	$1 \sim 100000$ [pulse/s]	0	K594	K894	Double word
	Speed	1 ~ 100,000[pulse/s]	0	%KD297	%KD447	Double word
	Dwell	0 ~ 50,000[unit:ms]	0	K596	K896	Word
			0	%KW596	%KW896	

Ston	ltem	Setting range	Initial	Dedicate	ed K area	Doto cizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		ADC	K6084	K9084	
	Coord.	U. ABS, T. INC	ADS	%KX9732	%KX14532	Bit
	Pattorn			K6082~83	K9082~83	
	Fallelli	0. END, 1. REEF, 2. CONT	END	%KX9730~31	%KX14530~31	Bit
	Control	0 : POS. 1 : SPD	POS	K6081	K9081	Bit
	Control		100	%KX9729	%KX14529	
	Method		CINI	K6080	K9080	Dit
		U. SIN, T. REP	211	%KX9728	%KX14528	DIL
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K609	K909	Word
			0	%KW609	%KW909	
8	Address 2 147 483 648	$2147482648 \sim 2147482647$ [pulse]	0	K600	K900	Double word
	[pulse]	-2,147,483,648~2,147,483,647 [pulse]	0	%KD300	%KD450	
	M Code	0 ~ 65 535	0	K607	K907	Word
	W Code	0 ~ 00,000	0	%KW607	%KW907	word
	A/D No.	0 : No.1. 1 : No.2. 2 : No.3. 3 : No.4	0	K6086~87	K9086~87	Bit
				%KX9734~35	%KX14534~35	
	Speed	$1 \sim 100000$ [pulse/s]	0	K604	K904	Double word
	Opeeu		0	%KD302	%KD452	
	Durall		0	K606	K906	Word
	Dwell		0	%KW606	%KW906	vvoru

Stop	ltom	Sotting rongo	Initial	Dedicate	ed K area	Doto cizo
Step	item	Setting range	value	X axis	Y axis	Dala Size
	Coord		ADC	K6184	K9184	
	Coold.	U. ABS, T. INC	AD3	%KX9892	%KX14692	Bit
	Pattern		END	K6182~83	K9182~83	D .4
	1 alloin	0. END, T. KEEF, Z. CONT	LIND	%KX9890~91	%KX14690~91	Bit
	Control		POS	K6181	K9181	Bit
	Control	0.F03, 1.3FD	F03	%KX9889	%KX14689	
	Method		CIN	K6180	K9180	Bit
			SIN	%KX9888	%KX14688	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K619	K919	
			0	%KW619	%KW919	Word
9	Address 2 147 492 64	2 147 492 649 - 2 147 492 647 [pulse]	0	K610	K910	Double word
	[pulse]	-2,147,483,848**2,147,483,847 [pulse]	0	%KD305	%KD455	
	M Code	0 ~ 65 535	0	K617	K917	Word
	M Oode	0.000	0	%KW617	%KW917	Word
		0 · No 1 1 · No 2 2 · No 3 3 · No 4	0	K6186~87	K9186~87	Bit
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX9894~95	%KX14694~95	Dit
	Oneral	4 400 000[million/1	0	K614	K914	Double word
	Speed	1 ~ 100,000[pulse/s]	0	%KD307	%KD457	
	Dwell	0 ~ 50,000[unit: ^{ms}]		K616	K916	Word
			0	%KW616	%KW916	

Ston	ltom	Setting range	Initial	Dedicate	d K area	Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord			K6284	K9284	
	Coord.	U: ABS, T: INC	ABS	%KX10052	%KX14852	Bit
	Dottorn			K6282~83	K9282~83	
	Fallem	0. END, 1. REEF, 2. CONT	END	%KX10050~51	%KX14850~51	Bit
	Control		POS	K6281	K9281	
	Control	0. FO3, 1. 3FD	F03	%KX10049	%KX14849	Bit
	Method	0 · SIN 1 · REP	CIN	K6280	K9280	Bit
	Method		511	%KX10048	%KX14848	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K629	K929	Word
			0	%KW629	%KW929	
10	Address	$2147482648\sim 2147482647$ [pulso]	0	K620	K920	Double word
	[pulse]	-2,147,403,040 -2,147,403,047 [puise]	0	%KD310	%KD460	
	M Code	0 ~ 65 535	0	K627	K927	Word
	M Code	0 ~ 00,000	0	%KW627	%KW927	word
	A/D No.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	K6286~87	K9286~87	Bit
				%KX10054~55	%KX14854~55	
	Speed	$1 \sim 100000$ [pulse/s]	0	K624	K924	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD312	%KD462	
	Dwell	0 ~ 50,000[unit:ʷs]	0	K626	K926	Word
			0	%KW626	%KW926	

Stop	Itom	Setting range	Initial	Dedicated K area		Data sizo
Step	nem	Setting range	value	X axis	Y axis	Dala Size
	Coord			K6384	K9384	
	Coord.	U. ABS, T. INC	ADS	%KX10212	%KX15012	Bit
	Pattern		END	K6382~83	K9382~83	
	Fallem	0. END, T. REEF, Z. CONT	END	%KX10210~11	%KX15010~11	Bit
	Control		POS	K6381	K9381	
	Control	0. F03, 1. 3FD	F03	%KX10209	%KX15009	Bit
	Method		SIN	K6380	K9380	Bit
	Method		OIN	%KX10208	%KX15008	Dit
		0 20 (0 80 for birth and)	0	K639	K939	
	REP Step		0	%KW639	%KW939	Word
11	Address		0	K630	K930	Double
	[pulse]	-2,147,483,648~2,147,483,647 [pulse]	0	%KD315	%KD465	word
	M Codo	0 65 525	0	K637	K937	Word
	M Code	0~ 65,535	0	%KW637	%KW937	word
	A/D No	0 · No 1 1 · No 2 2 · No 3 3 · No 4	0	K6386~87	K9386~87	Bit
			Ū.	%KX10214~15	%KX15014~15	
	Speed	1 . 100.000[puloo/o]	0	K634	K934	Double
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD317	%KD467	word
	D "			K636	K936	
	Dwell	$[0 \sim 50,000[unit:^{ms}]]$	U	%KW636	%KW936	Word

Ston	Itom	Sotting range	Initial	Dedicated K area		Doto cizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord			K6484	K9484	
	Coord.	U. ABS, T. INC	ADS	%KX10372	%KX15172	Bit
	Dottorn			K6482~83	K9482~83	
	Fallem	0. END, 1. REEF, 2. CONT	END	%KX10370~71	%KX15170~71	Bit
	Control		DOC	K6481	K9481	Bit
	Control	0. FOS, 1. SFD	F03	%KX10369	%KX15169	
	Mathad		CINI	K6480	K9480	Bit
	Method	U. SIN, T. REF	311	%KX10368	%KX15168	
	REP Step	$0 \sim 30 (0 \sim 80 \text{ for high - end})$	0	K649	K949	
			0	%KW649	%KW949	vvord
12	Address [pulse]	-2,147,483,648~2,147,483,647 [pulse]	0	K640	K940	Double word
				%KD320	%KD470	
		0.05.505	0	K647	K947	
	M Code	0~65,535	0	%KW647	%KW947	vvord
	A/D No.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	K6486~87	K9486~87	Bit
				%KX10374~75	%KX15174~75	
	Spood	$1 \sim 100.000$ [pulso/c]	0	K644	K944	Double word
	Speed	1 ~ 100,000[pulse/s]	0	%KD322	%KD472	
	Durall		0	K646	K946	Word
	Dweii		U	%KW646	%KW946	word

Ston	ltom	Setting range	Initial	Dedicate	d K area	Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord			K6584	K9584	
	Coold.	U. ABS, T. INC	ADS	%KX10532	%KX15332	Bit
	Dottorn			K6582~83	K9582~83	
	Fallem	0. END, 1. REEF, 2. CONT	END	%KX10530~31	%KX15330~31	Bit
	Control		DOC	K6581	K9581	Bit
	Control	0.100, 1.010	105	%KX10529	%KX15329	
	Mathad		CIN	K6580	K9580	Bit
	Method	U. SIN, T. REP	3111	%KX10528	%KX15328	
	REP Step	0, 20, (0, 0) for kirk and	0	K659	K959	
			0	%KW659	%KW959	Word
13	Address	-2,147,483,648~2,147,483,647 [pulse]	0	K650	K950	Double word
	[pulse]		0	%KD325	%KD475	Double word
	M Code	0 - 65 535	0	K657	K957	Mord
	M Code	0~03,335	0	%KW657	%KW957	word
	A/D No.	0 : No.1. 1 : No.2. 2 : No.3. 3 : No.4	0	K6586~87	K9586~87	Bit
		,, _,, _	-	%KX10534~35	%KX15334~35	
	Speed	1 . 100 000[puloe/o]	0	K654	K954	Double word
	Speed	1 ~ 100,000[pulse/s]	0	%KD327	%KD477	
	Dwell	Dwell 0 ~ 50,000[unit:ms]		K656	K956	Word
			U	%KW656	%KW956	

Ston	ltom	Setting range	Initial	Dedicated K area		Data sizo
Step	item	Setting range	value	X axis	Y axis	Dala Size
	Coord		ARC	K6684	K9684	
	Coold.		ABS	%KX10692	%KX15492	Bit
	Pattern		END	K6682~83	K9682~83	Bit
		0. END, 1. REEF, 2. CONT		%KX10690~91	%KX15490~91	
	Control			K6681	K9681	
	Control	0 : POS, 1 : SPD	P05	%KX10689	%KX15489	Bit
	Method		SIN	K6680	K9680	Bit
		U. SIN, T. REF	311	%KX10688	%KX15488	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K669	K969	Word
14			0	%KW669	%KW969	
14	Address	2 1 47 492 649 - 2 1 47 492 647 [puloe]	0	K660	K960	Double word
	[pulse]	-2,147,403,048 - 2,147,403,047 [puise]	0	%KD330	%KD480	
	M Code	0 - 65 535	0	K667	K967	Word
	M Code	0~00,000	0	%KW667	%KW967	word
			0	K6686~87	K9686~87	Dit
	A/D NO.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	%KX10694~95	%KX15494~95	Bit
	Spood	1 - 100 000[puloo/o]	0	K664	K964	Double word
	Speed	1 ~ 100,000[pulse/s]	0	%KD332	%KD482	Double Word
	Durall	0 ~ 50,000[unit: ^{ms}]	_	K666	K966	Word
	Dwell		U	%KW666	%KW966	

Stop	Itom	Setting range	Initial	Dedicate	d K area	Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord			K6784	K9784	
	Coord.	U: ABS, 1: INC	ABS	%KX10852	%KX15652	Bit
	Dottorn			K6782~83	K9782~83	
	Fallem	0. END; 1. REEF, 2. CONT	END	%KX10850~51	%KX15650~51	Bit
	Control		DOS	K6781	K9781	
	Control	0.F03, 1.3FD	FU3	%KX10849	%KX15649	Bit
	Method		CIN	K6780	K9780	Bit
		U. SIN, T. KEP	311	%KX10848	%KX15648	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K679	K979	Word
15			0	%KW679	%KW979	
15	Address	2 1 47 492 649 - 2 1 47 492 647 [pulse]	0	K670	K970	Double word
	[pulse]	-2,147,483,648~2,147,483,647 [pulse]	0	%KD335	%KD485	
	M Codo	0 65 525	0	K677	K977	
	M Code	0 ~ 65,535	0	%KW677	%KW977	word
			0	K6786~87	K9786~87	Dit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX10854~55	%KX15654~55	DIL
	Spood	$1 \sim 100.000$ [pulso/c]	0	K674	K974	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD337	%KD487	
	Dwell	0 50 000[upit:ms]	0	K676	K976	Word
			U	%KW676	%KW976	

Stop	ltem	Setting range	Initial	I Dedicated K area		Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		ADC	K6884	K9884	
	C0010.	U. ABS, T. INC	AD3	%KX11012	%KX15812	Bit
	Pattern	0 : END. 1 : KEEP. 2 : CONT	END	K6882~83	K9882~83	Bit
		0. END, 1. REEF, 2. CONT		%KX11010~11	%KX15810~11	
	Control		POS	K6881	K9881	
	Control	0.100, 1.010	103	%KX11009	%KX15809	Bit
	Method	0 : SIN. 1 : REP	SIN	K6880	K9880	Bit
			SIN	%KX11008	%KX15808	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K689	K989	Word
16			U	%KW689	%KW989	
10	Address	$-2147483648 \sim 2147483647$ [nulse]	0	K680	K980	Double word
	[pulse]	-2,147,400,040 2,147,400,047 [puise]	U	%KD340	%KD490	
	M Code	0 ~ 65 535	0	K687	K987	Word
	Ni Code	0~00,000	0	%KW687	%KW987	word
		$0 \cdot N = 1 \cdot 1 \cdot N = 2 \cdot 2 \cdot N = 3 \cdot 3 \cdot N = 4$	0	K6886~87	K9886~87	Bit
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX11014~15	%KX15814~15	Dit
	Speed	$1 \sim 100.000$ [pulse/s]	0	K684	K984	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD342	%KD492	Double word
	Dwoll		0	K686	K986	Word
	Dweil		0	%KW686	%KW986	vvoru

Stop	ltom	Setting range	Initial	Dedicate	d K area	Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord			K6984	K9984	
	Coold.	U. ABS, T. INC	ADS	%KX11172	%KX15972	Bit
	Dottorn			K6982~83	K9982~83	
	Fallelli	0. END, 1. REEF, 2. CONT	END	%KX11170~71	%KX15970~71	Bit
	Control		POS	K6981	K9981	
	Control	0.F03, 1.3FD		%KX11169	%KX15969	Bit
	Method		SINI	K6980	K9980	Bit
		U. SIN, T. REF	SIN	%KX11168	%KX15968	Dit
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K699	K999	Word
17			0	%KW699	%KW999	
17	Address		0	K690	K990	Double word
	[pulse]	-2,147,463,646~2,147,463,647 [puise]		%KD345	%KD495	
	M Codo	0 65 525	0	K697	K997	Word
	M Code	0 ~ 89,935	0	%KW697	%KW997	word
			0	K6986~87	K9986~87	Dit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX11174~75	%KX15974~75	DIL
	Speed	$1 \sim 100.000$ [pulso/s]	0	K694	K994	Double word
		$1 \sim 100,000$ [pulse/s]	0	%KD347	%KD497	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	K696	K996	Word
			U	%KW696	%KW996	

Stop	Itom	Setting range	Initial	Dedicate	d K area	Doto cizo
Step	item	Setting range	value	X axis	Y axis	Dala Size
	Coord			K7084	K10084	
	Coold.	U. ABS, T. INC	AD3	%KX11332	%KX16132	Bit
	Pattern	0 · END 1 · KEEP 2 · CONT	END	K7082~83	K10082~83	
				%KX11330~31	%KX16130~31	Bit
	Control		POS	K7081	K10081	
	Control	0.100, 1.010	100	%KX11329	%KX16129	Bit
	Method		SIN	K7080	K10080	Bit
			OIN	%KX11328	%KX16128	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K709	K1009	Word
18			0	%KW709	%KW1009	
10	Address	-2 147 483 648~2 147 483 647 [pulse]	0	K700	K1000	Double word
	[pulse]	-2,147,403,040 2,147,403,047 [puise]	0	%KD350	%KD500	
	M Code	0 - 65 535	0	K707	K1007	\A/ord
	IN CODE	0~03,333	0	%KW707	%KW1007	word
			0	K7086~87	K10086~87	Bit
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX11334~35	%KX16134~35	Dit
	Speed	1 a. 100 000[puloo/o]	0	K704	K1004	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD352	%KD502	
	Durall	0 50 000[upitumo]	0	K706	K1006	\\/ord
	Dweii		U	%KW706	%KW1006	word

Ston	ltem	Setting range	Initial	I Dedicated K area		Data sizo
Step	nem	Setting range	value	X axis	Y axis	Dala Size
	Coord			K7184	K10184	
	Coold.	U. ABS, T. INC	ADS	%KX11492	%KX16292	Bit
	Dottorn			K7182~83	K10182~83	
	Fallelli	0. END, 1. KEEP, 2. CONT	LIND	%KX11490~91	%KX16290~91	Bit
	Control		POS	K7181	K10181	
		0.F03, 1.3FD	F03	%KX11489	%KX16289	Bit
	Method		SIN	K7180	K10180	Dit
			311	%KX11488	%KX16288	Dit
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K719	K1019	Word
10			0	%KW719	%KW1019	
13	Address	-2,147,483,648~2,147,483,647 [pulse]	0	K710	K1010	Double word
	[pulse]			%KD355	%KD505	
	M Codo	0 65 525	0	K717	K1017	Word
	W Code	0~05,555	0	%KW717	%KW1017	word
			0	K7186~87	K10186~87	Bit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX11494~95	%KX16294~95	Bit
	Speed	$1 \sim 100.000$ [pulso/s]	0	K714	K1014	Double word
		$1 \sim 100,000$ [pulse/s]	0	%KD357	%KD507	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	K716	K1016	Word
			0	%KW716	%KW1016	

Ston	Itom	Soffing range	Initial	Dedicate	d K area	Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		ABS	K7284	K10284	
	00010.	U. ABS, T. INC	ABS	%KX11652	%KX16452	Bit
	Pattern		END	K7282~83	K10282~83	Bit
		0. END, T. KEEF, Z. CONT		%KX11650~51	%KX16450~51	
	Control		POS	K7281	K10281	Bit
		0.100, 1.310	105	%KX11649	%KX16449	
	Method		SIN	K7280	K10280	Bit
			511	%KX11648	%KX16448	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K729	K1029	Word
20			0	%KW729	%KW1029	
20	Address	2 147 492 649 - 2 147 492 647 [puloo]	0	K720	K1020	Double word
	[pulse]	-2,147,403,040 -2,147,483,047 [pulse]		%KD360	%KD510	
	M Codo	0 65 525	0	K727	K1027	Word
	M Code	0~05,555	0	%KW727	%KW1027	
			0	K7286~87	K10286~87	Dit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX11654~55	%KX16454~55	DIL
	Speed	1 - 100.000[puloo/o]	0	K724	K1024	Double word
	Speed	1 ¹⁰ 100,000[pulse/s]	0	%KD362	%KD512	
	Dwall	0 50 000[upitumo]	0	K726	K1026	\\/ord
	Dweil		U	%KW726	%KW1026	word

Stop	ltom	Setting range	Initial	Dedicate	d K area	Doto cizo
Step	item	Setting range	value	X axis	Y axis	Dala Size
	Coord			K7384	K10384	
	Coold.	U. ABS, T. INC	ADO	%KX11812	%KX16612	Bit
	Pattorn			K7382~83	K10382~83	
	1 alloin	0. END, 1. REEF, 2. CONT	LIND	%KX11810~11	%KX16610~11	Bit
	Control		DOC	K7381	K10381	
	Control	0.F03, 1.3FD	F03	%KX11809	%KX16609	Bit
	Method		CINI	K7380	K10380	Dit
		U. SIN, T. REF	SIN	%KX11808	%KX16608	Dit
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K739	K1039	Word
0.1			0	%KW739	%KW1039	
21	Address		0	K730	K1030	Double word
	[pulse]	-2,147,483,648~2,147,483,647 [pulse]		%KD365	%KD515	
	M Codo	0 65 525	0	K737	K1037	Word
	IN CODE	0~05,555	0	%KW737	%KW1037	word
			0	K7386~87	K10386~87	Bit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX11814~15	%KX16614~15	Bit
	Speed	$1 \sim 100000$ [pulse/s]	0	K734	K1034	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD367	%KD517	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	K736	K1036	Word
	Dwell		U	%KW736	%KW1036	

Stop	Sten Item Setting rat	Sotting range	Initial	Dedicate	d K area	Data size
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		ABC	K7484	K10484	
	00010.		ADO	%KX11972	%KX16772	Bit
	Dottorn			K7482~83	K10482~83	
	Pallem	0. END, 1. REEF, 2. CONT	LIND	%KX11970~71	%KX16770~71	Bit
	Control		DOS	K7481	K10481	
		0.F03, 1.3FD	100	%KX11969	%KX16769	Bit
	Method		SIN	K7480	K10480	Bit
			SIN	%KX11968	%KX16768	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K749	K1049	Word
22			0	%KW749	%KW1049	
22	Address	2 1 4 7 4 9 2 6 4 9 - 2 1 4 7 4 9 2 6 4 7 [pulse]	0	K740	K1040	Double word
	[pulse]	-2,147,403,040 -2,147,403,047 [pulse]		%KD370	%KD520	
	M Code	0 65 525	0	K747	K1047	\M/ord
	W Code	0 ~ 65,535	0	%KW747	%KW1047	word
			0	K7486~87	K10486~87	Dit
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX11974~75	%KX16774~75	Bit
	Spood	$1 \sim 100.000$ [pulso/s]	0	K744	K1044	Double word
	Speed	1 - 100,000[puise/s]	0	%KD372	%KD522	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	K746	K1046	Word
			U	%KW746	%KW1046	woru

Ston	ltem	Setting range	Initial	Dedicated K area		Data sizo
Step	nem	Setting range	value	X axis	Y axis	Dala Size
	Coord			K7584	K10584	
	Coold.	U. ABS, T. INC	ADS	%KX12132	%KX16932	Bit
	Pattern	0 · END 1 · KEEP 2 · CONT		K7582~83	K10582~83	
		0. END, T. REEP, Z. CONT	END	%KX12130~31	%KX16930~31	Bit
	Control		DOS	K7581	K10581	
		0.F03, 1.3FD	FU3	%KX12129	%KX16929	Bit
	Method		CIN	K7580	K10580	Bit
		U. SIN, T. KEP	SIN	%KX12128	%KX16928	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K759	K1059	
00			0	%KW759	%KW1059	Word
23	Address	-2,147,483,648~2,147,483,647 [pulse]	0	K750	K1050	
	[pulse]			%KD375	%KD525	Double word
	MCada	0 05 505	0	K757	K1057) Marid
	M Code	0 ~ 65,535	0	%KW757	%KW1057	vvora
			0	K7586~87	K10586~87	Dit
	A/D NO.	0. N0.1, 1. N0.2, 2. N0.3, 3. N0.4	0	%KX12134~35	%KX16934~35	DIL
	Speed	1 - 100.000[puloo/o]	0	K754	K1054	Double word
	Speea	$1 \sim 100,000$ [pulse/s]	0	%KD377	%KD527	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	K756	K1056	Word
			0	%KW756	%KW1056	

Stop	ltem	Setting range	Initial	Dedicated K area		Data sizo
Step	item	Setting range	value	X axis	Y axis	Dala Size
	Coord			K7684	K10684	
	Coold.	U. ABS, T. INC	AD3	%KX12292	%KX17092	Bit
	Pattern		END	K7682~83	K10682~83	
		0. END, 1. REEF, 2. CONT		%KX12290~91	%KX17090~91	Bit
	Control		DOS	K7681	K10681	
	Control		105	%KX12289	%KX17089	Bit
	Method		CIN	K7680	K10680	Bit
			311	%KX12288	%KX17088	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K769	K1069	
0.4			0	%KW769	%KW1069	VVord
24	Address		0	K760	K1060	Double word
	[pulse]	-2,147,483,648~2,147,483,647 [pulse]		%KD380	%KD530	
	M Codo	0 65 535	0	K767	K1067) A / a rad
	IN CODE	0~00,000	0	%KW767	%KW1067	word
			0	K7686~87	K10686~87	Bit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX12294~95	%KX17094~95	Bit
	Speed	$1 \sim 100000$ [pulse/s]	0	K764	K1064	Double word
	Speea	$1 \sim 100,000$ [pulse/s]	0	%KD382	%KD532	
	Dwoll	0 50 000[upit:ms]	0	K766	K1066	Word
	Dweil	0 ~ 50,000[unit	0	%KW766	%KW1066	vvoru

Stop	Itom	Setting range	Initial	Dedicated K area		Data sizo
Step	nem	Setting range	value	X axis	Y axis	Data Size
	Coord		ADC	K7784	K10784	
	C0010.	U. ABS, T. INC	AD3	%KX12452	%KX17252	Bit
	Pattern		END	K7782~83	K10782~83	
		0. END, 1. REEF, 2. CONT		%KX12450~51	%KX17250~51	Bit
	Control		POS	K7781	K10781	
		0.F03, 1.3FD	F03	%KX12449	%KX17249	Bit
	Method	0 : SIN, 1 : REP	CIN	K7780	K10780	Bit
			SIN	%KX12448	%KX17248	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K779	K1079	Word
05			0	%KW779	%KW1079	
25	Address		0	K770	K1070	Double word
	[pulse]	-2,147,463,646°2,147,463,647 [puise]	0	%KD385	%KD535	
	M Code	0 65 525	0	K777	K1077	
	W Code	0 ~ 65,555	0	%KW777	%KW1077	word
				K7786~87	K10786~87	i.
	A/D No.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	%KX12454~55	%KX17254~55	Bit
	Speed	1 - 100.000[puloo/o]	0	K774	K1074	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD387	%KD537	
	Dwall	0 ~ 50,000[unit: ^{ms}]	0	K776	K1076	Word
	Dwell		0	%KW776	%KW1076	

Stop	ltom	Setting range	Initial	Dedicate	d K area	Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		ARC	K7884	K10884	
	Coold.	0. ABS, 1. INC	ADS	%KX12612	%KX17412	Bit
	Pattern		END	K7882~83	K10882~83	Bit
				%KX12610~11	%KX17410~11	
	Control		POS	K7881	K10881	Bit
			100	%KX12609	%KX17409	
	Method		SIN	K7880	K10880	Bit
			0111	%KX12608	%KX17408	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K789	K1089	Word
26			0	%KW789	%KW1089	
20	Address	$-2.147.483.648 \sim 2.147.483.647$ [pulse]	0	K780	K1080	Double word
	[pulse]	-2,1+7,+00,0+0 2,1+7,+00,0+7 [pulse]		%KD390	%KD540	
	M Code	0 ~ 65 535	0	K787	K1087	Word
	W Code	0~00,000	0	%KW787	%KW1087	
		$0 \cdot N = 1 \cdot 1 \cdot N = 2 \cdot 2 \cdot N = 3 \cdot 3 \cdot N = 4$	0	K7886~87	K10886~87	Bit
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX12614~15	%KX17414~15	Dit
	Speed	$1 \sim 100.000$ [pulse/s]	0	K784	K1084	Double word
	Speed	1 100,000[puise/s]	0	%KD392	%KD542	
	Dwell	0 50 000[upitumo]	0	K786	K1086	Word
	Dwell		0	%KW786	%KW1086	vvolu

Stop	Itom	Setting range	Initial	Dedicate	d K area	Data sizo
Step	nem	Setting range	value	X axis	Y axis	Dala Size
	Coord			K7984	K10984	
	C0010.	U. ABS, T. INC	ADO	%KX12772	%KX17572	Bit
	Dottorn		END	K7982~83	K10982~83	
	rattern	0. END, 1. REEF, 2. CONT		%KX12770~71	%KX17570~71	Bit
	Control		DO0	K7981	K10981	
	Control	0.F03, 1.3FD	F03	%KX12769	%KX17569	Bit
	Method		CIN	K7980	K10980	Bit
		U. SIN, T. REP	5111	%KX12768	%KX17568	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K799	K1099	Word
07			0	%KW799	%KW1099	
21	Address	2 1 4 7 4 9 2 6 4 9 - 2 1 4 7 4 9 2 6 4 7 [puloo]	0	K790	K1090	Double word
	[pulse]	-2,147,463,646°2,147,463,647 [pulse]		%KD395	%KD545	
	M Code	0 65 525	0	K797	K1097	
	W Code	0 ~ 65,535	0	%KW797	%KW1097	vvora
			0	K7986~87	K10986~87	Dit
	A/D NO.	0. N0.1, 1. N0.2, 2. N0.3, 3. N0.4	0	%KX12774~75	%KX17574~75	DIL
	Cread	4 400.000[mulas/a]	0	K794	K1094	Double word
	Speed	1 ~ 100,000[pulse/s]	0	%KD397	%KD547	
	Dwell	0 ~ 50,000[unit: ^{ms}]		K796	K1096	Word
			0	%KW796	%KW1096	

Stop	ltem	Setting range	Initial	Dedicate	d K area	Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		ADC	K8084	K11084	
	00010.	U. ABS, T. INC	AD3	%KX12932	%KX17732	Bit
	Pattern	0 · END 1 · KEEP 2 · CONT	END	K8082~83	K11082~83	
		0. END, 1. REEF, 2. CONT		%KX12930~31	%KX17730~31	Bit
	Control		POS	K8081	K11081	
	Control	0.F03, 1.3FD	100	%KX12929	%KX17729	Bit
	Method		SIN	K8080	K11080	Bit
			Silv	%KX12928	%KX17728	Bit
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K809	K1109	Word
28			0	%KW809	%KW1109	
20	Address	$-2147483648 \sim 2147483647$ [pulse]	0	K800	K1100	Double word
	[pulse]		U	%KD400	%KD550	
	M Code	0 ~ 65 535	0	K807	K1107	Word
		0.00,000	Ŭ	%KW807	%KW1107	word
		$0 \cdot No 1 \cdot 1 \cdot No 2 \cdot 2 \cdot No 3 \cdot 3 \cdot No 4$	0	K8086~87	K11086~87	Bit
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	Ū	%KX12934~35	%KX17734~35	Dit
	Speed	$1 \sim 100000$ [nulse/s]	0	K804	K1104	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	Ū	%KD402	%KD552	
	Dwoll	0 50 000[upit:ms]	0	K806	K1106	Word
	Dweii		0	%KW806	%KW1106	vvolu

Ston	ltom	Setting range	Initial	Dedicate	ed K area	Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		ADC	K8184	K11184	
	Coold.	U. ABS, T. INC	AD3	%KX13092	%KX17892	Bit
	Dottorn			K8182~83	K11182~83	
	Fallem	0. END, 1. REEF, 2. CONT	END	%KX13090~91	%KX17890~91	Bit
	Control		DOG	K8181	K11181	
	Control	0.F03, 1.3FD	F03	%KX13089	%KX17889	Bit
	Method		CIN	K8180	K11180	Dit
			SIN	%KX13088	%KX17888	Dit
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K819	K1119	
20			0	%KW819	%KW1119	Word
29	Address	2 147 492 649 - 2 147 492 647 [pulse]	0	K810	K1110	Double word
	[pulse]	-2,147,483,848~2,147,483,847 [puise]		%KD405	%KD555	
	M Codo	0 65 525	0	K817	K1117	Word
	M Code	0 ~ 65,535	0	%KW817	%KW1117	
			0	K8186~87	K11186~87	Dit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX13094~95	%KX17894~95	DIL
	Speed	1 a. 100 000[puloo/o]	0	K814	K1114	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD407	%KD557	
	Dwoll	0 ~ 50,000[unit:ʷs]	0	K816	K1116	Word
	Dwell		U	%KW816	%KW1116	

Stop	ltom	Setting range	Initial	Dedicated K area		Data sizo
Step	item	Setting range	value	X axis	Y axis	Dala Size
	Coord		ADC	K8284	K11284	
	C0010.	U. ABS, T. INC	ADS	%KX13252	%KX18052	Bit
	Pattern			K8282~83	K11282~83	
	Fallem	U. END, T. REEF, Z. CONT	END	%KX13250~51	%KX18050~51	Bit
	Control		POS	K8281	K11281	-
	Control		100	%KX13249	%KX18049	Bit
	Method		SIN	K8280	K11280	Bit
				%KX13248	%KX18048	Dit
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K829	K1129	Word
30			Ŭ	%KW829	%KW1129	
50	Address	-2 147 483 648 ~ 2 147 483 647 [pulse]	0	K820	K1120	Double word
	[pulse]	2,147,400,040 2,147,400,047 [pulse]	Ŭ	%KD410	%KD560	
	M Code	0 ~ 65 535	0	K827	K1127	Word
	W Code	0~00,000	Ū	%KW827	%KW1127	word
		$0 \cdot N = 1 \cdot 1 \cdot N = 2 \cdot 2 \cdot N = 3 \cdot 3 \cdot N = 4$	0	K8286~87	K11286~87	Bit
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX13254~55	%KX18054~55	Dit
	Speed	1 - 100.000[puloo/o]	0	K824	K1124	Double word
	Speed	1 ~ 100,000[pulse/s]	0	%KD412	%KD562	
	Dwoll	0 ~ 50,000[unit:ms]	0	K826	K1126	Word
	Dwell		U	%KW826	%KW1126	word

Ston	ltom	Softing range	Initial	Dedicate	ed K area	Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		ADC	K23484	K28484	
	Coold.	U. ABS, T. INC	AD3	%KX37572	%KX45572	Bit
	Pattern			K23482~83	K28482~83	
		0. END, 1. REEF, 2. CONT		%KX37570~71	%KX45570~71	Bit
	Control		POS	K23481	K28481	
		0.F03, 1.3FD		%KX37569	%KX45569	Bit
	Method		SIN	K23480	K28480	Bit
		U. SIN, T. KEF	SIN	%KX37568	%KX45568	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2349	K2849	
31			0	%KW2349	%KW2849	Word
01	Address	$2147482648\sim 2147482647$ [pulco]	0	K2340	K2840	Double
	[pulse]	-2,147,403,040 2,147,403,047 [puise]		%KD1170	%KD1420	word
	M Code	0 ~ 65 535	0	K2347	K2847	Word
	M Code	0 ~ 00,000	0	%KW2347	%KW2847	word
		$0 \cdot N_0 = 1 \cdot 1 \cdot N_0 = 2 \cdot N_0 = 3 \cdot N_0 = 4$	0	K23486~87	K28486~87	Bit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX37574~75	%KX45574~75	Bit
	Speed	$1 \sim 100000$ [pulse/s]	0	K2344	K2844	Double
	Opeeu	$1 \sim 100,000$ [pulse/s]	0	%KD1172	%KD1422	word
	Dwell	0 50 000[upit:ms]	0	K2346	K2846	Word
			U	%KW2346	%KW2846	

• Operation step 31~80 is available for only high end type (H type).

Stop	ltom	Sotting range	Initial	Dedicate	ed K area	Data sizo
Step	nem	Setting range	value	X axis	Y axis	Data Size
	Coord		ABS	K23584	K28584	
	00010.	0. ABS, 1. INC	AD3	%KX37732	%KX45732	Bit
	Pattern			K23582~83	K28582~83	
	rallem		LIND	%KX37730~31	%KX45730~31	Bit
	Control		POS	K23581	K28581	
	Control		100	%KX37729	%KX45729	Bit
	Method	0 : SIN. 1 : REP	SIN	K23580	K28580	Bit
	Method		OIN	%KX37728	%KX45728	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2359	K2859	
30			0	%KW2359	%KW2859	vvora
52	Address	-2 147 483 648 ~ 2 147 483 647 [pulse]	0	K2350	K2850	Double
	[pulse]	-2,1+7,+00,0+0 2,1+7,+00,0+7 [pulse]	0	%KD1175	%KD1425	word
	M Code	0 - 65 535	0	K2357	K2857	Word
	M Code	0~00,000	0	%KW2357	%KW2857	word
			0	K23586~87	K28586~87	Bit
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX37734~35	%KX45734~35	Bit
	Speed	$1 \sim 100.000$ [pulso/c]	0	K2354	K2854	Double
	Speed	1 ~ 100,000[pulse/s]	0	%KD1177	%KD1427	word
	Dwell	0 - 50 000[upit:ms]	0	K2356	K2856	Word
	Dweii		U	%KW2356	%KW2856	word

Stop	ltom	Sotting range	Initial	Dedicate	ed K area	Data cizo
Step	nem	Setting range	value	X axis	Y axis	Data Size
	Coord		ADC	K23684	K28684	
	Coold.	U. ABS, T. INC	AD3	%KX37892	%KX45892	Bit
	Pattorn			K23682~83	K28682~83	
	Fallem	0. END; 1. REEF, 2. CONT	END	%KX37890~91	%KX45890~91	Bit
	Control		POS	K23681	K28681	
	Control	0.F03, 1.3FD	F03	%KX37889	%KX45889	Bit
	Method		CINI	K23680	K28680	Dit
	Method	U. SIN, T. KEP	SIN	%KX37888	%KX45888	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2369	K2869	
22			0	%KW2369	%KW2869	Word
33	Address	-2,147,483,648~2,147,483,647 [pulse]	0	K2360	K2860	Double
	[pulse]			%KD1180	%KD1430	word
	M Code	0 65 525	0	K2367	K2867	
	IN Code	0 ~ 65,535	0	%KW2367	%KW2867	word
			0	K23686~87	K28686~87	Dit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX37894~95	%KX45894~95	ы
	Speed	1 - 100.000[puloo/o]	0	K2364	K2864	Double
	Speed	1 ~ 100,000[pulse/s]	0	%KD1182	%KD1432	word
	Dwall		0	K2366	K2866	Word
	Dweii		U	%KW2366	%KW2866	word

Stop	Itom	Setting range	Initial	Dedicate	ed K area	Data sizo
Step	nem	Setting range	value	X axis	Y axis	Dala Size
	Coord			K23784	K28784	
	Coord.	U. ABS, T. INC	ADS	%KX38052	%KX46052	Bit
	Pattorn			K23782~83	K28782~83	
	Fallem	U. END, T. REEF, Z. CONT	END	%KX38050~51	%KX46050~51	Bit
	Control		POS	K23781	K28781	
	Control	0.103, 1.310	105	%KX38049	%KX46049	Bit
	Method	0 : SIN. 1 : REP	SIN	K23780	K28780	Bit
	Method		OIN	%KX38048	%KX46048	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2379	K2879	Word
			Ŭ	%KW2379	%KW2879	
34	Address	-2,147,483,648~2,147,483,647 [pulse]	0	K2370	K2870	Double word
	[pulse]			%KD1185	%KD1435	
	M Codo	0 65 525	0	K2377	K2877	
	IVI Code	0~05,555	0	%KW2377	%KW2877	word
		$0 \cdot N = 1 \cdot 1 \cdot N = 2 \cdot 2 \cdot N = 3 \cdot 2 \cdot N = 4$	0	K23786~87	K28786~87	Di+
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX38054~55	%KX46054~55	Bit
	Onesd	4 400 000[]	0	K2374	K2874	Double
	Speed	1 ~ 100,000[pulse/s]	0	%KD1187	%KD1437	word
	Dwoll	0 50 000[;it.mo]	0	K2376	K2876	Word
	Dwell		U	%KW2376	%KW2876	woru

Ston	Itom	Setting range	Initial	Dedicate	ed K area	Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord			K23884	K28884	
	Coord.		ABS	%KX38212	%KX46212	Bit
	Pattern			K23882~83	K28882~83	
		0: END, 1: KEEP, 2. CONT	END	%KX38210~11	%KX46210~11	Bit
	Control		DOS	K23881	K28881	
	Control	0: POS, 1: SPD	P05	%KX38209	%KX46209	Bit
	Method		CINI	K23880	K28880	Dit
		U:SIN, 1. KEP	SIN	%KX38208	%KX46208	Dil
	REP Step	0 ~ 30 (0 ~ 80 for high - end)		K2389	K2889	
25			U	%KW2389	%KW2889	Word
35	Address	2 147 492 649 a 2 147 492 647 [puloo]	0	K2380	K2880	Double word
	[pulse]	-2,147,463,046 ² 2,147,463,047 [puise]		%KD1190	%KD1440	Double word
	MCode	0 65 525		K2387	K2887	Word
	IVI Code	0~05,535	0	%KW2387	%KW2887	woru
				K23886~87	K28886~87	Dit
	A/D NO.	0. N0.1, 1. N0.2, 2. N0.3, 3. N0.4	0	%KX38214~15	%KX46214~15	Dit
	Spood			K2384	K2884	Double word
	Speed	1 ~ 100,000[pulse/s]	0	%KD1192	%KD1442	Double word
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	K2386	K2886	Word
			0	%KW2386	%KW2886	

Stop	Item Setting range	Initial	Dedicate	ed K area	Doto cizo	
Step	item	Setting range	value	X axis	Y axis	Dala Size
	Coord			K23984	K28984	
	Coord.	U. ABS, T. INC	ADS	%KX38372	%KX46372	Bit
	Pattorn			K23982~83	K28982~83	
	Fallem	0. END, T. REEF, Z. CONT	END	%KX38370~71	%KX46370~71	Bit
	Control		POS	K23981	K28981	
	Control	0.100, 1.010	103	%KX38369	%KX46369	Bit
	Method		SIN	K23980	K28980	Bit
			SIN	%KX38368	%KX46368	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2399	K2899	Word
36			0	%KW2399	%KW2899	
00	Address	ddress	0	K2390	K2890	Double word
	[pulse]	-2,1+7,+00,0+0 2,1+7,+00,0+7 [puise]		%KD1195	%KD1445	
	M Code	0 ~ 65 535	0	K2397	K2897	Word
	W Code	0~00,000	0	%KW2397	%KW2897	word
			0	K23986~87	K28986~87	Di+
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX38374~75	%KX46374~75	Bit
	Speed	$1 \sim 100.000$ [pulse/s]	0	K2394	K2894	Double word
	Speed	1 ~ 100,000[pulse/s]	0	%KD1197	%KD1447	Double word
	Dwell (0 ~ 50,000[unit: ^{ms}]	0	K2396	K2896	Word
			U	%KW2396	%KW2896	

Ston	Itom	Setting range	Initial	Dedicate	ed K area	Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		ADC	K24084	K29084	
	Coord.	U. ABS, T. INC	ADS	%KX38532	%KX46532	Bit
	Dottorn			K24082~83	K29082~83	
	1 attern	0. END, 1. REEF, 2. CONT	END	%KX38530~31	%KX46530~31	Bit
	Control		DOS	K24081	K29081	
	Control	0.F03, 1.3FD	FU3	%KX38529	%KX46529	Bit
	Method		CINI	K24080	K29080	Bit
		U. SIN, T. KEP	SIN	%KX38528	%KX46528	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2409	K2909	
07			0	%KW2409	%KW2909	Word
37	Address		0	K2400	K2900	Double word
	[pulse]	-2,147,483,648~2,147,483,647 [pulse]		%KD1200	%KD1450	
	M Codo	0 65 525	0	K2407	K2907	Word
	W Code	0~00,000	0	%KW2407	%KW2907	word
			0	K24086~87	K29086~87	Dit
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX38534~35	%KX46534~35	Dit
	Speed	1 - 100.000[pulse/s]	0	K2404	K2904	Daubla word
		$1 \sim 100,000$ [pulse/s]	0	%KD1202	%KD1452	Double word
	Dwell 0 ~ 50	0 ~ 50,000[unit: ^{ms}]	0	K2406	K2906	Word
			U	%KW2406	%KW2906	

Ston	ltem	Setting range	Initial	I Dedicated K area		Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		ADC	K24184	K29184	
	C0010.	U. ABS, T. INC	AD3	%KX38692	%KX46692	Bit
	Pottorn			K24182~83	K29182~83	
	1 attern	U. END, T. REEF, Z. CONT	LIND	%KX38690~91	%KX46690~91	Bit
	Control		POS	K24181	K29181	
	Control	0.103, 1.310	105	%KX38689	%KX46689	Bit
	Method		SIN	K24180	K29180	Bit
				%KX38688	%KX46688	5
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2419	K2919	Word
20			0	%KW2419	%KW2919	
30	Address	Address 2 147 482 648 - 2 147 482 647 [pulce]	0	K2410	K2910	Double word
	[pulse]	-2,147,403,040 2,147,403,047 [puise]	0	%KD1205	%KD1455	
	M Code	0 65 525	0	K2417	K2917) (/ a mal
	M Code	0~00,000	0	%KW2417	%KW2917	word
			0	K24186~87	K29186~87	Dit
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX38694~95	%KX46694~95	DIL
	Speed	1 a. 100 000[puloo/o]	0	K2414	K2914	Devilta
	Speed	1 ~ 100,000[pulse/s]	0	%KD1207	%KD1457	Double word
	Dwoll		0	K2416	K2916	Word
	Dweil		U	%KW2416	%KW2916	vvora

Stop	ltem	Setting range	Initial	I Dedicated K area		Data sizo
Step	item	Setting range	value	X axis	Y axis	Dala Size
	Coord			K24284	K29284	
	Coord.	U. ABS, T. INC	ADS	%KX38852	%KX46852	Bit
	Pattern			K24282~83	K29282~83	
		U. END, T. REEF, Z. CONT		%KX38850~51	%KX46850~51	Bit
	Control		POS	K24281	K29281	
		0.F03, 1.3FD	100	%KX38849	%KX46849	Bit
	Method		CINI	K24280	K29280	Bit
			Sin	%KX38848	%KX46848	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2429	K2929	
20			0	%KW2429	%KW2929	vvord
39	Address	-2,147,483,648~2,147,483,647 [pulse]	0	K2420	K2920	Double word
	[pulse]			%KD1210	%KD1460	
	M Code	0 - 65 535	0	K2427	K2927	Word
	W Code	0~03,535	0	%KW2427	%KW2927	word
			_	K24286~87	K29286~87	D:4
	A/D NO.	0 . NO.1, 1 . NO.2, 2 . NO.3, 3 . NO.4	0	%KX38854~55	%KX46854~55	Bit
	Spood	$1 \sim 100.000$ [pulso/c]	0	K2424	K2924	Double word
	Speed	1 ~ 100,000[pulse/s]	0	%KD1212	%KD1462	
	Dwell	Dwell 0 ~ 50,000[unit:™s]	0	K2426	K2926	Word
	Dwell		U	%KW2426	%KW2926	

Stop	Itom	Sotting range	Initial	Dedicated K area		Doto cizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		ADC	K24384	K29384	
	Coold.	U. ABS, T. INC	AD3	%KX39012	%KX47012	Bit
	Pattern	0 : END, 1 : KEEP, 2 : CONT	END	K24382~83	K29382~83	
				%KX39010~11	%KX47010~11	Bit
	Control		POS	K24381	K29381	
		0.F03, 1.3FD	F03	%KX39009	%KX47009	Bit
	Method	0 : SIN, 1 : REP	CINI	K24380	K29380	Bit
			SIN	%KX39008	%KX47008	Dit
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2439	K2939	
40			0	%KW2439	%KW2939	VVord
40	Address		0	K2430	K2930	Double word
	[pulse]	-2,147,483,648~2,147,483,647 [pulse]	0	%KD1215	%KD1465	
	M Codo	0 65 525	0	K2437	K2937	Word
	M Code	0~00,000	0	%KW2437	%KW2937	word
			0	K24386~87	K29386~87	Dit
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX39014~15	%KX47014~15	Bit
	Speed	$1 \sim 100.000$ [pulse/s]	0	K2434	K2934	- Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1217	%KD1467	
	Dwoll	0 50 000[upit:ms]	0	K2436	K2936	Word
	Dweii		0	%KW2436	%KW2936	vvolu

Stop	ltom	Sotting rongo	Initial	al Dedicated K area		Doto cizo
Step	nem	Setting range	value	X axis	Y axis	Dala Size
	Coord		ADC	K24484	K29484	
	Coord.	U. ABS, T. INC	ADS	%KX39172	%KX47172	Bit
	Pattorn			K24482~83	K29482~83	
	Fallem	0. END, 1. REEF, 2. CONT	END	%KX39170~71	%KX47170~71	Bit
	Control		DOS	K24481	K29481	
	Control	0.F03, 1.3FD	F03	%KX39169	%KX47169	Bit
	Method		SIN	K24480	K29480	Bit
		U. SIN, T. REP	SIN	%KX39168	%KX47168	Dit
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2449	K2949	
			0	%KW2449	%KW2949	VVord
41	Address	-2,147,483,648~2,147,483,647 [pulse]	0	K2440	K2940	Double word
	[pulse]			%KD1220	%KD1470	
	M Codo	0 65 525	0	K2447	K2947) A / a mal
	M Code	0~05,555	0	%KW2447	%KW2947	word
			0	K24486~87	K29486~87	Dit
	A/D NO.	0 : N0.1, 1 : N0.2, 2 : N0.3, 3 : N0.4	0	%KX39174~75	%KX47174~75	Bit
	Spood	$1 \sim 100.000$ [pulso/s]	0	K2444	K2944	Deuble word
	Speed	1 ~ 100,000[pulse/s]	0	%KD1222	%KD1472	Double word
	Dwell 0	0 ~ 50,000[unit: ^{ms}]	0	K2446	K2946	Word
			0	%KW2446	%KW2946	

Ston	ltem	Setting range	Initial	Dedicated K area		Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		ADS	K24584	K29584	
	C0010.	U. ABS, T. INC	AD3	%KX39332	%KX47332	Bit
	Pattern			K24582~83	K29582~83	Bit
		0. END, 1. REEF, 2. CONT	END	%KX39330~31	%KX47330~31	
	Control		POS	K24581	K29581	
		0. F03, T. 3FD	F03	%KX39329	%KX47329	Bit
	Method		CINI	K24580	K29580	Bit
			311	%KX39328	%KX47328	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2459	K2959	
			0	%KW2459	%KW2959	vvora
42	Address	-2,147,483,648~2,147,483,647 [pulse]		K2450	K2950	Double word
	[pulse]		0	%KD1225	%KD1475	
	M Codo	0 65 535	0	K2457	K2957)A/ard
	M Code	0~00,000	0	%KW2457	%KW2957	word
			0	K24586~87	K29586~87	Dit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX39334~35	%KX47334~35	DIL
	Speed	1 - 100 000[pulpo/o]	0	K2454	K2954	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1227	%KD1477	
	D =			K2456	K2956) A / a mal
	Dweii		0	%KW2456	%KW2956	vvora

Ston	ltem	Setting range	Initial	Dedicated K area		Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord			K24684	K29684	
	Coord.	U: ABS, 1: INC	ABS	%KX39492	%KX47492	Bit
	Dottorn			K24682~83	K29682~83	
	Fallem	U. END, T. KEEP, Z. CONT	END	%KX39490~91	%KX47490~91	Bit
	Control		DOC	K24681	K29681	
		0.F03, 1.3FD	F03	%KX39489	%KX47489	Bit
	Method		SIN	K24680	K29680	Di+
			SIN	%KX39488	%KX47488	Bit
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2469	K2969	Word
13			0	%KW2469	%KW2969	
40	Address	$2147482648\sim 2147482647$ [pulse]	0	K2460	K2960	Double word
	[pulse]	-2,147,403,040 2,147,403,047 [puise]		%KD1230	%KD1480	
	M Code	0 - 65 535	0	K2467	K2967	Word
	W Code	0~05,555	0	%KW2467	%KW2967	word
			0	K24686~87	K29686~87	Di+
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX39494~95	%KX47494~95	Bit
	Speed	$1 \sim 100000$ [pulse/s]	0	K2464	K2964	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1232	%KD1482	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	K2466	K2966	Word
	Dwell		U	%KW2466	%KW2966	

Ston	Itom	Setting range	Initial	I Dedicated K area		Data sizo
Step	nem	Setting range	value	X axis	Y axis	Data Size
	Coord			K24784	K29784	
	Coord.	U. ABS, T. INC	ADS	%KX39652	%KX47652	Bit
	Pattorn			K24782~83	K29782~83	
	Falleni	0. END, 1. REEF, 2. CONT	LIND	%KX39650~51	%KX47650~51	Bit
	Control		POS	K24781	K29781	
		0. FO3, 1. 3FD	F03	%KX39649	%KX47649	Bit
	Method		CINI	K24780	K29780	Bit
		U. SIN, T. KEF	311	%KX39648	%KX47648	Dit
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2479	K2979	Word
4.4			0	%KW2479	%KW2979	
44	Address	-2,147,483,648~2,147,483,647 [pulse]	0	K2470	K2970	Double word
	[pulse]			%KD1235	%KD1485	
	M Codo	0 65 525	0	K2477	K2977	
	M Code	0 ~ 65,535	0	%KW2477	%KW2977	vvora
			0	K24786~87	K29786~87	Dit
	A/D NO.	0. N0.1, 1. N0.2, 2. N0.3, 3. N0.4	0	%KX39654~55	%KX47654~55	DIL
	Speed	1 a. 100 000[pulse/s]	0	K2474	K2974	Daulala sugard
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1237	%KD1487	Double word
	Dwell	Dwell 0 ~ 50,000[unit: ^{ms}]	0	K2476	K2976	Word
			U	%KW2476	%KW2976	

Ston	ltom	Setting range	Initial	Dedicate	ed K area	Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		ADC	K24884	K29884	
	Coold.	U. ABS, T. INC	AD3	%KX39812	%KX47812	Bit
	Pattorn			K24882~83	K29882~83	
	Fallem	0. END; 1. REEF, 2. CONT	LIND	%KX39810~11	%KX47810~11	Bit
	Control		POS	K24881	K29881	
	Control	0.F03, 1.3FD		%KX39809	%KX47809	Bit
	Method		SIN	K24880	K29880	Bit
			SIN	%KX39808	%KX47808	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2489	K2989	
45			0	%KW2489	%KW2989	Word
45	Address	0.4.47,400,040, 0.4.47,400,047 [auto a]	0	K2480	K2980	Double word
	[pulse]	-2,147,463,648~2,147,463,647 [puise]		%KD1240	%KD1490	
	M Codo	0 65 525	0	K2487	K2987))/ord
	M Code	0~05,555	0	%KW2487	%KW2987	word
			0	K24886~87	K29886~87	Bit
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX39814~15	%KX47814~15	Dit
	Spood	$1 \sim 100.000$ [pulso/c]	0	K2484	K2984	Devible word
	Speea	$1 \sim 100,000$ [pulse/s]	0	%KD1242	%KD1492	Double word
	Dwoll	0 50 000[upit:ms]	0	K2486	K2986	Word
	Dweii		U	%KW2486	%KW2986	woru

Stop	o Item Setting range	Initial	Dedicate	ed K area	Doto cizo	
Step	item	Setting range	value	X axis	Y axis	Dala Size
	Coord			K24984	K29984	
	Coold.	U. ABS, T. INC	AD3	%KX39972	%KX47972	Bit
	Pattorn			K24982~83	K29982~83	
	Fallem	0. END, 1. REEF, 2. CONT	END	%KX39970~71	%KX47970~71	Bit
	Control		DOS	K24981	K29981	
	Control	0.100, 1.010	103	%KX39969	%KX47969	Bit
	Method		SIN	K24980	K29980	Bit
			011	%KX39968	%KX47968	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2499	K2999	Word
46			0	%KW2499	%KW2999	
40	Address	ess 2 147 493 649 ~ 2 147 493 647 [pulse]	0	K2490	K2990	Double word
	[pulse]	-2,147,403,040 2,147,403,047 [puise]	0	%KD1245	%KD1495	
	M Code	0 - 65 535	0	K2497	K2997	Word
	IN CODE	0~05,555	0	%KW2497	%KW2997	word
			0	K24986~87	K29986~87	Dit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX39974~75	%KX47974~75	DI
	Speed	$1 \sim 100.000$ [pulso/s]	0	K2494	K2994	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1247	%KD1497	Double word
	Dwell	0 - 50 000[unit:ms]	0	K2496	K2996	Word
	Dweii		U	%KW2496	%KW2996	word

Ston	Itom	Setting range	Initial	I Dedicated K area		Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord			K25084	K30084	
	C0010.	U. ABS, T. INC	AD3	%KX40132	%KX48132	Bit
	Pattern			K25082~83	K30082~83	
		0. END, T. REEF, Z. CONT	END	%KX40130~31	%KX48130~31	Bit
	Control		POS	K25081	K30081	
		0.F03, 1.3FD	105	%KX40129	%KX48129	Bit
	Method	0 : SIN, 1 : REP	CINI	K25080	K30080	Dit
			SIN	%KX40128	%KX48128	Bit
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2509	K3009	
47			0	%KW2509	%KW3009	Word
47	Address		0	K2500	K3000	Double word
	[pulse]	-2,147,483,648~2,147,483,647 [pulse]		%KD1250	%KD1500	
	M Codo	0 65 525	0	K2507	K3007	Word
	W Code	0~85,555	0	%KW2507	%KW3007	word
			0	K25086~87	K30086~87	D:4
	A/D NO.	0. N0.1, 1. N0.2, 2. N0.3, 3. N0.4	0	%KX40134~35	%KX48134~35	DIL
	Creed	4 400.000[mulas/s]	0	K2504	K3004	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1252	%KD1502	
	Dwall	0 ~ 50,000[unit:ms]	0	K2506	K3006	Word
	Dwell		U	%KW2506	%KW3006	

Ston	ltom	Sotting range	Initial	I Dedicated K area		Doto cizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		ABS	K25184	K30184	
	00010.	0. ABS, 1. INC	ABS	%KX40292	%KX48292	Bit
	Pattern	0 : END, 1 : KEEP, 2 : CONT		K25182~83	K30182~83	
			LIND	%KX40290~91	%KX48290~91	Bit
	Control	0 : POS, 1 : SPD	POS	K25181	K30181	
			100	%KX40289	%KX48289	Bit
	Method		SIN	K25180	K30180	Bit
				%KX40288	%KX48288	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2519	K3019	Word
48			0	%KW2519	%KW3019	
40	Address	-2,147,483,648~2,147,483,647 [pulse]	0	K2510	K3010	Double word
	[pulse]			%KD1255	%KD1505	
	M Code	0 - 65 535	0	K2517	K3017) A / a rad
	IN CODE	0~00,000	0	%KW2517	%KW3017	word
			0	K25186~87	K30186~87	Dit
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX40294~95	%KX48294~95	Bit
	Speed	$1 \sim 100000$ [pulse/s]	0	K2514	K3014	Double word
	Speed	1 · 100,000[puise/s]	0	%KD1257	%KD1507	Double word
	Dwall		0	K2516	K3016	Word
	Dweil		0	%KW2516	%KW3016	vvoru

Stop	ltom	Setting range	Initial	Dedicate	ed K area	Doto cizo
Step	nem	Setting range	value	X axis	Y axis	Data Size
	Coord		ADC	K25284	K30284	
	Coold.	U. ABS, T. INC	ADS	%KX40452	%KX48452	Bit
	Dottorn			K25282~83	K30282~83	
	Pattern	0. END, T. REEF, Z. CONT	END	%KX40450~51	%KX48450~51	Bit
	Control	0 : POS, 1 : SPD	POS	K25281	K30281	
			F03	%KX40449	%KX48449	Bit
	Method	0 : SIN, 1 : REP	SIN	K25280	K30280	Bit
			SIN	%KX40448	%KX48448	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2529	K3029	Word
10			0	%KW2529	%KW3029	
49	Address	$2147482648\sim 2147482647$ [pulco]	0	K2520	K3020	Double word
	[pulse]	-2,147,403,040 -2,147,483,047 [pulse]		%KD1260	%KD1510	
	M Code	0 65 525	0	K2527	K3027	Word
	W Code	0~00,000	0	%KW2527	%KW3027	word
			0	K25286~87	K30286~87	Dit
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX40454~55	%KX48454~55	Bit
	Spood	$1 \sim 100.000$ [pulso/s]	0	K2524	K3024	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1262	%KD1512	Double word
	Dwoll	0 ~ 50,000[unit:ʷs]		K2526	K3026	Word
	Dwell		0	%KW2526	%KW3026	

Stop	Itom	Sotting range	Initial	I Dedicated K area		Doto cizo
Step	nem	Setting range	value	X axis	Y axis	Data Size
	Coord		ABC	K25384	K30384	
	Coold.	U. ABS, T. INC	AD3	%KX40612	%KX48612	Bit
	Pattern		END	K25382~83	K30382~83	
				%KX40610~11	%KX48610~11	Bit
	Control		POS	K25381	K30381	Bit
		0.103, 1.310	100	%KX40609	%KX48609	
	Method		SIN	K25380	K30380	Bit
			SIN	%KX40608	%KX48608	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2539	K3039	Word
50			0	%KW2539	%KW3039	
50	Address	-2,147,483,648~2,147,483,647 [pulse]	0	K2530	K3030	Double word
	[pulse]			%KD1265	%KD1515	
	M Code	0 65 525	0	K2537	K3037	Word
	M Code	0~05,555	0	%KW2537	%KW3037	
			0	K25386~87	K30386~87	D.1
	A/D NO.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	%KX40614~15	%KX48614~15	Bit
	Speed	1 a. 100 000[puloo/o]	0	K2534	K3034	Double word
	Speed	1 *** 100,000[pulse/s]	0	%KD1267	%KD1517	
	Dwall		0	K2536	K3036	Word
	Dweil		0	%KW2536	%KW3036	vvolu

Stop	Itom	Setting range	Initial	I Dedicated K area		Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord			K25484	K30484	
	Coold.	U. ABS, T. INC	AD3	%KX40772	%KX48772	Bit
	Dottorn			K25482~83	K30482~83	
	Fallem	U. END, T. KEEP, Z. CONT	END	%KX40770~71	%KX48770~71	Bit
	Control		DOO	K25481	K30481	
		0 : POS, 1 : SPD	FU3	%KX40769	%KX48769	Bit
	Method		CINI	K25480	K30480	Bit
		U: SIN, T: REP	SIN	%KX40768	%KX48768	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2549	K3049	Word
51			0	%KW2549	%KW3049	
51	Address		0	K2540	K3040	Double word
	[pulse]	-2,147,463,646~2,147,463,647 [pulse]		%KD1270	%KD1520	
	M Codo	0 65 525	0	K2547	K3047	Word
	M Code	0 ~ 65,535	0	%KW2547	%KW3047	vvora
			0	K25486~87	K30486~87	Dit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX40774~75	%KX48774~75	DIL
	Speed	$1 \sim 100.000$ [pulso/s]	0	K2544	K3044	Double word
		1 ~ 100,000[pulse/s]	0	%KD1272	%KD1522	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	K2546	K3046	Word
			U	%KW2546	%KW3046	

Ston	Itom	Sotting rongo	Initial	I Dedicated K area		Data sizo
Step	item	Setting range	value	X axis	Y axis	Dala Size
	Coord		ADC	K25584	K30584	
	Coold.	U. ABS, T. INC	AD3	%KX40932	%KX48932	Bit
	Dottorn			K25582~83	K30582~83	
	Pallem	U. END, T. KEEP, Z. CONT	LIND	%KX40930~31	%KX48930~31	Bit
	Control		POS	K25581	K30581	
	Control	0.F03, 1.3FD		%KX40929	%KX48929	Bit
	Method		SIN	K25580	K30580	Bit
			Silv	%KX40928	%KX48928	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2559	K3059	Word
52			0	%KW2559	%KW3059	
JZ	Address	Address 2 147 482 648 ~ 2 147 483 647 [pulce]	0	K2550	K3050	Double word
	[pulse]	-2,147,403,040 2,147,403,047 [puise]	0	%KD1275	%KD1525	
	M Codo	0 65 535	0	K2557	K3057) () o rel
	IN CODE	0~ 65,555	0	%KW2557	%KW3057	word
			0	K25586~87	K30586~87	Dit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX40934~35	%KX48934~35	Bit
	Speed	$1 \sim 100.000$ [pulso/s]	0	K2554	K3054	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1277	%KD1527	Double word
	Dwoll	0 50 000[upit:ms]	0	K2556	K3056	Word
	Dweii	0 ~ 50,000[unit	0	%KW2556	%KW3056	woru

Ston	ltom	Setting range	Initial	Dedicate	d K area	Doto cizo
Step	nem	Setting range	value	X axis	Y axis	Dala Size
	Coord			K25684	K30684	
	Coord.	U. ABS, T. INC	ADS	%KX41092	%KX49092	Bit
	Pattern			K25682~83	K30682~83	
		0. END, 1. REEF, 2. CONT	END	%KX41090~91	%KX49090~91	Bit
	Control		DOS	K25681	K30681	
	Control		F03	%KX41089	%KX49089	Bit
	Method	0 : SIN, 1 : REP	SIN	K25680	K30680	Bit
			SIN	%KX41088	%KX49088	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2569	K3069	Word
53			0	%KW2569	%KW3069	
55	Address	0 1 4 7 4 9 9 6 4 9 - 0 1 4 7 4 9 9 6 4 7 [puloo]	0	K2560	K3060	Double word
	[pulse]	-2,147,403,040 -2,147,403,047 [pulse]		%KD1280	%KD1530	
	M Codo	0 65 525	0	K2567	K3067	Word
	M Code	0~ 65,555	0	%KW2567	%KW3067	word
			0	K25686~87	K30686~87	Bit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX41094~95	%KX49094~95	Bit
	Speed	$1 \sim 100.000$ [pulso/s]	0	K2564	K3064	Double word
	Speea	$1 \sim 100,000$ [pulse/s]	0	%KD1282	%KD1532	Double word
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	K2566	K3066	Word
			0	%KW2566	%KW3066	

Step	ltem	Setting range	Initial	Dedicated K area		Doto cizo
			value	X axis	Y axis	Data Size
	Coord.	0 : ABS, 1 : INC	ABS	K25784	K30784	Bit
				%KX41252	%KX49252	
	Pattern		END	K25782~83	K30782~83	Bit
		0. END, 1. REEF, 2. CONT		%KX41250~51	%KX49250~51	
	Control		POS	K25781	K30781	Bit
	Control	0.F03, 1.3FD	F03	%KX41249	%KX49249	
	Method	0 : SIN, 1 : REP	SIN	K25780	K25780 K30780	Bit
			311	%KX41248	%KX49248	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2579	K3079	Word
54				%KW2579	%KW3079	
54	Address [pulse]	-2,147,483,648~2,147,483,647 [pulse]	0	K2570	K3070	Double word
				%KD1285	%KD1535	
	M Code	0 ~ 65,535	0	K2577	K3077	Word
			0	%KW2577 %KW3077 ^v	word	
	A/D No.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	K25786~87	K30786~87	Bit Double word
			0	%KX41254~55	%KX49254~55	
	Speed	1 ~ 100,000[pulse/s]	0 K2574 %KD1287	K2574	K3074	
				%KD1287	%KD1537	
	Dwell	0 - 50 000[upit:ms]	0	K2576	K3076	Word
	Dweii	0 ~ 50,000[unit	0	%KW2576	%KW3076	woru

Step	ltem	Setting range	Initial	Dedicated K area		Data cizo
			value	X axis	Y axis	Data Size
	Coord.	0 : ABS, 1 : INC	ABS	K25884	K30884	Bit
				%KX41412	%KX49412	
	Pattern	0 : END, 1 : KEEP, 2 : CONT	END	K25882~83	K30882~83	Bit
				%KX41410~11	%KX49410~11	
	Control		POS	K25881	K30881	
	Control	0.F03, 1.3FD		%KX41409	%KX49409	Bit
	Method	0 : SIN, 1 : REP	CIN	K25880	K25880 K30880	Dit
			SIN	%KX41408	%KX49408	DIL
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2589	K3089	Word
55				%KW2589	%KW3089	
55	Address [pulse]	-2,147,483,648~2,147,483,647 [pulse]	0	K2580	K3080	Double word
				%KD1290	%KD1540	
	M Code	0 ~ 65,535		K2587	K3087	Word
			0	%KW2587	%KW3087	
	A/D No.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	K25886~87	K30886~87	Bit
				%KX41414~15	%KX49414~15	
	Speed	1 ~ 100,000[pulse/s]	0	K2584	K3084	Double word
				%KD1292	%KD1542	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	K2586	K3086	Word
				%KW2586	%KW3086	

Step	ltem	Setting range	Initial	Dedicated K area		Doto cizo
			value	X axis	Y axis	Data Size
	Coord.	0 : ABS, 1 : INC	ABS	K25984	K30984	Bit
				%KX41572	%KX49572	
	Pattern		END	K25982~83	K30982~83	Bit
		0. END, T. REEF, Z. CONT		%KX41570~71	%KX49570~71	
	Control		POS	K25981	K30981	Bit
	Control	0. FO3, 1. 3FD	F03	%KX41569	%KX49569	
	Method	0 : SIN, 1 : REP	SIN	K25980	K25980 K30980	Dit
			SIN	%KX41568	%KX49568	DIL
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2599	K3099	Word
				%KW2599	%KW3099	
56	Address [pulse]	-2,147,483,648~2,147,483,647 [pulse]		K2590	K3090	Double word
			0	%KD1295	%KD1545	
	M Code	0 ~ 65,535	K2597	K2597	K3097	Word
			0	%KW2597	%KW3097	
	A/D No.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	K25986~87	K30986~87	Bit
				%KX41574~75	%KX49574~75	
	Speed	1 ~ 100,000[pulse/s]	0	K2594 K3094	Double word	
			0	%KD1297	%KD1547	
	Dwall			K2596	K3096	Word
	Dweii	v ~ 50,000[unit.⊪s]	U	%KW2596	%KW3096	woru

Step	ltem	Setting range	Initial	Dedicated K area		Doto cizo
			value	X axis	Y axis	Data Size
	Coord.	0 : ABS, 1 : INC	ABS	K26084	K31084	Bit
				%KX41732	%KX49732	
	Dettern		END	K26082~83	K31082~83	
	Fallem	0. END, 1. REEF, 2. CONT		%KX41730~31	%KX49730~31	Bit
	Control		POS	K26081	K31081	Bit
	Control	0.F03, 1.3FD	F03	%KX41729	%KX49729	
	Mathad	0 : SIN, 1 : REP	SIN	K26080	K26080 K31080	Dit
	Method		SIN	%KX41728	%KX49728	DIL
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2609	K3109	Word
57				%KW2609	%KW3109	
57	Address	Address -2 147 483 648 ~ 2 147 483 647 [pulse]	0	K2600	K3100	Double word
	[pulse]	-2,147,403,040 2,147,403,047 [puise]		%KD1300	%KD1550	
	M Code	0 ~ 65,535	0	K2607	K3107	Word
			0	%KW2607	%KW3107	
	A/D No.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	K26086~87	K31086~87	Bit Double word
				%KX41734~35	%KX49734~35	
	Speed	1 ~ 100,000[pulse/s]	0	K2604	K3104	
			0	%KD1302	%KD1552	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	K2606	K3106	Word
				%KW2606	%KW3106	

Step	ltem	Setting range	Initial	Dedicated K area		Doto cizo
			value	X axis	Y axis	Data Size
	Coord.	0 : ABS, 1 : INC	ABS	K26184	K31184	Bit
				%KX41892	%KX49892	
	Dottorn	0 : END, 1 : KEEP, 2 : CONT	END	K26182~83	K31182~83	Bit
	Pattern			%KX41890~91	%KX49890~91	
	Control		DOS	POS K26181 K31181 %KX41889 %KX49889	K31181	
	Control	0. FO3, 1. 3FD	FU3		Bit	
	Method	0 : SIN, 1 : REP	SIN	K26180	K31180	Bit
			SIN	%KX41888	%KX49888	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2619	K3119	Word
58				%KW2619	%KW3119	
	Address	2 1 4 7 4 9 2 6 4 9 - 2 1 4 7 4 9 2 6 4 7 [puloo]	0	K2610	K3110	Double word
	[pulse]	-2,147,463,646~2,147,463,647 [pulse]	0	%KD1305	%KD1555	
	M Code	0 ~ 65,535	0	K2617	K2617 K3117	Word
			0	%KW2617	%KW3117	
	A/D No.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	K26186~87	K31186~87	Bit
				%KX41894~95	%KX49894~95	
	Speed	1 ~ 100,000[pulse/s]	0	0 K2614 K3114 Dou %KD1307 %KD1557 Dou		
			0		%KD1557	Double word
	Dwall		0	K2616	K3116	Word
	Dweii		U	%KW2616	%KW3116	word
Ston	Itom	Setting range	Initial	I Dedicated K area		Data cizo
------	----------	--------------------------------------	---------	--------------------	-------------	-------------
Step	nem	Setting range	value	X axis	Y axis	Data Size
	Coord			K26284	K31284	
	Coord.	U: ABS, 1: INC	ABS	%KX42052	%KX50052	Bit
	Dottorn		END	K26282~83	K31282~83	
	Fallem	0. END, 1. REEF, 2. CONT		%KX42050~51	%KX50050~51	Bit
	Control		DOS	K26281	K31281	
	Control	0.POS, 1.SPD	P05	%KX42049	%KX50049	Bit
	Method		CINI	K26280	K31280	Dit
		U. SIN, I. KEP	SIN	%KX42048	%KX50048	DIL
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2629	K3129	
50			0	%KW2629	%KW3129	Word
59	Address	-2,147,483,648~2,147,483,647 [pulse]	0	K2620	K3120	Double word
	[pulse]			%KD1310	%KD1560	
	M Codo	0 65 525	0	K2627	K3127)A/ord
	IN CODE	0~05,555	0	%KW2627	%KW3127	word
			0	K26286~87	K31286~87	Dit
	A/D NO.	0. NO.1, 1. NO.2, 2. NO.3, 3. NO.4	0	%KX42054~55	%KX50054~55	Bit
	Spood	$1 \sim 100.000$ [pulse/c]	0	K2624	K3124	Deuble werd
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1312	%KD1562	Double word
	Dwell	ell 0 ~ 50,000[unit:ms]	0	K2626	K3126	Word
			0	%KW2626	%KW3126	vvolu

Stop	Itom	Sotting range	Setting range Initial Dedicated K area		Doto cizo	
Step	nem	Setting range	value	X axis	Y axis	Data Size
	Coord		ABS	K26384	K31384	
	00010.	U. ABS, T. INC	ABS	%KX42212	%KX50212	Bit
	Pattern			K26382~83	K31382~83	
	1 attern	0. END, T. KEEF, Z. CONT	LITE	%KX42210~11	%KX50210~11	Bit
	Control	0 : POS. 1 : SPD	DOS	K26381	K31381	
	Control	0.100, 1.010	103	%KX42209	%KX50209	Bit
	Method		SIN	K26380	K31380	Bit
				%KX42208	%KX50208	Bit
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2639	K3139	Word
60			0	%KW2639	%KW3139	
00	Address	$\frac{1}{2}$ = 2 147 482 648 \sim 2 147 482 647 [pulco]	0	K2630	K3130	Double word
	[pulse]	-2,147,403,040 2,147,403,047 [puise]	0	%KD1315	%KD1565	
	M Code	0 - 65 535	0	K2637	K3137	\\/ord
	IN CODE	0~03,333	0	%KW2637	%KW3137	word
			0	K26386~87	K31386~87	Dit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX42214~15	%KX50214~15	DIL
	Speed	1 . 100.000[puloo/o]	0	K2634	K3134	
	Speed	1 ~ 100,000[pulse/s]	0	%KD1317	%KD1567	Double word
	Durall	0 50 000[0	K2636	K3136)A/and
	Dwell		0	%KW2636	%KW3136	vvora

Ston	Itom	Item Setting range Initia	Initial	Dedicate	d K area	Doto cizo
Step	item	Setting range	value	X axis	Y axis	Dala Size
	Coord		ADC	K26484	K31484	
	Coold.	0. ABS, 1. INC	AD3	%KX42372	%KX50372	Bit
	Pattorn	0 · END 1 · KEEP 2 · CONT		K26482~83	K31482~83	
	Fallem	0. END, 1. REEF, 2. CONT	END	%KX42370~71	%KX50370~71	Bit
	Control		POS	K26481	K31481	
	Control	0.F03, 1.3FD		%KX42369	%KX50369	Bit
	Method		CINI	K26480	K31480	Bit
			311	%KX42368	%KX50368	Dit
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2649	K3149	Word
61			0	%KW2649	%KW3149	
01	Address	SS 2 147 483 648~2 147 483 647 [pulse]	0	K2640	K3140	Double word
	[pulse]		0	%KD1320	%KD1570	
	M Code	0 ~ 65 535	0	K2647	K3147	Word
	W Code	0~00,000	0	%KW2647	%KW3147	word
			0	K26486~87	K31486~87	Dit
	A/D NO.	0. NO.1, 1. NO.2, 2. NO.3, 3. NO.4	0	%KX42374~75	%KX50374~75	DIL
	Speed	1 - 100 000[pulse/s]	0	K2644	K3144	Davible
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1322	%KD1572	Double word
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	K2646	K3146	Word
			0	%KW2646	%KW3146	

Ston	ltem	Setting range	Initial	Dedicate	d K area	Data sizo
Step		Setting range	value	X axis	Y axis	Dala Size
	Coord		ADC	K26584	K31584	
	Coold.	U. ABS, T. INC	ADS	%KX42532	%KX50532	Bit
	Pattern			K26582~83	K31582~83	
		0. END, T. REEF, Z. CONT	LIND	%KX42530~31	%KX50530~31	Bit
	Control		POS	K26581	K31581	
		0.F03, 1.3FD	FU3	%KX42529	%KX50529	Bit
	Method		CINI	K26580	K31580	Bit
		U. SIN, T. KEF	SIN	%KX42528	%KX50528	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2659	K3159	
60			0	%KW2659	%KW3159	vvord
02	Address	0.447.400.040 0.447.400.047 [pulse]	0	K2650	K3150	Double word
	[pulse]	-2,147,483,648~2,147,483,647 [puise]	0	%KD1325	%KD1575	
	M Codo	0 65 525	0	K2657	K3157	
	M Code	0~05,555	0	%KW2657	%KW3157	word
			0	K26586~87	K31586~87	Dit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX42534~35	%KX50534~35	DIL
	Speed	$1 \sim 100.000$ [pulso/s]	0	K2654	K3154	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1327	%KD1577	
	Dwall		0	K2656	K3156	Word
	Dweii		U	%KW2656	%KW3156	word

Ston	Itom	Setting range	Initial	I Dedicated K area		Data sizo
Step	item	Setting range	value	X axis	Y axis	Dala Size
	Coord			K26684	K31684	
	Coord.	U: ABS, 1: INC	ABS	%KX42692	%KX50692	Bit
	Pattern		END	K26682~83	K31682~83	
		U. END, T. KEEP, Z. CONT		%KX42690~91	%KX50690~91	Bit
	Control	0 : POS, 1 : SPD	DOS	K26681	K31681	
			FU3	%KX42689	%KX50689	Bit
	Mathad		CINI	K26680	K31680	Bit
	Ivietriou	U. SIN, T. REP	SIN	%KX42688	%KX50688	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2669	K3169	
			0	%KW2669	%KW3169	Word
63	Address	-2,147,483,648~2,147,483,647 [pulse]	0	K2660	K3160	Double word
	[pulse]		0	%KD1330	%KD1580	
	M Codo	0 65 535	0	K2667	K3167	Word
	W Code	0~00,000	0	%KW2667	%KW3167	volu
				K26686~87	K31686~87	-
	A/D No.	0 : No.1, 1 : No.2, 2 : No.3, 3 : No.4	0	%KX42694~95	%KX50694~95	Bit
	Speed	1 a. 100 000[puloo/o]	0	K2664	K3164	Dauble werd
	Speea	$1 \sim 100,000$ [pulse/s]	0	%KD1332	%KD1582	Double word
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	K2666	K3166	Word
			U	%KW2666	%KW3166	

Stop	Itom	Sotting range	Initial	Initial Dedicated K area		ed K area	Doto cizo
Step	nem	Setting range	value	X axis	Y axis	Data Size	
	Coord		ABC	K26784	K31784		
	Coold.	0. ABS, 1. INC	ADO	%KX42852	%KX50852	Bit	
	Pattern			K26782~83	K31782~83		
	Pallem	0. END, T. REEF, Z. CONT	LIND	%KX42850~51	%KX50850~51	Bit	
	Control	0 : POS, 1 : SPD	POS	K26781	K31781		
			105	%KX42849	%KX50849	Bit	
	Method	0 : SIN, 1 : REP	SIN	K26780	K31780	Bit	
			0111	%KX42848	%KX50848		
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2679	K3179	Word	
64			0	%KW2679	%KW3179		
04	Address	ress	0	K2670	K3170	Double word	
	[pulse]	2,147,400,040 2,147,400,047 [puise]	Ŭ	%KD1335	%KD1585		
	M Code	0 ~ 65 535	0	K2677	K3177	Word	
		0.400,000	Ŭ	%KW2677	%KW3177	Word	
		$0 \cdot No = 1 \cdot 1 \cdot No = 2 \cdot No = 3 \cdot 3 \cdot No = 4$	0	K26786~87	K31786~87	Bit	
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX42854~55	%KX50854~55	Dit	
	Speed	$1 \sim 100000$ [pulse/s]	0	K2674	K3174	Double word	
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1337	%KD1587	Double word	
	Dwoll	0 50 000[unit:ms]	0	K2676	K3176	Word	
	Dweii		0	%KW2676	%KW3176	vvolu	

Sten	ltem	Setting range	Initial	Dedicated K area		Doto cizo
Step		Setting range	value	X axis	Y axis	Data Size
	Coord		ADC	K26884	K31884	
	Coold.	U. ABS, T. INC	AD3	%KX43012	%KX51012	Bit
	Pattern	0 : END, 1 : KEEP, 2 : CONT		K26882~83	K31882~83	
			LIND	%KX43010~11	%KX51010~11	Bit
	Control	0 : POS, 1 : SPD	POS	K26881	K31881	
			105	%KX43009	%KX51009	Bit
	Method	0 : SIN, 1 : REP	SIN	K26880	K31880	Bit
			311	%KX43008	%KX51008	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2689	K3189	
6E			0	%KW2689	%KW3189	Word
00	Address		0	K2680	K3180	Double word
	[pulse]	-2,147,483,848~2,147,483,847 [puise]		%KD1340	%KD1590	
	M Codo	0 65 525	0	K2687	K3187	\M/ord
	IN CODE	0~05,555	0	%KW2687	%KW3187	word
			0	K26886~87	K31886~87	Dit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX43014~15	%KX51014~15	Dit
	Speed	$1 \sim 100.000$ [pulso/s]	0	K2684	K3184	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1342	%KD1592	
	Dwell		0	K2686	K3186	Word
		0 ~ 50,000[unit	0	%KW2686	%KW3186	

Ston	ltem	Setting range	Initial	I Dedicated K area		Data sizo
Step	item	Setting range	value	X axis	Y axis	Dala Size
	Coord		ABS	K26984	K31984	
	Coold.	U. ABS, T. INC	AB3	%KX43172	%KX51172	Bit
	Pattern			K26982~83	K31982~83	
	1 attern	0. END, T. KEEF, Z. CONT	LIND	%KX43170~71	%KX51170~71	Bit
	Control	0 : POS. 1 : SPD	POS	K26981	K31981	
	Control	0.100, 1.010		%KX43169	%KX51169	Bit
	Method		SIN	K26980	K31980	Bit
				%KX43168	%KX51168	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2699	K3199	Word
66			Ŭ	%KW2699	%KW3199	
00	Address	-2 147 483 648~2 147 483 647 [pulse]	0	K2690	K3190	Double word
	[pulse]		0	%KD1345	%KD1595	
	M Code	0 ~ 65 535	0	K2697	K3197	Word
	M Code	0~00,000	0	%KW2697	%KW3197	word
			0	K26986~87	K31986~87	D it
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	U	%KX43174~75	%KX51174~75	Bit
	Speed	$1 \sim 100.000$ [pulso/s]	0	K2694	K3194	Double word
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1347	%KD1597	
	Dwell	0 - 50 000[upit:ms]	0	K2696	K3196	Word
	Dweii		0	%KW2696	%KW3196	woru

Ston	Itom	Setting range	Initial	Dedicated K area		Data sizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord			K27084	K32084	
	Coord.	U. ABS, T. INC	ABS	%KX43332	%KX51332	Bit
	Dottorn		END	K27082~83	K32082~83	
	Fallelli	U. END, T. REEF, Z. CONT		%KX43330~31	%KX51330~31	Bit
	Control		POS	K27081	K32081	
		0.F03, 1.3FD	103	%KX43329	%KX51329	Bit
	Method	0 : SIN, 1 : REP	CINI	K27080	K32080	Dit
			SIN	%KX43328	%KX51328	Dit
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2709	K3209	Word
67			0	%KW2709	%KW3209	
07	Address	0.147.492.649 - 0.147.492.647 [puloo]	0	K2700	K3200	Double word
	[pulse]	-2,147,463,646 ^{°°} 2,147,463,647 [pulse]		%KD1350	%KD1600	
	M Code	0 65 525	0	K2707	K3207	
	W Code	0~ 65,555	0	%KW2707	%KW3207	word
			0	K27086~87	K32086~87	Dit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX43334~35	%KX51334~35	BI
	Speed	1 a. 100 000[pulse/s]	0	K2704	K3204	Double word
	Speea	$1 \sim 100,000$ [pulse/s]	0	%KD1352	%KD1602	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	K2706	K3206	Word
			0	%KW2706	%KW3206	

Ston	ltom	Sotting range	Initial	Dedicated K area		Doto cizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord		ABC	K27184	K32184	
	00010.	0. ABS, 1. INC	ADO	%KX43492	%KX51492	Bit
	Pattern		END	K27182~83	K32182~83	
	Falleni	0. LIND, T. KEEF, Z. CONT		%KX43490~91	%KX51490~91	Bit
	Control		POS	K27181	K32181	Bit
	Control	0.100, 1.010		%KX43489	%KX51489	
	Method		SIN	K27180	K32180	Bit
			Silv	%KX43488	%KX51488	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2719	K3219	Word
60			0	%KW2719	%KW3219	
08	Address	2 147 492 649 a 2 147 492 647 [puloo]	0	K2710	K3210	Double word
	[pulse]	-2,147,403,040 -2,147,403,047 [puise]	0	%KD1355	%KD1605	
	M Codo	0 65 525	0	K2717	K3217) A / a mal
	M Code	0 ~ 65,555	0	%KW2717	%KW3217	word
			0	K27186~87	K32186~87	Dit
	A/D NO.	0. N0.1, 1. N0.2, 2. N0.3, 3. N0.4	0	%KX43494~95	%KX51494~95	DIL
	Speed	1 . 100.000[pulles/o]	0	K2714	K3214	
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1357	%KD1607	Double word
	Dwall		0	K2716	K3216))(ord
	Dweil		0	%KW2716	%KW3216	vvora

Ston	ltom	Sotting range	Initial	Dedicate	ed K area	Doto cizo
Step	item	Setting range	value	X axis	Y axis	Data Size
	Coord			K27284	K32284	
	Coold.	U. ABS, T. INC	ADS	%KX43652	%KX51652	Bit
	Dottorn			K27282~83	K32282~83	
	rattern	U. END, T. KEEP, Z. CONT	END	%KX43650~51	%KX51650~51	Bit
	Control		POS	K27281	K32281	
	Control	0.F03, 1.3FD		%KX43649	%KX51649	Bit
	Method		CINI	K27280	K32280	Bit
		U. SIN, T. REP	SIN	%KX43648	%KX51648	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2729	K3229	Word
60			0	%KW2729	%KW3229	
03	Address	Address 2 147 492 649 - 2 147 492 647 [puloe]	0	K2720	K3220	Double word
	[pulse]	-2,147,403,040 2,147,403,047 [puise]	0	%KD1360	%KD1610	
	M Code	0 - 65 535	0	K2727	K3227	Word
	IN COde	0~03,333	0	%KW2727	%KW3227	word
			0	K27286~87	K32286~87	Bit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 5.10.4	0	%KX43654~55	%KX51654~55	Dit
	Speed	$1 \sim 100.000$ [pulso/s]	0	K2724	K3224	Double word
	Speed	1 ~ 100,000[pulse/s]	0	%KD1362	%KD1612	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	K2726	K3226	Word
			U	%KW2726	%KW3226	

Stop	Itom	Setting range	Initial	al Dedicated K area		Data sizo
Step	nem	Setting range	value	X axis	Y axis	Dala Size
	Coord		ADC	K27384	K32384	
	Coold.	U. ABS, T. INC	AD3	%KX43812	%KX51812	Bit
	Pattorn			K27382~83	K32382~83	
	Fallem	0. END, T. REEF, Z. CONT	END	%KX43810~11	%KX51810~11	Bit
	Control		DOC	K27381	K32381	
	Control	0. FO3, 1. 3FD	F03	%KX43809	%KX51809	Bit
	Method		CINI	K27380	K32380	Bit
		U. SIN, T. KEF	SIN	%KX43808	%KX51808	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2739	K3239	Word
70			0	%KW2739	%KW3239	
70	Address	2 1 4 7 4 9 2 6 4 9 . 2 1 4 7 4 9 2 6 4 7 [pulos]	0	K2730	K3230	Double word
	[pulse]	-2,147,463,646 ^{°°} 2,147,463,647 [puise]		%KD1365	%KD1615	
	M Codo	0 65 525	0	K2737	K3237	
	M Code	0 ~ 65,535	0	%KW2737	%KW3237	word
			0	K27386~87	K32386~87	Dit
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX43814~15	%KX51814~15	DIL
	Speed	1 - 100 000[puloo/o]	0	K2734	K3234	Devila word
	Speed	1 ~ 100,000[pulse/s]	0	%KD1367	%KD1617	Double word
	Dwoll	0 50 000[upit:ms]	0	K2736	K3236	Word
	Dweii		U	%KW2736	%KW3236	word

Ston	ltom	Item Setting range	Initial	Dedicate	ed K area	Doto cizo	
Step	item	Setting range	value	X axis	Y axis	Data Size	
	Coord			K27484	K32484		
	Coord.	0 : ABS, 1 : INC	ABS	%KX43972	%KX51972	Bit	
	Dottorn	0 : END, 1 : KEEP, 2 : CONT		K27482~83	K32482~83		
	Pallem		END	%KX43970~71	%KX51970~71	Bit	
	Control	0 : POS, 1 : SPD	DOS	K27481	K32481		
	Control		P05	%KX43969	%KX51969	Bit	
	Method	0 : SIN, 1 : REP	CINI	K27480	K32480	Rit	
			SIN	%KX43968	%KX51968	Dit	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2749	K3249	Word	
71			0	%KW2749	%KW3249		
7 1	Address	$-2.147.483.648 \sim 2.147.483.647$ [pulse]	0	K2740	K3240	Double word	
	[pulse]	-2,147,403,040 2,147,403,047 [puise]		%KD1370	%KD1620	Double word	
	M Codo	0 65 525	0	K2747	K3247)A/and	
	M Code	0~05,555	0	%KW2747	%KW3247	word	
			0	K27486~87	K32486~87	Bit	
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX43974~75	%KX51974~75	ы	
	Speed	1 - 100 000[pulce/c]	0	K2744	K3244	Double word	
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1372	%KD1622		
	Dwell	0 - 50 000[unit:ms]	0	K2746	K3246	Word	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	%KW2746	%KW3246	vvord	

Ston	ltom	Item Setting range	Initial	Dedicate	ed K area	Dete cize	
Step	item	Setting range	value	X axis	Y axis	Data Size	
	Coord		ADC	K27584	K32584		
	Coold.	U. ABS, T. INC	AD3	%KX44132	%KX52132	Bit	
	Pattorn			K27582~83	K32582~83		
	Fallem		END	%KX44130~31	%KX52130~31	Bit	
	Control	0 : POS, 1 : SPD	POS	K27581	K32581		
	Control		F03	%KX44129	%KX52129	Bit	
	Method		SIN	K27580	K32580	Dit	
		U. SIN, T. KEF	311	%KX44128	%KX52128	DIL	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2759	K3259	Word	
70			0	%KW2759	%KW3259		
12	Address	-2,147,483,648~2,147,483,647 [pulse]	0	K2750	K3250	Double word	
	[pulse]			%KD1375	%KD1625		
	M Codo	0 65 525	0	K2757	K3257		
	M Code	0 ~ 65,535	0	%KW2757	%KW3257	word	
			0	K27586~87	K32586~87	Dit	
	A/D NO.	0. N0.1, 1. N0.2, 2. N0.3, 3. N0.4	0	%KX44134~35	%KX52134~35	DIL	
	Speed	4 400 000[]	0	K2754	K3254	Davible ward	
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1377	%KD1627	Double word	
	Dwall		0	K2756	K3256		
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	%KW2756	%KW3256	vvora	

Stop	ltom	Item Setting range	Initial	Dedicate	ed K area	Doto cizo	
Step	nem	Setting range	value	X axis	Y axis	Data Size	
	Coord		ARC	K27684	K32684	Bit	
	Coord.	U. ABS, T. INC	ADS	%KX44292	%KX52292		
	Dottorn	0 : END, 1 : KEEP, 2 : CONT		K27682~83	K32682~83		
	Fallem		LIND	%KX44290~91	%KX52290~91	Bit	
	Control		DOS	K27681	K32681		
	Control	0 : POS, 1 : SPD	P05	%KX44289	%KX52289	Bit	
	Method	0 : SIN, 1 : REP	CINI	K27680	K32680	Dit	
			SIN	%KX44288	%KX52288	ы	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2769	K3269	Word	
72			0	%KW2769	%KW3269		
75	Address	$-2.147.483.648 \sim 2.147.483.647$ [pulse]	0	K2760	K3260	Double word	
	[pulse]	-2,147,403,040 2,147,403,047 [puise]		%KD1380	%KD1630		
	M Code	0 ~ 65 535	0	K2767	K3267	Word	
		0~03,333	0	%KW2767	%KW3267	word	
			0	K27686~87	K32686~87	Dit	
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX44294~95	%KX52294~95	DIL	
	Speed	1 . 100.000[puloo/o]	0	K2764	K3264	Double word	
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1382	%KD1632		
	Dwall		0	K2766	K3266	\M/ord	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	%KW2766	%KW3266	vvora	

Stop	Itom	Sotting rongo	Initial	Dedicate	d K area	Doto cizo	
Step	item	Setting range	value	X axis	Y axis	Data Size	
	Coord		ADC	K27784	K32784		
	Coold.	U. ABS, T. INC	AD3	%KX44452	%KX52452	Bit	
	Pattern			K27782~83	K32782~83		
			END	%KX44450~51	%KX52450~51	Bit	
	Control	0 : POS, 1 : SPD	POS	K27781	K32781		
	Control		FU3	%KX44449	%KX52449	Bit	
	Method	0 : SIN, 1 : REP	SIN	K27780	K32780	Di+	
			Silv	%KX44448	%KX52448	Dit	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2779	K3279	Word	
74			0	%KW2779	%KW3279		
74	Address [pulse]	-2,147,483,648~2,147,483,647 [pulse]	0	K2770	K3270	Double word	
				%KD1385	%KD1635		
	M Codo	0 65 525	0	K2777	K3277) A / a mal	
	M Code	0~85,555	0	%KW2777	%KW3277	word	
			0	K27786~87	K32786~87	Dit	
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX44454~55	%KX52454~55	Bit	
	Speed	4 400 000[]	0	K2774	K3274	Dauble ward	
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1387	%KD1637	Double word	
	Dwoll	0 50 000[upit:ms]	0	K2776	K3276	Word	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	%KW2776	%KW3276	vvora	

Ston	ltom	Item Setting range	Initial	Dedicate	d K area	Doto oizo	
Step	item	Setting range	value	X axis	Y axis	Data Size	
	Coord			K27884	K32884		
	Coord.	U.ABS, I.INC	ADS	%KX44612	%KX52612	Bit	
	Pattern	0 : END, 1 : KEEP, 2 : CONT		K27882~83	K32882~83		
			END	%KX44610~11	%KX52610~11	Bit	
	Control		DOS	K27881	K32881		
	Control	0: POS, 1: SPD	P03	%KX44609	%KX52609	Bit	
	Method		CINI	K27880	K32880	Dit	
		U. SIN, T. KEP	SIN	%KX44608	%KX52608	DIL	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2789	K3289	Word	
75			0	%KW2789	%KW3289		
75	Address		0	K2780	K3280	Devilia	
	[pulse]	[pulse] -2,147,483,648~2,147,483,647 [pulse] 0		%KD1390	%KD1640	Double word	
	M Codo	0 65 535	0	K2787	K3287	\A/a rd	
	W Code	0~00,000	0	%KW2787	%KW3287	vvora	
		$0 \cdot N \circ 1 \cdot 1 \cdot N \circ 2 \cdot 2 \cdot N \circ 3 \cdot 3 \cdot N \circ 4$	0	K27886~87	K32886~87	Bit	
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX44614~15	%KX52614~15	DIL	
	Croad	1 - 100 000[pulce/o]	0	K2784	K3284	Double word	
	Opeed	$1 \sim 100,000$ [pulse/S]	0	%KD1392	%KD1642		
	Dwell	0 - 50 000[upit:ms]	0	K2786	K3286	Word	
	Dwell	0 ~ 50,000[unit: ^{ms}]	U	%KW2786	%KW3286	vvora	

Stop	Item Setting range		Initial	Dedicate	d K area	Doto cizo	
Step	nem	Setting range	value	X axis	Y axis	Data Size	
	Coord		ABC	K27984	K32984		
	C0010.	0. ABS, 1. INC	ADO	%KX44772	%KX52772	Bit	
	Pattern	0 : END, 1 : KEEP, 2 : CONT		K27982~83	K32982~83		
				%KX44770~71	%KX52770~71	Bit	
	Control	0 : POS, 1 : SPD	POS	K27981	K32981		
	Control		FU3	%KX44769	%KX52769	Bit	
	Method	0 : SIN, 1 : REP	SIN	K27980	K32980	Dit	
	Method			%KX44768	%KX52768	BIL	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2799	K3299	Word	
70				%KW2799	%KW3299		
70	Address			K2790	K3290	Double word	
	[pulse] -2,147,483,648~2,147,483,647 [pulse] 0		%KD1395	%KD1645	Double word		
	M Codo	0 65 525	0	K2797	K3297	\\/ord	
		0~05,555	0	%KW2797	%KW3297	word	
			0	K27986~87	K32986~87	Dit	
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX44774~75	%KX52774~75	Bit	
	Speed	1 - 100.000[pulpo/o]	0	K2794	K3294	Double word	
	Speed	1 ¹⁰ 100,000[pulse/s]	0	%KD1397	%KD1647		
	Dwoll	0 50 000[upit:ms]	0	K2796	K3296	Word	
	Dweii	o ~ 50,000[unin.⊪s]	U	%KW2796	%KW3296	Word	

Ston	ltom	Item Setting range	Initial	Dedicate	d K area	Doto cizo	
Step	nem	Setting range	value	X axis	Y axis	Dala Size	
	Coord			K28084	K33084	Bit	
	Coold.	U. ABS, T. INC	ADS	%KX44932	%KX52932		
	Dottorn	m 0 : END, 1 : KEEP, 2 : CONT		K28082~83	K33082~83		
	Pallem		END	%KX44930~31	%KX52930~31	Bit	
	Control	0 : POS, 1 : SPD	DOS	K28081	K33081		
	Control		P05	%KX44929	%KX52929	Bit	
	Method			K28080	K33080	Dit	
		U. SIN, T. REP	SIN	%KX44928	%KX52928	DIL	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2809	K3309	Word	
77			0	%KW2809	%KW3309		
11	Address	$2147492649\sim 2147492647$ [pulse]	0	K2800	K3300	Double word	
	[pulse]	-2,147,403,040 -2,147,483,047 [pulse]	0	%KD1400	%KD1650	Double word	
	M Codo	0 65 525	0	K2807	K3307) () or al	
	W Code	0~05,555	0	%KW2807	%KW3307	word	
			0	K28086~87	K33086~87	Dit	
	A/D NO.	0.110.1, 1.110.2, 2.110.3, 3.110.4	0	%KX44934~35	%KX52934~35	Dit	
	Speed	4 400 000[]	0	K2804	K3304	Double word	
	Speed	$1 \sim 100,000$ [puise/s]	0	%KD1402	%KD1652	Double word	
	Dwoll	0 50 000[upit:ms]	0	K2806	K3306) A / a mal	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	%KW2806	%KW3306	vvora	

Stop	Itom	Setting range	Initial	Dedicate	ed K area	Doto cizo	
Step	item	Setting range	value	X axis	Y axis	Dala Size	
	Coord		ADC	K28184	K33184		
	Coord.	U.ABS, I.INC	ADS	%KX45092	%KX53092	Bit	
	Pattern	0 : END, 1 : KEEP, 2 : CONT		K28182~83	K33182~83		
			END	%KX45090~91	%KX53090~91	Bit	
	Control	0 : POS, 1 : SPD	POS	K28181	K33181		
	Control		FU3	%KX45089	%KX53089	Bit	
	Method		SIN	K28180	K33180	Dit	
			SIN	%KX45088	%KX53088	Dit	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2819	K3319	Word	
70			0	%KW2819	%KW3319		
10	Address	2 147 482 648 ~ 2 147 482 647 [pulco]	0	K2810	K3310	Double word	
	[pulse] -2,147,463,648~2,147,463,647 [pulse]		0	%KD1405	%KD1655	Double word	
	M Code	0 - 65 535	0	K2817	K3317	Word	
	W Code	0~00,000	0	%KW2817	%KW3317	word	
			0	K28186~87	K33186~87	D:4	
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX45094~95	%KX53094~95	Bit	
	0 1		0	K2814	K3314	Dauthlaurand	
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1407	%KD1657	Double word	
	Durall		0	K2816	K3316		
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	%KW2816	%KW3316	Word	

Ston	ltom	tem Setting range	Initial	Dedicate	ed K area	Dete cize	
Step	nem	Setting range	value	X axis	Y axis	Dala Size	
	Coord			K28284	K33284		
	Coold.	U. ABS, T. INC	ADS	%KX45252	%KX53252	Bit	
	Pattern			K28282~83	K33282~83		
			END	%KX45250~51	%KX53250~51	Bit	
	Control	0 : POS, 1 : SPD	POS	K28281	K33281		
	Control		P05	%KX45249	%KX53249	Bit	
	Method		CINI	K28280	K33280	Dit	
		U. SIN, T. KEP	SIN	%KX45248	%KX53248	ы	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2829	K3329	Word	
70			0	%KW2829	%KW3329		
79	Address	SS 2 1 47 492 649 - 2 1 47 492 647 [puloe]	0	K2820	K3320	Double word	
	[pulse]	-2,147,403,046 -2,147,483,047 [pulse]	0	%KD1410	%KD1660	Double word	
	M Codo	0 65 525	0	K2827	K3327	\0 /a and	
	IN Code	0 ~ 05,555	0	%KW2827	%KW3327	vvoru	
			0	K28286~87	K33286~87	Dit	
	A/D NO.	0. NO.1, 1. NO.2, 2. NO.3, 3. NO.4	0	%KX45254~55	%KX53254~55	DIL	
	Speed	1 . 100.000[puloo/o]	0	K2824	K3324		
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1412	%KD1662		
	Dwall		0	K2826	K3326	Word	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	%KW2826	%KW3326	vvord	

Ston	Itom	Item Setting range	Initial	Dedicate	ed K area	Data ciza	
Step	nem	Setting range	value	X axis	Y axis	Dala Size	
	Coord			K28384	K33384		
	Coord.	U. ABS, T. INC	ADS	%KX45412	%KX53412	Bit	
	Pattern			K28382~83	K33382~83		
			END	%KX45410~11	%KX53410~11	Bit	
	Control	0 : POS, 1 : SPD	POS	K28381	K33381		
	Control		100	%KX45409	%KX53409	Bit	
	Method		CINI	K28380	K33380	Bit	
			0111	%KX45408	%KX53408	Dit	
	REP Step	0 ~ 30 (0 ~ 80 for high - end)	0	K2839	K3339	Word	
80			0	%KW2839	%KW3339		
00	Address	$2147492649\sim 2147492647$ [pulso]	0	K2830	K3330	Double word	
	[pulse]	-2,147,403,040 2,147,403,047 [puise]	0	%KD1415	%KD1665	Double word	
	M Code	0 - 65 535	0	K2837	K3337	Word	
	M Code	0~00,000	0	%KW2837	%KW3337	word	
			0	K28386~87	K33386~87	Bit	
	A/D NO.	0.10.1, 1.10.2, 2.10.3, 3.10.4	0	%KX45414~15	%KX53414~15	Bit	
	Speed	1 . 100.000[puloe/c]	0	K2834	K3334	Double word	
	Speed	$1 \sim 100,000$ [pulse/s]	0	%KD1417	%KD1667	Double word	
	Dwoll	0 50 000[upit:ms]	0	K2836	K3336	Word	
	Dwell	0 ~ 50,000[unit: ^{ms}]	0	%KW2836	%KW3336	Word	

Appendix 3 Motor Wiring Example

Appendix 3.1 Stepping Motor Wiring Example

Here describes wiring example between XGB and stepping motor. In case of using stepping motor not described here, refer to relevant driver's user manual.

(1) Connection to a stepping motor driver (DC5V Power)



(2) Connection to a stepping motor driver (DC24V Power)

				Max. 2m	(Note 4)
	XGB PLC				Stepping motor driver
	Signal	Ch0	Ch1		
1	Pulse	P20	P21		CW-
1	Common	COM	COM	2K, 1/2W (klaste2)	CW+
	Direction	P22	P23	(NOLE2)	CCW-
1	Common	COM	COM	2K, 1/2W	CCW+
- 1	+24V Input	DC24V	DC24V	DC24V	
- 1					
				(Note5) (Note1)	
	DOG	P04	P06	(NOLET)	TIMING
1	Origin	P05	P07		COM
- 1	Low limit	P00	P02		
1	High limit	P01	P03		
(Note3)	Emg. stop	Inj	out		
	Common	COM)(Input	DC24V	

- (Note1) In case of VEXTA PKD, timing output is on every time a motor rotates 7.2 degrees. For precise home return, timing output and origin sensor should be structured by AND circuit. Depending on a system's features, it is recommended to use **home return only by DOG signal or origin sensor by origin signal** (XGB origin input rating is DC 24V).
- (Note2) Connect resistors suitable for the driver in series if DC24V is used.
- (Note3) Although origin, DOC, upper/lower limit signals are with fixed contact, it may be used for general input if they are not used. Emergency stop is available by the command (EMG).
- (Note4) In case of XGB standard type, since only pulse + direction mode is available, change input mode of stepping motor driver to 1 phase input mode.
- (Note 5) The above figure is example of XGB standard type. For high-end type, Origin, DOG, upper/lower limit input contact point is different with standard type.



Appendix 3.2 Servo Motor Wiring Example

Here describes wiring example between XGB and servo motor. In case of using servo motor not described here, refer to relevant driver's user manual.

(1) Connection to a servo motor driver (MR-J2/J2S- \Box A)



(Note1) The rating of XGB origin input is DC24V. Make sure to connect the open collector output of a driver.

- (Note2) Although origin, DOC, upper/lower limit signals are with fixed contact, it may be used for general input if they are not used. Emergency stop is available by the command (EMG).
- (Note3) In case of XGB standard type, since only pulse + direction mode is available, change input mode of servo motor driver to 1 phase input mode.
- (Note4) The above figure is example of XGB standard type. For high-end type, Origin, DOG, upper/lower limit input contact point is different with standard type.





(2) Connection to a servo motor driver (FDA-5000 AC Servo Driver)

(Note1) The rating of XGB is 24VDC. If it is line driver output, contact is not connected. In the case, use a convert from line driver output to open collector output or use home return only by DOG signal/origin sensor of origin signal.

(Note2) Although origin, DOC, upper/lower limit signals are with fixed contact, it may be used for general input if they are not used. Emergency stop is available by the command (EMG).

(Note3) If using DC24V, make sure to connect resistor suitable for a driver (1.5K, 1/2W) in series.

(Note4) Since the positioning pulse of XGB forward/reverse-rotates by the rotation direction as in the below figure, make sure to change the input mode of a servo motor driver into 1 phase input mode prior to use.



(3) Connection to a servo motor driver (XGT Servo XDA-S)

(a) In case of XBM-DN**S



- (Note1) The rating of Origin input for XGB stand type is 24VDC. If it is line driver output, contact can't be connected. In the case, use a convert from line driver output to open collector output or use home return only by DOG signal/origin sensor of origin signal.
- (Note2) Although origin, DOC, upper/lower limit signals are with fixed contact, it may be used for general input if they are not used. Emergency stop is available by the command (EMG).
- (Note3) The above wiring is applied when P07-01=27(positioning mode)
- (Note4) Since only pulse + direction mode is available for XGB standard type, make sure to change the input mode of a servo motor driver into pulse + direction mode prior to use
- (Note5) In the above wiring, Axis X of XGB standard built-in positioning is used.

(b) In case of XBC/XEC-DN**H



- (Note1) The rating of Origin input for XGB stand type is 24VDC. If it is line driver output, contact can't be connected. In the case, use a convert from line driver output to open collector output or use home return only by DOG signal/origin sensor of origin signal.
- (Note2) Although origin, DOC, upper/lower limit signals are with fixed contact, it may be used for general input if they are not used. Emergency stop is available by the command (EMG).
- (Note3) The above wiring is applied when P07-01=27(positioning mode)
- (Note4) Since pulse + direction mode and CW/CCW mode are available for XGB high-end type, make sure to change the input mode of a servo motor driver according to output mode of positioning module
- (Note5) In the above wiring, Axis X of XGB high-end type built-in positioning is used.



(4) Connection to a servo motor driver (XGT Servo XDL-S)

ſ

* This picture is based on 1-axis. For more information about 2-axis wiring, refer to pin information.

(Note1) Input Signal DI1~DIA, Output Signal DO1~DO5 is assigned initial signal from factory shipment (Note2) ** Not assigned Signal. Allocation can be changed by setting servo parameter

(b) In case of XBC/XEC-DN**H



* This picture is based on 1-axis. For more information about 2-axis wiring, refer to pin information.

(Note1) Input Signal D11~DIA, Output Signal DO1~DO5 is assigned initial signal from factory shipment (Note2) ** Not assigned Signal. Allocation can be changed by setting servo parameter

Appendix 4 Dimension (Unit : mm)

וזחו (1993) (1993) (1993) (1993) 60 XĠB E SULLING E 0 0 PWR EXPANSION CONNECTOR RUN 90 \leq ίΩ 4 0 0 L. Ŀ 30 64

٦

-. XBM-DR16S







- XB(E)C-DR20/30S(U), XB(E)C-DN20/30SU, XB(E)C-DP20/30SU

-. XB(E)C-DR40SU, XB(E)C-DN40SU, XB(E)C-DP40SU



-. XB(E)C-DR60SU, XB(E)C-DN60SU, XB(E)C-DP60SU



(3) Compact High-end type main unit

Γ

-. XBC-DN32H/XEC-DN32H/XEC-DP32H



-. XBC-DR32H/XEC-DR32H







-. XBC-DR64H/XEC-DR64H



(4) Extended I/O module

Γ

-. XBE-DC32A, XBE-TR32A



-. XBE-RY16A





-. XBE-DC08A, XBE-DC16A, XBE-TN08A, XBE-TN16A

-. XBE-DR16A, XBE-RY08A



(5) Communication module

Γ

-. XBL-C41/21A



-. XBL-EMTA



(5) Special module

-. XBF-AD04A



٦

-. XBF-DV04A



Warranty

1. Warranty Period

The product you purchased will be guaranteed for 18 months from the date of manufacturing.

2. Scope of Warranty

Any trouble or defect occurring for the above-mentioned period will be partially replaced or repaired. However, please note the following cases will be excluded from the scope of warranty.

- (1) Any trouble attributable to unreasonable condition, environment or handling otherwise specified in the manual,
- (2) Any trouble attributable to others' products,
- (3) If the product is modified or repaired in any other place not designated by the company,
- (4) Due to unintended purposes
- (5) Owing to the reasons unexpected at the level of the contemporary science and technology when delivered.
- (6) Not attributable to the company; for instance, natural disasters or fire
- 3. Since the above warranty is limited to PLC unit only, make sure to use the product considering the safety for system configuration or applications.

Environmental Policy

LS ELECTRIC Co., Ltd supports and observes the environmental policy as below.





www.ls-electric.com

LS ELECTRIC Co., Ltd.

- Headquarter
- LS-ro 127(Hogye-dong) Dongan-gu, Anyang-si, Gyeonggi-Do, 14119, Korea Seoul Office
- LS Yongsan Tower, 92, Hangang-daero, Yongsan-gu, Seoul, 04386, Korea Tel: 82-2-2034-4033, 4888, 4703 Fax: 82-2-2034-4588 E-mail: automation@ls-electric.com
- Overseas Subsidiaries
- LS ELECTRIC Japan Co., Ltd. (Tokyo, Japan) Tel: 81-3-6268-8241 E-Mail: japan@ls-electric.com
- LS ELECTRIC (Dalian) Co., Ltd. (Dalian, China) Tel: 86-411-8730-6495 E-Mail: china.dalian@lselectric.com.cn
- LS ELECTRIC (Wuxi) Co., Ltd. (Wuxi, China) Tel: 86-510-6851-6666 E-Mail: china.wuxi@lselectric.com.cn
- LS ELECTRIC Middle East FZE (Dubai, U.A.E.) Tel: 971-4-886-5360 E-Mail: middleeast@ls-electric.com
- LS ELECTRIC Europe B.V. (Hoofddorp, Netherlands)
- Tel: 31-20-654-1424 E-Mail: europartner@ls-electric.com • LS ELECTRIC America Inc. (Chicago, USA)
- Tel: 1-800-891-2941 E-Mail: sales.us@lselectricamerica.com • LS ELECTRIC Turkey Co., Ltd.
 - Tel: 90-212-806-1225 E-Mail: turkey@ls-electric.com

- Overseas Branches
- LS ELECTRIC Tokyo Office (Japan)
- Tel: 81-3-6268-8241 E-Mail: tokyo@ls-electric.com LS ELECTRIC Beijing Office (China)
- Tel: 86-10-5095-1631 E-Mail: china.auto@lselectric.com.cn • LS ELECTRIC Shanghai Office (China)
- Tel: 86-21-5237-9977 E-Mail: china.auto@lselectric.com.cn • LS ELECTRIC Guangzhou Office (China)
- Tel: 86-20-3818-2883 E-Mail: china.auto@lselectric.com.cn • LS ELECTRIC Chengdu Office (China)
- Tel: 86-28-8670-3201 E-Mail: china.auto@lselectric.com.cn
- LS ELECTRIC Qingdao Office (China) Tel: 86-532-8501-2065 E-Mail: china.auto@lselectric.com.cn • LS ELECTRIC Nanjing Office (China)
- Tel: 86-25-8467-0005 E-Mail: china.auto@lselectric.com.cn
- LS ELECTRIC Bangkok Office (Thailand) Tel: 66-90-950-9683 E-Mail: thailand@ls-electric.com
- LS ELECTRIC Jakarta Office (Indonesia) Tel: 62-21-2933-7614 E-Mail: indonesia@ls-electric.com
- LS ELECTRIC Moscow Office (Russia) Tel: 7-499-682-6130 E-Mail: info@lselectric-ru.com
- LS ELECTRIC America Western Office (Irvine, USA)
 - Tel: 1-949-333-3140 E-Mail: america@ls-electric.com

Disclaimer of Liability LS ELECTRIC has reviewed the information in this publication to ensure consistency with the hardware and software described. However, LS ELECTRIC cannot guarantee full consistency, nor be responsible for any damages or compensation, since variance cannot be precluded entirely. Please check again the version of this publication before you use the product. © LS ELECTRIC Co., Ltd 2015 All Right Reserved.